

ASS. REC. BY:

REF:

CS3/CTI19013979/Fcd317

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI

Date/Time: 8/8/19 @ 10:00am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBC 7824D

Insured: GBB 41534

at Workshop in/s

MCS Auto

Tel: 62961939

of 1100 Seangoon Road

Policy No: DMCVSN18376018000

Claim No: SNM19D203496C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:35am @ 13/8/19

Person Contacted: Stephanie

Vehicle IN / OUT

Date/Time	Action/Instruction
	Johnnie (X)
	FBC 7824D-X
	GBB 41534-X
	Dismantle: 14/8/2019
	After repair: 29/8/2019

ASS. REC. BY:

REF: CTP

PRS

ASSIGNMENT

From: _____ Date: 13/8/19

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: FBC 7824Dat Workshop m/s MCS Autoof 1100 Serangoon Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBC 7824D Yr Regn: JUL / 2008Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: SUZUKI DR2100SM c.c. 400Colour: BLACK A/C: Insured / Std / NI / NASp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SK44A104791Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 120/70R17 DunlopR: 160/60R17 Pirelli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 3 mm R/Bal. 3 mmL/Bal. - mm L/Bal. - mmD.O.A. 24/07/19 D.O.I. 13/8/19Survey held at gen enterpriseDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$2000 - \$2500
	Repair days: 4 days
	Request for new/2nd exhaust (need to provide invoice)
	MV: \$9500
	PV: \$6284
	NV: \$3000 *

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation: _____

S + RS, _____ \$

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / L&L: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

150

150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019		27 Sep 2019 16:50 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	MOHAMED FARHAN BIN MOHAMED SHARIFF, ID: S8136400A
Vehicle Reg. No.:	FBC7824D
Claim Type:	TP / SNM19D203496C02
Vehicle Reg. No. (Insured):	GBB4153G
Repairster:	Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 08/10/2019]

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Niyitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 8 August 2019 10:08 AM
To: Sally
Cc: assignments
Subject: RE: [Spam-pop3] RE: OUR REF: SNM19D203496-GBB4153G- CBS - FW: Fax Message NO.1911 PRS FBC7824D

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

-----Original Message-----

From: Sally [mailto:info@catherinelimllc.com]
Sent: Monday, 5 August, 2019 10:11 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: [Spam-pop3] RE: OUR REF: SNM19D203496-GBB4153G- CBS - FW: Fax Message NO.1911 PRS FBC7824D

Dear Sir (Without Prejudice)

We refer to your email.

Our client is not agreeable to your list of surveyor and we attached herewith our client's list of surveyor.

Regards

Sally Goh
Catherine Lim LLC
20 Havelock Road #03-01
Central Square
Singapore 059765
Email: info@catherinelimllc.com

-----Original Message-----

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]
Sent: Friday, August 02, 2019 6:02 PM
To: info@catherinelimllc.com
Subject: [Spam-pop3] RE: OUR REF: SNM19D203496-GBB4153G- CBS - FW: Fax Message NO.1911 PRS FBC7824D

WITHOUT PREJUDICE

Dear Sir,

We refer to your fax of 22.02.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

-----Original Message-----

From: Claims Dept of CTI
Sent: Friday, 2 August, 2019 5:47 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; info@catherinelimllc.com
Subject: OUR REF: SNM19D203496-GBB4153G- CBS - FW: Fax Message NO.1911 PRS FBC7824D

Dear Boon Sen,

Please conduct PRS for FBC7824D.

Note : officer in charge - Boon Sen 63896171.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: FA-X5575C-16A-CL
Sent: Friday, August 02, 2019 5:32 PM
To: Claims Dept of CTI
Subject: FW: Fax Message NO.1911

-----Original Message-----

From: RC6004F-15A-CL@sg.cntaiping.com [mailto:RC6004F-15A-CL@sg.cntaiping.com]
Sent: Friday, August 02, 2019 2:33 PM
To: FA-X5575C-16A-CL
Subject: Fax Message NO.1911

This E-mail was sent from "RC6004F-15A-CL" (MP C6004ex).

Queries to: RC6004F-15A-CL@sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	400A
Vehicle Details	
Vehicle No.:	FBC7824D
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Aug 2019
Vehicle Make:	SUZUKI
Vehicle Model:	DRZ400SM M
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	K419180272
Chassis No.:	SK44A104791
Maximum Power Output:	-
Open Market Value:	\$7,396.00
Original Registration Date:	04 Jul 2008
First Registration Date:	04 Jul 2008
Transfer Count:	5
Actual ARF Paid:	\$1,110.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jul 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$7,073.00
COE Rebate Amount:	\$6,284.00
Total Rebate Amount:	\$6,284.00

The information contained herein is correct as at 14 Aug 2019

OK



HUAWEI P30 Pro (128GB)
\$54
\$119 2-year plan
40GB + FREE weekend data

Home (U) > Motorbikes (/categories/motorbikes-108) > Motorbikes for Sale (/categories/motorbikes-108/motorbikes-for-sale-1592)
> Class 2A (/categories/motorbikes-108/motorbikes-for-sale-1592/class-2a-1594)



URGENT SALE!! SUZUKI DRZ 400 SM

19

Chat

Make Offer

1 week ago by eddyhazard (/eddyhazard)


S\$9,500

19 Likes

Used

In Class 2A (/categories/class-2a-1594)

Share This Listing



([https://www.facebook.com/sharer/sharer.php?](https://www.facebook.com/sharer/sharer.php?u=https://sg.carousell.com/p/urgent-sale-suzuki-drz-400-sm-244162985/)
u=<https://sg.carousell.com/p/urgent-sale-suzuki-drz-400-sm-244162985/>)
(<https://twitter.com/i?url=https://sg.carousell.com/p/urgent-sale-suzuki-drz-400-sm-244162985/>)



(/)

Bike model

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▾

Q SEARCH

VIEW ALL (/LISTING/USED/BIKES/LISTING/)



REPORT ERROR > (/LISTING/LISTING/ERROR/USED/BIKE/13810/)

+ ADD TO SHORTLIST

Like 0

Share

SHARE (WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USED/BIKE/SUZUKI-SUZUKI-DRZ400SM/13810/)

Suzuki DRZ400SM

Listing Type	Paid Ad
Brand	Suzuki (/listing/usedbike/brand/suzuki/)
Model	Suzuki DRZ400SM (/listing/usedbike/model/suzuki-drz400sm/)
Engine Capacity	398cc
Classification	Class 2A (/listing/usedbike/model/motorcycle-for-sale/class/class-2a/)
Registration Date	21/02/2008
COE Expiry Date	20/02/2028 (8 years 6 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Super Motards (/listing/usedbike/model/motorcycle-for-sale/super-motards/)

Price: ^{SGD}\$8999

DETAILS

Downpayments \$1500 Before Insurance. Viewing At Bike Production Pte Ltd. Please Kindly Call To Confirm Availability Before Viewing. Address: 610, Serangoon Road S(218216) Tel: 63922555. Trade In/ Re-Financing And Many Other Brands New And Used Models Available Too. Terms And Conditions.

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)



Suzuki DRZ400SM



Suzuki DRZ400SM



Suzuki DRZ400SM



Suzuki DRZ400SM

(/listing/usedbike/suzuki-suzuki-drz400sm/13810/) (/listing/usedbike/suzuki-suzuki-drz400sm/13710/) (/listing/usedbike/suzuki-suzuki-drz400sm/13468/) (/listing/usedbike/suzuki-suzuki-drz400sm/8998/)



Suzuki DRZ400SM



Suzuki DRZ400SM

(/listing/usedbike/suzuki-suzuki-drz400sm/10500/) (/listing/usedbike/suzuki-suzuki-drz400sm/11211/)



(/)

Bike model

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▾

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)



REPORT ERROR > (/LISTING/LISTING/ERROR/USEDBIKE/13710/)

★ ADD TO SHORTLIST

Like 0

Share

SHARE (WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/SUZUKI-SUZUKI-DRZ400SM/13710/)

Suzuki DRZ400SM

Listing Type	Paid Ad
Brand	Suzuki (/listing/usedbike/brand/suzuki/)
Model	Suzuki DRZ400SM (/listing/usedbike/model/suzuki-drz400sm/)
Engine Capacity	398cc
Classification	Class 2A (/listing/usedbike/model/motorcycle-for-sale/class/class-2a/)
Registration Date	05/03/2007
COE Expiry Date	31/01/2027 (7 years 5 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Super Motards (/listing/usedbike/model/motorcycle-for-sale/super-motards/)

Price: ^{SGD}\$9800

DETAILS

Suzuki DRZ400SM For Sale. Interested Parties Are Welcome To Neg. Trade/Loan Available. Do Visit Us At Wing Fuat @ Sims Place. No Early Settlement Fee.

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](/listing/usedbikes/listing/)



Suzuki DRZ400SM



Suzuki DRZ400SM



Suzuki DRZ400SM



Suzuki DRZ400SM

(/listing/usedbike/suzuki-suzuki-drz400sm/13810/)



Suzuki DRZ400SM

(/listing/usedbike/suzuki-suzuki-drz400sm/13710/)



Suzuki DRZ400SM

(/listing/usedbike/suzuki-suzuki-drz400sm/13468/)

(/listing/usedbike/suzuki-suzuki-drz400sm/10500/)

(/listing/usedbike/suzuki-suzuki-drz400sm/11211/)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/08/2019 12:58
Date Of Accident	24/07/2019 22:55
Exact Location Of Accident	WOODLANDS AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBC7824D
Insured/Policyholder	
Name Of Registered Owner	MOHAMED FARHAN BIN MOHAMED SHARIFF
NRIC No	S8136400A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86068256
Alternative Phone No	OTHERS-86068256

Vehicle Particulars

Manufacturer	SUZUKI
Model	DRZ-398CC 400SM (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MSD/VMT/18-995868-WTT
Cover Note Number	18/10/2018-03/01/2020

Driver

Name of Driver	MOHAMED FARHAN BIN MOHAMED SHARIFF
NRIC No	S8136400A
Date Of Birth	19/11/1981
Occupation	INDOOR
Date Of Driving Pass	13/10/2018
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-86068256
Fax Number	(LOCAL) +65-86068256
Contact Number	OTHERS-86068256
Email Address	NOEMAIL

Address	BLK 633D SENJA ROAD #04-137
Postcode	674633
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20190730/7011.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB4153G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHAMED FARHAN BIN MOHAMED SHARIFF
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBC7824D
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Refer to Police Report =
T/20190730/7011

VEH A

VEH B

VEH A = FBC7824D

VEH B = GBB4193 U


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190730/7011

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190730/7011

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/07/2019 11:28		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MOHAMED FARHAN BIN MOHAMED SHARIFF			Address: APT BLK 633D SENJA ROAD #04-137 SINGAPORE 674633		
ID Type / ID No.: NRIC NO / S8136400A			Contact No.: Home/Office: Mobile: 86068256		
Nationality: SINGAPORE CITIZEN			Email: mdfazhan@yahoo.com		
Sex: Male	Age: 37	Date of Birth: 19/11/1981	Type of Informant: Rider		
Race: Indian			Language: English		Institution / School Name:
Occupation: Driving and Motorbike Instructor			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/07/2019 22:55	Type of Location: Straight Road
Location: WOODLANDS Ave 4				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 50 Km/h
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Hit from the back				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBC7824D	Motorcycle	SUZUKI	DRZ400SM M	Black		0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBC7824D	MSIG INSURANCE (SINGAPORE) PTE. LTD.	60824360	17/10/2018	16/10/2019



**SINGAPORE
POLICE FORCE**



T/20190730/7011

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190730/7011

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MOHAMED FARHAN BIN MOHAMED SHARIFF	ID No.	S8136400A
Related Vehicle	FBC7824D (Motorcycle)	Contact No.	86068256
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Rider			
Name	MOHAMED FARHAN BIN MOHAMED SHARIFF	ID No.	S8136400A
Related Vehicle	NIL	Contact No.	86068256
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2A Date of Expiry: NIL
Date Treatment	24/07/2019	Date Discharge	29/07/2019
No. of Days granted Medical Leave	34	Degree of Injury	Serious

Brief Details.

I was travelling straight ahead along Woodlands Ave 4 when suddenly a lorry hit me from behind or from the side. My vehicle was moving and the cause of impact knocked me out. I regain back my conscious only inside the ambulance. The paramedic told me passer by and witnesses saw the lorry was travelling fast and even beat the red light. I was send to ICU and suffered mutiple injuries, abrasions, fracture ribs, pneumothorax and fracture scapula.



**SINGAPORE
POLICE FORCE**



T/20190730/7011

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190730/7011

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
RASHIDAH BINTE AZMAN
Contact No.: 65476216

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
30/07/2019 11:28

Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2019		27 Sep 2019 16:50 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: MOHAMED FARHAN BIN MOHAMED SHARIFF , ID: S8136400A									
Vehicle Reg. No.: FBC7824D		Date of Loss: 24/07/2019 22:00 - :59 [132 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D203496C02		Policy/Cover Note No.: DMCVSN18376018000							
Vehicle Reg. No. (Insured): GBB4153G		Policy No. (Claimant): MSD/VMT/18-995868-WTT							
		Excess: S\$0.00							
Repairer: Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 08/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


















































Claim Documents



























*FBC7824D (SNM19D203496C02)
[GBB4153G]
TP
MOHAMED FARHAN BIN MOHAMED SHARIFF
Jul 24 2019 10:00PM
[-]
Mcs Auto

Upload Documents | Upload Photos | Compose New Letter














View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Glen Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 13:11	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Glen Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 13:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	02/08/19 13:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	02/08/19 13:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	02/08/19 13:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	02/08/19 13:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	02/08/19 13:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	02/08/19 13:07	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
2	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
3	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
4	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
5	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
6	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
7	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
8	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
9	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
10	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
11	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
12	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
13	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
14	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
15	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
16	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
17	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
18	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
19	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
20	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
21	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
22	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
23	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
24	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
25	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
26	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
27	27/09/19 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
28	27/09/19 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
29	27/09/19 17:36	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Glen Enterprise Pte Ltd (HQ)	Thumbnail	Print
30	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
31	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
32	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
33	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
34	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
35	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
36	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
37	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
38	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/09/19 17:36	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	27/09/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	27/09/19 17:38	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
85	27/09/19 17:38	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Glen Enterprise Pte Ltd (HQ)	Thumbnail	Print
86	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	27/09/19 17:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Glen Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 13:10	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	02/08/19 13:10	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	02/08/19 13:10	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	
4	02/08/19 13:10	Sketch Plan #4 [Linked Accident Report Documents]	 Load TIF	
5	02/08/19 13:10	Sketch Plan #5 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Glen Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 13:11	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Glen Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 13:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	02/08/19 13:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	02/08/19 13:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	02/08/19 13:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	02/08/19 13:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	02/08/19 13:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	02/08/19 13:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Glen Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 13:10	Sketch Plan	 Load TIF	
2	02/08/19 13:10	Sketch Plan #2	 Load TIF	
3	02/08/19 13:10	Sketch Plan #3	 Load TIF	
4	02/08/19 13:10	Sketch Plan #4	 Load TIF	
5	02/08/19 13:10	Sketch Plan #5	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19013979/FCD3E2

Date: 04/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18376018000
Claimant Vehicle No :	FBC7824D	Insured Vehicle No :	GBB4153G
Date of Loss:	24/07/2019	Nature of Claim: TP	Claim No: SNM19D203496C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC7824D	Engine No:	K419180272
Make & Model:	SUZUKI DRZ400SMK5, 398cc	Chassis No:	SK44A104791
Reg. Date:	04/07/2008 (Man. Year: 2008)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	400 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	160/60 R17
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Pirelli 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	27/09/2019	Inspected At:	Mcs Auto (HQ)
Date Inspected:	13/08/2019		1100 Serangoon Rd
			Singapore 328195
Estimated Period of Repair:	4.0 days		

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$2,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Oct 2019)

Parts: N/A SUZUKI DRZ400SMK5 398cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBC7824D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >