

ASS. REC. BY:

REF: CS/FCI/9013983/k2td3/n2

Special Instruction:

Surveyor: KalvinASSIGNMENT (Office)From (Person): cws8ithera

of

FCIDate/Time: 9:44am @ 13/8/19

Estimated Cost: _____

Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

SHD1710L

Insured: _____

SHA9795E

at Workshop in/s _____

Premier Automotive

Tel: _____

65446689

of _____

23 chengji south Avenue 2 #03-02

Policy No: _____

Claim No: _____

D19005168MFSH

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. _____

5/8/2019

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement: _____

Date/Time: _____

10:09am @ 13/8/19

Person Contacted: _____

Vincent

Vehicle IN / OUT

Date/Time

Action/Instruction

Is brought ✓SHD1710L-XSHA9795E-X10/9-11:55am. Revised preli advised via email.

(08/11/13)

REF:

Surveyor: Kelvin**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 1710L Yr Regn: 24 Jan, 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Zoniq c.c. 1580Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 35082 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCB51CVK4122431Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD 6 Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 5/8/19 D.O.I. 9/9/19Survey held at Prem

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Boly

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/9/19	<u>Chk R/P \$500/2875. (Red: 420, 45%)</u> <u>FCI</u>
	<u>R/P</u>

RECEIVED 13 SEP 2019

Date/Time, File Pass to?

☐ : Prel. Report☒ : Final Report

1) 13/9 Typist

Date/Time, File Return to?

2)

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Report Format: TPLump Sum / 6 : \$ 500

90

50

50

20

210



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005168MFSH

Date: 10/09/2019

Our Ref: CS/FCI19013983/K1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1710L

Please be informed that we had conducted the inspection of the abovementioned vehicle 09/09/2019 at the premises of M/s Premier Automotive have the following to report: -

Workshop Estimate Amount	: S\$	<u>920.00</u>
Revised Estimate Amount	: S\$	<u>500.00</u>
"Check" Items Amount	: S\$	<u>0.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s body portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kalvin Ang

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-08-2019	Our Ref No. D19005168MFSH
Accident Date	05-08-2019	Claim Type. Third Party
Insured Vehicle	SHA9795E	Third Party Vehicle. SHD1710L
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 0	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 10 September 2019 11:55 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005168MFSH/1
Attachments: PRELI ADVISED OF SHD 1710L.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 1710L**
Number of days (estimated) : 2 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 13 August 2019 10:12 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005168MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 13 August 2019 9:44 AM
To: ASSIGNMENTS@LKKAUTO.COM

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport /Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1710L
 Previous Vehicle No.: -
 Effective Date of Ownership: 24 Jan 2019
 Original Regn Date: 24 Jan 2019
 Registration Date: 24 Jan 2019
 Year of Manufacture: 2018
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: AE IONIQ HEV 1.6 DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: KMHC851CVKU122471
 Engine No.: G4LEJU133968
 Motor No.: PM04JA4140DJ
 Engine Capacity /Power Rating: 1580 cc / 32.0 kW
 Maximum Power Output: 103.6 kW (138 bhp)

Propellant:	Petrol-Electric
Max Unladen Weight:	1370 kg
Maximum Laden Weight:	1870 kg
Open Market Value:	\$25,402.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jan 2027
Minimum PARF Benefit:	\$7,537.00
No. of Transfers:	0
IU Label No.:	1050453215
COE No.:	2019012401003975H
COE Expiry Date:	23 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Registration Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium:	- / \$26,047.00
PQP Paid:	\$20,838.00
QP (Regn Cat):	-
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$0.00
Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$5,402.00 (140%)
Actual ARF Paid:	\$12,563.00
Vehicle Lifespan Expiry Date:	23 Jan 2027
CO2 Emission:	86.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$15,000.00
CO Emission:	0.109280 (g/km)
HC Emission:	0.028670 (g/km)
NOx Emission:	0.002060 (g/km)
PM Emission:	0.052000 (mg/km)
Message:	This is a public service vehicle.

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Aug-19

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ WAGON REGN NO: SHD 1710 L

S/NETT

1 set	o/s door stickers		\$	100.00
	Sundry		\$	50.00 20
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front o/s door, etc		\$	450.00 200
	To putty and spray painting on the front o/s door		\$	200.00 160
	To apply rustproofing on repaired panels		\$	120.00 80
Total			\$	920.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hereby notify the Reparer of the following:

- To resurvey performed after spray painting
- To display damaged parts during resurvey
- Paint prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be recovered and is subject to the approval from Insurance Company

Noted by Reparer

Signature:

Date:

Kahin 1 (10/19)

9/9/19

2021

P/P

Alta Repair photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013983/K1td3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-09-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9795E	Veh. Inspected	SHD 1710L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005168MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	13/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVKU122471	Colour	SILVER	
Odometer	35082	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	9 mm	
L/H Front Tyre	195/65 R15	MICHELIN	9 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/08/2019	Inspection Date	09/09/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1710L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET O/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			150.00	120.00
	<u>LABOUR</u>			
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE OF THE FRONT O/S DOOR,ETC.		450.00	200.00
	TO PUTTY AND SPRAY PAINTING ON THE FRONT O/S DOOR.		200.00	180.00
	TO APPLY RUSTPROOFING ON REPAIRED PANELS.	NOT NECESSARY	120.00	-
			770.00	380.00
	GRAND TOTAL		920.00	500.00
RECOMMENDED COST OF REPAIRS				500.00

Report Ref No. CS/FCI19013983/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.