

22/05/2003

ASS. REC. BY:

REF:

083/ III 19014020/R1cd3

Special Instruction:

Surveyor: Rasi

ASSIGNMENT (Office)

From (Person):

Mener Daniel pool

of

III

Date/Time: 13/8/19 @ 4:04pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 6886K

Insured:

SHA 41815

at Workshop m/s

Hun Car Repair

Tel:

62741311

of

Blk 1001 Bukit Merah Lane 3 #01-49

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:17pm @ 13/8/19

Person Contacted:

Susan

Vehicle IN/OUT

☒

Date/Time	Action/Instruction	Is/In/Out (X)
	SLM 6886K - NBA/INC19013942/TI	DOA: 8/8/19
	SHA 41815 - NBA/INC19013942/TI	DOA: 8/8/19
	Disassemble: 15/8/2019 5.30pm	
	After repair: 26/8/2019 2.34pm	

ASS. REC. BY:

REF:

III

2372

PRS

## ASSIGNMENT

From:

Date:

14/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLM 6886K

at Workshop m/s

Han Car Repair

of 31k 1001 Bkt merah lane 3 #01-49

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS cup?

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLM 6886K

Yr Regn:

2017 / APR

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel 1.5X CVT c.c. 1496

Colour:

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

025073

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU11206001

Gen. Cond: Good ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

☒ BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

08/08/19

D.O.I.

14/08/19 5.46pm

Survey held at

HAN CAR REPAIR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range / days - (3k-4k) - 4 days

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others:

TOTAL

Report Formed:

PRS.

Lump Sum / L&amp;J: (\$

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified) <a href="#">Edit Reg</a>		13 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:									
Main Claimant: <b>GAN BENG TAT (YAN MINGDA)</b> , ID: S7732237Z									
Vehicle Reg. No.: <b>SLM6886K</b>		Date of Loss: 08/08/2019 12:00 - :59							
Claim Type: <b>TP</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>SHA4181J</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Han Car Repairs (HQ)</b> BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE, 159718 Alexandra - Tel: 62710275									
Handling Insurer: <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Zuhaidah Bte Samsuri</b> - 6347 6070]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 22/08/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Nivitha (LKK Auto)**

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 13 August 2019 4:04 PM  
**To:** Kuru & Co; sur@lkkauto.com; Admin-D (LKKAuto)  
**Cc:** Zuhaidah Samsuri  
**Subject:** RE: III-PRI / L19.1024.cj // ACCIDENT INVOLVING SLM 6886K & SHA 4181J ON 08/08/2019 AT/ALONG DEPOT ROAD (NEAR 138 DEPOT ROAD) NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY  
**Attachments:** 13082019152046.pdf

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SLM6886K  
III INSURED VEHICLE NO. : SHA4181J  
DATE OF LOSS : 08/08/2019

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Aida.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**  
**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

Daniel Pooi

**Motor Claims Department**

**India International Insurance Pte Ltd**

64 Cecil Street #04-02 IOB Building  
Singapore 049711

Tel: 6347 6100 Ext 202 Fax: 6224 4174

**S&P 'A-' rated Company**



**From:** Kuru & Co [mailto:kurulegal@yahoo.com.sg]  
**Sent:** Tuesday, 13 August, 2019 3:54 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>

**Subject:** Re: III-PRI / L19.1024.cj // ACCIDENT INVOLVING SLM 6886K & SHA 4181J ON 08/08/2019 AT/ALONG DEPOT ROAD (NEAR 138 DEPOT ROAD) NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Dear Sirs

Our client is objecting to your list of surveyors. Attached is our client's list of proposed surveyors for your consideration.

Please state the surveyor you will be appointing to be the single joint expert or that you are objecting to our client's proposed list of surveyors.

If we do not hear from you within 2 working days, it shall be deemed that you have agreed to the appointment of any of the surveyors listed by our client.

Regards

Irene

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

On Tuesday, 13 August 2019, 3:43:40 pm SGT, Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Daniel Pooi

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 202 Fax: 6224 4174

S&P 'A-' rated Company



---

**From:** Kuru & Co [mailto:kurulegal@yahoo.com.sg]

**Sent:** Tuesday, 13 August, 2019 3:34 PM

**To:** Motor Claim - III <motorclaim@iii.com.sg>; Sherini Pillai <sherini@iii.com.sg>

**Subject:** III-PRI / L19.1024.cj // ACCIDENT INVOLVING SLM 6886K & SHA 4181J ON 08/08/2019  
AT/ALONG DEPOT ROAD (NEAR 138 DEPOT ROAD) NOTIFICATION OF ACCIDENT AND PRE-REPAIR  
SURVEY

Dear sirs

**ACCIDENT INVOLVING SLM 6886K & SHA 4181J ON 08/08/2019**

**AT/ALONG DEPOT ROAD (NEAR 138 DEPOT ROAD)**

**NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for **Gan Beng Tat (Yan Mingda)**, whose vehicle registration number **SLM 6886K** was damaged in the above accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

A copy of our client's SAS report is enclosed.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Irene

Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.  
It may contain confidential and/or legally privileged information.  
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.  
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.  
Print this email only if it is absolutely necessary and help in preservation of environment.  
India International Insurance Pte Ltd.  
Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.  
It may contain confidential and/or legally privileged information.  
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.  
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.  
Print this email only if it is absolutely necessary and help in preservation of environment.  
India International Insurance Pte Ltd.  
Registration No. 198703792-K

**Nivitha (LKK Auto)**

**From:** Kuru & Co <kurulegal@yahoo.com.sg>  
**Sent:** Tuesday, 13 August 2019 4:19 PM  
**To:** sur@lkkauto.com; Admin-D (LKKAuto); Motor Claim - III  
**Cc:** Zuhaidah Samsuri  
**Subject:** Re: III-PRI / L19.1024.cj // ACCIDENT INVOLVING SLM 6886K & SHA 4181J ON 08/08/2019 AT/ALONG DEPOT ROAD (NEAR 138 DEPOT ROAD) NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Dear Sirs

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

**HAN CAR REPAIRS**

1001 Bt Merah Lane 3

#01-49 Alexandra Village Ind Est

Singapore 159718

**Tel: Susan Chin/ 62741311/62710275**

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Regards  
Irene  
Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

On Tuesday, 13 August 2019, 4:04:11 pm SGT, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO.	:	SLM6886K
III INSURED VEHICLE NO.	:	SHA4181J
DATE OF LOSS	:	08/08/2019



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/08/2019 16:49
Date Of Accident	08/08/2019 12:30
Exact Location Of Accident	DEPOT ROAD (NEAR 138 DEPOT ROAD)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM6886K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GAN BENG TAT (YAN MINGDA)
NRIC No	S7732237Z
Email Address	HANCARREPAIRS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97569100
Alternative Phone No	OFFICE-97569100

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090235505-02
Cover Note Number	

### Driver

Name of Driver	GAN BENG TAT (YAN MINGDA)
NRIC No	S7732237Z
Date Of Birth	31/10/1977
Occupation	OUTDOOR
Date Of Driving Pass	09/02/1996
Driving Experience	23 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97569100
Fax Number	
Contact Number	OFFICE-97569100
Email Address	HANCARREPAIRS@GMAIL.COM

Address	BLK 103A DEPOT ROAD #20-539
Postcode	101103
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA4181J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	ARUMUGAM RAJAGOPAL
NRIC/Passport Number	S0782785G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the forwarding of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time



Driver's Signature  
(if driver is not the policyholder)  
Date & Time



Reporting Centre Representative's Signature  
Name: Tay Jie  
NRIC FIN No.:

# Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Depot Road when vehicle (B) made an illegal

4-turn all of a sudden & hit my car (A)

## DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
Date & Time

Driver's Signature  
(if not at a loss the goods/property)  
Date & Time

Reporting Centre  
Name  
Date & Time

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	237Z
<b>Vehicle Details</b>	
Vehicle No.:	SLM6886K
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4406001
Chassis No.:	RU11206001
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,186.00
Original Registration Date:	13 Apr 2017
First Registration Date:	13 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$11,661.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2027
PARF Rebate Amount:	\$8,745.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,765.00
COE Rebate Amount:	\$39,636.00
<b>Total Rebate Amount:</b>	<b>\$48,381.00</b>

The information contained herein is correct as at 16 Aug 2019

OK

Not A Private Hire Unit! Top Quality February/2017 White Honda Vezel 1.5X In Stock Now! 1 Owner Only! Low Mileage Clocked! Best And Sellable Japanese Honda SUV! Available With Flexible Loan And Tenure...

Office No. - 68410062

Mr Lim - 90888810 | Audrey - 96528822

<b>Honda Vezel Hybrid 1.5A X</b>	<b>\$77,500</b>	<b>\$9,990 /yr</b>	<b>17-Feb-2017</b>	<b>1,496 cc</b>	<b>39,000 km</b>	<b>360 VR Cars</b>	<b>Available</b>
<b>Honda Sensing</b> (Petrol-Electric)							

1 Owner Low Mileage Unit! Very Well Maintained Black Interiors. Original White Paintwork With Bodykit. Side Step, Spoiler. Sports Rims With PS4 Tyres. Trade In/ Flexible Loan Available! Call Now To Vie...

Office No. - 69310005

Pauline - 96211963 | James Tan - 90700005

<b>Honda Vezel 1.5A X</b>	<b>\$71,800</b>	<b>\$8,680 /yr</b>	<b>28-Feb-2017</b>	<b>1,496 cc</b>	<b>36,126 km</b>	<b>Thong Lee Trading Pte Ltd</b>	<b>Available</b>
---------------------------	-----------------	--------------------	--------------------	-----------------	------------------	----------------------------------	------------------

Well Maintained With 1 Owner Only! Sporty Red And Black Interior And Seats! Flexible In-House Loan Scheme Available! Don't Miss Out On This Unit! By Appointment! Contact/SMS Our Appointed Sales Person...

Office No. - 68419655

Mervin Tan - 88289802 | Kelvin Tan - 90618082

<b>Honda Vezel Hybrid 1.5A X</b>	<b>\$73,800</b>	<b>\$9,450 /yr</b>	<b>03-Mar-2017</b>	<b>1,496 cc</b>	<b>50,000 km</b>	<b>Presto Expat Motoring Services Pte Ltd</b>	<b>Available</b>
----------------------------------	-----------------	--------------------	--------------------	-----------------	------------------	---	------------------

The Honda Vezel, A Conventional Crossover SUV That's Known For It's Great Looks And Good Driving Dynamics. Soft Touch Materials, Elegant Center Console, LED Lighting And Auto Air Conditioning With Tou...

Office No. - 67327737

Gary - 85117182

<b>Honda Vezel 1.5A X</b>	<b>\$71,800</b>	<b>\$8,710 /yr</b>	<b>07-Mar-2017</b>	<b>1,496 cc</b>	<b>26,800 km</b>	<b>1 &amp; Ones Motoring Pte Ltd</b>	<b>Available</b>
---------------------------	-----------------	--------------------	--------------------	-----------------	------------------	--------------------------------------	------------------

Most Popular And Reliable Japan SUV. Fully Serviced/Maintained, Original Stock Condition, 100% Accident Free. 1 Owner Only, Guaranteed Not PH/Rental Unit, Genuine Low Mileage Done, Like New Condition,...

Office No. - -

Vincent - 91915656

<b>Honda Vezel 1.5A X</b>	<b>\$71,500</b>	<b>\$8,580 /yr</b>	<b>07-Mar-2017</b>	<b>1,496 cc</b>	<b>41,000 km</b>	<b>Motorist Pte Ltd</b>	<b>Available</b>
---------------------------	-----------------	--------------------	--------------------	-----------------	------------------	-------------------------	------------------

Non PHV Unit! Low Depreciation With Regular Servicing. Well Maintained Unit. Loan Available From Interest Rates From 2.28%. Call Now To Book An Appointment To View This Beauty. Viewing Strictly Appoin...

Office No. - 65898800

Kanthan - 90225037 | Benedictine - 81813664

<b>Honda Vezel Hybrid 1.5A X</b>	<b>\$78,500</b>	<b>\$10,040 /yr</b>	<b>10-Mar-2017</b>	<b>1,496 cc</b>	<b>4,900 km</b>	<b>Prime Motor &amp; Leasing</b>	<b>Available</b>
----------------------------------	-----------------	---------------------	--------------------	-----------------	-----------------	----------------------------------	------------------

3 Years On 100000Km Warranty. High Trade In.

Office No. - 68984488

Eliz - 88680011 | Larry - 96861029 | Jack - 91096509

<b>Honda Vezel 1.5A X</b>	<b>\$69,800</b>	<b>\$8,550 /yr</b>	<b>20-Mar-2017</b>	<b>1,496 cc</b>	<b>27,000 km</b>	<b>1axis</b>	<b>Available</b>
---------------------------	-----------------	--------------------	--------------------	-----------------	------------------	--------------	------------------

100% Loan Available, We Are Full Loan Specialist, 1 Owner, Accident Free Unit, Act Now To Test Drive Now.

Office No. - -

Danny Teo - 93362309 | Catherine Lee - 90019707 | Kervin Chia - 88113768

<b>Honda Vezel 1.5A X</b>	<b>\$72,800</b>	<b>\$8,780 /yr</b>	<b>23-Mar-2017</b>	<b>1,496 cc</b>	<b>-</b>	<b>Prime Car Traders Pte Ltd</b>	<b>Available</b>
---------------------------	-----------------	--------------------	--------------------	-----------------	----------	----------------------------------	------------------

Low Mileage. Well Maintained Unit! Selling Cheap! Practical And Fuel Efficient SUV! Spacious And Easy To Maintain! High Loan And Trade In Available! Call Our Friendly Salesman For An Viewing By Appoin...

Office No. - 63166000

Tony - 90885037 | Jessy Ang - 91690999 | Nicolas Lim - 96849675

<b>Honda Vezel Hybrid 1.5A X</b>	<b>\$74,822</b>	<b>\$9,490 /yr</b>	<b>30-Mar-2017</b>	<b>1,496 cc</b>	<b>52,229 km</b>	<b>D2 Motors</b>	<b>Available</b>
----------------------------------	-----------------	--------------------	--------------------	-----------------	------------------	------------------	------------------

Full Specs Honda Sensing Vezel At The Price Of Non Sensing Vezel. Super Worthwhile! 1 Owner With 52k KM Done. Accident Free With New Paintwork Done. Definitely The Lowest Priced Sensing Vezel In Pre-O...

Office No. - 63655933

Wei Xiong - 92278426 | Cheong - 83802222 | Shaun - 96803767

<b>Honda Vezel 1.5A X</b>	<b>\$73,800</b>	<b>\$8,800 /yr</b>	<b>04-Apr-2017</b>	<b>1,496 cc</b>	<b>33,000 km</b>	<b>Viking Motor Pte Ltd</b>	<b>Available</b>
---------------------------	-----------------	--------------------	--------------------	-----------------	------------------	-----------------------------	------------------

Well Maintained By 1 Owner. Do Not Miss This Beautiful Unit, Flawless And Excellent Condition, Nice Number! STA Or Vicom Inspection Welcome. Loan / Trade-in Available. Call Now Before It Is Gone.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019 13:32 <a href="#">Edit Reg</a>		13 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	GAN BENG TAT (YAN MINGDA), ID: S7732237Z		
Vehicle Reg. No.:	SLM6886K	Date of Loss:	08/08/2019 12:00 - :59 [27 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHA4181J	Policy No. (Claimant):	
		Excess:	
Repairer:	Han Car Repairs (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE, 159718 Alexandra - Tel: 62710275		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by <b>Zuhaidah Bte Samsuri</b> - 6347 6070]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 22/08/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									











































## Claim Documents

\*SLM6886K  
[SHA4181J]  
TP  
GAN BENG TAT (YAN MINGDA)  
Aug 8 2019 12:00PM  
[-]  
Han Car Repairs

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
**View** [View in Browser](#) ▼

**Photos/Images**

LKK Auto Consultants Pte Ltd (HQ)			3 per page ▼	✓
No	Relabel/Reorder		Thumbnail	Print
1	20/08/19 14:29	General View	 Load JPG	✓
2	20/08/19 14:29	General View	 Load JPG	✓
3	20/08/19 14:29	General View	 Load JPG	✓
4	20/08/19 14:29	General View	 Load JPG	✓
5	20/08/19 14:29	General View	 Load JPG	✓
6	20/08/19 14:29	General View	 Load JPG	✓
7	20/08/19 14:29	General View	 Load JPG	✓
8	20/08/19 14:29	General View	 Load JPG	✓
9	20/08/19 14:29	General View	 Load JPG	✓
10	20/08/19 14:29	General View	 Load JPG	✓
11	20/08/19 14:29	General View	 Load JPG	✓
12	20/08/19 14:29	General View	 Load JPG	✓
13	20/08/19 14:29	General View	 Load JPG	✓
14	20/08/19 14:29	General View	 Load JPG	✓
15	20/08/19 14:29	General View	 Load JPG	✓
16	20/08/19 14:29	General View	 Load JPG	✓
17	20/08/19 14:29	General View	 Load JPG	✓
18	20/08/19 14:29	General View	 Load JPG	✓
19	20/08/19 14:29	General View	 Load JPG	✓
20	20/08/19 14:29	General View	 Load JPG	✓
21	20/08/19 14:29	General View	 Load JPG	✓
22	20/08/19 14:29	General View	 Load JPG	✓
23	20/08/19 14:29	General View	 Load JPG	✓
24	20/08/19 14:29	General View	 Load JPG	✓
25	20/08/19 14:29	General View	 Load JPG	✓
26	20/08/19 14:29	General View	 Load JPG	✓
27	20/08/19 14:29	General View	 Load JPG	✓
28	20/08/19 14:29	General View	 Load JPG	✓
29	20/08/19 14:29	General View	 Load JPG	✓
30	20/08/19 14:29	General View	 Load JPG	✓
31	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
32	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
33	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
34	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
35	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
37	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
38	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
39	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
40	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
41	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
42	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
43	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
44	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
45	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
46	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
47	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
48	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
49	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
50	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
51	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
52	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
53	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
54	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
55	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
56	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
57	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
58	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
59	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
60	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
61	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
62	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
63	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
64	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
65	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
66	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
67	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
68	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
69	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
70	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
71	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
72	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
73	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
74	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
75	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
76	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
77	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
78	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
79	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
80	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
81	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
82	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓
83	26/08/19 14:29	Photographs of Damaged Parts	 Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	26/08/19 14:29	Photographs of Damaged Parts	Load JPG	✓
85	26/08/19 14:29	Photographs of Damaged Parts	Load JPG	✓
86	26/08/19 14:29	Photographs of Damaged Parts	Load JPG	✓
87	26/08/19 14:29	Photographs of Damaged Parts	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	14/08/19 08:51	Singapore Accident Statement SHA4181J	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19014020/R1CD3S2  
Date: 29/08/2019

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SLM6886K	Insured Vehicle No :	SHA4181J
Date of Loss:	08/08/2019	Nature of Claim:	TP
		Claim No:	N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM6886K	Engine No:	L15B4406001
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11206001
Reg. Date:	13/04/2017 (Man. Year: 2016)	Odometer:	25073 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	13/08/2019	
Date Inspected:	14/08/2019 Inspected At:	Han Car Repairs (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE Singapore 159718
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

18

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2019)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM6886K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >