

ASS. REC. BY:

REF: ASM(CAXA)

ASSIGNMENT

From:

Date:

11/09/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SFP 97974

at Workshop m/s

Weavnes

of

45 Jerry Kee Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Car In

OIC: PUH1@81261237

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value:

\$210K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{cup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFP 97974 Yr Regn: 2017, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki F-100 R Sport C.C. 2795

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

3733

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SADCA 21409-HA494224

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/B / STD A/Rim or

Tyre Size:

F:

225/55RA.

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

11/9/19 @ 230pm

Survey held at

Weavnes Jerry Kee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / L.B.I. (\$