



**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Gan Choon Shan  Blk 467B Admiralty Drive #14-137 Singapore 752467  Contact No Mobile: 96611579	Cust No/Name	/Gan Choon Shan
	Reg No/Reg Date	SLT1611H / 20/10/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MJ5740729
	Engine No	G4FGHH679076
	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Term	Date/Time	Operator	55711
CSM00081	Cash	08/08/2019/ 15:49	442 / CocoLu	

  

Description of Goods	Qty	Unit Price	Total
E PNT88000 RENEW REAR AIRDAM, REPAIR REAR BUMPER	✓	550.00	
E PNT98000 SPRAY PAINT FOR REAR BUMPER, REAR AIRDAM	630	1000.00	
E PNT88000 REMOVE & INSTALL PARKING SENSOR	✓	60.00	
M SUNDRY Sundry	20	2.00	
E PNT88000 REMOVE & INSTALL REAR AIRDAM	✓	100.00	
A 90000001 CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM	✓	200.00	
M NEW K3 METAL STREAM MST	1.00	1177.00	00.00
			1177.00
			977

  

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

  

SURVEYOR NAME : Tan Kah 97495741

SURVEYOR SIGNATURE : [Signature]

DATE : 2/9/19 3:00pm

REMARKS : Resurvey after repair  
3 days  
sure/khandu.com

Confirm & accepted by

	Nett	* 3,089.00
7% GST on	3089.00	216.23
<b>Total Payable</b>		<b>3,305.23</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

VEHICLE NO : SLT 1611 H  
 MODEL : KIA CERATO K3 1.6 A SX SR  
 WIP : 55711

Material	:	\$	<u>977.00</u>
Labour	:	\$	<u>1,560.00</u>
Sub-Total	:	\$	<u>2,537.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>2,537.00</u>
GST 7%	:	\$	<u>177.59</u>
Grand Total	:	\$	<u>2,714.59</u>
Finalise By/Date	:	<u>LOI / 21/09/2019</u>	

☒ REVERT BACK WITHIN 7 DAYS,  
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 3 WORKING DAYS + 0 Days (0) Weekends  
 + 0 Days (0) Public Holiday  
 TOTAL DAYS REPAIR TOOK = 3

☒ TP claim SLW8468T

☒ Claim GIA / LTA fee \$2.00

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : NR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Gan Choon Shan	Cust No/Name /Gan Choon Shan
C/O AXA INSURANCE PTE LTD	Reg No/Reg Date SLT1611H / 20/10/2017
MOTOR CLAIM DEPARTMENT	Date In/Mileage 03/09/2019/ 37880
8 SHENTON WAY #24-01	Chassis/Package KNAFZ411MJ5740729 /FS315N
SINGAPORE 068811	Engine No G4FGHH679076
Contact No	Make/Model KIA/CERATO K3 1.6 A SX SR
02/09/	Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSK00001	Cash	21/09/2019/ 11:42	TLC	260 / AiTing	55711
Description of Goods/Services				Qty	Unit Price Disc% Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR AIR DAM, REPAIR REAR BUMPER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME					✓ 550.00
E PNT98000 RESPRAY ON REAR BUMPER, REAR AIR DAM, AND ALL OTHER AFFECTED AREAS TO THE SAME					✓ 630.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR					✓ 60.00
M SUNDRY SUNDRIES					✓ 20.00
E PNT88000 REMOVE & INSTALL REAR AIR DAM TO FACILITATE REPAIR					✓ 100.00
A 90000001 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE					✓ 200.00
X BODY KITS UNPAINTED K3				1.00	977.00 00.00 977.00
Z TEXT TP CLAIM AXA SLW8468T DOA : 07.08.19 SURVEYOR TAUFIKH LKK 02.09.19 REPAIR 03 DAYS					

Pro Forma

Cycle & Carriage celebrates 120 years.  
Visit [www.cyclecarriage.com/120](http://www.cyclecarriage.com/120) for more info!

Parts	977.00	Nett	2,537.00
Labour	1,540.00	7% GST on	177.59
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	2,714.59
Sundry/Others	20.00		
Total(w/o GST)	2,537.00		

This is not an official tax invoice.  
This is a computer generated document, no signature is required.