

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg No. M2-0020081-X



Final Report

Estimate No. : **b1 52281**
Date Estimated : **13/08/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -

Boh Thai See
132 Pasir Panjang Road
#05-03

Singapore 118549

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGW2011B	5L53297	25/09/2018	216i GT	0

DESCRIPTION	ACCOUNT:		
	ORIGINAL PRICE	DISC. %	NETT
To replace both right doors and attachments including to make good the rear bumper, rear right fender, right side skirting and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	4,250.00	0	4,250.00 /
To respray both right doors & handles, rear right fender, right roof frame, right side skirting cover and rear bumper etc.	4,528.00	0	4,528.00 /
To carry out body cavity preservation. (Per panel).	200.00	0	200.00 /
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00 /
To transfer lock mechanism from old to new doors including conduct checks on new door power window system for proper functions. (2 doors).	902.00	0	902.00 /
Sundries.	150.00	0	150.00 /

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# PLUG IN RETAINER	3.85	2	0	7.70 /
FRT RH DOOR	1,131.25	1	0	1,131.25 /
RR RH DOOR	1,131.25	1	0	1,131.25 /
RH SEALING COLUMN B BOTTOM	54.30	1	0	54.30 /
RH SEAL A PILLAR	54.30	1	0	54.30 /
# EXPANDING NUT 7X7 MM	1.00	4	0	4.00 /
# EXPANDING NUT 7X7 MM	1.00	2	0	2.00 /
#				
#				
#				
#				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52281**
Date Estimated : **13/08/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -
Boh Thai See
132 Pasir Panjang Road
#05-03

Singapore 118549

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGW2011B	5L53297	25/09/2018	216i GT	0

DESCRIPTION	ACCOUNT:		
	ORIGINAL PRICE	DISC. %	NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# PLUG IN RETAINER	3.85	2	0	7.70
# EXPANDING NUT 7X7 MM	1.00	4	0	4.00
# EXPANDING NUT 7X7 MM	1.00	2	0	2.00
#				
#				
#				
#				
#				
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	13.70
Total Labour & Parts :	13.70

Performance Motors Limited

A member of the Sime Derby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X




Final Report

#

SUPPLEMENTARY ITEMS

Total Labour :	10,180.00
Total Parts :	2,384.80
Total Labour & Parts :	12,564.80
Deduction for Excess :	
Total Repair Costs less Excess:	12,564.80
GST @7%:	879.54
Grand Total :	13,444.34



LOSS OF USE = \$60 X 8 DAYS
GIA SEARCH FEE - \$2.00

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

13 AUG 2019

E S T I M A T E

Estimate No. : b1 52281 Page No. : 1 of 5
Date Estimated : 13/08/2019
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -

Boh Thai See
132 Pasir Panjang Road
#05-03

Singapore 118549

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGW2011B	5L53297	25/09/2018	216i GT	0

DESCRIPTION**VALUE**

To replace right front door, right rear door & R/I rear bumper, right rear fender and side skirt and attachment include knocking cause by the accident.

4250 5,100.00

Painting right front door and handle, right rear door and handle, right rear fender, right roof frame, right side skirt, rear bumper.

4528 5,032.00

To carry out body cavity preservation.
(Per panel).

200 236.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To transfer lock mechanism from old to new doors including conduct checks on new door power window system for proper functions. (2 doors).

702 1,062.00

Sundries.

150.00

Total Labour 1: 11,757.00

DESCRIPTION**QTY PRIC****VALUE**

FRT RH DOOR / DD

1 1,131.25 1,131.25

RR RH DOOR / DD

1 1,131.25 1,131.25

RH LOWER REAR DOOR HINGE X N/A

1 58.60 58.60

RH UPPER REAR DOOR HINGE X N/A

1 58.60 58.60

DOOR HANDLE PAINTED OUTER RH (A96 M X R

1 533.55 533.55

RH OUTER DOOR HANDLE PRIMED X R

1 95.05 95.05

RH COVERING PRIMEND X N/A

1 47.55 47.55

RH COVERING PRIMEND X N/A

1 47.55 47.55

REAR DOOR BRAKE X N/A

1 73.85 73.85

FRT RH DOOR INSIDE CHANNEL SEALING X N/A

1 60.90 60.90

FRT RH DOOR EXTERIOR CHANNEL COVER X N/A

1 94.10 94.10

RH SEALING COLUMN B BOTTOM X N/A

1 54.30 54.30

REAR RH DOOR OUTER WEATHERSTRIP (AL X N/A

1 94.10 94.10

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52281
Date Estimated : 13/08/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGW2011B	5L53297	25/09/2018	216i GT	0

DESCRIPTION	QTY	PRIC	VALUE
REAR DOOR JOINT SEAL <i>✓ N/A</i>	1	31.95	31.95
REAR DOOR EDGE PROTECTION <i>✓ X N/A</i>	1	157.05	157.05
FRT DOOR EDGE PROTECTION <i>✓ X N/A</i>	1	157.05	157.05
RH SEAL A PILLAR <i>✓ N/A</i>	1	48.35	54.30 48.35
FRT DOOR JOINT SEAL <i>✓ N/A</i>	1	31.95	31.95

Total Parts : 3,907.00

LKR A... notify
the Rep... g:
• To resur...
• To d... ing resurvey
• Parts... information
• Third... without Prejudice* basis
• No illeg... allowed
• Supple... be resurveyed and
is subject... from Insurance Company

Acknowledged by...
Signature:
Date:

Claims OD / 3rd Party / Uninsured Losses / Direct Settlement

Regn No _____ Claim No _____

Date & Time *20/8/19, 1:00pm* Excess S\$ _____

Surveyor's Name *Steve (LKR)* Sign _____

Surveyor's Tel *8322 8873* Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PART YES / NO _____ YES / NO _____ YES / NO _____

Surveyor's Address _____

WML Original

*8 days
P/P
Ry Bel spy*

Labour 1	:	11,757.00
Parts	:	3,907.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,096.48
Grand Total	:	16,760.48

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **