

ASS. REC. BY:

REF: CS/SMD 19014086/ GS f3ⁿ²

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Agnes Chan Shui Hui of SMD

Date/Time: 14.8.19 840 a.m

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 3343 G

Insured: SKM 3336 m

at Workshop m/s My Car Consultant

Tel: 98 668832

of 53 Paga uli Industrial Park #01-33

Policy No: D19 MTPV 01000549

Claim No: CMTD1903783

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5.8.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 14.8.19 10.51 a.m

Person Contacted: Hui Qin

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SLH 3343 G -x

SKM 3336 m -x

19/08/19 @ 18:21 pm revised ZA to Agnes Chan via
meritum.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s My car
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLH3343G Yr Regn: 31 oct 2016
 Type: C M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Subaru Forester 2.0 1995
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 66507 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: IF1SJ5KC 5GG078819
 Gen. Cond: C Good / Fair / Poor / Burnt
 Steering: C In order / Jammed / Leaked / Burnt or
 Brake: C In order / Jammed / Leaked / Burnt or
 Modi: C Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245 / 45R19
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front Rear
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. D.O.I. 16-08-19
 Survey held at w/s 11:30
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Wt N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

limited \$800 with Hui Lin
(\$4,372.80 Red - 85%)

RECEIVED 20 AUG 2019

20/8/2019

Date/Time, File Pass to?

20/08/19

1) Type 4
Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:
 Transportation:
) S + RS, \$
) Photos
) Others

Report Format :

Lump Sum / I.B.I.: (\$ 800/- L/S)

TOTAL

250
11

261

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 19 Aug 2019

Preliminary Advice

Insured Vehicle No	: SKM3336M	Accident Date	: 05/08/2019
TP Vehicle No	: SLH3343G	Assignment Date	: 14/08/2019
Make	: SUBARU FORESTER	Est. Duration of Repair	: 2 days
Date of Inspection	: 16/08/2019		
Inspection At	: My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33 Singapore 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,172.80
Revised Amount	:S\$	1,009.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,009.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Aug 2019		14 Aug 2019 08:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		AIDA HANDJAJA, ID: S7777161A							
Main Claimant:		YEOH CHI WEI(YANG ZHIWEI), ID: S8115141E							
Vehicle Reg. No.:		SLH3343G	Date of Loss:	05/08/2019 14:00 - :59					
Claim Type:		TP / CMTD1903783	Policy/Cover Note No.:	D19MTPV01000549 (Comprehensive)					
Vehicle Reg. No. (Insured):		SKM3336M	Policy No. (Claimant):						
		Excess:							
Repairer:		My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33, 408934 Ubi - Tel:							
Handling Insurer:		Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/08/2019]							
Adj Asg. Remarks:		WS: HUI QIN 88668832							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	141E
Vehicle Details	
Vehicle No.:	SLH3343G
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Aug 2019
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0I-L CVT AWD SR
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	FB20Y436906
Chassis No.:	JF1SJ5KC5GG078819
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$16,868.00
Original Registration Date:	31 Oct 2016
First Registration Date:	31 Oct 2016
Transfer Count:	2
Actual ARF Paid:	\$16,868.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2026
PARF Rebate Amount:	\$12,651.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,410.00
COE Rebate Amount:	\$40,639.00
Total Rebate Amount:	\$53,290.00

The information contained herein is correct as at 16 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/08/2019 13:36
Date Of Accident	05/08/2019 14:50
Exact Location Of Accident	PARKWAY PARADE LEVEL 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH3343G
Insured/Policyholder	
Name Of Registered Owner	YEOH CHI WEI(YANG ZHIWEI)
NRIC No	S8115141E
Email Address	ATTITUDEYEOH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-84683881
Alternative Phone No	OTHERS-84683881

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER 2.0I-L CVT AWD SR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8VPCB1833670
Cover Note Number	

Driver

Name of Driver	YEOH CHI WEI(YANG ZHIWEI)
NRIC No	S8115141E
Date Of Birth	12/05/1981
Occupation	INDOOR
Date Of Driving Pass	25/04/2005
Driving Experience	14 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84683881
Fax Number	
Contact Number	OTHERS-84683881
Email Address	ATTITUDEYEOH@GMAIL.COM

Address	BLK 1G CANTOMENT ROAD #38-81
Postcode	085701
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN ATTACHED:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM3336M
Vehicle Make/Model/Colour	TOYOTA / CAMRY 2.5 AT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

- 5 AUG 2019

IDAC KAKI BUKIT (VAC)

Reporting Centre: 23 Kaki Bukit Ave 4
Name: Singapore 415933
NRIC/TIN: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 5th Aug 2019, at about 14:15hrs my vehicle was parked at Parkway Parade shopping mall, level 4. ^{owner of} SKM 3336M was doing a reversing into a lot on the left side of my car. While doing so, SKM 3336M scrap and hit the left side of my front bumper. The whole incident was recorded by my in-car camera. The owner of SKM 3336M left a note for me to contact her. The accident resulted to some scratches and dent on my front bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature

Date & Time: 5th Aug 2019 14:15

Driver's Signature
(if driver is not the policyholder)
Date & Time:

G:\ARAC\Sketch\plan\form-193

- 6 AUG 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre Personnel's Signature
Name: Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vockb@singnet.com.sg



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

- To display damaged parts for resurvey
- Prices are subject to confirmation
- Estimate survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimation

Acknowledged by Repairer

Signature:

Date:

Date: 13 Aug 19

Vehicle: SLH3343G

Make / Model: SUBARU/FORESTER 2.0

Chassis:

No.	Description		Unit Price	Amount
Parts Replacement:				
1	FRONT BUMPER <i>CA</i>	1	\$ 712.00	\$ 712.00
2	FRONT BUMPER BRACKET <i>X</i>	2	\$ 388.00	\$ 388.00
3	FRONT BUMPER INNER BRACKET <i>X</i>	1	\$ 146.00	\$ 146.00
4	FRONT BUMPER TOW COVER <i>X</i>	1	\$ 32.00	\$ 32.00
5	FRONT BUMPER LOWER GRILLE <i>X</i>	<i>NN</i> 1	\$ 46.00	\$ 46.00
6	FRONT BUMPER LOWER INNER BRACKET <i>X</i>	1	\$ 63.00	\$ 63.00
7	FRONT LH FOG LAMP <i>X</i>	1	\$ 460.00	\$ 460.00
8	FRONT LH FOG LAMP COVER <i>X</i>	1	\$ 58.00	\$ 58.00
9	FRONT LH FOG LAMP INNER BRACKET <i>X</i>	1	\$ 56.00	\$ 56.00
10	FRONT LH HEADLAMP <i>X</i>	1	\$ 2,680.00	\$ 2,680.00
				\$ 4,641.00
			Less 20%	\$ 928.20
			Total	\$ 3,712.80
S/Nett items:				
11	FRONT BUMPER CLIP <i>CA</i>	1 SET	\$ 40.00	\$ 30.00
12	FRONT NUMBER PLATE <i>X</i>	1	\$ 80.00	\$ 70.00
				\$ 100.00
Labour to:				
13	CHECK FRONT WIRING AND LIGHTNING SYSTEM		\$ 60.00	\$ 60.00
14	PANEL BEATING ON AFFECTED AREAS		\$ 600.00	\$ 600.00
15	SPRAY PAINTING ON AFFECTED AREAS		\$ 600.00	\$ 600.00
16	APPLY ANTI RUST ON AFFECTED AREAS		\$ 120.00	\$ 100.00
				\$ 1,360.00
<i>2 Days</i> <i>Unpainted repair</i> <i>After repair photo</i> <i>Amo Corp. 16/8/19</i>			Parts Replacement Amount	\$ 3,812.80
			Total Amount for Labour	\$ 1,360.00
			Total Amount	\$ 5,172.80
				5212.80

X NN
200
200
X NN
400

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19014086/GSF3N2

Date: 20/08/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01000549
Claimant Vehicle No :	SLH3343G	Insured Vehicle No :	SKM3336M
Date of Loss:	05/08/2019	Nature of Claim:	TP
		Claim No:	CMTD1903783

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH3343G	Engine No:	FB20Y436906
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Chassis No:	JF1SJ5KC5GG078819
Reg. Date:	31/10/2016 (Man. Year: 2016)	Odometer:	66507 km
Colour:	Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,832.80	599.60	3,233.20	84.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	400.00	980.00	71.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,212.80	999.60	4,213.20	80.82
Approved Total (Overridden) (\$\$)		800.00		
Nett Amount (\$\$)	5,212.80	800.00	4,412.80	84.65

INSPECTION

Date of Assignment:	14/08/2019	
Date Inspected:	16/08/2019	Inspected At: My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33 Singapore 408934
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2019)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH3343G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	712.00 FL	*712.00 FL
2	2		*FRONT BUMPER BRACKET	Not Necessary	388.00 FL	*- FL
3	1		*FRONT BUMPER INNER BRACKET	Not Necessary	146.00 FL	*- FL
4	1		*FRONT BUMPER TOW COVER	Not Necessary	32.00 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	46.00 FL	*- FL
6	1		*FRONT BUMPER LOWER INNER BRACKET	Not Necessary	63.00 FL	*- FL
7	1		*FRONT LH FOG LAMP	Not Necessary	460.00 FL	*- FL
8	1		*FRONT LH FOG LAMP COVER	Not Necessary	58.00 FL	*- FL
9	1		*FRONT LH FOG LAMP INNER BRACKET	Not Necessary	56.00 FL	*- FL
10	1		*FRONT LH HEADLAMP	Not Necessary	2,680.00 FL	*- FL
11	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
12	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,761.00	742.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	928.20	142.40
Total Parts (\$\$)	3,832.80	599.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	60.00	0.00
2	PANEL BEATING ON AFFECTED AREAS	New	600.00	200.00
3	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	200.00
4	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (\$\$)			1,380.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >