

ASS. REC. BY:

REF: CS/MSG 19014095/04f307

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Jordan Tayne King

of

MSG

Date/Time: 13.2.19 12.4 p.m.

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 8497L

Insured:

SDV 8811K

at Workshop m/s

Cycle or Carriage

Tel:

91792561

of

330 4th road 3

Policy No:

29080621

Claim No:

602013

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5.8.2019

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time:

14.2.19

10.39 a.m.

Person Contacted:

Mars

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 8497L - X
	SDV 8811K - CC31116017164 / R166342
	16/8/19 sent Prefi Revise by merinen

D.O.A. - 13/09/2016

ASS. REC. BY:

REF: MS19

ASSIGNMENT

From:

Date:

14/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLM 8497L

at Workshop m/s

Cycle & Carriage Fulco

of

330 ubi Road 3

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10am (waiting)
Mars

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

65k.

IDAC Accident Rpt:

Consistent? : Yes or No

CA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5- days

Res.:

Yes or No

Lum Sum:

1.3-1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

(up) 27AS2748

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM 8497L

Yr Regn:

4, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Kia Forte K3

c.c

158 /

Colour:

S. blue

A/C:

Insured / Std / NI / NA

Sp. Reading

65697

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAF2411MH566583 /

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215 / 50 ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

nexen

Front

Rear

R/Bal.

8

mm

R/Bal.

2

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

5/8/19

D.O.I.

14/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7 yrs. Sal. by 7500 net 1242

18/9/19 Confirmed final by \$6619.00 with tel (Red = \$8107.00, 55%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

18/9/19 - Typist

Report Format:

Lump Sum / L&L (\$)

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

200

Transportation:

S + RS \$

Photos

Others

TOTAL

211

P/P = \$6619.00

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Aug 2019		13 Aug 2019 17:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS			[Created by insurer]																					
Insured:	TAN KAI MING , ID: S7928491B, Tel: +6590218041, Email: NOEMAIL																							
Main Claimant:	LEE CHOR CHIANG , ID: S1327603Z																							
Vehicle Reg. No.:	SLM8497L	Date of Loss:	05/08/2019 14:00 - :59 [27 Months and 23 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / 602013	Policy/Cover Note No.:	29080621 (Comprehensive) Coverage: 13/06/2019 - 12/06/2020																					
Vehicle Reg. No. (Insured):	SDV8811K	Policy No. (Claimant):																						
		Excess:																						
RePAIRer:	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3, 408650 Ubi - Tel: 67461000																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/08/2019]																							
Driver/Custodian (Insured):	TAN KAI MING (39 / Male) , NRIC: S7928491B, Tel: +6590218041 Email: NOEMAIL																							
Adj Asg. Remarks:	on WP. Survey appointment on 14/08/2019 10AM owner waiting. Please contact us ASAP if you cannot attend this assignment. Liab: 100%. Contact: Mars @ 6594 9163 / 9179 2566.																							
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail																				
● MSIG_SG (13/08/2019): Cancellation of Assignment: SLM8497L																								
<div> ALL ASSOCIATED TASKS </div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> <table> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 16 Aug 2019

Preliminary Advice

Insured Vehicle No	: SDV8811K	Accident Date	: 05/08/2019
TP Vehicle No	: SLM8497L	Assignment Date	: 13/08/2019
Make	: KIA FORTE K3	Est. Duration of Repair	: 5.00
Date of Inspection	: 14/08/2019		
Inspection At	: CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD (HQ) 330 UBI ROAD 3 SINGAPORE 408650		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,726.00
Revised Amount	:S\$	6,169.00
Check Items (Estimated)	:S\$	2,054.00
Total	:S\$	8,223.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/08/2019 16:21
Date Of Accident	05/08/2019 14:20
Exact Location Of Accident	BEDOK NORTH AVENUE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM8497L
Insured/Policyholder	
Name Of Registered Owner	LEE CHOR CHIANG
NRIC No	S1327603Z
Email Address	CHORCHIANGLEE@YAHOO.COM
Mobile Phone No	(LOCAL) +65-81861743
Alternative Phone No	OTHERS-81861743

Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3-1.6 SX (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900091290
Cover Note Number	

Driver

Name of Driver	LEE CHOR CHIANG
NRIC No	S1327603Z
Date Of Birth	08/10/1958
Occupation	INDOOR
Date Of Driving Pass	12/12/1990
Driving Experience	28 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81861743
Fax Number	
Contact Number	OTHERS-81861743
EEmail Address	CHORCHIANGLEE@YAHOO.COM

Address	41A BEDOK RIA CRESCENT #04-09 SINGAPORE
Postcode	489929
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TANAH MERAH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 51 NEW UPPER CHANGI ROAD #01-1514 , POSTCODE: 461051 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4499999 - FAX NO: 62447251
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG BEDOK NORTH AVENUE 1, TRAFFIC LIGHT WAS STOP SIGNS I WAS SLOWN DOWN AND STOPPED MY CAR. A FEW SECOND LATER I FEEL AN IMPACT FROM BEHIND AND REALISED THAT VEHICLE B SDV8811K HAD KNOCKED ONTO MY CAR BACK. TOTAL 3 VEHICLE INVOLVED IN THIS INCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDV8811K
Vehicle Make/Model/Colour	TOYOTA ALTIS BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN KAI MING
NRIC/Passport Number	
Contact Number	90218041
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKQ9847U

Vehicle Make/Model/Colour

TOYOTA CAMRY

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

OW POH KHENG

NRIC/Passport Number

Contact Number

96267175

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

MOTOR ACCIDENT REPORT FORM

BASIC INFORMATION			
Date of Report:	06/08/2019		Time:
Date of Accident:	05/08/2019		Time: 1420
Exact Location of Accident:	Bedok North Avenue 1		
DETAILS OF OWN VEHICLE			
Vehicle Registration Number:	SLM8497L		Name of Registered Owner: Lee Chor Chiang
NRIC/Passport No./FIN:	S13276032		Company Reg. No.(for Company Veh): -
VEHICLE PARTICULARS			
Manufacturer:	KIA	Model:	Forté K3
Exact Purpose for which vehicle was being use at time of Accident	<input checked="" type="checkbox"/> Normal Usage <input type="checkbox"/> Others		
Are You Claiming Under Your Own Insurance?	<input type="checkbox"/> YES <input type="checkbox"/> NO Reporting Only <input checked="" type="checkbox"/> NO 3rd Party		
Vehicle Category	<input checked="" type="checkbox"/> Private car <input type="checkbox"/> Commercial Vehicle <input type="checkbox"/> Private Hire		
INSURANCE DETAILS			
Name of Insurance:	AIG		
Type of Coverage:	<input checked="" type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party		
Policy Number:	1900091290		
Driver when the Accident Happen			
Name of Driver:	Lee Chor Chiang		NRIC/Passport/Fin No: S13276032
Date of Birth:	08/10/1958		Occupation: Retiree
Date of Driving Pass:	12/12/1990		Gender: <input checked="" type="checkbox"/> Male <input type="checkbox"/> Female
Mobile No.:	81861743		Home No.: -
Address:	41A Bedok Ria Crescent #0409		Postal Code 48929
Email Address:	chorchianglee@yahoo.com		
Was the Driver an Employee of the Insured's Company:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No State the relationship of the driver to insured Owner		
Vehicle Registration Number of driver's Own Vehicle:	-		
Insurance Company:	-		
OTHER INFORMATION OF THE ACCIDENT			
Type of Accident:	chain collision		
Weather Condition:	<input checked="" type="checkbox"/> Clear <input type="checkbox"/> Raining <input type="checkbox"/> Others, please specify		
Road Surface:	<input checked="" type="checkbox"/> Dry <input type="checkbox"/> Wet <input type="checkbox"/> Others, please specify		
Was Anybody Injured:	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
Was Any other material or Property Damaged:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Any Accident Photo in the Scene of Accident:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Was the Accident reported to police:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Which Police Station:	Tengah Merah NPP.		
Was notice of Intended Prosecution given:			
DETAILS OF OTHER VEHICLE (Please fill Annex A if more vehicles involve)			
Vehicle Registration Number:	SDV 8811K		Name of Registered Owner:
NRIC/Passport No./FIN:			Company Reg. No.(for Company Veh):
Name of Driver:	Tan Kai Ming		NRIC/Passport/Fin No:
Mobile No.:	90218041		Home No.:
Address:			Postal Code
Email Address:			
Insurance Company:			
Details of Passenger if any			
Passenger Name:			
Contact Number:			
Gender:			
Details of Injured Person			
Name:	Age:		
Address:			
Injured Sustained:	Injured Person in which vehicle:		
Were Seatbelts worn:	<input type="checkbox"/> Yes <input type="checkbox"/> No		
Were Injured Convey to Hospital by Ambulance:	<input type="checkbox"/> Yes <input type="checkbox"/> No		

MOTOR ACCIDENT REPORT FORM

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration No: SKQ 9847U		Vehicle Make / Model :	
Name of Driver	OW Poh Kheng	NRIC/Passport/Fin No :	
Contact Number:	96267175		
Address :			
Insurance Company Name :			

DETAILS OF OTHER PROPERTY 3

Vehicle Registration No:		Vehicle Make / Model :	
Name of Driver		NRIC/Passport/Fin No :	
Contact Number:			
Address :			
Insurance Company Name :			

DETAILS OF OTHER PROPERTY 4

Vehicle Registration No:		Vehicle Make / Model :	
Name of Driver		NRIC/Passport/Fin No :	
Contact Number:			
Address :			
Insurance Company Name :			

DETAILS OF OTHER PROPERTY 5

Vehicle Registration No:		Vehicle Make / Model :	
Name of Driver		NRIC/Passport/Fin No :	
Contact Number:			
Address :			
Insurance Company Name :			

Details of Witness if any

Witness Name:	
Contact Number:	
Email Address :	

Details of Injured Person

Name :		Age :	
Address			
Injured Sustained :		Injured Person in which vehicle:	
Were Seatbelts worn: <input type="checkbox"/> Yes <input type="checkbox"/> No			
Were Injured Convey to Hospital by Ambulance: <input type="checkbox"/> Yes <input type="checkbox"/> No			


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


6/8/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Bedok North Avenue 1, traffic light was stop signs. I was slow down and stopped my car. A few seconds later I feel an impact from behind and realised that vehicle B SDV 8811K had knocked onto my car back. Total 3 vehicle involved in this incident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

6/8/19.

GIARMC SketchPlanForm V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



CONFIDENTIAL

ANNEX E

NOTICE OF REPORTING

This is to confirm that Lee Chor Chiang, NRIC: S1327603Z, Tel: 81861743 has reported to the Police a non-injury traffic accident which occurred at Bedok North Avenue 3 on 5.08.2019 at 2:30 p.m. involving the following vehicles :-

- i) **SLM 8497L (Complainant vehicle)**
- ii) **SDV 8811K (Black Toyota Altis)**
- iii) **SKQ 9847U (Champaign brown Toyota Camry)**

2 If this accident was reported to the Police within 24 hours of its Occurrence, then he has complied with Sec 84(2) of the Road Traffic Act, Cap 276

Rank/Name of Issuing Officer: SI 98463 Rudi Kasim

Date: 5.08.2019

Time: 2030hrs

Station Diary ref: 20

Police Post/Unit: Tanah Merah NPP

Original - to be issued to informant
Duplicate - to be submitted to Traffic Police

CONFIDENTIAL



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lee Chor Chiang
Period of Insurance : 24 Apr 2019 To 12 Apr 2020
Engine No. : G4FGGH657361
Chassis No. : KNAFZ411MH5665831

Vehicle No. : SLM8497L
Policy No. : 1900091290
Endorsement No. :
Issued Date : 24 Apr 2019

ABOUT THE COVER

Make/Model : KIA FORTE K3 1.6 A SX

Engine Capacity/Tonnage : 1,591.00 CC

Driver Restriction : NA

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 1 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1800cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 169) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lee Chor Chiang - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 68328000

2.Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65694501

3.Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278600

4.Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 406650 67461000

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website www.aig.com or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 169), the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500710050

C&C FULCO-CORP SALES

22 UBI ROAD 4 FULCO BUILDING

SINGAPORE 408617 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte, Ltd.

M. J. J. J.
AIG Asia Pacific Insurance Pte
AUTHORISED REPRESENTATIVE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1327603Z



Name

LEE CHOR CHIANG

李 楚 璋

Race

CHINESE

Date of birth

08-10-1958

Country/Place of birth

SINGAPORE

Sex

M



REPUBLIC OF SINGAPORE
DRIVING LIC
Licence No. S1327603Z
Name



LEE CHOR CHIANG

Birth Date: 08 Oct 1958

Issue Date: 26 Nov 2003

001018386D




YOU ARE LICENSED TO DRIVE THE FOLLOWING CLASSES

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE


12 Dec 1996



Licence No: S1327603Z

NP 425A

5691234



NRIC No. S1327603Z



Date of issue
19-01-2017

Address

41A BEDOK RIA CRESCENT
#04-09
SINGAPORE 489929

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-127627

Date of Request: 06/08/2019

Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date 06/08/2019

Enquiry By Mars Ler Yeong Cherng

TP Vehicle No. SDV8811K

Accident Date 05/08/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SDV8811K	MSIG Insurance (Singapore) Pte. Ltd.	13/06/2019-12/06/2020	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-127627

Date of Request: 06/08/2019

Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date 06/08/2019

Enquiry By Mars Ler Yeong Cherng

TP Vehicle No. SDV8811K

Accident Date 05/08/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	603Z
Vehicle Details	
Vehicle No.:	SLM8497L
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Aug 2019
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	G4FGGH657361
Chassis No.:	KNAFZ411MH5665831
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$17,446.00
Original Registration Date:	13 Apr 2017
First Registration Date:	13 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$17,446.00 <i>8723</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2027
PARF Rebate Amount:	\$13,084.00
Intended COE Rebate Details	
COE Expiry Date:	12 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,765.00
COE Rebate Amount:	\$39,664.00
Total Rebate Amount:	\$52,748.00

The information contained herein is correct as at 14 Aug 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

FortyTwo

100 DAY FREE RETURNS



up to 50% off

WARDROBES

SHOP WARDROBES

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Land Rover Defender 90 Hard Top 2.2.



Comes With Many Accessories,
Call To Enquire.
Direct Owner StarAd

PRIME MOTOR & LEASING

ICHENG YONG CREDIT ENTERPRISES PTE.LTD. GROUP OF COMPANIES

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

31 vehicles

k3

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	k3		Any	Any	2017	Any	Any	Any	Available
	Kia	Cerato K3 1.6A	\$72,500	\$7,970 /yr	28-Nov-2017	1,591 cc	39,000 km	Sedan	Available
1 Owner. Pristine Condition. 5 Years Warranty With KIA! Full Servicing Records Available. Don't Miss! Trade In/ Flexible Loan Available,... 360 VR Cars Posted: 13-Aug-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia									
	Kia	Cerato K3 1.6A SX Sunroof	\$71,800	\$8,270 /yr	27-Apr-2017	1,591 cc	22,000 km	Sedan	Available
100% Loan Available. Offer Now, Free 1 Year Warranty, Free 1st Installment, Free 1 Year Insurance, Free Polishing, Chemical Wash Pac... Hua Yang Credit Pte Ltd Posted: 13-Aug-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia									
	Kia	Forte K3 1.6A	\$61,800	\$7,150 /yr	31-May-2017	1,591 cc	25,335 km	Sedan	Available
1 Owner. Popular And Reliable K3. Spacious Interior With Sporty Outlook! Well Maintained With Low Mileage Done And Still Under Warra... Mayfair Motoring Posted: 13-Aug-2019 Tags: 2017 Kia Forte, 2017 kia forte, Kia Forte, kia forte, Kia, Forte, forte, Used Kia									
	Kia	Cerato K3 1.6A	\$66,800	\$7,510 /yr	28-Aug-2017	1,591 cc	45,000 km	Sedan	Available
Selling Cheap! 5 Years Agent Warranty From C&C! Bidded Number! Low Down Payment Loan Packages Available! Attractive Interest Rat... Swee Seng Motors Posted: 10-Aug-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia									
	Beautify Car Look with HRE Design 18" Rims Stock Clearance Promotion HRE Design 18-8 5-120. Visit us @ Yap Brothers Motorsport, 32 Old Toh Tuck Rd, #01-09 Find out more!								
	Kia	Cerato K3 1.6A (OPC)	\$52,800	\$5,840 /yr	24-May-2017	1,591 cc	16,028 km	Sedan	Available
Low Mileage 16028km! Serviced By Agent! 5 Years C&C Warranty! Only 1 Owner! 100% Original! Drive And Feel Like A Brand New Car!... Posted: 09-Aug-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia									
	Kia	Forte K3 1.6A	\$64,800	\$7,570 /yr	19-May-2017	1,591 cc	28,815 km	Sedan	Available
Special Offer 1.5% Interest Rate! Agent Warranty Till Oct 2020. 10 Years Engine Warranty. Original Factory Unit From C&C, Buy With A... Republic Auto Posted: 09-Aug-2019 Tags: 2017 Kia Forte, 2017 kia forte, Kia Forte, kia forte, Kia, Forte, forte, Used Kia									
	Kia	Forte K3 1.6A EX	\$68,000	\$7,470 /yr	05-Dec-2017	1,591 cc	-	Sedan	Available
Elegant Grey, One Owner Only, Accident Free, Serviced By Agent, With Agent Warranty, Low Maintenance Cost, Very Well Maintained, E... Prime Motor & Leasing									

Compare

https://www.sgcarmart.com/used_cars/listing.php?MOD=k3&PRC=0&DEP=0&RGD=2017&VEH=0&... 14-Aug-19



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
MSIG INSURANCE (SINGAPORE) PTE LTD 16 RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581 Contact No 62209644	<table> <tr> <td>Cust No/Name</td><td>/Mr Lee Chor Chiang</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLM8497L / 13/04/2017</td></tr> <tr> <td>Date In/Mileage</td><td>10/09/2019/ 67946</td></tr> <tr> <td>Chassis No</td><td>KNAFZ411MH5665831</td></tr> <tr> <td>Engine No</td><td>G4FGGH657361</td></tr> <tr> <td>Make/Model</td><td>KIA/FORTE K3 1.6 A SX HADQ</td></tr> <tr> <td>Colour/Trim</td><td>4SS / WK</td></tr> </table>	Cust No/Name	/Mr Lee Chor Chiang	Reg No/Reg Date	SLM8497L / 13/04/2017	Date In/Mileage	10/09/2019/ 67946	Chassis No	KNAFZ411MH5665831	Engine No	G4FGGH657361	Make/Model	KIA/FORTE K3 1.6 A SX HADQ	Colour/Trim	4SS / WK
Cust No/Name	/Mr Lee Chor Chiang														
Reg No/Reg Date	SLM8497L / 13/04/2017														
Date In/Mileage	10/09/2019/ 67946														
Chassis No	KNAFZ411MH5665831														
Engine No	G4FGGH657361														
Make/Model	KIA/FORTE K3 1.6 A SX HADQ														
Colour/Trim	4SS / WK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
F0000017	Credit	17/09/2019/ 17:31		218 / MarsLer	30143	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC / SCANNING				250.00
S	MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				80.00
S	MIPNT88088	TO TRANSFER REAR BOOT COMPONENT & MECHANISM PARTS				300.00
S	MIPNT88088	TO REMOVE AND RE-INSTALL TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS				300.00
S	MIPNT88088	TO REPLACE REAR BOOT, REAR BUMPER, ETC				1375.00
		-REPAIR REAR END PANEL				
		STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL				100.00
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				1260.00
X	KS 69200 A7 040	TRUNK LID PANEL ASSY	1.00	1297.00	0.00	1297.00
X	KS 86310 A7 050	KIA SUB LOGO ASSY	1.00	37.00	0.00	37.00
X	KS 86311 A7 030	EMBLEM - CERATO	1.00	35.00	0.00	35.00
X	KS 87321 A7 000	WEATHERSTRIP - TRUNK	1.00	100.00	0.00	100.00
X	KS 86611 A7 810	COVER-REAR BUMPER	1.00	688.00	0.00	688.00
X	KS 86695 A7 810	COVER-REAR BUMPER, CE	1.00	347.00	0.00	347.00
X	KS 86631 A7 800	BEAM - REAR BUMPER	1.00	318.00	0.00	318.00
X	KS 81230 A7 020	LATCH ASSY - TRUNK L	1.00	112.00	0.00	112.00
X	KS 06032 50 037A	CLIP - BUMPER	10.00	2.00	0.00	20.00
Z	NOTES					
	ACCIDENT ON 05/08/2019 ALONG BEDOK NORTH AVENUE 1					
	OWNER CLAIMING THIRD PARTY					
	LOSS OF USE 05DAYS					
	TP # SDV8811K TP INS : MSIG					

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Parts	2,954.00
Labour	0.00
Standard Menu	0.00
Specialist Job	3,665.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	6,619.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MSIG INSURANCE (SINGAPORE) PTE LTD 16 RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581 Contact No 62209644	Cust No/Name /Mr Lee Chor Chiang Reg No/Reg Date SLM8497L / 13/04/2017 Date In/Mileage 07/08/2019/ 0 Chassis No KNAFZ411MH5665831 Engine No G4FGGH657361 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim 4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000017	Credit	07/08/2019/ 15:11	DS	218 / MarsLer	30143			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC / SCANNING						250.00
S	MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS						100.00
S	MIPNT88088	TO TRANSFER REAR BOOT COMPONENT & MECHANISM PARTS						600.00
S	MIPNT88088	TO REPLACE REAR REVERSE CAMERA LENS						350.00
S	MIPNT88088	TO REMOVE AND RE-INSTALL TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS						600.00
S	MIPNT88088	TO REPLACE REAR BOOT, REAR BUMPER, ETC						4200.00
		-CUT & RE-WELD REAR END PANEL						
		-TO REPAIR REAR FLOORING PANEL						
		STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS						300.00
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL						2940.00
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS						
M	KS 69200 A7 040	TRUNK LID PANEL ASSY			1.00	1297.00	0.00	1297.00
M	KS 86310 A7 050	KIA SUB LOGO ASSY			1.00	37.00	0.00	37.00
M	KS 86311 A7 030	EMBLEM - CERATO			1.00	35.00	0.00	35.00
P	KS 87210 A7 000	SPOILER - REAR			1.00	590.00	0.00	590.00
M	KS 87321 A7 000	WEATHERSTRIP - TRUNK			1.00	100.00	0.00	100.00
M	KS 85770 A7 000W K	TRIM - TRANSVERSE RE			1.00	58.00	0.00	58.00
P	KS 81230 A7 020	LATCH ASSY - TRUNK L			1.00	112.00	0.00	112.00
P	KS 86611 A7 810	COVER-REAR BUMPER			1.00	688.00	0.00	688.00
P	KS 86695 A7 810	COVER-REAR BUMPER, CE			1.00	347.00	0.00	347.00
M	KS 92405 A7 500	LH REFLECTOR REFLEX			1.00	99.00	0.00	99.00
M	KS 92406 A7 500	RH REFLECTOR REFLEX			1.00	99.00	0.00	99.00
M	KS 95720 A7 0003 D	ULTRASONIC SENSOR AS			4.00	177.00	0.00	708.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
MSIG INSURANCE (SINGAPORE) PTE LTD 16 RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581 Contact No 62209644	<table> <tr> <td>Cust No/Name</td><td>/Mr Lee Chor Chiang</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLM8497L / 13/04/2017</td></tr> <tr> <td>Date In/Mileage</td><td>07/08/2019/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAFZ411MH5665831</td></tr> <tr> <td>Engine No</td><td>G4FGGH657361</td></tr> <tr> <td>Make/Model</td><td>KIA/FORTE K3 1.6 A SX HADQ</td></tr> <tr> <td>Colour/Trim</td><td>4SS / WK</td></tr> </table>	Cust No/Name	/Mr Lee Chor Chiang	Reg No/Reg Date	SLM8497L / 13/04/2017	Date In/Mileage	07/08/2019/ 0	Chassis No	KNAFZ411MH5665831	Engine No	G4FGGH657361	Make/Model	KIA/FORTE K3 1.6 A SX HADQ	Colour/Trim	4SS / WK
Cust No/Name	/Mr Lee Chor Chiang														
Reg No/Reg Date	SLM8497L / 13/04/2017														
Date In/Mileage	07/08/2019/ 0														
Chassis No	KNAFZ411MH5665831														
Engine No	G4FGGH657361														
Make/Model	KIA/FORTE K3 1.6 A SX HADQ														
Colour/Trim	4SS / WK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000017	Credit	07/08/2019/ 15:11	DS	218 / MarsLer	30143
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M KS 91891 A7 050	WIRING HARNESS-BWS E	1.00	216.00	0.00	216.00
M KS 86613 A7 001	LH SIDE BRACKET - RE	1.00	29.00	0.00	29.00
M KS 86614 A7 001	RH SIDE BRACKET - RE	1.00	29.00	0.00	29.00
M KS 86631 A7 800	BEAM - REAR BUMPER	1.00	318.00	0.00	318.00
M KS 86636 A7 000	BRACKET - REAR BEAM	2.00	5.00	0.00	10.00
M KS 86635 A7 000	BRACKET - REAR BEAM	1.00	5.00	0.00	5.00
M KS 86633 A7 800	LH BRACKET - REAR BE	1.00	3.00	0.00	3.00
M KS 86634 A7 800	RH BRACKET - REAR BE	1.00	3.00	0.00	3.00
M KS 86641 A7 800	LH STAY - REAR BUMPE	1.00	120.00	0.00	120.00
P KS 86642 A7 800	RH STAY - REAR BUMPE	1.00	120.00	0.00	120.00
M KS 95420 A7 200	ANTENNA ASSY-SMARTKE	1.00	69.00	0.00	69.00
P KS 0G032 50 037A	CLIP - BUMPER	10.00	2.00	0.00	20.00
M KS 69100 A7 600	PANEL ASSY - BACK	1.00	274.00	0.00	274.00

Z NOTES

ACCIDENT ON 05/08/2019 ALONG BEDOK NORTH AVENUE 1

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP # SDV8811K TP INS : MSIG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Parts	5,386.00
Labour	0.00
Standard Menu	0.00
Specialist Job	9,340.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	14,726.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Aug 2019		13 Aug 2019 17:16 Edit Adj Rpt	\$6,619.00 Edit Estimates	\$6,619.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TAN KAI MING, ID: S7928491B, Tel: +6590218041, Email: NOEMAIL	
Main Claimant:	LEE CHOR CHIANG, ID: S1327603Z	
Vehicle Reg. No.:	SLM8497L	Date of Loss: 05/08/2019 14:00 - :59 [27 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 602013	Policy/Cover Note No.: 29080621 (Comprehensive) Coverage: 13/06/2019 - 12/06/2020
Vehicle Reg. No. (Insured):	SDV8811K	Policy No. (Claimant):
		Excess:
Repairer:	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3, 408650 Ubi - Tel: 67461000	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 12/09/2019]	
Driver/Custodian (Insured):	TAN KAI MING (39 / Male) , NRIC: S7928491B, Tel: +6590218041 Email: NOEMAIL	
Adj Asg. Remarks:	on WP. Survey appointment on 14/08/2019 10AM owner waiting. Please contact us ASAP if you cannot attend this assignment. Liab: 100%. Contact: Mars @ 6594 9163 / 9179 2566.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> MSIG_SG (13/08/2019): Cancellation of Assignment: SLM8497L 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLM8497L (602013)

[SDV8811K]

TP















































LEE CHOR CHIANG

Aug 5 2019 2:00PM

[TAN KAI MING]

Cycle & Carriage Fulco Motor Dealer Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>	
Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/08/19 10:42	Accident Statement From: SC - Reg. No: SDV8811K, Claimant: TAN KAI MING		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/08/19 17:01	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/08/19 18:03	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	14/08/19 18:04	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
4	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
5	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
6	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
7	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
8	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
9	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
10	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
11	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
12	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
13	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
14	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
15	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
16	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
17	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
18	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
19	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
20	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
21	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
22	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
23	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
24	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
25	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
26	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
27	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
28	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
29	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
30	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
31	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
32	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
33	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
34	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
35	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
36	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>
37	14/08/19 18:04	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
38	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
49	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
50	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
51	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
52	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
53	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
54	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
55	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
56	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
57	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
58	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
59	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
60	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
61	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
62	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
63	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
64	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
65	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
66	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
67	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
68	14/08/19 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
69	18/09/19 08:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	18/09/19 08:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	18/09/19 08:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	18/09/19 08:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	18/09/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	18/09/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	18/09/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	18/09/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	18/09/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	18/09/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	18/09/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	18/09/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/08/19 10:42	REPAIR EST	 Load PDF	
2	08/08/19 13:40	Acknowledge PRI	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	08/08/19 14:18	email-survey appointment	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014095/UYF3E2

Date: 04/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29080621

Claimant Vehicle No : SLM8497L

Insured Vehicle No : SDV8811K

Date of Loss: 05/08/2019

Nature of Claim: TP

Claim No: 602013

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM8497L

Make & Model: KIA FORTE K3, 1.6 SX (A)

Engine No: G4FGGH657361

Reg. Date: 13/04/2017 (Man. Year: 2016)

Chassis No: KNAFZ411MH5665831

Colour: Silver

Odometer: 65697 km

Engine Capacity: 1591 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50Z R17

Rear Tyre Size: 215/50Z R17

Front Left Side: Nexen 8 mm

Rear Left Side: Nexen 8 mm

Front Right Side: Nexen 8 mm

Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,386.00	2,954.00	2,432.00	45.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,340.00	3,665.00	5,675.00	60.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,726.00	6,619.00	8,107.00	55.05
+ GST 7.00/7.00% (S\$)	1,030.82	463.33	567.49	55.05
Nett Amount (S\$)	15,756.82	7,082.33	8,674.49	55.05

INSPECTION

Date of Assignment: 13/08/2019

Date Inspected: 14/08/2019 Inspected At:

Cycle & Carriage Fulco Motor Dealer
Pte Ltd (HQ)
330 Ubi Road 3
Singapore 408650

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2019)
Parts:	143	KIA FORTE K3 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM8497L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRUNK LID PANEL ASSY	Bent / Buckled	1,297.00 FS	*1,297.00 FS
2	1		*KIA SUB LOGO ASSY	Necessary	37.00 FS	*37.00 FS
3	1		*EMBLEM - CERATO	Necessary	35.00 FS	*35.00 FS
4	1		*SPOILER - REAR	Not Necessary	590.00 FS	*- FS
5	1		*WEATHERSTRIP - TRUNK	Deformed / Twisted	100.00 FS	*100.00 FS
6	1		*TRIM - TRANSVERSE RE	Not Necessary	58.00 FS	*- FS
7	1		*LATCH ASSY - TRUNK L	Shorted / Twisted	112.00 FS	*112.00 FS
8	1		*COVER - REAR BUMPER	Dented / Deformed	688.00 FS	*688.00 FS
9	1		*COVER - REAR BUMPER, CE	Grazed	347.00 FS	*347.00 FS
10	1		*LH REFLECTOR REFLEX	Not Necessary	99.00 FS	*- FS
11	1		*RH REFLECTOR REFLEX	Not Necessary	99.00 FS	*- FS
12	4		*ULTRASONIC SENSOR AS	Not Necessary	708.00 FS	*- FS
13	1		*WIRING HARNESS - BWS E	Not Necessary	216.00 FS	*- FS
14	1		*LH SIDE BRACKET - RE	Not Necessary	29.00 FS	*- FS
15	1		*RH SIDE BRACKET - RE	Not Necessary	29.00 FS	*- FS
16	1		*BEAM - REAR BUMPER	Cracked	318.00 FS	*318.00 FS
17	2		*BRACKET - REAR BEAM	Not Necessary	10.00 FS	*- FS
18	1		*BRACKET - REAR BEAM	Not Necessary	5.00 FS	*- FS
19	1		*LH BRACKET - REAR BE	Not Necessary	3.00 FS	*- FS
20	1		*RH BRACKET - REAR BE	Not Necessary	3.00 FS	*- FS
21	1		*LH STAY - REAR BUMPE	Not Necessary	120.00 FS	*- FS
22	1		*RH STAY - REAR BUMPE	Not Necessary	120.00 FS	*- FS
23	1		*ANTENNA ASSY - SMARTKE	Not Necessary	69.00 FS	*- FS
24	10		*CLIP - BUMPER	Necessary	20.00 FS	*20.00 FS
25	1		*PANEL ASSY - BACK	Repair	274.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	5,386.00	2,954.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC / SCANNING	New	250.00	250.00
2	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO TRANSFER REAR BOOT COMPONENT & MECHANISM PARTS	New	600.00	300.00
4	TO REPLACE REAR REVERSE CAMERA LENS	New	350.00	0.00
5	TO REMOVE AND RE-INSTALL TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	600.00	300.00
6	TO REPLACE REAR BOOT, REAR BUMPER, ETC. - CUT & RE-WELD REAR END PANEL. - TO REPAIR REAR FLOORING PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	4,200.00	1,375.00
7	TO APPLY SEALANT KIT ON NEW PANEL	New	300.00	100.00
8	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	2,940.00	1,260.00
Gross Labour Cost (\$\$)			9,340.00	3,665.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >