

ASS. REC. BY:

REF:

CS/MSG19014101/AGVD3m2

Special Instruction:

Surveyor:

Adnan

## ASSIGNMENT (Office)

From (Person):

Crystal Lee

of

MS1A

Date/Time:

14/8/19 @ 11.20am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 8408 L

Insured:

SLR 6172K

at Workshop m/s

Chew Motor

Tel:

6747 9241

of

1 Kaki Bukit Ave 6 # 01-11

Policy No:

29114756

Claim No:

602509

Sum Insured:

Excess:

Make of Veh:

D.O.A.

7/8/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:33am @ 14/8/19

Person Contacted:

Jukys

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction	Estimate
	SLX 8408 L - X	<input checked="" type="checkbox"/>
	SLR 6172K - X	
15/8/19	Informed Crystal pending workshop est by email	
28/8/19	Adrian confirmed LS \$ 3500 (Red H59840, 567)	
28/8/19	Send preli revised via merimen	

ASS. REC. BY:

REF:

Adrian

# ASSIGNMENT

25/11/09.

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLX8408L Yr Regn: 2009 / Nov

Type: MC / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit c.c. 1339

Colour: Purple A/C: Insured / Std / NI / NA

Sp. Reading: 176761 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GEH261423

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SR / STD A/Rim or

Tyre Size: F: 165/65R14

R: 165/65R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. _____		D.O.I. <u>13/08/19</u>	

Survey held at Chew

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS16.

MV: 11:51k

PV: 7:8k

Nett: 3:7k

Date/Time, File Pass to?

1) 28/8- typist

3)

5)

Prel. Report:

Final Report:

Date/Time, File Return to?

2)

4)

6)

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.  
\_ S + RS, \_ SI  
Photos  
Others  
TOTAL

Date:

150  
11

161

28/8/2019

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Irene Tan Gek Ing	Date:	28 Aug 2019

**Preliminary Advice**

Insured Vehicle No	: SLR6172K	Accident Date	: 07/08/2019
TP Vehicle No	: SLX8408L	Assignment Date	: 15/08/2019
Make	: HONDA FIT	Est. Duration of Repair	: 6
Date of Inspection	: 13/8/2019		
Inspection At	: CHEW MOTOR PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,098.40
Revised Amount	:S\$	3,500.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,500.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2019		15 Aug 2019 11:32 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	R&R CAR RENTAL, Co. Reg. No.: 53288192C		
Vehicle Reg. No.:	SLX8408L	Date of Loss:	07/08/2019 22:00 - :59 [116 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 602509	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLR6172K	Policy No. (Claimant):	
		Excess:	
Repairer:	Chew Motor Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #01-11/41, Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67479241 / 65095545		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 16/08/2019]		
Driver/Custodian (Insured):	KASHMIRA SHASHIKANT MEHTA (), NRIC: S7803157C, Tel: +6581303623 Email:		
Adj Asg. Remarks:	on WP. (Manual Assign). OI:Grab. Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Sukyi @ 6747 9241. Manual assigned to LKK via email on 14/08/19.		

[View All](#)   [Compose Case Mail](#)

**ASSOCIATED MAIL RECEIVED**

There are no mail for this case.

**ALL ASSOCIATED TASKS** 
[View All](#)   [Search Tasks](#)   [Create New Task](#)   [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 15 August 2019 10:03 AM  
**To:** 'Crystal Lee'  
**Cc:** 'Ong Zi Hui'; SUR  
**Subject:** RE: Survey Request - Manual Assigned-SLX 8408L

Dear Crystal,

Please be informed that we have inspected the vehicle SLX 8408L on 13/8/2019

We are pending estimate from repairer.

Kindly create claim in merimen.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Sent:** Wednesday, 14 August 2019 12:19 PM  
**To:** 'Crystal Lee' <crystal\_lee@sg.msiga-asia.com>; assignments <assignments@lkkauto.com>  
**Cc:** 'Ong Zi Hui' <zihui\_ong@sg.msiga-asia.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: Survey Request - Manual Assigned

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Crystal Lee [[mailto:crystal\\_lee@sg.msiga-asia.com](mailto:crystal_lee@sg.msiga-asia.com)]  
**Sent:** Wednesday, 14 August 2019 11:20 AM  
**To:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Cc:** Ong Zi Hui <zihui\_ong@sg.msiga-asia.com>  
**Subject:** Survey Request - Manual Assigned

**SLX8408L CLAIMING SLR6172K (GRAB) DOA: 07/08/19**

**Manual Assigned**

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

**Crystal Lee**

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Helene Phua

**Sent:** Wednesday, 14 August, 2019 10:01 AM

**To:** Crystal Lee <[crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)>; Ong Zi Hui <[zihui\\_ong@sg.msig-asia.com](mailto:zihui_ong@sg.msig-asia.com)>

**Subject:** FW: FW: SLX8408L CLAIMING SLR6172K (GRAB) DOA: 07/08/19

*Have a great week ahead!*

**Helene Phua**

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Helene Phua

**Sent:** Wednesday, 14 August, 2019 10:01 AM

**To:** 'Chew Motor Pte. Ltd.' <[claims@chewmotor.com](mailto:claims@chewmotor.com)>

Cc: Nabilah Rasol <nabilah\_rasol@sg.msig-asia.com>; Irene Tan <irene\_tan@sg.msig-asia.com>  
Subject: RE: FW: SLX8408L CLAIMING SLR6172K (GRAB) DOA: 07/08/19

Hi Sukyi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

**Helene Phua**

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Chew Motor Pte. Ltd. [<mailto:claims@chewmotor.com>]

**Sent:** Tuesday, 13 August, 2019 11:38 AM

**To:** Winnie Chua <[pingping\\_chua@sg.msig-asia.com](mailto:pingping_chua@sg.msig-asia.com)>

**Cc:** Helene Phua <[helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)>; Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>

**Subject:** Re: FW: SLX8408L CLAIMING SLR6172K (GRAB) DOA: 07/08/19

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Without Prejudice

Hi Winnie

Please arrange for :

- 1) LKK Auto Consultants Pte Ltd

\*\*\*Please take note this claim under Chew Motor Pte Ltd\*\*\*



Please kindly take note that we have a mutual agreement on the selection of appointed surveyor from your panel surveyor's list. We hope that there will not be any further changes to the finalised repair cost after confirmation with your appointed surveyor or at the stage of LOD.

*\*Please kindly take note that CHEW MOTOR PTE LTD is GST-registered.\**

Regards,

Sukyi Chong

**Chew Motor Pte Ltd**  
(GST Registration No.: 201718369R)  
1 Kaki Bukit Ave 6  
Blk A #01-11 Autobay  
Singapore 417883  
T : 6747 9241  
F : 6741 7276

On Tue, Aug 13, 2019 at 11:02 AM Winnie Chua <[pingping\\_chua@sg.msig-asia.com](mailto:pingping_chua@sg.msig-asia.com)> wrote:

Hi,

We refer to your email/faxed dated 13/08/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors (Appointment is full on 13.08.19)**

\*This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor\*

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Frankie Pang
2) Kenneth Kong	7) Ng You Han
3) Marcus Chua	8) Gary Soon
4) Henry Ng	9) Chow Bo Xiong
5) Lau Kwok Kwong	10) Axel Lee



NB:

(a) **\*Fast lane settlement is not applicable for cases that liability is in dispute\***

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | [pingping\\_chua@sg.msig-asia.com](mailto:pingping_chua@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Chew Motor Pte. Ltd. [<mailto:claims@chewmotor.com>]  
**Sent:** Saturday, August 10, 2019 3:26 PM  
**To:** Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>  
**Subject:** SLX8408L CLAIMING SLR6172K

---

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Motor Claims Department,

Kindly send your list of surveyor for PRI.

Thank you!

*\*Please kindly take note that CHEW MOTOR PTE LTD is GST-registered.\**

Regards,

**Chew Motor Pte Ltd**  
(GST Registration No.: 201718369R)

1 Kaki Bukit Ave 6

Blk A #01-11 Autobay

Singapore 417883

T : 6747 9241

F : 6741 7276

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**Nivitha (LKK Auto)**

---

**From:** Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Sent:** Wednesday, 14 August 2019 11:20 AM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Ong Zi Hui  
**Subject:** Survey Request - Manual Assigned

**SLX8408L CLAIMING SLR6172K (GRAB) DOA: 07/08/19**

**Manual Assigned**

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

**Crystal Lee**

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Helene Phua

**Sent:** Wednesday, 14 August, 2019 10:01 AM

**To:** Crystal Lee <crystal\_lee@sg.msig-asia.com>; Ong Zi Hui <zihui\_ong@sg.msig-asia.com>

**Subject:** FW: FW: SLX8408L CLAIMING SLR6172K (GRAB) DOA: 07/08/19

*Have a great week ahead!*

**Helene Phua**

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



**MSIG**



A Member of **MS&AD** INSURANCE GROUP

**From:** Helene Phua  
**Sent:** Wednesday, 14 August, 2019 10:01 AM  
**To:** 'Chew Motor Pte. Ltd.' <[claims@chewmotor.com](mailto:claims@chewmotor.com)>  
**Cc:** Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>; Irene Tan <[irene\\_tan@sg.msig-asia.com](mailto:irene_tan@sg.msig-asia.com)>  
**Subject:** RE: FW: SLX8408L CLAIMING SLR6172K (GRAB) DOA: 07/08/19

Hi Sukyi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

*Have a great week ahead!*

**Helene Phua**  
Admin Assistant, Claims Services  
D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Chew Motor Pte. Ltd. [<mailto:claims@chewmotor.com>]  
**Sent:** Tuesday, 13 August, 2019 11:38 AM  
**To:** Winnie Chua <[pingping\\_chua@sg.msig-asia.com](mailto:pingping_chua@sg.msig-asia.com)>  
**Cc:** Helene Phua <[helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)>; Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>  
**Subject:** Re: FW: SLX8408L CLAIMING SLR6172K (GRAB) DOA: 07/08/19

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Without Prejudice

Hi Winnie

Please arrange for :

- 1) LKK Auto Consultants Pte Ltd

\*\*\*Please take note this claim under Chew Motor Pte Ltd\*\*\*

Please kindly take note that we have a mutual agreement on the selection of appointed surveyor from your panel surveyor's list. We hope that there will not be any further changes to the finalised repair cost after confirmation with your appointed surveyor or at the stage of LOD.

*\*Please kindly take note that CHEW MOTOR PTE LTD is GST-registered.\**

Regards,

Sukyi Chong

**Chew Motor Pte Ltd**  
(GST Registration No.: 201718369R)  
1 Kaki Bukit Ave 6  
Blk A #01-11 Autobay  
Singapore 417883  
T : 6747 9241  
F : 6741 7276

On Tue, Aug 13, 2019 at 11:02 AM Winnie Chua <[pingping\\_chua@sg.msig-asia.com](mailto:pingping_chua@sg.msig-asia.com)> wrote:

Hi,

We refer to your email/faxed dated 13/08/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors (Appointment is full on 13.08.19)**

\*This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor\*

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Frankie Pang
---------------	-----------------

2) Kenneth Kong	7) Ng You Han
3) Marcus Chua	8) Gary Soon
4) Henry Ng	9) Chow Bo Xiong
5) Lau Kwok Kwong	10) Axel Lee

NB:

(a) **\*Fast lane settlement is not applicable for cases that liability is in dispute\***

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | [pingping\\_chua@sg.msig-asia.com](mailto:pingping_chua@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

From: Chew Motor Pte. Ltd. [<mailto:claims@chewmotor.com>]

Sent: Saturday, August 10, 2019 3:26 PM

To: Claims <claims@sg.msig-asia.com>  
Subject: SLX8408L CLAIMING SLR6172K

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Motor Claims Department,

Kindly send your list of surveyor for PRI.

Thank you!

*\*Please kindly take note that CHEW MOTOR PTE LTD is GST-registered.\**

Regards,

**Chew Motor Pte Ltd**  
(GST Registration No.: 201718369R)

1 Kaki Bukit Ave 6

Blk A #01-11 Autobay

Singapore 417883

T : 6747 9241

F : 6741 7276

---

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.





**DAVANTI**  
Proven Performance Tyre



31 Aug & 1 Sep | 10am - 8pm  
Downtown East Corpark B

**SEE YOU @ BOOTH 2!**

**SPARKO Kakis @ \$356** includes GST

**FREE** 1 Essential Servicing & 1 Grooming (worth \$236 total)

Plus Many Other Benefits!



Follow us: f @

jazz
 Price Range  Depreciation  2010  Vehicle Type

## Used Car Comparison

--- Comparing 4 Vehicles ---

**Honda Jazz 1.3A L**



[Add to Shortlist](#)

**Honda Jazz 1.3A L**



[Add to Shortlist](#)

**Honda Jazz 1.3M L**



[Add to Shortlist](#)

**Honda Jazz 1.3A L**



[Add to Shortlist](#)

[Clear All](#)
[Add all to Shortlist](#)
[Back to search result](#)

CAR DETAILS				
Price	\$15,333	\$19,000	\$16,800	\$21,800
Instalment	\$3,604	\$1,242	\$1,205	\$992
Registration Date	17-Nov-2009	02-Aug-2010	07-Jul-2010	20-Dec-2010
Manufactured	2008	2009	2008	2009
Mileage	102,060 km	120,000 km	-	-
Transmission	Auto	Auto	Manual	Auto
Engine Cap	1,339 cc	1,339 cc	1,339 cc	1,339 cc
Road Tax	\$590 /yr	\$590 /yr	\$590 /yr	\$590 /yr
Power	73.0 kW (97 bhp)	73.0 kW (97 bhp)	73.0 kW (97 bhp)	73.0 kW (97 bhp)
Curb Weight	1,060 kg	1,060 kg	1,060 kg	1,090 kg
Features	1.3L I-VTEC Super Fuel Efficient Engine, Smooth 5-Speed Auto Gearbox Transmission, ABS, 2 x SRS Airbags, Key Immobilizer, Paddle Shifters. View Specs	1.3L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Paddle Shifters, Reverse Sensors, Multifunction Steering Control, Knockdown Rear Seats.	1.4L Inline 4 Cylinder Engine, 5 Speed Manual Transmission, SRS Airbags, Knockdown Rear Seats.	1.3L I-VTEC Engine Transmission, SRS Sensors/Multi Func With Paddle Shifter Seats.
Accessories	Factory Fitted Audio System, Reverse Sensors, Leather Seats, Sport Rims, V-Kool Tinted Film, Remote/Immobilizer, Auto Retractable Folding Mirror.	Sports Rims, Leather Seats, Fog Lamps, Reverse Sensors, Retractable Mirrors With Signal Indicators.	Leather Seats, Reverse Sensor, Factory Fitted Audio System, Sports Rims	Sports Rims, Leath Reverse Sensors, F With Signal Indicat
Description	100% Loan Approval, \$550 Monthly Installment, High Loan Available, Renew 10 Years COE \$4.6k Yearly Depreciation Only, New Paintwork, New Rims And Tyres, Low Mileage, Excellent Maintained Condition, No Repairs Needed And Comes With 6 Months Warranty.	Very Low Mileage! Comes With Mugen Bodykit! Priced To Sell! Car Is In Excellent Condition. Comfortable Drive, Must View To Believe! Accident Free Car, Serious Offers Will Be Considered. Lowest Loan Available, Trade In Accepted. Call For Viewing/Enquiries!	Still In Good Condition, Clean Unit, No Repair Needed. Reliable And Easy To Maintain. Good For Short Term Drive, Cheaper Than Rental. Trade In Welcome. Flexible Loan Package With Low Interest Rate Available. Call Now For Appointment.	Regular Serviced A Previous Owner. Si Gearbox Transmiss Needed. Good For Idea For COE Rene Spacious, Not Only But She Provides A Trade In/Bank/In Here. Start Calling Gone!
COE	N.A.	\$28,467	\$27,389	\$47,604
OMV	\$20,547	\$19,220	\$16,856	\$19,942
ARF	\$20,547	\$19,220	\$16,856	\$19,942
Depreciation	N.A.	\$9,680 /yr	\$9,320 /yr	\$8,740 /yr
No. of Owners	2	4	2	2
Type of Vehicle	Hatchback	Hatchback	Hatchback	Hatchback
Category	PARF Car	PARF Car	PARF Car	PARF Car
Availability	Available	Available	Available	Available
SELLER INFORMATION				

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business  
Owner ID: 192C

**Vehicle Details**

Vehicle No.: SLX8408L  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 10 Aug 2019  
Vehicle Make: HONDA  
Vehicle Model: FIT 1.3G A  
Primary Colour: Pink  
Manufacturing Year: 2009  
Engine No.: L13A4284844  
Chassis No.: GE61261423  
Maximum Power Output: 73.0 kW (97 bhp)  
Open Market Value: \$14,668.00  
Original Registration Date: 26 Nov 2009  
First Registration Date: 26 Nov 2009  
Transfer Count: 5  
Actual ARF Paid: \$14,668.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 25 Nov 2019  
PARF Rebate Amount: \$7,334.00

**Intended COE Rebate Details**

COE Expiry Date: 25 Nov 2019  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$16,747.00  
COE Rebate Amount: \$488.00  
**Total Rebate Amount: \$7,822.00**

The information contained herein is correct as at 10 Aug 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/08/2019 13:54
Date Of Accident	07/08/2019 22:45
Exact Location Of Accident	AYER RAJAH EXPRESSWAY TWDS PANDAN RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX8408L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	R&R CAR RENTAL
Co Reg No	53288192C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98188106
Alternative Phone No	OFFICE-98188106

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5110777060
Cover Note Number	

### Driver

Name of Driver	TAN POH KEE
NRIC No	S1737466D
Date Of Birth	30/11/1966
Occupation	INDOOR
Date Of Driving Pass	20/07/2015
Driving Experience	4 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90090394
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 403 PANDAN GARDENS #11-22
Postcode	600403
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI POLICE DIVISIONAL HQ (D DIVISION )
Police Station Address	ROAD: 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7740000 - FAX NO: 67741705
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR6172K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

TAN POH KEE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN

Towards Pandan Road

SLX 8408L

SLR 6172K

AYE FLUYER

A = SLX 8408L  
B = SLR 6172K

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO REPORT NO. D/20190808/7022

### DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name  
NRIC/FIN No:





**SINGAPORE  
POLICE FORCE**



D/20190808/7022

1 of 2

**POLICE REPORT (NP299)**

Report No. D/20190808/7022

Police Station Of Origin  
Clementi Division HQ  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No:1800-7740000

Date/Time Report Made 08/08/2019 19:09	Vide Report No.	Station Diary No.
Name Of Informant TAN POH KEE	Address APT BLK 403 PANDAN GARDENS #11-22 SINGAPORE 600403	
ID Type / ID No. NRIC NO / S1737466D	Contact No. Home/Office: Mobile: 90090394	
Nationality SINGAPORE CITIZEN	Email Address tanpolly@yahoo.com	
Occupation Healthcare assistant	Sex Female	Age 52
Institution/School Name	Date of Birth 30/11/1966	Race Chinese
	Language English	
Date/Time Of Incident 07/08/2019 22:45 - 07/08/2019 22:55	Location Of Incident AYER RAJAH EXPRESSWAY	

**Brief details.**

ON 07/08/2019, ABOUT 10.45PM, I WAS ON MY WAY HOME, AND AS I WAS APPROACHING THE TRAFFIC JUNCTION, I FELT A GREAT IMPACT AT THE BACK OF MY CAR.  
AS I CAME DOWN THE VEHICLE, I REALISED THAT VEHICLE NO. SLR6172K, DRIVEN BY MS. KASHMIRA OF S7803157C, CRASHED INTO THE BACK OF MY VEHICLE.  
WE EXCHANGE PARTICULARS AND LEFT THE SCENE.  
DUE TO THE GREAT IMPACT, I VISITED THE A&E AT NATIONAL UNIVERSITY HOSPITAL THE FOLLOWING DAY AND WAS GIVEN 3 DAYS MC AND WOULD BE FOLLOWING UP WITH THE

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 08/08/2019 19:09
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE  
POLICE FORCE**



D/20190808/7022

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. D/20190808/7022

DOCTOR.

Subjects Involved			
Victim			
Person Name	TAN POH KEE		
ID Type	NRIC NO	ID No	S1737466D
Gender	Female	Age	52
Race	Chinese	Language	English
Occupation	Healthcare assistant	Address Type	
Address	APT BLK 403 PANDAN GARDENS #11-22 SINGAPORE 600403		Mobile No 90090394
Is Informant A Victim?	Yes		
Person Name	TAN POH KEE (Informant)		

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

08/08/2019 19:09

Classification Of Case:



Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

## CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R **13/08/2019**

TPMS19  
Veron

GE61261423

Accident date: 07/08/2019

Estimated repair cost for vehicle no: SLX8408L HONDA FIT 1.3 G A '09

CHASSIS: GE61261423

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$820.30
2	1	Rear Boot Lid Emblem Logo <i>None</i>		\$38.10
3	1	Rear Boot Lid Fit Logo <i>None</i>		\$38.00
4	1	Rear Boot Lid Inner Lock <i>Dmgd.</i>		\$232.10
5	1	Rear Boot Lid Inner Rubber <i>None</i>		\$128.10
6	1	Rear Boot Lid Inner Trim Board <i>None</i>		\$296.70
7	1	Rear Boot Lid Windscreen Seal <i>None</i>		\$136.20
8	2	Rear Tail Lamp <i>cracked</i>	\$296.50	\$593.00
9	4	Rear Tail Lamp Clip <i>None</i>	\$8.00	\$32.00
10	1	Rear Bumper <i>Dented</i>		\$494.60
11	8	Rear Bumper Clip <i>None</i>	\$6.50	\$52.00
12	2	Rear Bumper Side Retainer <i>None</i>	\$28.70	\$57.40
13	1	Rear Bumper Towing Cover <i>None</i>		\$28.00
14	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00
15	1	Rear End Panel <i>Dented</i>		\$365.30
16	1	Rear End Panel Top Garnish <i>Damaged</i>		\$140.20
17	1	Rear Spare Tyre Panel Top Cover <i>Dented</i>		\$260.40
18	1	Rear Spare Tyre Panel Top Sponge <i>cracked</i>		\$206.00
19	1	Rear Spare Tyre Panel Sealant <i>None</i>		\$450.00

Subtotal :- **\$4,718.40**

3281.10 S.N: 200  
2624.88

### Labour charges

To remove & refit rear cushion

~~\$280.00~~ 60

To remove & refit rear windscreen

\$120.00 ✓

Gum

~~\$50.00~~ ✓

To remove & refit reverse sensor

~~\$100.00~~ 50

To check wiring

~~\$80.00~~ 30

Tuff kote

~~\$150.00~~ 60

Panel beating

~~\$1,200.00~~ 800

Spray painting

~~\$1,400.00~~ 800

Subtotal :- \$3,380.00

Total:- \$8,098.40

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4744.88

H/s: 3.5K (Nett Value)

06 Days.

~~3.5 Days~~

3.5K

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014101/AGVD3N2

Date: 03/09/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SLX8408L	Insured Vehicle No :	SLR6172K
Date of Loss:	07/08/2019	Nature of Claim:	TP
		Claim No:	602509

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLX8408L	Engine No:	L13A4284844
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61261423
Reg. Date:	26/11/2009 (Man. Year: 2009)	Odometer:	176761 km
Colour:	Purple		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	165/65 R14	Rear Tyre Size:	165/65 R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,718.40	2,824.88	1,893.52	40.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,970.00	1,410.00	41.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,098.40</b>	<b>4,794.88</b>	<b>3,303.52</b>	<b>40.79</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,500.00</b>		
<b>(\$\$)</b>	<b>8,098.40</b>	<b>3,500.00</b>	<b>4,598.40</b>	<b>56.78</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>566.89</b>	<b>245.00</b>	<b>321.89</b>	<b>56.78</b>
<b>Nett Amount (\$\$)</b>	<b>8,665.29</b>	<b>3,745.00</b>	<b>4,920.29</b>	<b>56.78</b>

## INSPECTION

Date of Assignment:	15/08/2019
Date Inspected:	13/08/2019 Inspected At:

Chew Motor Pte Ltd (HQ)  
No 1 Kaki Bukit Ave 6, #01-11/41,  
Autobay@Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 Sep 2019)
<b>Parts:</b> 144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLX8408L)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	820.30 F	*771.00 FL
2	1		*REAR BOOT LID EMBLEM LOGO	Not Necessary	38.10 F	*- FL
3	1		*REAR BOOT LID FIT LOGO	Necessary	38.00 F	*38.00 FL
4	1		*REAR BOOT LID INNER LOCK	Damaged	232.10 F	*189.00 FL
5	1		*REAR BOOT LID INNER RUBBER	Not Necessary	128.10 F	*- FL
6	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	296.70 F	*- FL
7	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	136.20 F	*136.20 FL
8	2		*REAR TAIL LAMP	Cracked	593.00 F	*593.00 FL
9	4		*REAR TAIL LAMP CLIP	Not Necessary	32.00 F	*- FL
10	1		*REAR BUMPER	Deformed	494.60 F	*494.60 FL
11	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	57.40 F	*57.40 FL
13	1		*REAR BUMPER TOWING COVER	Not Necessary	28.00 F	*- FL
14	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
15	1		*REAR END PANEL	Dented	365.30 F	*365.30 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	140.20 F	*140.20 FL
17	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	260.40 F	*260.40 FL
18	1		*REAR SPARE TYRE PANEL TOP SPONGE	Cracked	206.00 F	*206.00 FL
19	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	450.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,718.40</b>	<b>3,481.10</b>
<b>- List Item Discount on L Items 0.00/20.00% (S\$)</b>	<b>0.00</b>	<b>656.22</b>
<b>Total Parts (S\$)</b>	<b>4,718.40</b>	<b>2,824.88</b>

Report was unsubmitted during this print-out.



**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT REAR CUSHION	New	280.00	60.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	50.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
5	TO CHECK WIRING	New	80.00	30.00
6	TUFF KOTE	New	150.00	60.00
7	PANEL BEATING	New	1,200.00	800.00
8	SPRAY PAINTING	New	1,400.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,380.00</b>	<b>1,970.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;