

TP claim AIG - LKK survey

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	11:20hrs
ACCIDENT DATE	6-Aug-19
BUS CAPTAIN NAME	AMIRUL HAKIM BIN ABD RAHMAN
EMPLOYEE NUMBER	

BUS REGISTRATION NUMBER	SG1009H
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.	Part or Item Description	Quantity	Total Cost
77200621	RADIATOR FLAP	1	\$5,103.58
77200124	REAR CORNER BUMPER O/S/R	1	\$746.18
77200612	SIDE MARKER LIGHT	1	\$80.00
77014459	DOWEL (ANCHOR)	2	\$3.60
			5933.36
		7% GST	\$415.34
		PARTS TOTAL COST	\$6,348.70

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO REMOVE & REPLACE DAMAGED PARTS	3 DAYS 1300	\$1,950.00
PUTTY AND SPRAY PAINTING	4 DAYS 1625	\$2,600.00
	2925	
	7% GST	\$318.50
	LABOUR TOTAL COST	\$4,868.50

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	
---------------------------------	--

SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	
-------------------	--

SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	
		Date Out From Repairs	
		Number of Days Under Repair	8
BUS TYPE (SD / DD)			
LOSS OF USE COST		\$2,400.00	

SUMMARY	
SECTION NO.	COST
1	\$6,348.70
2	\$4,868.50
3	-
4	-
5	\$2,400.00
ESTIMATED ACCIDENT REPAIR COST	\$13,617.20

5933.36
2925
8858.36

~~4/5 \$7100~~
06 days

Tanpha 97495749
wp'
14/8/19 @ 340.
Resurvey before paint.
5-6 days.
sur@kkanto.com
tanpha@kkanto.com

x 90% LUMP SUM
= \$8,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____