

ASS. REC. BY:

REF:

es/MS419014124/Ktd3021

Special Instruction:

Sponsor:

Kannan

## ASSIGNMENT (Office)

From (Person):

menmen Fierel P00

of

MS14

Date/Time:

14/8/19 @ 1:43pm

Estimated Cost:

Bill to:

OD/IT WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLC 3021 L

Insured:

SGV 2209D

at Workshop m/s

Autowork House

Tel:

6:4528211

of

176 Sin Ming Drive # 02-01

Policy No:

291196790MX

Claim No:

60263

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/8/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1:49pm @ 14/8/19

Person Contacted:

chew

Vehicle IN/OUT

Date/Time

Action/Instruction

Schmidt ✓

SLC 3021 T-X

SGV 2209D - CCB LAXA 12023519 / Ur f3.3

JDA: 12/11/2012

15/8:-

Revised via menmen preli advise

ASS. REC. BY:

REF:

1756/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Vsh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 3021

Yr Regn: 09/05/16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS Syphy

c.c. 1598

Colour:

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

7115P

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MNTBBAB1720023882

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

13/8/19

D.O.I.

14/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

Rear end jammed GIA not ready

11 Rm 85350/ena1

RECEIVED 18 FEB 2020

refinalize #4900/- 1 Red. 11206.69

17/2/2020

Date/Time, File Pass to?



: Prell. Report

11/18/2 Typist



: Final Report

Date/Time, File Return to?

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

200

Transportation:

S - R.S. \$

F - R.S.

Others

TOTAL

211

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

4900

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Aug 2019		14 Aug 2019 13:43 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TEO HWEE HOON, ID: S7441441I		
Main Claimant:	SOH BOON PING, ID: S7737609G		
Vehicle Reg. No.:	SLC3021L	Date of Loss:	13/08/2019 08:00 - :59 [39 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29119679QMX (Comprehensive) Coverage: 20/03/2019 - 24/05/2020
Vehicle Reg. No. (Insured):	SGV2209D	Policy No. (Claimant):	
		Excess:	
Repairer:	Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01, 575721 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]		
Driver/Custodian (Insured):	TEO HWEE HOON (44 / Female) , NRIC: S7441441I Email:		
Adj Asg. Remarks:	on WP, (Manual Assign) Liab: Dispute(NR), Agree on SJE, Assign: LKK Auto Consultants Pte Ltd, Contact: WK Chew @ 6452 8211, Manual assigned via email to LKK on 14/08/2019.		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Sent:** Wednesday, 14 August 2019 11:15 AM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Ong Zi Hui  
**Subject:** Survey Request - Manual Assigned

**Request for Single Jointed Expert Inspection for SLC3021L in an accident involving SGV2209D (MSIG) on 13-08-2019**

### Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Helene Phua

**Sent:** Wednesday, 14 August, 2019 10:29 AM

**To:** Crystal Lee <crystal\_lee@sg.msig-asia.com>; Ong Zi Hui <zihui\_ong@sg.msig-asia.com>

**Subject:** FW: Request for Single Jointed Expert Inspection for SLC3021L in an accident involving SGV2209D (MSIG) on 13-08-2019

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Helene Phua

**Sent:** Wednesday, 14 August, 2019 10:29 AM

**To:** [claim.autoworxhouse@gmail.com](mailto:claim.autoworxhouse@gmail.com)

**Cc:** Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>; Fievel Foo <[Fievel\\_Foo@sg.msig-asia.com](mailto:Fievel_Foo@sg.msig-asia.com)>

**Subject:** RE: Request for Single Jointed Expert Inspection for SLC3021L in an accident involving SGV2209D (MSIG) on 13-08-2019

Dear Sirs,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

*Have a great week ahead!*

**Helene Phua**

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Admin [<mailto:claim.autoworxhouse@gmail.com>]

**Sent:** Tuesday, August 13, 2019 2:56 PM

**To:** Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>

**Subject:** Request for Single Jointed Expert Inspection for SLC 3021 L in an accident involving SGV 2209 D on 13-08-2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sirs,

We have been authorised by Mr Soh Boon Ping, the registered owner of motor vehicle SLC3021 Lat the material time of accident to make a claim against your insured.

Please give us the list of panel of your survey firms for our selection to inspect the above said vehicle or you may assign our choice from either one of the 3 survey firms,

- 1) Premier Appraiser Services
- 2) LKK Auto Consultants Pte Ltd
- 3) AJAX Inspection Services Pte Ltd

Please advise us with your assigned surveyor, name and contact number for this matter.

Kindly contact us at [claims.autoworxhouse@gmail.com](mailto:claims.autoworxhouse@gmail.com) or call 64528211 before coming to ensure the vehicle is in the workshop.

Thank you.

Best regards,

WK Chew  
Autoworx House

---

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## Denise Tay (LKKAUTO)

---

**From:** claim.autoworxhouse@gmail.com  
**Sent:** Thursday, 9 January 2020 5:42 PM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** RE: SLC 3021 L NISSAN SYLPHY DOA 13082019

Dear Denise,

We accept your offer.  
Thank you.

Best regards,  
Ms. Lee  
Autoworx House  
No.176 Sin Ming Drive  
#02-01 Singapore 575721  
Tel: 96725547 / 87668115  
Fax: 64517423

-----Original Message-----

**From:** Denise Tay (LKKAUTO) <denisetay@lkkauto.com>  
**Sent:** Monday, December 23, 2019 9:36 AM  
**To:** claim.autoworxhouse@gmail.com  
**Cc:** admin@supreme.sg  
**Subject:** RE: SLC 3021 L NISSAN SYLPHY DOA 13082019

Dear Ms Lee,

Please see estimate marking.

Correct calculation is lump sum \$4,900/- , 7 days

Parts after 30% = \$1,757.77  
Nett after 10% = \$1,955.25  
S/Nett after 10% = \$245  
Labour = \$2,190  
Total = \$6,148.02

Please check and confirm.

Best Regards,  
Denise Tay | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** claim.autoworxhouse@gmail.com <claim.autoworxhouse@gmail.com>  
**Sent:** Tuesday, 5 November 2019 11:35 AM  
**To:** Denise Tay (LKKAUTO) <denisetay@lkkauto.com>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 15 Aug 2019

## Preliminary Advice

Insured Vehicle No	: SGV2209D	Accident Date	: 13/08/2019
TP Vehicle No	: SLC3021L	Assignment Date	: 14/08/2019
Make	: NISSAN SYLPHY	Est. Duration of Repair	: 7.00
Date of Inspection	: 14/08/2019		
Inspection At	: AUTOWORX HOUSE - SIN MING (HQ) 176 SIN MING DRIVE #02-01 SINGAPORE 575721		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear. portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,106.69
Revised Amount	:S\$	7,250.59
Check Items (Estimated)	:S\$	3,661.73
Total	:S\$	10,912.32
Lump Sum Repair	:S\$	

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GfA Records Management Centre established by the General Insurance Association of Singapore (GfA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/08/2019 16:57
Date Of Accident	13/08/2019 08:40
Exact Location Of Accident	PIE TOWARDS TUAS JALAN BAHAR FLYOVER
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC3021L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SOH BOON PING
NRIC No	S7737609G
Email Address	MERVYN2277@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81009147
Alternative Phone No	OTHERS-81009147

### Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 1.6 PREMIUM
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900080293
Cover Note Number	

### Driver

Name of Driver	SOH BOON PING
NRIC No	S7737609G
Date Of Birth	22/12/1977
Occupation	INDOOR
Date Of Driving Pass	22/02/2002
Driving Experience	17 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81009147
Fax Number	
Contact Number	OTHERS-81009147
Email Address	MERVYN2277@GMAIL.COM

Address	BLK 61 CEHSTNUT AVENUE #03-04
Postcode	679522
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20190813/2099.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV2209D
Vehicle Make/Model/Colour	HONDA VEZEL 1.5X A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	SOH BOON PING
Approximate Age	41
Injuries Sustain	BACK PAIN
Injured person in which vehicle?	SLC3021L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 61 CHESTNUT AVENUE #03-04
Postcode	679522

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time: 13 AUG 2019  
16:57h

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 13 AUG 2019  
16:57h

Reporting Centre Personnel's Signature  
Name: Poh KYAN CHOO  
NRIC/FIN No: S3810583A

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was driving on the extreme right lane along PIE towards Tuar direction. At the Salan Bakar Flyover, vehicles in front of me stopped. I stopped my vehicle too. Vehicle B (8GV 2209I) did not stop in time, collided into the rear of my vehicle with a hard impact.

DECLARATION

(We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time 3 AUG 2019

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time 3 AUG 2019

  
 Reporting Centre Personnel's Signature  
 Name: P. N. / W. B. CHAI  
 NRIC/FIN No.: 3840555A



**SINGAPORE  
POLICE FORCE**



T/20190813/2099

1 of 4

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

Report No. T/20190813/2099

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/08/2019 15:21		Vide Report No.:		Station Diary No.: 97
<b>Informant's Particulars</b>				
Name of Informant: SOH BOON PING		Address: APT BLK 61 CHESTNUT AVENUE #03-04 SINGAPORE 679522		
ID Type / ID No.: NRIC NO / S7737609G		Contact No.: Home/Office:		Mobile: 81009147
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 41	Date of Birth: 22/12/1977	Type of Informant: Driver	
Race: Chinese		Language:		Institution / School Name:
Occupation: MANAGER		Driving Licence Information: Class: 3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 13/08/2019 08:40	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE(TUAS) - NEAR JALAN BAHAR FLYOVER				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SGV2209D	Car	HONDA	VEZEL 1.5X A	Blue	Slightly Damaged	0
SLC3021L	Car	NISSAN	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR	Black	Seriously Damaged	0

Details of Vehicle Insurance			
Vehicle No.	Insurance Company	Insurance No.	Effective / Expiry Date



**SINGAPORE  
POLICE FORCE**



T/20190813/2099

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

2 of 4  
Report No. T/20190813/2099

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLC3021L	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1900080293	09/05/2019	08/05/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Teo Hwee Hoon		ID No.	S7441441I
Related Vehicle	SGV2209D (Car)		Contact No.	83229379
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of injury	NIL
Driver				
Name	SOH BOON PING		ID No.	S7737809G
Related Vehicle	SLC3021L (Car)		Contact No.	81009147
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	13/08/2019		Date Discharge	13/08/2019
No. of Days granted Medical Leave	05		Degree of Injury	Slight

**Brief Details.**

On 13/08/2019 at 0840hrs, I was driving my black Nissan, SLC3021L on the right most lane along PIE (Tuas) near the Jalan Bahar flyover. I observed the vehicle in front of me jam braked thus, I also jam braked and was able to avoid collision with the vehicle in front. I suddenly felt an impact at the rear of my vehicle. When I exited my vehicle I observed a blue Honda, SGV2209D had collided against the rear of my vehicle. There were slight scratches on the Honda's front body panel.

My vehicle rear body panel was badly damaged.

There was no traffic police nor ambulance required at scene. After we drove off, I subsequently felt my body aching and immediately went to Mount Alvernia Hospital to make a check. I received 5 days medical certificate from 13/08/2019 to 17/08/2019.



**SINGAPORE  
POLICE FORCE**



T/20190813/2099

3 of 4

Report No. T/20190813/2099

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

CONTINUATION OF REPORT





**SINGAPORE  
POLICE FORCE**



T/20190813/2099

4 of 4

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

Report No. T/20190813/2099

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 SITI KHAIRUNNISA BINTE RAMANAH

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

13/08/2019 15:21

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

Authentication Stamp

NP188



# CERTIFICATE OF INSURANCE

## AUTOPLUS PRIVATE VEHICLE

**Name of Policyholder** : Soh Boon Ping  
**Period of Insurance** : 09 May 2019 To 08 May 2020  
**Engine No.** : HR160692388  
**Chassis No.** : MNTBBAB17Z0023882

**Vehicle No.** : SLC3021L  
**Policy No.** : 1900080293  
**Endorsement No.** :  
**Issued Date** : 05 Apr 2019

### ABOUT THE COVER

**Make/Model** : NISSAN SYLPHY 1.6 PREMIUM  
**Engine Capacity/Tonnage** : 1,598.00 CC  
**Driver Restriction** : NA  
**Person or Classes of Persons Entitled to Drive\*** :  
**Sum Insured** :  
**Market Value** :  
**Off Peak Car** : No  
**First Year of Registration** : 2016  
**Insuring with COE/PAF** : Yes

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

\* You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

**Age Condition** : All Age Condition

**Limitation as to use\*** :

(Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, peace-making, reliability trial or speed testing, the damage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

\* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 186) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

**Section 1**  
Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

**Section 2**  
Property Damage - \$0

**Windscreen** : \$100

**Named Driver and Excess** (where applicable)

Soh Boon Ping - \$500 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorized Repairers (for claims related repairs)  
Any accident repairs to the vehicle must be carried out by one of our Authorized Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.  
For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 8338 6200. Alternatively, You may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 186), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1988 (Malaysia))

0504389000

OS INSURANCE AGENCY  
18 SHENTON WAY #01-16 AIG BUILDING  
SINGAPORE 079120

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*M. J. J. J.*

AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORIZED REPRESENTATIVE



# Mount Alvernia Hospital Medical Certificate

24-Hour Walk-in Clinic and  
Emergency Department

No. M19000021573

This is to certify that SOH BOON PING, S7737609G, is granted Outpatient Sick Leave for 5 day(s) from 13-Aug-2019 to 17-Aug-2019.

Remark :

This medical certificate is not valid for absence from Court or judicial proceeding unless specifically stated.

Dr. Chandra Prem Khatriani

MCR : 62730E

A&E / 24-HOUR WALK-IN CLINIC

Mount Alvernia Hospital  
820 Thomson Road  
Singapore 574623  
Tel: 63476210

13/08/2019

Date



820 THOMSON ROAD SINGAPORE 574623  
MAIN LINE: 6347 6886 WEBSITE: www.mountalvernia.sg  
GST REGN NO: M4-0003321-B

Patient Name : SOH BOON PING  
ID No. : S7737609G  
Account No. : 0190726664

Receipt No. : 190101286  
Date : 13/08/2019  
Page : 1 of 1

Item	Qty	UCM	Amount (\$)
ANAREX (PARA450/ORPH35)	20	EA	7.00
ARCOXIA TAB 120MG	10	EA	37.80
FASTUM GEL 30G	1	EA	5.60
OUTPATIENT NURSING SERVICE	1	EA	22.00
BMO CONSULTATION FEE	1	EA	37.00
			109.40
Total Charges			7.66
GST @ 7%			117.06
			117.06

Paid:

AMERICAN EXPRESS BY SOH BOON PING  
Mode of Payment : AMERICAN EXPRESS

Reference No. :

This is a computer generated official receipt, no signature is required.

Accident Photo



Accident Photo



Accident Photo



CHASSIS NUMBER



# AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 64528211 FAX: 64517420

## ESTIMATE

SOH BOON PING  
c/o 46 Lentor Plain  
Singapore 786548

Date: 14/08/2019

7 days

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE: NISSAN SYLPHY / SLC 3021 L</b>		
1 pc	rear boot lid 901.20	990.70
2 pcs	rear boot hinge @ 326.40	652.80
2 pcs	rear boot lamp 141.60 o/s car @ 486.20 n/s	972.40
1 pc	rear boot lock catch	197.60
1 pc	rear bumper 623.80	893.90
2 pcs	rear bumper side retainer @ 58.40	116.80
1 pc	rear end panel 464.50	896.00
2 pcs	rear tail lamp housing panel 263.20 @ 376.80	753.60
1 pc	rear spare tyre panel	956.60
2 pcs	rear fender water channel panel @ 286.30	572.60
Sub-total		7,003.00
Less 30%		2,100.90
Sub-total(a)		4,902.10
1 pc	rear boot lower moulding 174.90	388.40
1 pc	rear boot upper moulding 185.70	491.50
1 pc	rear boot emblem logo	73.90
1 pc	rear boot emblem 'SYLPHY'	54.60
1 pc	rear boot emblem 'XTRONIC CVT'	53.30
1 pc	rear boot weatherstrip 101.50	226.40
1 pc	rear boot lock assy 146.20	277.10
1 pc	rear boot lock sensor 198.20	264.80
1 pc	rear boot lid lock switch	341.30
1 pc	rear boot lid inner trim 138.80	314.60
2 pcs	rear bumper reflector 661.90	346.40
1 pc	rear end panel garnish 125.30	286.10
2 pcs	rear tail lamp 504.10	1,085.80
2 pcs	rear tail lamp side clip	12.40
sub-total		4,216.60

LWK Auto Consultants hereby certify the Repairer of the following:

- To ensure bottom of car is properly
- To ensure damaged parts are properly
- Parts prices are subject to change
- Third party survey is not a 'Minimum Required' level
- No illegal modification is allowed
- Supplementary work must be requested and
- It subject to final approval from Insurance Company



	Balance brought forwards.		4,216.60	
2 pcs	rear fender inner trim	nett @ 457.60	<i>Sn</i> 915.20	X
2 pcs	rear fender dust cover	nett @ 196.30	<i>Sn</i> 392.60	X
1 pc	rear exhaust silencer	nett	<i>Sn</i> 1,046.10	X
1 pc	spare tyre top board <i>280</i>	nett	<i>nd</i> 342.00	<i>✓</i>
2 pcs	rear number plate lamp	nett @ 246.30	<i>Sn</i> 492.60	X
		Sub-total	7,405.10	
		Less 10%	740.51	
		Sub-total (b)	6,664.59	
	Sub-total for (a) + (b)	Sub-total	11,566.69	
1 set	reverse sensor	s.nett	<i>nd</i> 220.00	<i>200sn</i>
1 pc	number plate	s.nett	<i>nd</i> 35.00	<i>35sn</i>
1 pc	number plate casing	s.nett	35.00	
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.		1,600.00	<i>900l</i>
	To check wiring system.		60.00	<i>20l</i>
	To apply rust proofing on affected areas.		150.00	<i>60l</i>
	To apply putty & spray painting on affected areas.		1,600.00	<i>1000l</i>
	To install reverse sensors.		80.00	<i>50l</i>
	To remove carpet, trimming and seats to enable repair.		150.00	<i>80l</i>
	To carry out exhaust works.		<i>na</i> 100.00	X
	To apply water proofing sealant on affected areas.		150.00	<i>30l</i>
	To bench pull chassis alignment and realign.		<i>na</i> 300.00	X
	Towing charges.		60.00	<i>50l</i>
		Total	16,106.69	

## ...CLAIM SUBFOLDER...(Pending for Survey Report)










CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Aug 2019		14 Aug 2019 13:43 <a href="#">Edit Adj Rpt</a>	<b>S\$4,900.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by insurer]</span>									
Insured:	<b>TEO HWEE HOON</b> , ID: S74414411								
Main Claimant:	<b>SOH BOON PING</b> , ID: S7737609G								
Vehicle Reg. No.:	<b>SLC3021L</b>	Date of Loss:	13/08/2019 08:00 - :59 [39 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 602613</b>	Policy/Cover Note No.:	29119679 (Comprehensive) Coverage: 20/03/2019 - 24/05/2020						
Vehicle Reg. No. (Insured):	<b>SGV2209D</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Autoworx House - Sin Ming (HQ)</b> 176 SIN MING DRIVE #02-01, 575721 Sin Ming - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Fievel Foo Wenyao</b> - 6643 1316]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 13/09/2019]</b>								
Driver/Custodian (Insured):	TEO HWEE HOON (44 / Female) , NRIC: S74414411 Email:								
Adj Asg. Remarks:	on WP. (Manual Assign) Liab: Dispute(NR). Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: WK Chew @ 6452 8211. Manual assigned via email to LKK on 14/08/2019.								
<b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (03/02/2020): 3rd party survey report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLC3021L (602613)  
[SGV2209D]  
TP  
SOH BOON PING  
Aug 13 2019 8:00AM  
[TEO HWEE HOON]  
Autoworx House - Sin Ming

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	15/08/19 13:59	Adjuster Immediate Advice					Load HTM		
2	15/08/19 14:01	Adjuster Immediate Advice					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
2	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
3	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
4	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
5	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
6	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
7	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
8	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
9	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
10	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
11	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
12	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
13	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
14	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
15	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
16	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
17	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
18	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
19	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
20	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
21	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
22	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
23	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
24	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
25	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
26	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
27	17/02/20 17:03	General View					Load JPG	<input checked="" type="checkbox"/>	
28	17/02/20 17:06	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
29	17/02/20 17:06	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
30	17/02/20 17:06	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
31	17/02/20 17:06	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
32	17/02/20 17:06	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
33	17/02/20 17:06	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	17/02/20 17:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/08/19 10:57	PRI - SELECT LKK	 Load PDF	
2	14/08/19 10:57	OI Accident Report	 Load PDF	
3	14/08/19 10:57	TP SLC3021L E-REPORT	 Load PDF	
4	14/08/19 11:18	Agree on SJE	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	14/08/19 13:41	Survey Request - Manual Assigned	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014124/KTD3E2

Date: 18/02/2020

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29119679

Claimant Vehicle No: SLC3021L

Insured Vehicle No: SGV2209D

Date of Loss: 13/08/2019

Nature of Claim: TP

Claim No: 602613

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLC3021L

Make &amp; Model: NISSAN SYLPHY, 1.6 (A)

Reg. Date: 09/05/2016 (Man. Year: 2016)

Colour: Metallic Black

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: HR16969238B

Chassis No: MNTBBAB17Z0023882

Odometer: 71159 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Firestone 7 mm

Rear Left Side: Firestone 7 mm

Front Right Side: Firestone 7 mm

Rear Right Side: Firestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,856.69	3,958.02	7,898.67	66.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	2,190.00	2,060.00	48.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,106.69</b>	<b>6,148.02</b>	<b>9,958.67</b>	<b>61.83</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>16,106.69</b>	<b>4,900.00</b>	<b>11,206.69</b>	<b>69.58</b>

## INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 14/08/2019 Inspected At:

Autoworx House - Sin Ming (HQ)

176 SIN MING DRIVE #02-01

Singapore 575721

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2020)
<b>Parts:</b>	143	NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC3021L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Bent	990.70 FL	*901.20 FL
2	2	*REAR BOOT HINGE	Repair	652.80 FL	*- FL
3	2	*REAR BOOT LAMP	O/S Cracked/N/S Mtg Distorted	972.40 FL	*141.60 FL
4	1	*REAR BOOT LOCK CATCH	Repair	197.60 FL	*- FL
5	1	*REAR BUMPER	Bent	893.90 FL	*623.80 FL
6	2	*REAR BUMPER SIDE RETAINER	Distorted	116.80 FL	*116.80 FL
7	1	*REAR END PANEL	Bent	896.00 FL	*464.50 FL
8	2	*REAR TAIL LAMP HOUSING PANEL	Bent	753.60 FL	*263.20 FL
9	1	*REAR SPARE TYRE PANEL	Repair	956.60 FL	*- FL
10	2	*REAR FENDER WATER CHANNEL PANEL	Repair	572.60 FL	*- FL
11	1	*REAR BOOT LOWER MOULDING	Dented	388.40 FN	*174.90 FN
12	1	*REAR BOOT UPPER MOULDING	Warped	491.50 FN	*185.70 FN
13	1	*REAR BOOT EMBLEM LOGO	Necessary	73.90 FN	*73.90 FN
14	1	*REAR BOOT EMBLEM SYLPHY	Necessary	54.60 FN	*54.60 FN
15	1	*REAR BOOT EMBLEM XTRONIC CVT	Necessary	53.30 FN	*53.30 FN
16	1	*REAR BOOT WEATHERSTRIP	Dented	226.40 FN	*101.50 FN
17	1	*REAR BOOT LOCK ASSY	Jammed	277.10 FN	*146.20 FN
18	1	*REAR BOOT LOCK SENSOR	Dented	264.80 FN	*198.20 FN
19	1	*REAR BOOT LID LOCK SWITCH	Serviceable	341.30 FN	*- FN
20	1	*REAR BOOT LID INNER TRIM	Distorted	314.60 FN	*138.60 FN
21	2	*REAR BUMPER REFLECTOR	Mtg Cracked	346.40 FN	*123.80 FN
22	1	*REAR END PANEL GARNISH	Distorted	286.10 FN	*125.30 FN
23	2	*REAR TAIL LAMP	Mtg Cracked / Cut	1,085.80 FN	*504.10 FN
24	2	*REAR TAIL LAMP SIDE CLIP	Necessary	12.40 FN	*12.40 FN
25	2	*REAR FENDER INNER TRIM	Serviceable	915.20 FN	*- FN
26	2	*REAR FENDER DUST COVER	Serviceable	392.60 FN	*- FN
27	1	*REAR EXHAUST SILENCER	Repair	1,046.10 FN	*- FN
28	1	*SPARE TYRE TOP BOARD	Dented	342.00 FN	*280.00 FN
29	2	*REAR NUMBER PLATE LAMP	Serviceable	492.60 FN	*- FN
30	1	*SET REVERSE SENSOR	Dented	220.00 FS	*200.00 FS
31	1	*NUMBER PLATE }	Dented	35.00 FS	*45.00 FS
32	1	*NUMBER PLATE CASING }		35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,698.10</b>	<b>4,928.60</b>
- List Item Discount on L Items 30.00/30.00% (\$\$)	2,100.90	753.33
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	740.51	217.25
<b>Total Parts (\$\$)</b>	<b>11,856.69</b>	<b>3,958.02</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE, PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,600.00	900.00
2	TO CHECK WIRING SYSTEM	New	60.00	20.00
3	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	150.00	60.00
4	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,000.00
5	TO INSTALL REVERSE SENSORS	New	80.00	50.00
6	TO REMOVE CARPET, TRIMMING AND SEATS TO ENABLE REPAIR	New	150.00	80.00
7	TO CARRY OUT EXHAUST WORKS	New	100.00	0.00
8	TO APPLY WATER PROOFING SEALANT ON AFFECTED AREAS	New	150.00	30.00
9	TO BENCH PULL CHASSIS ALIGNMENT AND REALIGN	New	300.00	0.00
10	TOWING CHARGES	New	60.00	50.00
Gross Labour Cost (S\$)			<b>4,250.00</b>	<b>2,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >