

22/03/2012

ASS. REC. BY:

REF: CS/PC1 K904142/US f3n2 Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Joannay of PC1 Date/Time: 14.8.19 4.28p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD TP WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKE 51554 Insured: SH 9107Aat Workshop m/s Fastech Tel: 67465405of 1 Kallai Bukit Ave 6 #01-46Policy No: \_\_\_\_\_ Claim No: D19605214 MFS4

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 12.8.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 14.8.19 4.32p.m Person Contacted: Nancy Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKE 51554 - CS/AXA 1601842m/ bgh3c2</u> <u>POA - 04/10/2016</u>
	<u>SH 9107A - X</u>

(08/11/13) wef  
ASS. REC. BY: Marcus

REF: Tei

**ASSIGNMENT**

From: f Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SKF SLEF  
at Workshop m/s: Al.  
of: SH/9107A  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SKF SLEF Yr Regn: 3 12  
Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA  
Make: Volkswagen Golf Cabriolet 1390  
Colour: White A/C: Insured / Std / NI / NA  
Sp. Reading: 113453 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WVWZZZ1KZCK024169  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: 225/40ZR18  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: 6 mm Rear: 6 mm  
R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm  
L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm  
D.O.A. 12/8/19 D.O.I. 14/8/19  
Survey held at \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 44k.  
IDAC Accident Rpt: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: 4 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Date / Time Action / Instruction net 8489  
LYA 35511 2yrs. 6m. ap 1/k.  
16/9/19 2/5 = 4020 confid with Al.  
( \$ 7,685.00 red 66% )

RECEIVED 17 SEP 2019

Date/Time, File Pass to? 17/09/19  
1) Typist  
Date/Time, File Return to? \_\_\_\_\_  
2) \_\_\_\_\_

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 4  
Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
Photos \_\_\_\_\_  
Others \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Report Format :  
Lump Sum / I.B.I. (\$ 4,000/- 45)

170+15
50
50
70
355

TOTAL

**MOTOR SURVEY ASSIGNMENT**

Date	13-08-2019	Our Ref No. D19005214MFSH
Accident Date	12-08-2019	Claim Type. Third Party
Insured Vehicle	SH9107A	Third Party Vehicle. SKE5155Y
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 15 August 2019 5:11 PM  
**To:** 'Joanne Yong'; 'CWS Motor Claims'  
**Cc:** assignments; SUR; Admin-D (LKKAuto)  
**Subject:** RE: SURVEY ASSESSMENT - D19005214MFSH/1

Dear Joanne,

Please be informed that we have inspected the vehicle SKE 5155Y on 13/08/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Wednesday, 14 August 2019 4:32 PM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D19005214MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Wednesday, 14 August 2019 4:28 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong <Joanneyong@msfirstcapital.com.sg>  
**Subject:** PRI: SURVEY ASSESSMENT - D19005214MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

① X

volkswagen golf cabriolet

Price Range

Depreciation

2012

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Faster Auto Trading » Volkswagen Golf Cabriolet 1.4A TSI

## Volkswagen Golf Cabriolet 1.4A TSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



<b>Price</b>	\$46,800		
<b>Depreciation</b>	\$11,590 /yr <a href="#">View models with similar depre</a>	<b>Reg Date</b>	24-Feb-2012 (2yrs 6mths 10days COE left)
<b>Mileage</b>	80,000 km (10.7k /yr)	<b>Manufactured</b>	2011
<b>Road Tax</b>	\$620 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b>	\$35,107 as of today ( <a href="#">change</a> )	<b>OMV</b>	\$34,860
<b>COE</b>	\$55,997	<b>ARF</b>	\$34,860
<b>Engine Cap</b>	1,390 cc	<b>Power</b>	118.0 kW (158 bhp)
<b>Curb Weight</b>	1,503 kg	<b>No. of Owners</b>	1
<b>Type of Vehicle</b>	Sports Car		

## Features

Powerful And Responsive 1.4L TSI Twincharged Engine, 7 Speed DSG, ABS, 6 SRS Airbags, Factory Audio System, Navigation, Auto Climate Aircon. View specs of the Volkswagen Golf GTI (2003-2009)

## Accessories

17" Alloy Rims, Grey Leather Upholstery, Soft Top Convertible Roof, Retractable Side Mirrors, All Round Parking Sensors, Knockdown Rear Seats.

## Description

1 Owner, Full Serviced Histories, 100% Loan And Balloon Scheme Available, 1 Year Unlimited Mileage Warranty, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.

## Category

PARF Car

## Status

Available

## Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Compare


Car Valuation - Free



Location Map

## Price Chart

## Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

## Seller Information

## Company

Faster Auto Trading

\* dealer's pricelist

\* 61 vehs sold | 57 vehs available

## Address

511 Guillemard Road #02-17A

Search cars nearby this location

## Location

Grandlink Square

## Office No

64761970

volkswagen golf cabriolet

Price Range

Depreciation

2012

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Cars 88 Pte Ltd » Volkswagen Golf Cabriolet 1.4A TSI

## Volkswagen Golf Cabriolet 1.4A TSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

**Price** \$46,500**Depreciation** \$11,070 /yr  
[View models with similar depre](#)**Reg Date** 22-Mar-2012  
(2yrs 7mths 8days COE left)**Mileage** 112,000 km (15.1k /yr)**Manufactured** 2012**Road Tax** \$620 /yr**Transmission** Auto**Dereg Value** \$35,781 as of today ([change](#))**OMV** \$35,318**COE** \$55,997**ARF** \$35,318**Engine Cap** 1,390 cc**Power** 118.0 kW (158 bhp)**Curb Weight** 1,503 kg**No. of Owners** 3**Type of Vehicle** Sports Car**Features**

Powerful Yet Fuel Efficient 1.4L TSI Twin Charged Engine Paired To Volkswagen's Award Winning DSG 7 Speed Auto Transmission With Paddle Shifters! View specs of the Volkswagen Golf GTI (2003-2009)

**Accessories**

Sport Rims, Knockdown Rear Seats, Fog Lamps, Paddle Shift, Factory Built In GPS/DVD, Multi-Function Steering Wheel, Bluetooth, Navigation.

**Description**

Purchase From An Award Winning Dealership! Beautiful Matte Pearl White, Lady Driver! Head Turner Cabriolet Drive In Style! Fully Stock Unit, Beautiful Unit With Best Condition In The Market. Well Taken Care Of And Maintained, Always Shelter Parked, Non-Smoking, Accident Free. Call Us Now For An Non-Obligatory Viewing! Strictly By Appointment Only.

**Category**

PARF Car, Premium-Ad Car

**Status**

Available

**Resources**


Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)

Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

**Seller Information****Company**

Cars 88 Pte Ltd



• dealer's pricelist

• 55 vehs sold | 49 vehs available

**Address**

210 Turf Club Road Lot B20

[Search cars nearby this location](#)**Location**

Car Mall @ The Grandstand

**Contact Person(s)**

Barry

82828788

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 279Z

### Vehicle Details

Vehicle No.: SKE5155Y

Vehicle to be Exported: No

Intended Deregistration Date: 15 Aug 2019

Vehicle Make: VOLKSWAGEN

Vehicle Model: GOLF CABRIOLET 1.4 TSI AT 5172Q5

Primary Colour: White

Manufacturing Year: 2011

Engine No.: CAV380162

Chassis No.: WVVZZZ1KZCK024169

Maximum Power Output: 118.0 kW (158 bhp)

Open Market Value: \$34,860.00

Original Registration Date: 09 Mar 2012

First Registration Date: 09 Mar 2012

Transfer Count: 0

Actual ARF Paid: \$34,860.00 17432

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 08 Mar 2022

PARF Rebate Amount: \$20,916.00

### Intended COE Rebate Details

COE Expiry Date: 08 Mar 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$57,009.00

COE Rebate Amount: \$14,595.00

**Total Rebate Amount: \$35,511.00**

The information contained herein is correct as at 13 Aug 2019

OK



Date of Accident : 12/8/19 Accident Time: 9.15pm (24-HR-Format)  
Accident Place : Along PIE towards city  
Vehicle No. (Car Plate No.) : SKF5155Y Make/Model: Volkswagen  
Insurance Company : Direct Policy No: MT/0040137  
Owner or Company Name /IC No. : Wong Chey Way 879702792  
Owner or Company Contact No. : \_\_\_\_\_ Owner's Hp 97418071 Company Tel \_\_\_\_\_  
DRIVER'S Name / IC No. : as above  
DRIVER'S Date Of Birth : 29/11/1979 DRIVER'S License Pass Date 18/5/2004  
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner  
DRIVER'S Address : BLK 757 Pagar Ris st 71 #07-160  
DRIVER'S Contact No./ Alt No. : 1) \_\_\_\_\_ 2) 5510757  
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
Email Address : \_\_\_\_\_  
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
Number of Passengers (Including Driver): 3 person  
Was there any video Captured by car camera: YES \ NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle No: <u>SH 9107A (1st car)</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

**\* NEW - Passenger's name & gender:**

NG SEOK QUEEN - FEMALE

WONG CHEUK KEONG - MALE


## SKETCH PLAN


### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN****DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

on the stated date and time I was driving my vehicle A  
along PIE towards city. Suddenly vehicle B hit on my  
rear portion.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.


  
Policyholder's Signature

Date & Time:

  
Driver's Signature

(If driver is not the policyholder)

Date & Time:

  
Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7970279Z



WONG CHENG WAY

黄振威

CHINESE

29-11-1979 M

MALAYSIA

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S7970279Z

WONG CHENG WAY

Birth Date: 29 Nov 1979

Issue Date: 22 Aug 2017



2030105

NRIC No: S7970279Z



Valid Until: 30-12-1996

APT BLK 757 PASIR RIS STREET 71 #07-160  
SINGAPORE 510757

NRIC No: S7970279Z


Date: 28-02-2005 (R) No: 5145051

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

EFFECTIVE DATE

Class 3 Motor cars with unladen weight  $\leq 3000\text{kg}$  with  $\leq 7$  passengers, exclusive of driver; and other motor vehicles with unladen weight  $\leq 2500\text{kg}$  18 May 2004

NP 428A



FASTECH AUTO PTE LTD  
BLK 1 KAKI BUKIT AVE 6  
#01-46/48/50 AUTOBAY  
SINGAPORE 417883

not Adhoral  
Mark  
4/s \$ 4000  
Hdy.

VEHICLE No.SKE 5155Y

1PC	REAR BUMPER	1421.30
1PC	REAR BUMPER LOWER GARNISH	
2PCS	REAR BUMPER REFLECTORS @\$105.00	
2PCS	REAR BUMPER SIDE RETAINERS @\$66.00	
1PC	REAR BUMPER REINFORCEMENT	476.52
1SET	REAR BUMPER CLIPS	
1PCS	REAR BUMPER PDC SENSORS	
1PC	REAR BUMPER LAMP	
2PCS	TAILLAMPS @\$615.00	
1PC	REAR END PANEL	
1PC	REAR END PANEL TOP GARNISH	
1PC	BOOTLID	
1PC	BOOTLID INNER LOCK	
1PC	BOOTLID WEATHERSTRIP	
1PC	REAR LICENCE PLATE W/HOLDER	
1PC	REAR END PANEL SEALANT	

200/20	\$1,455.10	—
200/20	\$366.50	—
11	\$210.00	X
11	\$132.00	X
11	\$695.00	—
11	\$50.00	—
11	\$980.00	2005.~ 1 set
11	\$120.00	X
11	\$1,230.00	X
11	\$989.00	—
11	\$295.00	X
11	\$1,485.00	X
11	\$365.00	X
11	\$311.00	X
11	\$50.00	405.~
11	\$50.00	—
	\$8,765.60	
	8783.60	

TO CHECK WIRING  
TO DISMANTLE & REPLACING PDC SENSOR  
TO DISMANTLE & REFIX CUSHION UPHOLSTERY  
TO SPRAY PROOFING  
TO TRANSFER BOOTLID MECHANISM  
LABOUR FOR PANEL BEATING & REPALCING PARTS  
TO PUTTY & SPRAY PAINTING

	\$80.00	20
	\$80.00	50
	\$120.00	100
	\$80.00	50
11	\$80.00	X
	\$980.00	600
	\$1,500.00	800
TOTAL	\$11,685	
	11703.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:


3353.32  
52  
- 5045.65

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19014142/Usf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-09-2019		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 9107A	Veh. Inspected	SKE 5155Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005214MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	14/08/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN GOLF CABRIOLET (A)	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WVWZZZ1KZCK024169	Colour	WHITE	
Odometer	113453	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 ZR18	PIRELLI	6 mm	
L/H Front Tyre	225/40 ZR18	PIRELLI	6 mm	
R/H Rear Tyre	225/40 ZR18	PIRELLI	6 mm	
L/H Rear Tyre	225/40 ZR18	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/08/2019	Inspection Date	14/08/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 5155Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DENTED / DEFORMED	1,455.10	1,421.30
1	REAR BUMPER LOWER GARNISH	DEFORMED / TORN	366.50	366.50
2	REAR BUMPER REFLECTORS @\$105.00	NOT NECESSARY	210.00	-
2	REAR BUMPER SIDE RETAINERS @\$66.00	NOT NECESSARY	132.00	-
1	REAR BUMPER REINFORCEMENT	BENT	695.00	476.52
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER LAMP	NOT NECESSARY	120.00	-
2	TAILLAMPS @\$615.00	NOT NECESSARY	1,230.00	-
1	REAR END PANEL	DENTED / BENT	989.00	989.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	295.00	-
1	BOOTLID	TO REPAIR SEE LABOUR	1,485.00	-
1	BOOTLID INNER LOCK	NOT NECESSARY	365.00	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	311.00	-
1	REAR END PANEL SEALANT	NECESSARY	50.00	50.00
	LESS 5% DISCOUNT		-	-167.67
			7,753.60	3,185.65
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER PDC SENSORS (SN)	SHORTED	980.00	200.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
			1,030.00	240.00
<b>LABOUR</b>				
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REPLACING PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	100.00
	TO SPRAY PROOFING.		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID.		980.00	600.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			2,920.00	1,620.00
	<b>GRAND TOTAL</b>		<b>11,703.60</b>	<b>5,045.65</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,000.00</b>

Report Ref No. CS/FCI19014142/Usf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.