SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies,
- 5. Any false reporting may be referred to the Police for investigation,
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties

	ACCIDENT STATEMENT
Date Of Report	08/08/2019 17:10
Date Of Accident	08/08/2019 01:50
Exact Location Of Accident	NORTH BRIDGE ROAD // BRAS BASAH ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC6643U
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	

Vehicle Particulars

KIA Manufacturer

OPTIMA-1.7 D (A) Model

Exact Purpose for which vehicle was being used at

time of accident

HIRED & REWARDS

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage THIRD PARTY

Fleet Policy YES

Policy Number 5107202885

Cover Note Number

Driver

Name of Driver MOK HOCK SENG

NRIC No S1710089J Date Of Birth 01/05/1965 Occupation OUTDOOR Date Of Driving Pass 15/06/1993

Driving Experience 26 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-83020918

Fax Number

Contact Number

EMail Address NOEMAIL

BLK 23 #20-153 Address

TEBAN GARDENS ROAD

Postcode 600023

Was driver an employee of the Insured's Company NO

OTHER - RELIEF If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

NO

NO

NO

YES Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

BOTH VEHICLES - NO PAX

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

YES

NO

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA4719J

Vehicle Make/Model/Colour COMFORT TAXI

Details Of Properties VEH. B Vehicle Category TAXI

Name of Driver SYED IBRAHIM B S HAMID

NRIC/Passport Number S1400733D

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MOK HOCK SENG

Page 2 of 16

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SEEKING FOR MEDICAL

SHC6643U

YES

NO

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

0 5 AUG 2019

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature


Date & Time:

Driver's Signature (If driver is not the policyholder)

R 1710189/1

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:



(If driver is not the policyholder)

Date & Time:

Name:

NRIC/FIN No.:

Date & Time:

Page 5 of 16

Describe Circumstance of the Accident.

ON 08/08/2019 @ 0150HRS, I WAS DRIVING MY TAXI (SHC 6643 U) - TRAVELLING ALONG NORTH BRIDGE ROAD INTO THE TRAFFIC JUNCTION OF BRAS BASAH ROAD IN LANE 3 (ARROW ON ROAD SURFACE SHOWS STRAIGHT AHEAD & LEFT TURN).

AS I WAS MOVING AHEAD - WITH MY LEFT INDICATOR, TO TURN LEFT & WITHIN MY LANE, SUDDENLY I FELT AN IMPACT FROM MY LEFT.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE B (SHA 4719 J - COMFORT TAXI) WHICH WAS INITIALLY FROM LANE 4, HAD COLLIDED ONTO THE LEFT REAR OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE LEFT REAR PORTION AND VEHICLE B HAD DAMAGES ON THE FRONT RIGHT PORTION.

AS A RESULT, I FELT SOME DISCOMFORT & WILL SEEK FOR MEDICAL TREATMENT. NO AMBULANCE AT SCENE.

NO PASSENGERS ONBOARD BOTH VEHICLES.

*VIDEO FOOTAGE CAPTURED

