

ASS. REC. BY:

REF: CS/PCJ 19014168/KLSF3

Special Instruction:

Surveyor: Calvin

ASSIGNMENT (Office)

From (Person): Serene

of

FCI

Date/Time: 14.8.19 6.02p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6643 V

Insured:

SHA 4719J

at Workshop m/s Premier Automotive

Tel:

62148880

of 23 Changi South Ave 2 # 0302

Policy No:

Claim No:

D19005203MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 15.8.19 8.42am

Person Contacted:

Vincent Chua

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 6643V - 1A/TP 12003753/e1

P.O.A - 21/02/2012

SHA 4719J - CC3/ LCR 17010053/41W4342

D.O.A - 21/08/2017

15/08/19 @ 17:27 pm revised PA to cover for vic email.

(08/11/13)

REF:

Surveyor: Kalvin

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 66434 Yr Regn: 27 Feb 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1685Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 458809 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNABM414AF55 78377

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD AR Rim orTyre Size: F: 205/65R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 8/8/19 D.O.I. 15/8/19Survey held at PRAC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rear.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
19/8/19	Check PIP \$380 / 20% ( \$1,421.20 Red - 79% )

RECEIVED 19 AUG 2019

Date/Time, File Pass to?

19/08/19

1) Typ. 5

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

100

50

50

20

220

Report Format :

Lump Sum / I.B. (\$) 380/- PIP



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005203MFSH

Date: 15 August 2019

Our Ref: CS/FCI19014168/K1sf3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6643U .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/08/2019 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,801.20</u> .
Revised Estimate Amount	: S\$ <u>380.00</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

**Description of Damage:**

The vehicle sustained damages at the n/s rear portion.



**Comments/ Present Status:**

Damages Consistent.  
Repair days: 2 Days

Yours faithfully,  
Kalvin Ang  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	13-08-2019	<b>Our Ref No.</b> D19005203MFSH
<b>Accident Date</b>	07-08-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA4719J	<b>Third Party Vehicle.</b> SHC6643U
<b>Survey Location</b>	23 CHANGI SOUTH AVENUE 2 #03-02	
<b>Contact Person.</b>	VINCENT CHUA	
<b>Contact No.</b>	62148880/ 0	<b>Fax No.</b> 62141511
<b>Survey Type</b>	WITHOUT PREJUDICE: NO EST. COR - WE ADMIT LIABILITY QUANTUM TO BE AGREED	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 15 August 2019 5:27 PM  
**To:** 'Serene Ler'; 'CWS Motor Claims'  
**Cc:** SUR; assignments  
**Subject:** RE: SURVEY ASSESSMENT - D19005203MFSH/1  
**Attachments:** SHC 6643U - Preli Advise.pdf

Dear Serene,

Enclosed preliminary revised of vehicle SHC 6643U.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Thursday, 15 August 2019 5:23 PM  
**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Subject:** FW: SURVEY ASSESSMENT - D19005203MFSH/1

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Wednesday, 14 August 2019 6:02 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>  
**Subject:** PRI: SURVEY ASSESSMENT - D19005203MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

Text size +

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	27 Feb 2015 / 08:58:42	Receipt No.:	AACCK001-AX239-150227-000002
Asset Type:	Vehicle	Transaction Amount:	\$66,712.00
Asset ID:	SHC6643U	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150227085842110214		

Vehicle No.:	SHC6643U
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	27 Feb 2015
Original Registration Date:	27 Feb 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5578377
Engine No.:	D4FDEH313330
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$20,834.00
Minimum PARF Benefit:	\$8,200.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	27 Feb 2015 08:58:42
COE No.:	2015022701001611N
COE Expiry Date:	26 Feb 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$52,904.00
Lifespan Expiry Date:	26 Feb 2023








## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19014168/K1sf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-08-2019	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 4719J	Veh. Inspected	SHC 6643U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005203MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	14/08/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5578377	Colour	SILVER	
Odometer	458809	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/08/2019	Inspection Date	15/08/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6643U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	TO REPAIR SEE LABOUR	206.00	-
1	REAR BUMPER N/S REFLECTOR	SERVICEABLE	46.00	-
	LESS 10% DISCOUNT		-94.80	-
			853.20	-
<b>SPECIAL NETT ITEMS</b>				
1	REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	REAR BUMPER TOP PROTECTOR (SN)	NOT NECESSARY	80.00	-
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			178.00	-
<b>LABOUR</b>				
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE REAR BUMPER.INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER COVER.		450.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER.		200.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			770.00	380.00
<b>GRAND TOTAL</b>			<b>1,801.20</b>	<b>380.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>380.00</b>

Report Ref No. CS/FCI19014168/K1sf3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.