



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte.Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 14/08/2019

User ID : GohKK2

### Section A - Accident Details

Registration Number	SMB235A
Case Reference Number	BUS/08/19/7004
Registration Date	21/2/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Dickie Goh Thien Hock
Type of Accident	Side Swipe
Accident Date and Time	3/8/2019 2:19 PM
Accident Reported Date and Time	5/8/2019 11:14 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB235A-LEFT REAR PORTION SMF8296A ( TP ) INSURED WITH AIG
Prepared Date and Time	14/8/2019 10:38 AM
Chassis Number	WMAA22222C7001242
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$2,441.16	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$4,117.16</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$4,100.00</b>	<b>\$0.00</b>
Number of Repair Days	3.0	2
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	14/08/2019 10:47 AM	
Signature		
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/08/2019

User ID : GohKK2

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$1,060.00	795
Total Labour	\$1,060.00	

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	528
Total Spray Painting & Panel Beating	\$616.00	

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010299	VE	88-25320-6008	LAMP,INDICATOR:LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace X	
6010298	VE	88-25225-6039	LAMP,STOP:LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace /	
6010060	Body	F01001-CW271	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace -RP	
6010005	BODY LH	A01001-CW561	PANEL,SIDE:L11,FOR MAN A22 BUS	1.00	\$1,092.50	100.00	\$0.00	Repair X R	
Total					\$4,483.00		\$3,051.45		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Steve  
8322 8813

LM AL AM 14/8/19, 2:30 pm  
2 dy  
L/S  
Ry AL dy

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: