



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/09/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB235A
Case Reference Number	BUS/08/19/7004
Registration Date	21/2/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Dickie Goh Thien Hock
Type of Accident	Side Swipe
Accident Date and Time	3/8/2019 2:19 PM
Accident Reported Date and Time	5/8/2019 11:14 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102828
Special Instruction to ARC, if any	SMB235A-LEFT REAR PORTION SMF8296A (TP) INSURED WITH AIG
Prepared Date and Time	14/8/2019 10:38 AM
Chassis Number	WMAA22ZZ2C7001242
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$795.00
Total Spray Cost	\$616.00	\$528.00
Total Spare Part Cost	\$2,441.16	\$1,523.81
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,117.16	\$2,846.81
Lump Sum Total	\$4,100.00	\$2,850.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Kok Khoo Goh	STEVE CHEN
ARC / Surveyor Sign Off Date	14/08/2019 10:47 AM	14/08/2019 3:42 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/09/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	\$795.00
Total Labour	\$1,060.00	\$795.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	\$528.00
Total Spray Painting & Panel Beating	\$616.00	\$528.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010299	VE	88-25320-6008	LAMP,INDICATOR,LED (MAN BUS)	0.00	\$1,274.10	0.00	\$0.00	Replace	Not Given
6010298	VE	88-25225-6039	LAMP,STOP,LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	Replace
6010060	Body	F01001-CW271	COVER,REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010005	BODY LH	A01001-CW561	PANEL,SIDE,L11,FOR MAN A22 BUS	1.00	\$1,092.50	100.00	\$0.00	Repair	Repair
Total					\$4,483.00		\$1,904.76		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1904.76
- 20% Surplus
1523.80
795
528
4/5 - 2846.80
= 2850



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
00 Woodlands Industrial Park E4, Singapore 757705	
FAX Number	63085582
Estimator Telephone Number	68652623
Accident Reporting Number	68652672

Date Generated : 14/08/2019

User ID : GohKK2

Section A - Accident Details	
Registration Number	SMB235A
Case Reference Number	BUS/08/19/7004
Registration Date	21/2/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F (A22)
Name of Driver	Dickus Goh Then Hock
Type of Accident	Side Sweep
Accident Date and Time	3/8/2019 2 19 PM
Accident Reported Date and Time	5/8/2019 11 14 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special instruction to ARC, if any	SMB235A-LEFT REAR PORTION SMF8296A (TP) INSURED WITH AIG
Prepared Date and Time	14/8/2019 10 38 AM
Chassis Number	WMAA222ZC7001242
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,050.00	\$0.00
Total Spray Cost	\$615.00	\$0.00
Total Spare Part Cost	\$2,441.15	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,117.15	\$0.00
Lump Sum Total	\$4,100.00	\$0.00
Number of Repair Days	3.0	2
Prepared / Adjusted By	Koh Khoo Goh	
ARC / Surveyor Sign Off Date	14/08/2019 10:47 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63885582
Estimator Telephone Number 68852623
Accident Reporting Number 68852672

Date Generated : 14/08/2019

User ID : GohKK2

Part 1 - Labour Works									
Job Scope		Estimated Item / A/E		Estimated by Surveyor, if applicable					
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS		\$1,000.00		795					
Total Labour		\$1,000.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Estimated Item / A/E		Estimated by Surveyor, if applicable					
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$616.00		526					
Total Spray Painting & Panel Beating		\$616.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expenses									
Job Scope		Estimated Item / A/E		Estimated by Surveyor, if applicable					
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Quantity / Approved	Surveyor's Approval
9010299	VE	88-25320-6006	LAMP INDICATOR LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace X	
9010298	VE	88-25225-6036	LAMP STOP LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace /	
9010080	Body	F01001-CW271	COVER REAR TAIL LAMP LH FOR MAN A22 BUS	1.00	\$874.70	10.00	\$877.23	Replace -	
9010005	BODY LH	A01001-CW561	PANEL SIDE L11 FOR MAN A22 BUS	1.00	\$1,062.50	100.00	\$0.00	Repair X	
Total					\$4,483.00		\$3,061.46		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Stole
8322 8813

LAL AM
2 kg

L/S

Ry AL My

14/8/19, 2:30 pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: