

ASS. REC. BY:

REF: CS/CT1 19014219/UA83N2

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Chong Bin Sen of CT1

Date/Time: 23.9.19 17.19 p.m

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 5826X

Insured: PC 794L

at Workshop m/s Zoom Autoworks
of 130 Bedok Reservoir Road

Tel: 94507920

Policy No: DM BLSN17462118011

Claim No: SNM 1912203K 32102

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 21.7.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 24.9.19 10.000.m

Person Contacted:

Elin Cai

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction
	(✓) Estimate inspection: BIK 15 Kati Bukit Road 4, Banting h2 Centre #01-53
	PC 5826X - CCB/CT1 19014219/AL93 DOA - 21/07/2019
	PC 794L - CCB/CT1 19014219/AL93 DOA - 21/07/2019

REF: C71

ASS. REC. BY:

ASSIGNMENT

From:

Date:

24.9.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

PC 5826X

at Workshop m/s

Zoom Auto works

of

Blk 15 Kaki Bukit Road 4 #01-53

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

PC5826X

Yr Regn:

5-17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Zygo 6199

C.C

2982

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

149396

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KDH 201 0187593

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

6

mm

Rear

6

mm

R/Bal.

R/Bal.

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/7/19

D.O.I.

24/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time

Action / Instruction

26/9/19 9/24 2141.15 car found with E.I.1. (Rear to S613.77, 77.1.)

RECEIVED 27 SEP 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 27/9 2141.15

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos:

Others:

220

TOTAL

Rep. Form:

MER-TO

Lump Sum / TP. to:

2141.15

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2019		23 Sep 2019 17:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant:		ANDERCO PTE. LTD., Co. Reg. No.: 199400384G							
Vehicle Reg. No.:		PC5826X	Date of Loss:	21/07/2019 16:00 - :59					
Claim Type:		TP / SNM19D203432C02	Policy/Cover Note No.:	DMB1SN17467118011					
Vehicle Reg. No. (Insured):		PC794L	Policy No. (Claimant):	GA351567					
		Excess:	S\$0.00						
Repairer:		Zoom Autowerks Pte Ltd (HQ) 130 Bedok Reservoir Road, Eunos Spring, #08-1339, 470130 Bedok - Tel: 94507920							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]							
Claimant's Insurer:		AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/10/2019]							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 23 September, 2019 5:16 PM
To: Zoom Autowerks
Cc: assignments
Subject: RE: OUR REF: SNM19D203432-PC794L-CBS - Pre-Repair Inspection for PC 5826 X // Accident on 21/07/2019 @ 16:10HR at along Junction of Tuas Road & Pioneer Road involving Vehicle Number PC 5826 X & PC 794 L

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Please merimen.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]

Sent: Monday, September 23, 2019 3:34 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D203432-PC794L-CBS - Pre-Repair Inspection for PC 5826 X // Accident on 21/07/2019 @ 16:10HR at along Junction of Tuas Road & Pioneer Road involving Vehicle Number PC 5826 X & PC 794 L

Dear All,

Kindly arrange LKK Marcus Chua..

On Mon, Sep 23, 2019, 15:04 Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice

Dear Sir,

LKK

STA

LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, September 23, 2019 3:02 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; zoomautowerks@gmail.com

Subject: OUR REF: SNM19D203432-PC794L-CBS - Pre-Repair Inspection for PC 5826 X // Accident on 21/07/2019 @ 16:10HR at along Junction of Tuas Road & Pioneer Road involving Vehicle Number PC 5826 X & PC 794 L

Dear Boon Sen,

Please conduct PRS for PC5826X.

Note officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

Sent: Monday, 23 September, 2019 11:52 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Pre-Repair Inspection for PC 5826 X // Accident on 21/07/2019 @ 16:10HR at along Junction of Tuas Road & Pioneer Road involving Vehicle Number PC 5826 X & PC 794 L

Dear Sir/Madam,

We are instructed by Anderco Pte Ltd to notify you of a road traffic accident on 21/07/2019 at about 16:10HR at along Junction of Tuas Road & Pioneer Road involving our client's vehicle registration number PC 5826 X and vehicle registration number PC 794 L driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 417808.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

09450 7920

zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	384G
Vehicle Details	
Vehicle No.:	PC5826X
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 3.0 DX A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1KD2573338
Chassis No.:	KDH2010187593
Maximum Power Output:	-
Open Market Value:	\$36,014.00
Original Registration Date:	22 May 2017
First Registration Date:	22 May 2017
Transfer Count:	0
Actual ARF Paid:	\$1,801.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,906.00
COE Rebate Amount:	\$35,134.00
Total Rebate Amount:	\$35,134.00

The information contained herein is correct as at 25 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/07/2019 13:49
Date Of Accident	21/07/2019 16:10
Exact Location Of Accident	JUNCTION OF TUAS RD & PIONEER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC5826X
Insured/Policyholder	
Name Of Registered Owner	ANDERCO PTE. LTD.
Co Reg No	199400384G
Email Address	ANDREW@ANDERCO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-68620049

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA351567
Cover Note Number	

Driver

Name of Driver	THIYAGARAJAN VAITHIYANATHAN
NRIC No	G7583768U
Date Of Birth	20/04/1981
Occupation	OUTDOOR
Date Of Driving Pass	16/10/2006
Driving Experience	12 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96405500
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NIL
Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : SAKTHIDEL
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

ON 21/07/2019 AT ABOUT 1610 HRS. WHILE MY VEHICLE STATIONARY AT TUAS RD WAITING FOR TRAFFIC LIGHT TURNING TO PIONEER RD. SUDDENLY I FEEL AN IMPACT FROM MY REAR. I NOTICED THAT REAR OF MY VEHICLE HAD COLLIDED BY VEHICLE B. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC794L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category BUS

Name of Driver LI CHANGGUI

NRIC/Passport Number G8131072L

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to circumstances

☐ Claim own policy
☐ Claim third party
☒ Claim OD / ~~TP~~ at other works hop _____
☐ For record purpose

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

☐ Claim own policy
☐ Claim third party
☒ Claim OD / TP at other works hop
☐ For record purpose

Policy No. GA351567

Insurer ATA Veh. No. PC 5826X

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring
#08-1339 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

Car Number: PC5826X
Model: Toyota Hiace

Date: 23/09/2019

Not Allowed
Lian
P/P 2141.15
24/9/19
4dy.

Damaged Area: (Rear RH Side Portion Damaged)

Repairer Estimation Cost of Repair :
Supplementary may be included during the cost of repair :

Parts / Material :

- 1 Rear RH Side Panel
- 2 Rear RH Side Glass Inner Seal
- 3 Rear Tailgate Panel
- 4 Rear Tailgate Glass Inner Seal
- 5 Rear Bumper
- 6 Rear Bumper Bracket
- 7 Rear Bumper Clips
- 8 Rear RH Taillamp 388.20
- 9 Rear RH Taillamp Inner Panel
- 10 Rear RH Taillamps Clips
- 11 Rear RH Side Lower Panel Garnish

Quantity			
2	\$	1,110.80	X
11	\$	295.00	X
2	\$	1,929.73	X
11	\$	145.00	X
11	\$	625.70	X
11	\$	148.70	X
\$6.00 X 10pcs	11	\$	60.00
510	\$	565.30	X
11	\$	465.40	X
11	\$	12.00	X
2	\$	195.60	X
Parts :	\$	5,553.23	
Less Parts 25% :	\$	1,388.30	
Total Parts :	\$	4,164.92	

Special Net Items :

- Rear Tailgate Advertisement Sticker 1set
- Rear Tailgate Advertisement Sticker Wordings 1set
- Rear Tailgate Glass Sealant
- Tailgate Sticker 70km/h
- Rear RH Side Panel Advertisement Sticker 1set
- Rear RH Side Panel Advertisement Sticker Wordings 1set

11	\$	250.00	✓
11	\$	220.00	150
11	\$	150.00	X
11	\$	50.00	10
11	\$	250.00	✓
11	\$	220.00	✓
Total S/N Parts :	\$	1,140.00	

Labour :

- To Remove & Renew RH Side Affected Accident Areas
- To Putty, Spray Paint on LH Side Affected Accident Areas
- To Check & Re-Connect all electrical wiring
- To Remove & Install Rear Tailgate Glass to Assist Repairs
- To Remove & Install Rear RH Side Glass
- To Rust Proof Affected Areas

\$	1,100.00	450
\$	900.00	500
\$	50.00	20
\$ 11	150.00	X
\$ 11	150.00	X
\$ 11	100.00	X
Total Labour :	\$	2,450.00

TOTAL PARTS :	\$	4,164.92
TOTAL SPECIAL NET ITEM :	\$	1,140.00
TOTAL LABOUR :	\$	2,450.00
TOTAL REPAIR COST :	\$	7,754.92

P-388.20
252
P-291.15
S-N-880.00
L-970.00
2141.15

DATE OF SURVEY / INSPECTED:
RECOMMENDED PART BY PART / LUMP SUM :
RECOMMENDED NUMBER OF DAYS :
SURVEY BY / SURVEYOR FIRM :
RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
FINALISED AMOUNT :

LKK Auto Consultants hereby notify the Repairer of the following:

- The repairer shall be responsible for the repair.
- The repairer shall be responsible for the repair.
- The repairer shall be responsible for the repair.
- The repairer shall be responsible for the repair.
- The repairer shall be responsible for the repair.
- The repairer shall be responsible for the repair.
- The repairer shall be responsible for the repair.
- The repairer shall be responsible for the repair.

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19014219/UQF3N2

Date: 01/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN17467118011	
Claimant Vehicle No :	PC5826X	Insured Vehicle No :	PC794L	
Date of Loss:	21/07/2019	Nature of Claim:	TP	Claim No: SNM19D203432C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC5826X	Engine No:	1KD2573338
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	KDH2010187593
Reg. Date:	22/05/2017 (Man. Year: 2015)	Odometer:	149396 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,304.92	1,171.15	4,133.77	77.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	970.00	1,480.00	60.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	7,754.92	2,141.15	5,613.77	72.39

INSPECTION

Date of Assignment:	23/09/2019	
Date Inspected:	24/09/2019	Inspected At:
		BLK 15 KAKI BUKIT BROAD 4 , BARTLEY BIZ #01-53 REPAIRER: ZOOM AUTOWERKS PTE LTD

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Sep 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5826X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH SIDE PANEL	Repair	1,110.80 FL	*- FL
2	1		*REAR RH SIDE GLASS INNER SEAL	Not Necessary	295.00 FL	*- FL
3	1		*REAR TAILGATE PANEL	Repair	1,929.73 FL	*- FL
4	1		*REAR TAILGATE GLASS INNER SEAL	Not Necessary	145.00 FL	*- FL
5	1		*REAR BUMPER	Not Necessary	625.70 FL	*- FL
6	1		*REAR BUMPER BRACKET	Not Necessary	148.70 FL	*- FL
7	10		*REAR BUMPER CLIPS	Not Necessary	60.00 FL	*- FL
8	1		*REAR RH TAILLAMP	Broken	565.30 FL	*388.20 FL
9	1		*REAR RH TAILLAMP INNER PANEL	Not Necessary	465.40 FL	*- FL
10	1		*REAR RH TAILLAMP CLIPS	Not Necessary	12.00 FL	*- FL
11	1		*REAR RH SIDE LOWER PANEL GARNISH	Repair	195.60 FL	*- FL
12	1		*SET REAR TAILGATE ADVERTISEMENT STICKER	Necessary	250.00 FS	*250.00 FS
13	1		*SET REAR TAILGATE ADVERTISEMENT STICKER WORDINGS	Necessary	220.00 FS	*150.00 FS
14	1		*REAR TAILGATE GLASS SEALANT	Not Necessary	150.00 FS	*- FS
15	1		*TAILGATE STICKER 70KM/H	Necessary	50.00 FS	*10.00 FS
16	1		*SET REAR RH SIDE PANEL ADVERTISEMENT STICKER	Necessary	250.00 FS	*250.00 FS
17	1		*SET REAR RH SIDE PANEL ADVERTISEMENT STICKER WORDINGS	Necessary	220.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,693.23	1,268.20
- List Item Discount on L Items 25.00/25.00% (S\$)	1,388.31	97.05
Total Parts (S\$)	5,304.92	1,171.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RENEW RH SIDE AFFECTED ACCIDENT AREAS	New	1,100.00	450.00
2	TO PUTTY, SPRAY PAINT ON LH SIDE AFFECTED ACCIDENT AREAS	New	900.00	500.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO RMEOVE & INSTALL REAR TAILGATE GLASS TO ASSIST REPAIRS	New	150.00	0.00
5	TO RMEOVE & INSTALL REAR RH SIDE GLASS	New	150.00	0.00
6	TO RUST PROOF AFFECTED AREAS	New	100.00	0.00
Gross Labour Cost (\$\$)			2,450.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >