



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/08/2019

User ID : BoonChew Tay

Section A - Accident Details			
Registration Number	SG10202		
Case Reference Number	BUS/08-19-6001		
Registration Date	27/12/2017		
Company Type	SMRT Buses Ltd		
Make	MERCEDFS		
Model	MBOC530		
Name of Driver	Lim Peng Hooi		
Type of Accident	Head to Rear		
Accident Date and Time	9/8/2019 5:08 PM		
Accident Reported Date and Time	9/8/2019 6:45 AM		
Is Surveyor Required?	No		
Survey by			
Vehicle is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number			
Special Instruction to ARC if any	SG10202-REAR PORTION SKP5206B (TP) INSURED WITH AIG		
Prepared Date and Time	14/8/2019 10:11 AM		
Chassis Number	WEB62808323129419		
Mileage			
Work Shop			
Repair Completion Date and Time			
Section B - Summary of Repair Estimates			
Summary of Repair Estimates			
	Quotation from ARC	Adjusted by Surveyor, if applicable	
Total Labour Cost	\$7,650.00	\$0.00	
Total Spray Cost	\$432.00	\$0.00	
Total Spare Part Cost	\$5,988.64	\$0.00	
Total Other Cost	\$0.00	\$0.00	
TOTAL COST	\$19,070.64	\$0.00	
Lump Sum Total	\$0.00	\$0.00	
Number of Repair Days	7.0		
Prepared / Adjusted By	Boon Chew Tay		
ARC / Surveyor Sign Off Date	14/08/2019 10:39 AM		
Signature			
Remarks			
Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685662
Estimator Telephone Number : 68662633
Accident Reporting Number : 68662672

Date Generated : 14/08/2019
User ID : BoonChewTay

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR		Submitted by Surveyor, if applicable					
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$2,650.00		2120 /					
Total Labour		\$2,650.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from AR		Submitted by Surveyor, if applicable					
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$432.00		340 /					
Total Spray Painting & Panel Beating		\$432.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from AR		Submitted by Surveyor, if applicable					
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
8009909	BODY RH		BUMPER REAR RH FOR MB CITARO Q530	1.00	\$837.84	10.00	\$754.06	Replace	OK
6009907	Body		BUMPER REAR CENTRE FOR MB CITARO Q530	1.00	\$1,791.33	10.00	\$1,612.20	Replace	OK
6009880	VE		LAMP TAIL REAR RH FOR MB CITARO Q530	1.00	\$1,261.71	10.00	\$1,135.54	Replace	X
6010010	VE		LAMP EXTERIOR REAR FOG LAMP FOR MB CITARO	1.00	\$63.15	10.00	\$56.84	Replace	X
		MA62R6402114	CROSS BAR REAR BUMPER (SBS VERSION)	1.00	\$2,700.00	10.00	\$2,430.00	Replace	OK
Total					\$6,654.03		\$5,968.64		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	APG Check	Surveyor Check
Total									

Steve
8322 8813

unz April 14/8/19, 234

5 ch
L/S
Ry
after

4796-26
-20% L/S
3837.00
2120

340
6297.00

L/S = 6300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: