

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

China Taiping
CP/P

Date: 14.08.2019

Time: 08:39:37

Page: 1/2

Lkt - kalvin. TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO

: 305324236

REGN NO

: SHA9369C

MILEAGE

: 0000000000

MAKE

: HYUNDAI

MODEL

: I-40

DATE OF REGN

: 24.11.2016

DATE/TIME IN

: 13.08.2019 14:00

ACCIDENT DATE

: 12.08.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-0103-2014-A REAR DOOR APPS STICKER RH 1 80.00 0.00 80.00 ✓

0002 04-01-0103-0658-G REAR WHEEL CAP RH 1 107.10 20.00 85.68 ✓

SUB-TOTAL : 165.68

JOB NATURE

0000 20-05 REAR HANKOOK TYRE RH

~~216.00~~ X

0001 20-05 Rear Fender Adv.Sticker RH

100.00 ✓

0002 20-05 Rear Door Adv.Sticker RH

100.00 ✓

0003 20-05 Rear Bumper Adv.Sticker

50.00 ✓

0004 PB PANEL BEATING

~~560.00~~ 200

0005 SP SPRAYPAINT CHARGE

~~750.00~~ 600

0006 20-00 TUFF COAT ON AFFECTED PARTS.

~~60.00~~ X

0007 L WHEEL ALIGNMENT

~~120.00~~ X

SUB-TOTAL : 1,956.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

China Taiping

Date: 14.08.2019

Time: 08:39:37

Page: 2

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305324236
REGN NO : SHA9369C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 24.11.2016
DATE/TIME IN : 13.08.2019 14:00
ACCIDENT DATE : 12.08.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Limf

TOTAL : 2,121.68

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kelua 10/10/19
14/8/19 1040hrs
2 Days
PIP
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: