

ASS. REC. BY:

REF:

08/11/10/14252/4/d3n2

Special Instruction:

Assigner: Marcus

ASSIGNMENT (Office)

Muller

From (Person): Hor Yinn

of

AG

Date/Time: 15/8/19 @ 10.43am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 8000Y

Insured:

SGT 279A

at Workshop in/s

Uni Automotive

Tel:

9798 1616

of

1 Kelki Buleit Ave 6 # 01-94 Autobay

Policy No:

2100015819

Claim No:

066646265156

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12.18pm @ 15/8/19

Person Contacted:

Alvin

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate ✓

SLK 8000Y-X

SGT 279A - CS/MIS/11000759/Rvg

DOA: 8/1/2011



(08/11/13) wef

ASS. REC. BY: *Marias*

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) *2318 Typist* ☐ : Preli. Report ☒ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Photos

Others

TOTAL

250  
11

261

RECEIVED 26 AUG 2019

2/8/19 4/5 @ 2402 confid with Alvin  
(Red: 3317 24, 58%)

**PRE-REPAIR INSPECTION REQUEST – SLK8000Y vs SGT279A (OI) on D.O.A.: 12/08/2019**

From: Hor, Yinnul  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divi  
Sent: 8/15/2019 10:43:08 AM  
Attachments:  slk8000-pri-3\_08152019\_101500.pdf  SLK 8000Y- PRI\_08142019\_041507.pdf  SLK 8000Y- PRI\_08142019\_041507.pdf

Hi,

Please refer to the enclosed request from **C Paglar & Co.**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

*Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Singapore FNOL | Claims Operations – Auto

[Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** PRI Cpaglar [mailto:pri@cpaglar.com.sg]

**Sent:** Thursday, August 15, 2019 10:32 AM

**To:** Hor, Yinnul

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahxin

**Subject:** [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGT279A AND SLK8000Y ON 12/08/2019

This message is from an external sender; be cautious with links and attachments.

**WITHOUT PREJUDICE**

Dear Sirs,

We enclose herewith our letter dated 15th August 2019 for your attention.

Thanks and Regards,  
Linda Md Shah  
on behalf of C Paglar & Co  
GST Registration No. M90371275E

On Thu, Aug 15, 2019 at 9:13 AM Hor, Yinnul <[Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com)> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน  
ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려  
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,  
membuka attachment.

[Click here](#) by 2019-08-22 09:13 +08 to read your message.  
After that, open the attachment.

[More info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul.Hor@aig.com  
To: pri@cpaglar.com.sg  
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com  
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGT279A AND SLK8000Y ON 12/08/2019  
Date: Thu, 15 Aug 2019 01:13:07 +0000  
Without Prejudice

Your Reference : CP/PRI/SLK8000/19/LD (SF)  
Our Reference : SGT279A

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Singapore FNOL | Claims Operations – Auto

[Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** PRI Cpaglar [mailto:pri@cpaglar.com.sg]  
**Sent:** Wednesday, August 14, 2019 4:45 PM  
**To:** Lim, Sheng Yang; Abu Kassim, Noor Mariesa; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Md Ishak, Mohd Imran  
**Cc:** Constance Paglar  
**Subject:** [EXTERNAL] OUR REF: CP/PRI/SLK8000/19/LD (SF) YOUR REF: SGT 279A NOTICE OF ROAD TRAFFIC ACCIDENT ON ROAD TRAFFIC ACCIDENT ON 12TH AUGUST 2019 INVOLVING MOTOR VEHICLE NO. SLK 8000Y AND SGT 279A ALONG HOLLAND ROAD TOWARDS HOLLAND VILLAGE (DEMPSEY ROAD) A...

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

Enclosed is a copy of our letter dated 14th August 2019 for your necessary action.

Regards,

Shu Fong  
For and on behalf of  
Messrs C Paglar & Co  
50 Chin Swee Road  
#05-03 Thong Chai Building  
Singapore 169874  
Tel: 6536 5456  
Fax: 6536 8706

GST Registration Number: M90371275E

# CPc

## C PAGLAR & CO

ADVOCATES & SOLICITORS

UEN NO. 53130985A GST REG NO. M90371275E

50 Chin Swee Road  
#05-03 Thong Chai Building  
Singapore 169874

Telephone: (65) 6536 5456

Facsimile: (65) 6836 2195

Email: pri@cpaglar.com.sg

SERVICE OF COURT DOCUMENTS BY FACSIMILE  
WILL NOT BE ACCEPTED

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SGT 279A  
Our Reference: CP/PRI/SLK8000/19.ld

Date : 15<sup>th</sup> August 2019

BY EMAIL

**AIG ASIA PACIFIC INSURANCE PTE LTD**

ATTN: MOTOR CLAIMS DEPT

Dear Sirs,

**CORRESPONDENCE PURSUANT TO PARAGRAPH 2.9 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES**

We refer to your email dated 15<sup>th</sup> August 2019.

We have our client's instructions to agree to use Mr. Marcus Chua from LKK Auto Consultants Pte Ltd as the Single Joint Expert.

Please note that the said vehicle can be inspected at:

UNIMOTOR COMPANY  
1 Kaki Bukit Avenue 6  
#01-94 Autobay@KB  
Singapore 417883  
Contact No.: 9798 1616 (Alvin)

**KINDLY REPLY BY EMAIL ONLY: pri@cpaglar.com.sg**

Please note that the vehicle will only be available for the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you. All our client's rights are expressly reserved.

Yours faithfully,



**C PAGLAR & CO**

cc. [Client by Fax 6747 2373 Only] – (SLK 8000Y)

Please initial here after completion of  
pre-repair inspection.  
Thank you

.....  
Appointed Surveyor (Name & Signature)

.....  
Date & Time of Inspection

Form 3

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



civic

Price Range

Depreciation

&gt; 10 year(s)

Vehicle Type

Home » Used Cars » 88 Motor Trading » Honda Civic 1.8A VTi-S (COE till 02/2027)

## Honda Civic 1.8A VTi-S (COE till 02/2027)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

# 88 汽车贸易

## MOTOR TRADING


**Price** \$45,800

**Depreciation** \$6,120 /yr

**Reg Date** 12-Feb-2007  
(7yrs 5mths 23days COE left)

**Mileage** 103,000 km (8.2k /yr)

**Manufactured** 2006

**Road Tax** \$1,174 /yr

**Transmission** Auto

**Dereg Value** \$38,994 as of today (change)

**OMV** \$20,032

**COE** \$52,077

**ARF** \$22,036

**Engine Cap** 1,799 cc

**Power** 103.0 kW (138 bhp)

**Curb Weight** 1,219 kg

**No. of Owners** 2

**Type of Vehicle** Mid-Sized Sedan

### Features

We Provide After Hours Viewing! Simply Call Us Today To Make An Appointment. Best Conditioned, Cheapest In Market! View specs of the Honda Civic (2006-2012)

### Description

\$0 Downpayment, Monthly \$798. 1 Transfer, Low Mileage! Major Wear And Tear Parts Replaced, Worry Free Unit Available For Test Drive. New Upholstery New Paintwork!. Kindly Call Us Today For Viewing Or Appointment. STA Or Workshop Evaluation Welcomed, High Loan/Insurance Flexibility. Call Now!

### Category

COE Car, Low Mileage Car

### Status

Available

Compare



Shortlist

Compare

Report Error

More

### Seller Information

**Company** 88 Motor Trading  
» dealer  
» 199 vehicles  
★ PREMIUM DEALER

**Address** 200 Jale Kaper Road  
Carpark  
Search

**Location** Textile Road

**Website** www.88motor.com

**Office No** 629111

**Contact Person(s)** Lek Ben Mr Ho



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	858D
<b>Vehicle Details</b>	
Vehicle No.:	SLK8000Y
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	R18A12036349
Chassis No.:	JHMFD16307S217218
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$19,673.00
Original Registration Date:	05 Jul 2007
First Registration Date:	05 Jul 2007
Transfer Count:	5
Actual ARF Paid:	\$21,641.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	04 Jul 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$52,473.00
COE Rebate Amount:	\$41,320.00
<b>Total Rebate Amount:</b>	<b>\$41,320.00</b>

The information contained herein is correct as at 19 Aug 2019

OK



MSFS1906135 / Kian Fook Sing Motor Workshop - Darby  
ENTRY DATE & TIME: 14/08/2019 12:39  
SUBMITTED BY: Yeh Boi

Your NCD will be affected due to late reporting  
Actual e-Filing Submission Date & Time: 14/08/2019 13:35

#### SINGAPORE ACCIDENT STATEMENT

##### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

##### ACCIDENT STATEMENT

Date Of Report	14/08/2019 12:39
Date Of Accident	12/08/2019 14:40
Exact Location Of Accident	HOLLAND RD TWDS HOLLAND VILLAGE (DEMPSEY ROAD )
Country/State of Loss	SINGAPORE

##### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK8000Y
Insured/Policyholder	
Name Of Registered Owner	EXCLUSIVE LIMO & CAR RENTALS
Co Reg No	52963858D
Email Address	JOHNNY@EXCLUSIVELIMO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62850020
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC-1.8 L (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A 29090375 MCX
Cover Note Number	01/08/2019 TO 31/07/2020
Driver	
Name of Driver	DARBY MICHAEL CHARLES
Work Permit No	G5872073P
Date Of Birth	20/05/1959
Occupation	INDOOR
Date Of Driving Pass	01/01/2000
Driving Experience	19 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96902933
Fax Number	
Contact Number	
EMail Address	MIKEDARBY100@HOTMAIL.COM

Page 1 of 2

Address	24 KHEAM HOCK RD #03-08 GALLOP COURT (S) 298795
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-

Contact Number

E-Mail Address

MIKEDARBY100@HOTMAIL.COM

Page 1 of 2

Address

24 KHEAM HOCK RD #03-08 GALLOP COURT (S) 296795

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

-  
-  
-

Insurance Company of Driver's Own Vehicle

-  
-  
-

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : WIFE  
GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TANGLIN POLICE DIVISIONAL HQ ( 'E' DIVISION )

Police Station Address ROAD, 21 KAMPONG JAVA ROAD , POSTCODE: 228892 , COUNTRY: SINGAPORE

Police Station Contact TEL NO. 1800-3910000 - FAX NO. 63964900

Was notice of Intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

refer with attach police report.

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGT279A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Page 2 of 2

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

refer with arttech.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer with attach.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_ Driver's Signature \_\_\_\_\_  
Policyholder's Title \_\_\_\_\_ Driver's Title \_\_\_\_\_  
Reporting Centre Personnel's Signature \_\_\_\_\_

Date & Time:	(If driver is not the policyholder)	Name:
Date & Time:		NRIC/ID No.:



police report Pg. 1

**SINGAPORE  
POLICE FORCE**

E/20190812/7015

1 of 3

**POLICE REPORT (NP299)**

Report No. E/20190812/7015

Police Station Of Origin  
Tanglin Division HQ  
21 Kampong Java Road SINGAPORE  
228892  
Tel No: 1800-3910000

Date/Time Report Made 12/08/2019 19:50	Video Report No.	Station Diary No.
Name Of Informant DARBY MICHAEL CHARLES	Address 24 KHEAM HOCK ROAD #03-08 GALLOP COURT SINGAPORE 298795	
ID Type / ID No. FIN NO / G5872073P	Contact No. Home/Office:	Mobile: 97267111
Nationality BRITISH	Email Address mikedarby100@hotmail.com	
Occupation	Sex	Age
Insurance underwriter	Male	60
Institution/School Name	Language	Date of Birth
	English	20/05/1959
Date/Time Of Incident 12/08/2019 14:40	Location Of Incident DEMPSEY ROAD	Race Caucasian

**Brief details.**

I WAS DRIVING HONDA CIVIC - SLK8000Y ALONG HOLLAND ROAD AND STOPPED AT THE TRAFFIC LIGHTS AT JUNCTION WITH DEMPSEY ROAD  
VEHICLE TOYOTA - SGT 279A PROCEEDED TO DRIVE INTO THE BACK OF MY HONDA STRIKING HEAVILY THE PASSENGER SIDE REAR WING  
I ASKED THE DRIVER TO GIVE ME HIS DETAILS BUT HE REFUSED TO LEAVE THE VEHICLE SAYING HE 'MADE A MISTAKE' AND SPEAKING INCOHERENTLY  
HE THEN LOCKED THE DOOR, REVERSED ACROSS A LANE OF ONCOMING TRAFFIC AND

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 12/08/2019 19:50
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

police report Pg. 1



SINGAPORE  
POLICE FORCE



E/20190812/7015

2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20190812/7015

PROCEEDED TO RAPIDLY DRIVE AWAY AND LEAVE THE SCENE

Subjects Involved			
Suspect			
Person Name	UNKNOWN		
Gender	Male	Age	50-55
Race	Indian		
Victim			
Person Name	DARBY MICHAEL CHARLES		
ID Type	FIN NO	ID No	G5872073P
Gender	Male	Age	60
Race	Caucasian	Language	English
Occupation	Insurance underwriter	Address Type	
Address	24 KHEAM HOCK ROAD #03-08 GALLOP COURT SINGAPORE 298795	Mobile No	97267111
Is Informant A	Yes		
Victim?			
Person Name	michael darby		
ID Type	PASSPORT	ID No	560853228
Gender	Male	Age	60
Race	Caucasian	Language	English
Signature Of Officer Recording The Report:		Signature Of Informant:	
Not applicable		The identity of the person making this report has been authenticated by SingPass. No signature is required.	
Signature Of Interpreter:		Date/Time:	
Not applicable		12/08/2019 19:50	
Officer In-Charge Of Case:		Classification Of Case:	
Authentication Stamp			

police report Pg. 1



# 友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

LKK

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

DATE: 15/08/2019

OUR REF: UAPL1288

Registration No.: 203165/00D

REPAIR ESTIMATE YOUR INSURED VEHICLE HONDA CIVIC NO: SLK8000Y

1 REAR BOOT ASSY		R	\$	760.60	X
1 REAR BOOT LOCK		17	\$	213.30	X
2 REAR BOOT HINGES		17	\$	113.40	X
1 REAR BOOT STRIKER		17	\$	42.20	X
1 REAR L/H BOOT LAMPS		17	\$	226.10	X
1 REAR BOOT WEATHERSTRIP		17	\$	123.30	X
1 REAR BOOT HONDA EMBLEM		111	\$	28.80	✓
1 REAR BOOT 1.6 EMBLEM		111	\$	26.20	✓
1 REAR BOOT IVTEC EMBLEM		111	\$	28.60	✓
1 REAR BOOT CIVIC EMBLEM		111	\$	32.70	✓
1 REAR L/H TAILLAMP ASSY	325.50	111	\$	413.60	✓
1 REAR L/H TAILLAMP LOWER BRACKET		111	\$	47.00	✓
1 REAR L/H TAILLAMP PANEL		111	\$	122.60	X
1 REAR TAIL END PANEL	306.10	111	\$	483.60	✓
1 REAR BUMPER FACE	638	111	\$	688.20	✓
1 REAR L/H BUMPER SIDE TOP HOLDER BRACKET	15.20	111	\$	51.60	✓
1 REAR L/H BUMPER SIDE LOWER HOLDER BRACKET		111	\$	43.20	X
2 REAR GROMMET		111	\$	16.00	X
10 REAR BUMPER CLIPS	39.00	111	\$	55.00	✓
1 REAR PANEL LINING		111	\$	156.30	X
			\$	3,672.30	
			\$	734.46	
			\$	2,937.84	

LESS 20% .....

## SPECIAL NETT:-

1 REAR REVESE SENSOR

should \$ 280.00 200 s.w

## LABOUR CHARGES:-

TO DISM/REWIRE REAR DAMAGED PORTION	\$	120.00	20
TO PANEL BEAT DAMAGED PORTION, CHASSIS FRAME AND RENEW PARTS	\$	1,000.00	680
TO PUTTY AND RESPRAY DAMAGED PORTION	\$	1,000.00	750
TO SPARY UNDERCOATING IN REPAIR	\$	150.00	30
TO DISM/REFIX SEAT, PANEL LINING, ROOF LINING	\$	150.00	80
TO DISM/RENEW REAR REVESE SENSOR	\$	80.00	50
	\$	5,717.84	

LKK Auto Consultants hence notify the Repairer of the following:

- To remove surface after spray painting
- To replace damaged part(s) during resurvey
- All work must be subject to confirmation
- This estimate is on a "Without Prejudice" basis
- No further deduction is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

p-1497-1  
20%  
1197.68  
3007.68  
202  
2406.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19014252/UTD3N2

Date: 28/08/2019

**REFERENCE**

<b>Handling Insurer:</b>	AIG Asia Pacific Insurance Pte. Ltd.	<b>Policy No:</b>	2100015819
<b>Claimant Vehicle No :</b>	SLK8000Y	<b>Insured Vehicle No :</b>	SGT279A
<b>Date of Loss:</b>	12/08/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	0666462651SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	SLK8000Y	<b>Engine No:</b>	R18A12036349
<b>Make &amp; Model:</b>	HONDA CIVIC, 1.8 L (A)	<b>Chassis No:</b>	JHMF16307S217218
<b>Reg. Date:</b>	05/07/2007 (Man. Year: 2007)	<b>Odometer:</b>	28319 km
<b>Colour:</b>	Silver		
<b>Engine Capacity:</b>	1799 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	205/65R16	<b>Rear Tyre Size:</b>	205/65R16
<b>Front Left Side:</b>	Nexen 6 mm	<b>Rear Left Side:</b>	Nexen 6 mm
<b>Front Right Side:</b>	Nexen 6 mm	<b>Rear Right Side:</b>	Nexen 6 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,217.84	1,397.68	1,820.16	56.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,610.00	890.00	35.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,717.84</b>	<b>3,007.68</b>	<b>2,710.16</b>	<b>47.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,717.84</b>	<b>2,400.00</b>	<b>3,317.84</b>	<b>58.03</b>

**INSPECTION**

Date of Assignment: 15/08/2019

Date Inspected: 15/08/2019 Inspected At:

 Uni Automotive Pte Ltd (HQ)  
 NO. 1 KAKI BUKIT AVE 6 #01-94  
 AUTOBAY@KAKI BUKIT  
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT ASSY	Repair	760.60 FL	*- FL
2	1		*REAR BOOT LOCK	Not Necessary	213.30 FL	*- FL
3	2		*REAR BOOT HINGES	Not Necessary	113.40 FL	*- FL
4	1		*REAR BOOT STRIKER	Not Necessary	42.20 FL	*- FL
5	1		*REAR L/H BOOT LAMPS	Not Necessary	226.10 FL	*- FL
6	1		*REAR BOOT WEATHERSTRIP	Not Necessary	123.30 FL	*- FL
7	1		*REAR BOOT HONDA EMBLEM	Necessary	28.80 FL	*28.80 FL
8	1		*REAR BOOT 1.6 EMBLEM	Necessary	26.20 FL	*26.20 FL
9	1		*REAR BOOT IVTEC EMBLEM	Necessary	28.60 FL	*28.60 FL
10	1		*REAR BOOT CIVIC EMBLEM	Necessary	32.70 FL	*32.70 FL
11	1		*REAR L/H TAILLAMP ASSY	Cracked	413.60 FL	*325.50 FL
12	1		*REAR L/H TAILLAMP LOWER BRACKET	Bent	47.00 FL	*47.00 FL
13	1		*REAR L/H TAILLAMP PANEL	Repair	122.60 FL	*- FL
14	1		*REAR TAIL END PANEL	Dented	483.60 FL	*306.10 FL
15	1		*REAR BUMPER FACE	Dented/Deformed	688.20 FL	*638.00 FL
16	1		*REAR L/H BUMPER SIDE TOP HOLDER BRACKET	Bent	51.60 FL	*25.20 FL
17	1		*REAR L/H BUMPER SIDE LOWER HOLDER BRACKET	Not Necessary	43.20 FL	*- FL
18	2		*REAR GROMMET	Not Necessary	16.00 FL	*- FL
19	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*39.00 FL
20	1		*REAR PANEL LINING	Not Necessary	156.30 FL	*- FL
21	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,952.30</b>	<b>1,697.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>734.46</b>	<b>299.42</b>
<b>Total Parts (\$\$)</b>	<b>3,217.84</b>	<b>1,397.68</b>

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISM/REWIRE REAR DAMAGED PORTION	New	120.00	20.00
2	TO PANEL BEAT DAMAGED PORTION,CHASSIS FRAME AND RENEW PARTS	New	1,000.00	680.00
3	TO PUTTY AND RESPRAY DAMAGED PORTION	New	1,000.00	750.00
4	TO SPRAY UNDERCOATING IN REPAIR	New	150.00	30.00
5	TO DISM/REFIX SEAT,PANEL LINING,ROOF LINING	New	150.00	80.00
6	TO DISM/RENEW REAR REVERSE SENSOR	New	80.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,500.00</b>	<b>1,610.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;