SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aloresalu.	
	ACCIDENT STATEMENT
Date Of Report	15/08/2019 17:22
Date Of Accident	15/08/2019 07:30
Exact Location Of Accident	UPP THOMSON FLYOVER NEAR L/P: 279
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLJ9624X
Insured/Policyholder	
Name Of Registered Owner	JOANNE HO LI HUA
NRIC No	S6998043J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96229937
Alternative Phone No	OFFICE-96229937
Vehicle Particulars	
Manufacturer	CHEVROLET
Model	MALIBU 2.4L AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	ТВА
Cover Note Number	
Dulivan	

Driver

Name of Driver HO PENG SOON
NRIC No S2555487F
Date Of Birth 04/10/1962
Occupation INDOOR
Date Of Driving Pass 20/08/1988

Driving Experience 30 YEARS AND 11 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90885584

Fax Number

Contact Number OFFICE-90885584

EMail Address NOEMAIL

Address 10 RIVERVALE LINK

#02-16

Postcode 545044

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

......

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

3 NO

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NO

2

NO

NO

NAME: : SOPHIA HO JIN WEN

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? YES

Remarks/ Reasons: VIDEO FOOTAGE WITH DRIVER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKC3476U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Page 2 of 19

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLB9666S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Nama:

NRIC/FIN No.

Accident Sketch Plan



Accident Sketch Plan

On 15.08.19 at about 07:30 hours at along SLE towards BKE (At Upper Thomson Flyover at Lamp Post 279). While I was travelling straight on the lane one and traffic was heavy, my front vehicle slow down and stop hence I follow suit.

Suddenly, I heard a loud bang from behind and the impact forced my vehicle (A) to move forward to hit onto the rear portion of Vehicle (C). When I alighted I realized it was vehicle (B) who hit my rear portion of my vehicle (A) causing damages to my front & rear portion of my vehicle. It was a chain collision of total 3 vehicles involved. I wish to state that I have one passenger inside the vehicle.

Vehicle (A): SLJ9624X

Vehicle (B): SKC3476U

Vehicle ('C): SLB9666S

10

Accident Photo CHEVROLET CHEVRO







