

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



Survey & repair  
20/08 @ 10am  
Survey before 12pm

GST REG. NO : M2 - 0020081 - X

15 AUG 2019

**E S T I M A T E**

Estimate No. : b1 52321  
Date Estimated : 14/08/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

**- ESTIMATE REPAIR FOR -**

Yong Chin Kuan  
151 Holland Road  
#01-02

Singapore 278580

**- ACCOUNT - 121**

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL     | MILEAGE |
|-----------|-------------|------------|-----------|---------|
| SLG3604J  | NU32076     | 28/09/2016 | 318iA/4Dr | 0       |

DESCRIPTION

To replace front bumper, air duct and attachments.

2975 4,250.00

Painting front bumper.

934 1,038.00

To replace left or right headlight.

408 481.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To supply front emboss number plate.

580 83.00

Sundries.

? 150.00

Total Labour 1: **6,179.00**DESCRIPTION

FRT BUMPER TOP MOUNT ?  
INSERT AIR INLET MIDDLE (m) - OR  
FINISHER ROD CENTRE (SPORT) / CUT  
LH FINISHER ROD (SPORT) / MS  
RH FINISHER ROD (SPORT) (AL) / CAT  
FRT BUMPER TOWING LUG COVER PRIMED / CUT  
RH OPEN GRID (SPORT) / BR  
LH PARTIALLY OPEN GRID (SPORT) X  
FRT SHOCK ABSORBER ECE / BR  
FRT BUMPER PANEL PRIMED (SPORT LINE) / PD  
FRT LH GRILLE (SPORT) X  
FRT RH GRILLE (SPORT) / CUT  
SUPPORT NUMBER PLATE ECE / BR  
AIR DUCT RADIATOR / CRV  
PLAQUE 82MM / OR  
RH HEADLIGHT LED TECHNOLOGY / BR

| QTY | PRIC     | VALUE    |
|-----|----------|----------|
| 1   | 378.10   | 378.10   |
| 1   | 120.60   | 120.60   |
| 1   | 54.55    | 54.55    |
| 1   | 56.00    | 56.00    |
| 1   | 56.00    | 56.00    |
| 1   | 43.25    | 43.25    |
| 1   | 88.35    | 88.35    |
| 1   | 91.75    | 91.75    |
| 1   | 54.50    | 54.50    |
| 1   | 1,037.05 | 1,037.05 |
| 1   | 128.60   | 128.60   |
| 1   | 128.60   | 128.60   |
| 1   | 69.25    | 69.25    |
| 1   | 61.50    | 61.50    |
| 1   | 71.25    | 71.25    |
| 1   | 3,068.40 | 3,068.40 |

Total Parts : **5,507.75**

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



**GST REG. NO : M2 - 0020081 - X**

**E S T I M A T E**

Estimate No. : **b1 52321**  
Date Estimated : **14/08/2019**  
Prepared By : **Inthiran A/L Thurasamy**

Page No. : **2 of 5**

| REGN. NO.       | CHASSIS NO.    | REGN. DATE        | MODEL            | MILEAGE  |
|-----------------|----------------|-------------------|------------------|----------|
| <b>SLG3604J</b> | <b>NU32076</b> | <b>28/09/2016</b> | <b>318iA/4Dr</b> | <b>0</b> |

**L&K Auto Consultants hence notify**  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|                                                              |                            |
|--------------------------------------------------------------|----------------------------|
| Claims OD / 3rd Party / Uninsured losses / Direct Settlement |                            |
| Regn No. <u>20/8/19</u>                                      | Claim No. _____            |
| Date & Time <u>11.00am</u>                                   | Excess S\$ _____           |
| Surveyor's Name <u>Stek CLK</u>                              | Sign _____                 |
| Surveyor's Tel <u>8322 8873</u>                              | Authorised <u>Yes / No</u> |
| Authorised Date _____                                        | Time _____                 |
| RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No       |                            |
| Surveyor's E-mail _____                                      |                            |
| No. of Working Days Recommend _____                          |                            |

*WML M/L*  
*5 days*  
*P/P*  
*Ry Def spy*

|                |   |                  |
|----------------|---|------------------|
| Labour 1       | : | <b>6,179.00</b>  |
| Parts          | : | <b>5,507.75</b>  |
| Labour 2       | : | <b>0.00</b>      |
| Excess         | : | <b>0.00</b>      |
| Total GST @ 7% | : | <b>818.07</b>    |
| Grand Total    | : | <b>12,504.82</b> |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*