

REF: ASM (ACA)

Surveyor

ASSIGNMENT

From: Date: 16.8.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKU 4817T
at Workshop m/s Asia Motorsports
of 15 Kaki Bukit Road #01-051 53

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: S212.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKU 4817T Yr Regn: 7115

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A1)

Make: Hyundai Elantra c.c 1591

Colour: 319ek A/C: Insured / Std / NI / NA

Sp. Reading: 94201 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KM HDM 41 CM FU 502823

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 45 R17 R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. mm L/Bal. mm

D.O.A. 10/8/19 D.O.I. 10/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L7A 42502 S yrs. 11m.
healy 1756

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, \$ SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)