

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM19014311/T1ga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KITTY			Date: 09-04-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJY 1655D	Veh. Inspected	SKQ 1012P	
	Policy No.	GA409493	Coverage (\$)	0.00	
	Claim No.	S9M01WTK	Excess (\$)	0.00	
	Assign From		Assign Date	16/08/2019	
2. Vehicle Particulars & Condition					
	Make & Model	RENAULT GRAND SCENIC	c.c	1461	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	VF1RFA00059238184	Colour	GREY	
	Odometer	22496	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/55 R20	CONTINENTAL	6 mm	
	L/H Front Tyre	195/55 R20	CONTINENTAL	6 mm	
	R/H Rear Tyre	195/55 R20	CONTINENTAL	6 mm	
	L/H Rear Tyre	195/55 R20	CONTINENTAL	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/08/2019	Inspection Date	04/09/2019	
	Survey held at	WEARNES AUTOMOTIVE PTE LTD			
		249 ALEXANDRA ROAD SINGAPORE 159935			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				