

Surveyor: Hock Ann Ato

DOI: 20/8/19  
Tue

Date / Time: 16/08/2019  
Registered in Merimen: 16/08/2019

**Pre-assign / CCU / FTE**



Insured Vehicle No. : SHB 4335C Claim No. : \_\_\_\_\_  
 Name of Insured : COMFORT TRANSPORTATION PTE LTD Policy No. : \_\_\_\_\_  
 Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_ Make / Model : \_\_\_\_\_  
 Excess Sec II : \$5 D.O.A : 08/08/2019 14:15 Place of Accident : OUTSIDE CONRAD CENTENNIAL SINGAPORE  
 Is driver the owner? ( YES  NO  ) Nature of Accident : \_\_\_\_\_  
 If NO, Driver Name / Age : \_\_\_\_\_ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
 Driver Tel No. : \_\_\_\_\_ (V/L: YES  NO  ) Insured Liability : \_\_\_\_\_ % Final ? Yes / No

**SGF588G**



INSRS:  
WSP: TEAMWORK  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time	STAGE	DATE / PIC
	SGF 588G - NA/INC19014064/z4 ;	DOA:08/08/19
	NA/MSG18022187/r3 ;	DOA:08/12/18
	NA/INC18005569/h4 ;	DOA:24/3/18
	CS/FCI17021230/Dvbn2 ;	DOA:3/11/17
	SHB 4335C - NS/INC18010999/K1sbn2	DOA:16/6/18
	CC4/III18014242/Nhb3	DOA:01/8/18
	CC4/III18006069/Sub3q2	DOA:02/4/18
	CC3/CTI18000024/K1es3s2	DOA:28/12/17
	CC3/AIG11017007/H1sa3w2	DOA19/08/11
<u>23/8/19</u>	File -> Hock Ann as requester	
<u>23/9/19</u>	File -> type made.	
<u>24/9/19</u>	File -> su li to suet W	
<u>24/10/19</u>	File pass to mk to close.	
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

**PRELIMINARY ADVICE** Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

**FINALIZATION** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_

Repair Cost: \$5 \_\_\_\_\_ days) Reduction: \_\_\_\_\_ % Email  Call

**FINAL SETTLEMENT** Date/Time: 24/10/19 Confirm with Shen Shan Email  Call

Final Liability: % 100 Agreed / Assessed) BOLA S/N No. : KPL If NO or B 28, Ass. Lia :

Repair Cost: W/651 \$5 3370-50

Loss of Rental (LOR): \$5 6W-00 ( 6 days) x 1100

Loss of Use (LOU): \$5 - (\$ x days)

Loss of Income (LOI): \$5 - (\$ x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search \$5 26.95

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/Independent)

Legal Cost \$5 -

Total: \$5 4006.95 Global Sum \$5: 4006.95

**FINAL PAYMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$5 4006.95 Name 1: TEAMWORK Garage Per Gtd

Payee 2: (Strike if N.A.) \$5 \_\_\_\_\_ Name 2: \_\_\_\_\_

Payee 3: (Strike if N.A.) \$5 \_\_\_\_\_ Name 3: \_\_\_\_\_

**COPY SENT**  
1/11/19

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: SP
- 3) Survey fee: 500.00

ASSIGNMENT

From: \_\_\_\_\_ Date: 2018/2019  
 Estimated Cost: \_\_\_\_\_  
 OD / (TP) WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: SQF 588G  
 at Workshop n/s Teamwork Garage  
 of 53 ubi Ave 1 # 01-24  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SQF 588G Yr Regn: 02/016/2016  
 Type: (M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: T. corolla Altis classic cc 1598  
 Colour: peach white AC: Insured / Std / NI / NA  
 Sp. Reading: 265895 T/Ratio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MRO53REH104548436  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: (Inorder) / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: (Inorder) / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Tyre Size: F: 205/55/R16  
 R: 205/55/R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or continental / (Frt) Pirelli (Rear)  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 4 mm R/Bal. 4 mm  
 L/Bal. 4 mm L/Bal. 4 mm  
 D.O.A. 8/8/17 D.O.I. 20/8/18  
 Survey held at Teamwork Garage

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est Repairs: 5 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lup  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / (O/S) / N/S / UIC / Rooftop or \_\_\_\_\_  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV - 62985</u>
	<u>PU - 42650</u>
	<u>NV - 20300</u>
	<u>US \$ 3150 (Red) \$ 8623.94 2371</u>
	<u>MV 61-62</u>

*\* Remarks: This case vehicle SQF 588G already discuss workshop Finalised Amount cor \$3150 and DOR 5 days, Agree by Teamwork -> (Darren)*

Date/Time, File Press to?  : Prel. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp 1\$  
 : Interview 1\$  
 : Tech. Invs 1\$  
 : Wheel and 1\$

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 3+RS: \$ \_\_\_\_\_  
 Flares: \_\_\_\_\_  
 Other: \_\_\_\_\_  
 TOTAL: \_\_\_\_\_

Report Format: \_\_\_\_\_  
 Lump Sum / I.B.F.: \_\_\_\_\_

INDIA INTERNATIONAL INSURANCE

Vehicle number	SGF588G
Make / Model	TOYOTA/ALTIS
Chassis number	MRO53REH104548436
Accident date	08.08.19
Reference	1908-20

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER ✓ BR	582.00 458 ✓
1	FRONT BUMPER BRACKET <del>BR</del> ? X SVC	<del>182.40</del>
2	FRONT BUMPER RETAINER ✓ DD	204.00 110 ✓
1	FRONT BUMPER REINFORCMENT - photo ✓ DD	458.20 361 ✓
1	FRONT BUMPER LOWER GRILLE X SVC	<del>186.00</del>
1	FRONT GRILLE ASSY ✓ CRA	678.00 372.80 ✓
1	FRONT FOG LAMP R/H ✓ CRA	390.00 244.70 ✓
1	FRONT FOG LAMP COVER R/H ✓ MIS	114.00 ✓
1	FRONT GRILLE EMBLEM ✓ nec	81.60 ✓
1	FRONT BRACE PANEL R X SVC	<del>186.00</del>
1	FRONT SUPPORT PANEL - photo - R X SVC	<del>1186.80</del>
1	FRONT SUPPORT PANEL TOP GARNISH X SVC	<del>78.00</del>
1	FRONT RH HEADLAMP ✓ CRA	2795.00 750 ✓
1	FRONT RH FENDER R X SVC	<del>937.20</del>
1	FRONT RH FENDER EMBLEM ✓ nec	89.10 ✓
1	FRONT FENDER INNER SHIELD ✓ CRA	240.00 96 ✓
1	BONNET R X SVC	<del>1244.40</del>
1	BONNET INSULATOR X SVC	<del>342.00</del>
1	BONNET HINGE R X SVC	<del>180.00</del>
1	FRONT RH SHOCK ABSORBER X SVC	<del>559.10</del>
1	FRONT RH KUNCKLE ARM X SVC	<del>501.30</del>
1	FRONT RH KUNCKLE ARM BEARING X SVC	<del>211.50</del>
1	FRONT RH LOWER ARM. BT ✓	339.60 275 ✓
		11766.20
	Less 25%	2941.55
	Subtotal	8824.65
	Balance C/F	8824.65
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	8824.65
1 SET	FRONT BUMPER CLIP ✓ nec	50.00 \$20
1 SET	SUPPORT PANEL TOP GARNISH CLIP X NV	<del>80.00</del>
1 SET	FRONT GRILLE CLIP ✓ nec	80.00 \$20
	Subtotal	210.00
	Balance C/F	9034.65
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	9034.65

S/No	LABOUR AND MISCELLANEOUS CHARGES	Balance B/F
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	50.00 \$ 20
3	CHECK FRONT WHEEL ALIGNMENT → Alignment report)	200.00 \$ 50
4	PANEL BEATING ON AFFECTED AREAS	1000.00 \$ 600
6	SPRAY PAINTING ON AFFECTED AREAS (penak white) 4ps	1000.00 \$ 800
7	APPLY ANTI RUST ON AFFECTED AREAS	100.00 \$ 20
	Subtotal	2350.00
	Grand total	11384.65

→ 21/6/19  
 → repair support panel / \$ 700  
 → replace support panel

L/S repair  
 Hoek Ann  
 85311883  
 5.35pm 20/8/19  
 resurvey after paint  
 without prejudice  
 Hoek Ann @ kilcauto.com  
 5 day  
  
 4/9/19



TeamWork Garage Pte Ltd  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 Register number : 201015366H  
 REPAIR PERFORMA INVOICE

INDIA INTERNATIONAL INSURANCE

Vehicle number	SGF588G
Make / Model	TOYOTA/ALTIS
Chassis number	MRO53REH104548436
Accident date	08.08.19
Reference	1908-20

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER SPONGE ✓ CRA	199.20 79 ✓
1	Wiper Tank ✓ 00	319.80 175 ✓
		519.80
	Less 25%	130.55
	Subtotal	389.25
	Balance C/F	389.25

*Resurvey  
 21/8/19 5:45 pm  
 \* please noted that  
 after change first low Am - RH  
 need to request second  
 amount report \*  
 \* after paint photo \**

parts = 3206.20  
 less 25%  
 2404.65

parts = 2404.65  
 special  
 ment = 40

labour = 1490  
 3934.65

4% less - 20%  
 3147.72

Total  
 4% amount = \$3150 //

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

11723-90



[> Back to OneMotoring](#)**Enquire Transfer Fee**

<b>Vehicle Details</b>			
Vehicle No.:	SGF588G		
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	TOYOTA		
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT		
Chassis No.:	MR053REH104548436		
Propellant:	Petrol		
Engine No.:	1ZRX560814		
Engine Capacity:	1598 cc		
Maximum Power Output:	90.0 kW ( 120 bhp )		
Maximum Laden Weight:	1640 kg		
Unladen Weight:	1205 kg		
Year Of Manufacture:	2016		
Original Registration Date:	02 Jun 2016		
Lifespan Expiry Date:	-		
COE Category:	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium:	\$43,000.00		
COE Expiry Date:	01 Jun 2026		
Road Tax Expiry Date:	01 Dec 2019		
PARF Eligibility Expiry Date:	01 Jun 2026		
Inspection Due Date:	01 Jun 2021		
Intended Transfer Date:	20 Aug 2019		
CO2 Emission:	151.00 (g/km)		
CEV/VES Rebate Utilised Amount:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
<b>Amount Payable</b>			
	<b>Amount Before GST (S\$)</b>	<b>GST Amount (S\$)</b>	<b>Amount After GST (S\$)</b>
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

You may print this page for reference.

OK

Print



31 Aug - 1 Sep 2019  
DOWNTOWN EAST  
10am to 8pm

**GREAT PRICES. BETTER CARS. COE Renewed Cars**



• \$0 Down payment • Low Monthly Installments • 1 Year Warranty • 100% Approvals

C S M O  
A T O M O B I L E S

DEALS starting from as low as **\$450/mth**

Toyota Corolla

Price Range

Depreciation

2016

Vehicle Type

Advanced Search

Home » Used Cars » Jack Cars Enterprise Pte Ltd » Toyota Corolla Altis 1.6A

## Toyota Corolla Altis 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

**Price** \$68,800**Depreciation** \$8,780 /yr  
View models with similar depre**Reg Date** 09-May-2016  
(6yrs 8mths 17days COE left)**Mileage** 31,266 km (9.5k /yr)**Manufactured** 2015**Road Tax** \$742 /yr**Transmission** Auto**Dereg Value** \$46,467 as of today (change)**OMV** \$19,589**COE** \$47,300**ARF** \$19,589**Engine Cap** 1,598 cc**Power** 90.0 kW (120 bhp)**Curb Weight** 1,205 kg**No. of Owners** 1**Type of Vehicle** Mid-Sized Sedan**Features**

Reliable 4 Cylinder Inline 16 Valve DOHC Dual VVT-I Valvematic, 7 Speed Super CVT-I, Multi-Function Steering, ABS, Airbags, Keyless Entry/Start. View specs of the Toyota Corolla Altis (2014)

**Accessories**

Factory Fitted Audio System With Bluetooth, GPS, Reverse Cam/Sensors, Electric Leather Seat, Solar Film, Auto Headlight, Auto Dimming Rear Mirror.

**Description**

100% Loan Available With Our Flexible In-House Loan Options! Warranty By Borneo Motors Till May 2021. Premium Grey With Premium Black Leather Seats. Well Maintained By One Owner. Excellent Condition! Call Our Friendly Salesperson Now Or Walk In For Viewing With No Obligations!

**Category**

PART Car, Low Mileage Car

**Status**

Available

**Resources****Car Valuation - Free**

Find out the market value of your existing car for free. Get started


**Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. Find out more



## Price Chart

## Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

## Seller Information

<b>Company</b>	Jack Cars Enterprise Pte Ltd • Dealer's pricelist • 10 vehs sold   24 vehs available	
<b>Address</b>	62 Changi Road #01-02 Search cars nearby this location	
<b>Office No</b>	67411900	
<b>Contact Person(s)</b>	Lester Osman	96814408 91608107



**31 AUGUST-1 SEPTEMBER @ DOWNTOWN EAST**

**THE ULTIMATE PRE-OWNED SALES**

**ENJOY HUGE SAVINGS + FREE SERVICING & WARRANTY + FREE GROOMING**



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Nissan GT-R 3.8A ( COE TILL JUNE 2028)



Well Maintained , low mileage  
Come with nice sport rim and  
body kit.  
Allowell Motor (Mark)



**VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND**

**HOTLINE: 6741 9997** [View our cars](#)

Browse by Category » Back ( 1 2 3 ) Next »

Sort by Date Posted 20 results/page

50 vehicles

Toyota Corolla

RECOMMEND SEARCH

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>Toyota Corolla</b>	Any	Any	<b>2016</b>	Any	Any	Any	Available
	<b>Toyota Corolla Altis 1.6A Classic</b>	<b>\$66,800</b>	<b>\$8,810 /yr</b>	<b>17-Mar-2016</b>	<b>1,598 cc</b>	<b>50,655 km</b>	Sedan	Available
Mileage Done At Only 15,000 KM Yearly Plus Borneo Motor Warranty Till Jan 2021 For Your Total Peace Of Mind Purchase! This Car Needs No Further Introduction, Well Known For Its Overall Reliability Where Reliability And Fuel Efficiency, Moreover The Spacious And Comfort...								
Posted: 26-Jul-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Altis 1.6A</b>	<b>\$68,800</b>	<b>\$8,780 /yr</b>	<b>09-May-2016</b>	<b>1,598 cc</b>	<b>31,266 km</b>	Sedan	Available
100% Loan Available With Our Flexible In-House Loan Option! Warranty By Borneo Motors Till May 2021, Premium Grey With Premium Black Leather Seats. Well Maintained By One Owner. Excellent Condition! Call Our Friendly Salesperson Now Or Walk In For Viewing WL...								
Jack Cars Enterprise Pte Ltd Posted: 23-Jul-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Altis 1.6A Elegance</b>	<b>\$68,888</b>	<b>\$8,870 /yr</b>	<b>19-Apr-2016</b>	<b>1,598 cc</b>	<b>31,223 km</b>	Sedan	Available
1 Owner Only! Cheapest With The Lowest Mileage Clocked In The Market, Owner Reluctant Sale! Servicing Just Done! Owner Consignment Unit! Price Negotiable! High Trade In With Attractive Loan Interest Rate From 1.99% Onwards Available! Don't Miss! Call Now!								
Posted: 21-Jul-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Altis 1.6A Elegance</b>	<b>\$77,800</b>	<b>\$9,250 /yr</b>	<b>19-Dec-2016</b>	<b>1,598 cc</b>	<b>39,568 km</b>	Sedan	Available
Facelifted Elegance Model! 1 Owner, New 6 Month Road/Tax, Low Mileage Done, Agent Maintained. Flexible Loan Available, Trade In Welcome. Call Now For Viewing.								
Posted: 17-Jul-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>The Toyota Previa is the de facto MPV</b>							
The Toyota Previa is an MPV that excels with its space, practicality and a level of luxury some may not reach.								
Find out more!								
	<b>Toyota Corolla Altis 1.6A Classic</b>	<b>\$70,800</b>	<b>\$9,440 /yr</b>	<b>08-Mar-2016</b>	<b>1,598 cc</b>	<b>45,000 km</b>	Sedan	Available
1 Owner. Accident Free. Well Maintained By Agent. Low Mileage Done Annually, Exclusive Interest Rates At 2.48%. Please Call For Viewing And Enquiry.								
Wearnes Automotive Pte Ltd Posted: 16-Jul-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	<b>Toyota Corolla Altis 1.6A Classic</b>	<b>\$70,800</b>	<b>\$8,480 /yr</b>	<b>28-Dec-2016</b>	<b>1,598 cc</b>	<b>51,000 km</b>	Sedan	Available
High Trade In/Loan Available, 1 Careful Owner, Low Mileage, Excellent Condition, 3 Years Warranty By Borneo Motors, STA Evaluation Welcome, Price Negotiable, Please Call/WhatsApp Now To Arrange An Viewing Appointment.								
BKW Automobile Pte Ltd Posted: 11-Jul-2019 Tags: 2016 Toyota Corolla, 2016 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
<b>Compare</b>	<b>yota Corolla Axio 1.5A X</b>	<b>\$57,800</b>	<b>\$7,750 /yr</b>	<b>06-Sep-2016</b>	<b>1,496 cc</b>	<b>-</b>	Sedan	Available

**Hock Ann (LKK Auto)**

---

**From:** Hock Ann (LKK Auto)  
**Sent:** Thursday, 19 September, 2019 5:32 PM  
**To:** Darren  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** RE: SGF 588G FINALIZED CALCULATE EXTIMATE

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear letitia/darren,

Good day, o.k will be process base on finalized total amount COR \$ 3150 and DOR 5 days close.

Thanks.

Best Regards,  
**Hock Ann** | Assistant Automotive Assessor  
**LKK Auto Consultants**  
Phone: 6741 3061 | Email: [HockAnn@lkkauto.com](mailto:HockAnn@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Darren [mailto:claims@teamworkgarage.com]  
**Sent:** Thursday, 19 September, 2019 5:07 PM  
**To:** Hock Ann (LKK Auto)  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** RE: SGF 588G FINALIZED CALCULATE EXTIMATE

Hi Hock Ann,

We confirmed COR @ \$3150 and DOR 5 days

Darren  
Teamwork Garage Pte Ltd  
53 Ubi Avenue 1  
#01-24 Paya Ubi Industrial Park  
Singapore 408934  
Tel: 68442475  
Fax: 68442474

---

**From:** [Hock Ann \(LKK Auto\)](mailto:Hock Ann (LKK Auto))  
**Sent:** Tuesday, 10 September 2019 6:08 PM  
**To:** [Darren](mailto:Darren)  
**Cc:** [Hsiao Tong \(LKKAuto\)](mailto:Hsiao Tong (LKKAuto))  
**Subject:** SGF 588G FINALIZED CALCULATE EXTIMATE

Hi Darren,



Kindly attached refer SGF 588G Toyota altis finalized updated calculate estimate on 10.9.2019 ,

COR - \$ 3150

DOR – 5 DAYS

Please refer adjustment updated estimate calculate finalized total L/sump amount \$ 3150 if agree total L/sump amount and repair days,

Please to updated email asap.

Thanks.

Best Regards,

**Hock Ann** | Assistant Automotive Assessor

**LKK Auto Consultants**

Phone: 6741 3061 | Email: [HockAnn@lkkauto.com](mailto:HockAnn@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Catherine Chong (LKK Auto)**

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Friday, 16 August, 2019 1:28 PM  
**To:** Darren; sur@lkkauto.com; Admin-D (LKKAuto)  
**Cc:** Manivel Priyadarshini  
**Subject:** RE: OUR REF : 1908-20 // YOUR REF : SHB4335C ACCIDENT INVOLVINGSHB4335C(III) AND SGF588G on 8/8/2019  
**Attachments:** 2019\_08\_14\_14\_40\_16.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SGF588G and let us have your report urgently.

This claim will be handled by Priya,

\*Kindly upload this survey request email to merimen.

Thank You.

*David Pool*

**Motor Claims Department**  
**India International Insurance Pte Ltd**  
64 Cecil Street #04-02 IOB Building  
Singapore 049711  
Tel: 6347 6100 Ext 202 Fax: 6224 4174  
**S&P 'A-' rated Company**



*p. Shu shan*

*T: 2.12 pm*

*V Dat*

*E: ✓*

---

**From:** Darren [mailto:claims@teamworkgarage.com]  
**Sent:** Friday, 16 August, 2019 11:00 AM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** RE: OUR REF : 1908-20 // YOUR REF : SHB4335C ACCIDENT INVOLVINGSHB4335C(III) AND SGF588G on 8/8/2019

Hi David,

Please appoint LKK.

Also can I check the liability for this case?

Darren  
Teamwork Garage Pte Ltd  
53 Ubi Avenue 1  
#01-24 Paya Ubi Industrial Park  
Singapore 408934  
Tel: 68442475  
Fax: 68442474

**From:** Motor Claim - III

**Sent:** Wednesday, 14 August 2019 3:08 PM

**To:** TEAMWORK

**Subject:** RE: OUR REF : 1908-20 // YOUR REF : SHB4335C ACCIDENT INVOLVING SHB4335C(III) AND SGF588G on 8/8/2019

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Daniel Pooi*

**Motor Claims Department  
India International Insurance Pte Ltd**

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 202 Fax: 6224 4174

**S&P 'A-' rated Company**



---

**From:** TEAMWORK [mailto:claims@teamworkgarage.com]

**Sent:** Wednesday, 14 August, 2019 2:41 PM

**To:** Motor Claim - III <motorclaim@iii.com.sg>

**Cc:** TEAMWORK <claims@teamworkgarage.com>

**Subject:** OUR REF : 1908-20 // YOUR REF : SHB4335C ACCIDENT INVOLVING SHB4335C AND SGF588G

WITHOUT PREJUDICE

OUR REF : 1908-20

YOUR REF : SHB4335C

Dear Sir / Madam,

PRE-REPAIR INSPECTION FOR SGF588G

ACCIDENT INVOLVING SHB4335C AND SGF588G ON 08.08.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regards,

*Shu Shan*

Teamwork Garage Pte Ltd  
Blk 53 Ubi Avenue 1  
#01-24  
Paya Ubi Industrial Park  
Singapore 408934  
Tel: 6844 2475  
Fax: 6844 2474

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



# Chassis Measurement Chart

Subsidiary/Branch-Company no.

Customer:

C&Y AUTO PTE LTD

TEAM WORK

53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK  
S'PORE 408934

Vehicle ident. no.

Repair order no.

Measurement made: Name *My*

Date:

20/08/2019

Reg. N.

First registration:

Type

Mileage: Km/miles

SGF 588 G

1908-20

TOYOTA ALTIS ZRE17 2013 - .... (64548)

km

Complaint or reason for measurement

Tyres: make		Description	Mileage: Km/miles			
			front LH	front RH	rear LH	rear RH
Pressure measured (cold) bar/psi/kPa			2.3	2.3	2.3	2.3
	external					
	centre					
	internal					
			Before correction			After correction
Vehicle level						
Camber +/- (°)	LH		-01.53°	-01.48° / +00.50° -00.50°		-01.53°
	RH		-01.68°	-01.48° / +00.50° -00.50°		-01.68°
REAR AXLE		total	+00.03° *	+00.48° / +00.40° -00.40°		+00.03° *
Toe +/- (°)	LH		+00.43°	+00.24° / +00.20° -00.20°		+00.43°
	RH		-00.40° *	+00.24° / +00.20° -00.20°		-00.40° *
Thrust angle			+00.41°			+00.41°
Camber +/- (°)	LH		-00.74°	-00.58° / +00.75° -00.75°		-00.73°
	RH		-03.07° *	-00.58° / +00.75° -00.75°		-03.05° *
Caster (°)	LH			+02.95° / +00.75° -00.75°		
	RH			+02.95° / +00.75° -00.75°		
FRONT AXLE		Lh steering lock lh wheel 20°				
		Rh steering lock rh wheel 20°				
Set Back			-00.22°			-00.21°
		total	+00.57° *	+00.00° / +00.32° -00.32°		+00.55° *
Toe +/- (°)	LH		-00.09°	+00.00° / +00.16° -00.16°		-00.10°
	RH		+00.66° *	+00.00° / +00.16° -00.16°		+00.65° *
Maximum steering angle on wheel side on inside of bend (°)	LH					
	RH					

check only & print Alignment result - \$30



# Chassis Measurement Chart

Subsidiary/Branch-Company no. <b>C&amp;Y AUTO PTE LTD</b>		Customer: <b>TEAM WORK</b>	
53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK S'PORE 408934		Vehicle ident. no.	Repair order no.
Reg. N: <b>SGF 588 G</b>		Measurement made: Name	Date: <b>20/08/2019</b>
First registration: <b>1908-20</b>	Type: <b>TOYOTA ALTIS ZRE17</b>	Mileage: Km/miles	<b>2013 - .... (64548)</b> <b>km</b>

Complaint or reason for measurement

Tyres: make	Description	Mileage: Km/miles	
		front LH	front RH
		rear LH	rear RH
Pressure measured (cold) bar/psi/kPa		2.3	2.3
	external		
Tread depth (mm)	centre		
	internal		
	<b>Before correction</b>		<b>After correction</b>
Vehicle level			
Camber +/- (°)	LH	-01.53°	-01.48° / +00.50° -00.50°
	RH	-01.68°	-01.48° / +00.50° -00.50°
<b>REAR AXLE</b>	total	+00.03° *	+00.48° / +00.40° -00.40°
Toe +/- (°)	LH	+00.43°	+00.24° / +00.20° -00.20°
	RH	-00.40° *	+00.24° / +00.20° -00.20°
Thrust angle		+00.41°	+00.41°
Camber +/- (°)	LH	-00.74°	-00.58° / +00.75° -00.75°
	RH	-03.07° *	-00.58° / +00.75° -00.75°
Caster (°)	LH		+02.95° / +00.75° -00.75°
	RH		+02.95° / +00.75° -00.75°
<b>FRONT AXLE</b>	Lh steering lock lh wheel 20°		
	Rh steering lock rh wheel 20°		
Set Back		-00.22°	-00.21°
	total	+00.57° *	+00.00° / +00.32° -00.32°
Toe +/- (°)	LH	-00.09°	+00.00° / +00.16° -00.16°
	RH	+00.66° *	+00.00° / +00.16° -00.16°
Maximum steering angle on wheel side on inside of bend (°)	LH		
	RH		



# Chassis Measurement Chart

Subsidiary/Branch-Company no. <b>C&amp;Y AUTO PTE LTD</b> 53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK S'PORE 408934		Customer: <b>TEAM WORK</b>	
Reg. N: <b>SGF 588 G</b>		First registration: <b>1908-20.</b>	Type: <b>TOYOTA ALTIS ZRE17 2013 - .... (64548)</b>
Complaint or reason for measurement		Vehicle Ident. no.	Repair order no.
		Measurement made Name	Date: <b>23/08/2019</b>
			Mileage Km/miles: <b>km</b>

Tyres make	Description	Mileage: Km/miles	
		front LH	front RH
		rear LH	rear RH
Pressure measured (cold) bar/psi/kPa		2.3	2.3
	external		
Tread depth (mm)	centre		
	internal		
		Before correction	After correction
Vehicle level			
Camber +/- (°)	LH	-01.44°	-01.48°/ +00.50°-00.50°
	RH	-01.83°	-01.48°/ +00.50°-00.50°
<b>REAR AXLE</b>	total	+00.04° *	+00.48°/ +00.40°-00.40°
Toe +/- (°)	LH	+00.43°	+00.24°/ +00.20°-00.20°
	RH	-00.39° *	+00.24°/ +00.20°-00.20°
Thrust angle		+00.41°	+00.41°
Camber +/- (°)	LH	-00.60°	-00.58°/ +00.75°-00.75°
	RH	-01.25°	-00.58°/ +00.75°-00.75°
Caster (°)	LH		+02.95°/ +00.75°-00.75°
	RH		+02.95°/ +00.75°-00.75°
<b>FRONT AXLE</b>	Lh steering lock lh wheel 20°		
	Rh steering lock rh wheel 20°		
Set Back		-00.14°	-00.14°
Toe +/- (°)	total	-00.28°	+00.00°/ +00.32°-00.32°
	LH	-00.16°	+00.00°/ +00.16°-00.16°
	RH	-00.12°	+00.00°/ +00.16°-00.16°
Maximum steering angle on wheel side on inside of bend (°)	LH		
	RH		

Adjust front wheel Alignment **\$30**  
 \* second adjust report  
 after change low the front R/H



# Chassis Measurement Chart

Subsidiary/Branch-Company no		Customer	
C&Y AUTO PTE LTD		TEAM WORK	
53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK			
S'PORE 408934			
Vehicle ident. no.		Repair order no.	
Measurement made Name		Date:	
		23/08/2019	
Reg N:	First registration:	Type	Mileage Km/miles
SGF 588 G	1908-20	TOYOTA ALTIS ZRE17 2013 - .... (64548)	km
Complaint or reason for measurement			

Tyres: make Description Mileage: Km/miles

		front LH	front RH	rear LH	rear RH
Pressure measured (cold) bar/psi/kPa		2.3	2.3	2.3	2.3
	external				
Tread depth (mm)					
	centre				
	internal				
		Before correction		After correction	
Vehicle level					
REAR AXLE	Camber +/- (°)	LH	-01.44°	-01.48°/ +00.50°-00.50°	-01.44°
		RH	-01.83°	-01.48°/ +00.50°-00.50°	-01.83°
		total	+00.04° *	+00.48°/ +00.40°-00.40°	+00.04° *
	Toe +/- (°)	LH	+00.43°	+00.24°/ +00.20°-00.20°	+00.43°
		RH	-00.39° *	+00.24°/ +00.20°-00.20°	-00.39° *
	Thrust angle		+00.41°		+00.41°
FRONT AXLE	Camber +/- (°)	LH	-00.60°	-00.58°/ +00.75°-00.75°	-00.60°
		RH	-01.25°	-00.58°/ +00.75°-00.75°	-01.25°
		LH		+02.95°/ +00.75°-00.75°	
		RH		+02.95°/ +00.75°-00.75°	
	Lh steering lock lh wheel 20°				
	Rh steering lock rh wheel 20°				
	Set Back		-00.14°		-00.14°
		total	-00.28°	+00.00°/ +00.32°-00.32°	-00.28°
	Toe +/- (°)	LH	-00.16°	+00.00°/ +00.16°-00.16°	-00.16°
		RH	-00.12°	+00.00°/ +00.16°-00.16°	-00.12°
	Maximum steering angle on wheel side on inside of bend (°)	LH			
		RH			

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Aug 2019 18:58	<b>Clim Dtl Modified</b>	Claimant's Name: -> ONE2RENT CARS PTE LTD, Claimant's ID: -> 201306179N.	[A] HOW MEI KWAN
2	16 Aug 2019 18:58	<b>Clim Veh Model Changed</b>	(204463) TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A).	[A] HOW MEI KWAN
3	16 Aug 2019 18:58	<b>Clim Created</b>	Reg No: SGF588G, Acct Date: 2019/08/08, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Teamwork Garage Pte Ltd (HQ)	[A] HOW MEI KWAN
4	16 Aug 2019 18:58	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	16 Aug 2019 18:58	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/08/27	[A] HOW MEI KWAN
6	16 Aug 2019 18:58	<b>Adj Mandate Set</b>	Approved;0.00,Reinsp:Adj decides.	[A] HOW MEI KWAN
7	16 Aug 2019 18:58	<b>Label Added</b>	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	16 Aug 2019 18:58	<b>Adj Adjuster Assigned</b>	[None] -> BRYAN TANI	[A] HOW MEI KWAN
9	21 Aug 2019 17:06	<b>Adj Adjuster Assigned</b>	BRYAN TANI -> Lim Teow Guan	[A] HOW MEI KWAN
10	21 Aug 2019 17:06	<b>Clim Dtl Modified</b>	Insured Name: -> COMFORT TRANSPORTATION PTE LTD, Insured ID: -> 199303821R.	[A] HOW MEI KWAN
11	28 Aug 2019 10:13	<b>Adj Mandate Request</b>	Cur.Req:0.00:PODS Liability: TBA Remarks: Kindly provide insured video for our necessary action.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2250482	20/08/2019 10:37	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SGF588G	SHB4335C	11.77

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Aug 2019 18:58	<b>Cim Dtl Modified</b>	Claimant's Name: -> ONE2RENT CARS PTE LTD. Claimant's ID: -> 201306179N.	[A] HOW MEI KWAN
2	16 Aug 2019 18:58	<b>Cim Veh Model Changed</b>	(204463) TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A).	[A] HOW MEI KWAN
3	16 Aug 2019 18:58	<b>Cim Created</b>	Reg No: SGF588G. Acct Date: 2019/08/08. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Work shop: Teamwork Garage Pte Ltd (HQ)	[A] HOW MEI KWAN
4	16 Aug 2019 18:58	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	16 Aug 2019 18:58	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/08/27	[A] HOW MEI KWAN
6	16 Aug 2019 18:58	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	16 Aug 2019 18:58	<b>Label Added</b>	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	16 Aug 2019 18:58	<b>Adj Adjuster Assigned</b>	[None] -> BRYAN TANI	[A] HOW MEI KWAN
9	21 Aug 2019 17:06	<b>Adj Adjuster Assigned</b>	BRYAN TANI -> Lim Teow Guan	[A] HOW MEI KWAN
10	21 Aug 2019 17:06	<b>Cim Dtl Modified</b>	Insured Name: -> COMFORT TRANSPORTATION PTE LTD, Insured ID: -> 199303821R.	[A] HOW MEI KWAN
11	28 Aug 2019 10:13	<b>Adj Mandate Request</b>	Cur.Req:0.00:PODS Liability: TBA Remarks: Kindly provide insured video for our necessary action.	[A] CHEW HSIAO TONG
12	28 Aug 2019 11:16	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/08/27, Mandate Remarks: Video uploaded into merimen	[I] Priya
13	28 Aug 2019 11:16	<b>Adj Mandate Set</b>	Maintained:Video uploaded into merimen	[I] Priya
14	04 Sep 2019 14:18	<b>Video Downloaded</b>	Downloaded Video - Accident	[A] CHEW HSIAO TONG
15	23 Sep 2019 07:41	<b>Adj Mandate Request</b>	Cur.Req:0.00:PCDS Liability: 100% Remark: Third party was driving straight while our insured driver was making a turn	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None

Go

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Ac. Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2250482	20 Aug 2019 10:37:56	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SGF588G	SHB4335C	11.77
2260413	28 Aug 2019 11:15:56	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SGF588G	Priya	xx.xx

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	179N
Vehicle Details	
Vehicle No.:	SGF588G
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1ZRX560814
Chassis No.:	MR053REH104548436
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,982.00
Original Registration Date:	02 Jun 2016
First Registration Date:	02 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$17,982.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jun 2026
PARF Rebate Amount:	\$13,486.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,000.00
COE Rebate Amount:	\$29,302.00
<b>Total Rebate Amount:</b>	<b>\$42,788.00</b>

The information contained herein is correct as at 08 Aug 2019

OK

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Aug 2019 18:58	<b>Cim Dtl Modified</b>	Claimant's Name: -> ONE2RENT CARS PTE LTD, Claimant's ID: -> 201306179N.	[A] HOW MEI KWAN
2	16 Aug 2019 18:58	<b>Cim Veh Model Changed</b>	(204463) TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A).	[A] HOW MEI KWAN
3	16 Aug 2019 18:58	<b>Cim Created</b>	Reg No: SGF588G, Acct Date: 2019/08/08, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Teamwork Garage Pte Ltd (HQ)	[A] HOW MEI KWAN
4	16 Aug 2019 18:58	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	16 Aug 2019 18:58	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/08/27	[A] HOW MEI KWAN
6	16 Aug 2019 18:58	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	16 Aug 2019 18:58	<b>Label Added</b>	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	16 Aug 2019 18:58	<b>Adj Adjuster Assigned</b>	[None] -> BRYAN TANI	[A] HOW MEI KWAN
9	21 Aug 2019 17:06	<b>Adj Adjuster Assigned</b>	BRYAN TANI -> Lim Teow Guan	[A] HOW MEI KWAN
10	21 Aug 2019 17:06	<b>Cim Dtl Modified</b>	Insured Name: -> COMFORT TRANSPORTATION PTE LTD, Insured ID: -> 199303821R.	[A] HOW MEI KWAN
11	28 Aug 2019 10:13	<b>Adj Mandate Request</b>	Cur.Reg:0.00:PODS Liability: TBA Remarks: Kindly provide insured video for our necessary action.	[A] CHEW HSIAO TONG
12	28 Aug 2019 11:16	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/08/27, Mandate Remarks: Video uploaded into merimen	[I] Priya
13	28 Aug 2019 11:16	<b>Adj Mandate Set</b>	Maintained:Video uploaded into merimen	[I] Priya
14	04 Sep 2019 14:18	<b>Video Downloaded</b>	Downloaded Video - Accident	[A] CHEW HSIAO TONG
15	23 Sep 2019 07:41	<b>Adj Mandate Request</b>	Cur.Reg:0.00:PODS Liability: 100% Remark: Third party was driving straight while our insured driver was making a turn	[A] CHEW HSIAO TONG
16	23 Sep 2019 09:44	<b>Video Downloaded</b>	Downloaded Video - Accident	[I] Priya
17	23 Sep 2019 09:52	<b>Adj Mandate Set</b>	Approved:0.00.	[I] Priya
18	03 Oct 2019 17:13	<b>Adj Rpt Initiated</b>		[A] JOANNE LEE KHANG MIN
19	03 Oct 2019 17:13	<b>Cim Dtl Modified</b>	JPJ Reg. Date: -> 2016/06/02.	[A] JOANNE LEE KHANG MIN
20	03 Oct 2019 17:13	<b>Cim Details Notified</b>		[A] JOANNE LEE KHANG MIN
21	05 Oct 2019 09:45	<b>Adj Adjuster Assigned</b>	Lim Teow Guan -> LEE HOCK ANN	[A] CHEW HSIAO TONG

 **AUDIT TRAIL**

No.	On	Audit	Remarks	By
22	05 Oct 2019 09:49	Adj Mandate Request	Cur.Req:4106.95;PODS Liability: 100% *Quantum: (a)CORw/GST: \$3,370.50 + (b)LOR (7days x \$100.00): \$700.00 + (c)LTA/GIA search fee: \$36.45 = Total: \$4,106.95 *Vehicle Model: Toyota Corolla Altis (1598cc) *5 recommendation repair days + 1Sunday + 1p	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None

Go

**ACTIVITY**

No record

**Merimen Billing for this case - Transaction History**

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2250482	20 Aug 2019 10:37:56	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SGF588G	SHB4335C	11.77
2260413	28 Aug 2019 11:15:56	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SGF588G	Priya	xx.xx
2301802	03 Oct 2019 17:13:41	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGF588G	SHB4335C	11.77

# Print Received Message

This mail is associated with :

**\*SGF588G (MCT19080181)  
[SHB4335C]**

TP

ONE2RENT CARS PTE LTD

Aug 8 2019 2:00PM

[COMFORT TRANSPORTATION PTE LTD]

Teamwork Garage Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 07/10/2019 16:30 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$4106.95) - SGF588G - Claim Handler: Priya

Approved:4106.95.

## Hsiao Tong (LKKAuto)

---

**From:** TEAMWORK <claims@teamworkgarage.com>  
**Sent:** Saturday, 19 October 2019 10:02 AM  
**To:** Hsiao Tong (LKKAuto)  
**Cc:** TEAMWORK  
**Subject:** RE: <OFFER> Your Ref: 1908-20 (SGF588G) Our Ref: CC4/III19014331/Hpa3[ACCIDENT INVOLVING SHB 4335C(III) AND SGF 588G ON 08/08/2019]

Dear Hsiao Tong,

We refer to the offer below, it is acceptable.

Please let us have the DV soonest.

Thank you and have a nice day.

Regards,

*Shu Shan*

Teamwork Garage Pte Ltd  
Blk 53 Ubi Avenue 1  
#01-24  
Paya Ubi Industrial Park  
Singapore 408934  
Tel: 6844 2475  
Fax: 6844 2474

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Saturday, 19 October 2019 9:20 AM  
**To:** 'claims' (claims@teamworkgarage.com)  
**Subject:** <OFFER> Your Ref: 1908-20 (SGF588G) Our Ref: CC4/III19014331/Hpa3[ACCIDENT INVOLVING SHB 4335C(III) AND SGF 588G ON 08/08/2019]

Your Ref: **1908-20 (SGF588G)**  
Our Ref: CC4/III19014331/Hpa3

**Without Prejudice**

Dear Sirs/Mdm,

**ACCIDENT INVOLVING SHB 4335C(III) AND SGF 588G ON 08/08/2019**

We refer to the above matter.

We propose settlement at a global sum of **\$4,000.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**Teamwork Garage Pte Ltd**  
53 Ubi Avenue 1 #01-23/24 Singapore 408934  
Paya Ubi Industrial Park  
Tel: 6844 2475 Fax: 6844 2474  
Email: [claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)  
GST Register No: 201015366H

Hsiao Tong

19<sup>th</sup> September 2019

Our reference: 1908-20

Your reference: SHB4335C

**India International Insurance Pte Ltd**

64 Cecil Street  
#05-00 IOB Building  
Singapore 409711

**Attn: Motor Claims Department**

BY HAND

Dear Sir/ Madam,

Claimant : ONE2RENT CARS PTE  
Address : 70 UBI CRESCENT #01-12 S(408570)

We are instructed by the above named to claim damages against your insured/your insured's driver in connection with a road accident on 08/08/2019 along OUTSIDE CONRAD CENTENNIAL SINGAPORE involving our client's vehicle registration number SGF588G and vehicle registrations number SHB4335C driven by you/your insured's driver at the material time.

The accident was caused by your insured negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

Cost of Repair	:	\$ 3,370.50
Loss of Rental	:	\$ 840.00
LTA search fee	:	\$ 7.49
Purchase 3P GIA Report	:	\$ 29.00
<b>Total</b>	<b>:</b>	<b>\$ 4,246.99</b>

A copy of each of the following supporting documents are enclosed:-

- a) Our client's Accident Report / Police Report;
- b) COE/PARF Certificates;
- c) Owner / Driver's IC & Driving License;
- d) LTA search Invoice;
- e) Purchase 3P GIA Report;
- f) Letter Of Authorisation;
- g) Profoma Invoice;
- h) Rental Agreement & Official Receipt;

The demand herein is in respect of our client's claim for damages pertaining to their motor vehicle and any settlement following or subsequent of this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to personal injuries.

Please send to us an acknowledgement of receipt of this letter with 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim is quantified based on the supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Yours faithfully,



A handwritten signature in black ink, appearing to read "Litas", written over the circular stamp.

Teamwork Garage Pte Ltd

Encl.

# LETTER OF AUTHORIZATION

To III And teamwork garage pte ltd. (Third party insurance & Workshop)

Claimant ONE2RENT CARS PTE LTD

Dear Sirs,

I/We, ONE2RENT CARS PTE LTD owner of vehicle no. SGF5886

hereby authorize my/our repairer, TEAMWORK GARAGE PTE LTD

act as my/our agent and proceed on behalf for me/us with respect to my/our claim for repair costs and/or rental and/or loss of use ("claim") for my/our vehicle no. SGF 5886

to the accident which occurred at/along outside Conrad Centennial Singapore

involving vehicle nos. SHB4335C

I/We hereby irrevocably assign absolutely to you that I/we have authorized and assigned all compensation monies pertaining the above mentioned accident due to me/us to my/our repairer/solicitors TEAMWORK GARAGE PTE LTD. I/We hereby authorize you to forward and release all compensation settlement cheques(s) due to the settlement to my/our repairer/solicitors TEAMWORK GARAGE PTE LTD pertaining to above said accident whom I/we authorized and assigned to collect the said compensation monies.

I/We further acknowledge that any settlement the workshop may reach on my/our behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s concerned.

I/We acknowledge that the Discharge Voucher applies only to my/our property damage and will not affect any of the personal injuries claim(s) involved and/or uninsured losses claim in a later date. Further the settlement terms herein should not be used as an evidence to prejudice to any personal injuries claim(s) involved and/or other uninsured losses claim arising of the subject matter in the action.

Thank you.

Dated this 13 day of 08 (month) 20 19 (year)

Signature of owner vehicle (claimant) [Signature]

Name of owner of vehicle (claimant) ONE2RENT CARS PTE LTD

NRIC Number (claimant) 20130679N





INDIA INTERNATIONAL INSURANCE PTE LTD

Co Reg No: 198703792K | GST Reg No M2-0078006-X  
64 | Cecil Street | #04 | #05 | #06-02 | 10B Building | Singapore 049711  
Office: (65) 63476100 Email: insured@ii.com.sg  
Fax: (65) 62244174 Website: www.ii.com.sg

# EXPRESS SETTLEMENT

## DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT19080181  
Claimant Ref : SGF 588G

We/I, TEAMWORK GARAGE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 4,000.00 (Global Sum) ~~(SGF 588G), SGF 588G~~, vehicle no. SGF 588G that was damaged pursuant to the accident which occurred on 08/08/2019 (date) at OUTSIDE CONDRAD CENTENNIAL SINGAPORE (location) involving vehicle no. SHB 4335C (insured vehicle). This is pursuant to the inspection conducted on 20/08/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ONE2RENT CARS PTE LTD ("the third party claimant") of vehicle no. SGF 588G to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SGF 588G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,000.00 to TEAMWORK GARAGE PTE LTD

Dated this 1 day of 11 2019

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

**TEAMWORK GARAGE PTE LTD**  
No. 53 Ubi Avenue 1, #01-24  
Paya Ubi Industrial Park  
Singapore 408934  
Tel: 6844 2475 Fax: 6844 2474

  
Signed by "the workshop" (with chop)  


WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

  
Signed by appointed Surveyor  
  
**LKK Auto Consultants Pte Ltd**

199607198R

51 Ubi Avenue 1

#01-25 Paya Ubi Ind. Park S(408933)



# K & t Cars

53 Ubi Ave 1 #01-23 Paya Ubi Ind Park Singapore 408934  
Tel: 684 5938 Fax: 6285 5228 Email : kntcars@gmail.com  
Biz Reg. No.: 53208965X

No.: 3204

## OFFICIAL RECEIPT

Date: 19 SEP 2019

Received from Movement Cars pte Ltd

The Sum of Dollars Eight Hundred and forty Dollars only

Being payment of SKU 95326 20/08/2019 - 26/08/2019

\$ 840

Cheque No.: \_\_\_\_\_

K & t Cars  
[Signature]



Authorised Signature

# K & t Cars

53 Ubi Ave 1 #01-23 Paya Ubi Ind Park  
Singapore 408934  
Tel: 6645 5938 Fax: 6285 5228  
Email: kntcars@gmail.com  
Biz Reg. No.: 53208965X

## VEHICLE RENTAL AGREEMENT

NO.: KT-04186

Veh. No.: SKN9532G	Replace Veh. No.: SGF588G
Veh. M / M: toyota Altis	Replace Veh. M / M: toyota Altis

HIRER'S PARTICULAR		<input type="checkbox"/> SAME AS HIRER DRIVER'S PARTICULAR	
Name: Onevent Cars pte Ltd		Name: Mike ng yam seng	
Address:		Address:	
I/C:	D.O.B:	I/C: S13227604	D.O.B: 13/09/1958
Contact:	Pass Date:	Contact: 94314501	Pass Date: 25/06/1979

	A - ACCIDENT	Hirer's acceptance
	C - CRACKED	
	D - DENTS	Driver's acceptance
	S - SCRATCHES	

RENTAL DETAILS					
Mileage Out		REMARKS	Mileage In		REMARKS
Date Out	20/08/2019		Date In	26/08/2019	
Time Out			Time In		
ASSIGNED BY			CHECKED BY		

RENTAL CHARGES				PETROL / DIESEL LEVEL					
Daily	@ \$	120	7 Days @ \$ 840	OUT	E	¼	½	¾	F
Weekly	@ \$		Wks @ \$						
Monthly	@ \$		Mth @ \$	IN	E	¼	½	¾	F
Hours	@ \$		Hrs @ \$						
*Inclusive of additional charges (if any)			Amt payable* \$ 840	Petrol Charges	YES	NO	AMT: _____		
				CDW	YES	NO	AMT: _____		
Payment: <input type="checkbox"/> CASH <input type="checkbox"/> NETS <input type="checkbox"/> CHQ <input type="checkbox"/> VISA <input type="checkbox"/> MAST				Security Deposit	YES	NO	AMT: _____		
Bank / Cheque No.:				Advance Payment	YES	NO	AMT: _____		

I/We have read and agree to the terms and conditions stated on this page and overleaf. I/We am/are also aware that should there be any parking and/or traffic offence committed during the leasing period when the vehicle is in my/our possession, we will be billed accordingly. Subsequently, our personal details may be tender accordingly to the government parking and/or traffic offence department. With us undersigning below, I/We am/are sure that all information I/We have given to K & t CARS in connection with this agreement are true and accurate.

**IMPORTANT INFORMATION** (To be go through by the personnel of K & t CARS to the hirer and/or driver upon leasing of vehicle)

- Only persons above 26 and below 60 years of age with 2 years driving experience, authorised, licensed and signing this agreement may drive the vehicle.
- Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the company K & t CARS.
- Use of the vehicle illegal purpose such as in connection with theft, drug peddling or trafficking, smuggling is strictly prohibited.
- Additional drivers are required to register with us before they are allowed to drive the vehicle. Otherwise, he/she will not be protected by the insurance cover.
- The hirer shall be liable for excess charges for any late return of the rate shown per hour or on a per day basis.
- In case of any accident, the hirer MUST report to K & t CARS immediately regardless of the seriousness of the impact occurred. If there are bodily injuries, a police report MUST be made within the next 24 hours.
- In view of all accident, the hirer will bear the full responsibility for the SGD\$3,500/- excess payable to K & t CARS and also the first SGD\$3,500/- excess for damaged to the third party vehicle.

ACKNOWLEDGEMENT	
 Signature of hirer / driver (company stamp if any)	 Eor and on behalf of K & t CARS (authorised signature only)

Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 13 Aug 2019 / 18:31:25

Receipt Date/Time : 13 Aug 2019 / 18:31:24

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190813-002797

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
<b>Result of Insurance Enquiry - SHB4335C</b>				
As at 08 Aug 2019/14:15:00				
Insurance Co: INDIA INTL INS PTE LTD				
1	Insurance Enquiry - SHB4335C Enquiry Fee 20190813175134947593	7.00	0.49	7.49
<b>Sub-Total</b>		<b>7.00</b>	<b>0.49</b>	<b>7.49</b>
<b>Result of Insurance Enquiry - SHB271D</b>				
As at 11 Aug 2019/18:00:00				
Insurance Co: MS FIRST CAPITAL INSURANCE LIMITED				
2	Insurance Enquiry - SHB271D Enquiry Fee 20190813175134985258	7.00	0.49	7.49
<b>Sub-Total</b>		<b>7.00</b>	<b>0.49</b>	<b>7.49</b>
<b>Result of Insurance Enquiry - SGD8185T</b>				
As at 11 Aug 2019/12:05:00				
Insurance Co: NTUC INCOME INS CO-OP LTD				
3	Insurance Enquiry - SGD8185T Enquiry Fee 20190813175135013423	7.00	0.49	7.49
<b>Sub-Total</b>		<b>7.00</b>	<b>0.49</b>	<b>7.49</b>
<b>Total Before Rounding</b>		<b>21.00</b>	<b>1.47</b>	<b>22.47</b>
<b>Rounding Difference</b>				<b>0.02</b>
<b>Total Amount Payable</b>				<b>22.45</b>
Paid By				
		xxxxxxxxxxxx5880	Credit Card: Visa /MasterCard	22.45
<b>Total</b>				<b>22.45</b>
<b>Cash Change</b>				<b>0.00</b>
<b>Tendered Amount</b>				<b>22.45</b>
<b>Excess Refundable Amount</b>				<b>0.00</b>

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-19-131180  
Date of Request: 14/08/2019

Your Ref No: WALK IN SEAH

TEAMWORK GARAGE PTE LTD  
53 UBI AVE 1 #01-24, PAYA UBI INDUSTRIAL PARK  
SINGAPORE 408934

Dear Sir/Madam,

Your Vehicle No: SGF588G  
Date of Accident: 08/08/2019  
Place of Accident: CONRAD CENTENNIAL  
Involving Vehicle No: SHB4335C

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

GIRO  Cash  Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-19-131181

Date of Request: 14/08/2019

Your Ref No: WALK IN SEAH

TEAMWORK GARAGE PTE LTD  
53 UBI AVE 1 #01-24, PAYA UBI INDUSTRIAL PARK  
SINGAPORE 408934

Dear Sir/Madam,

Date of Accident: 08/08/2019

Vehicle No: SGF588G

Place of Accident: OUTSIDE CONRAD CENTENNIAL SINGAPORE

Involving Vehicle No: SHB4335C

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHB4335C	OUTSIDE CONRAD CENTENNIAL SINGAPORE	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Aug 2019 <a href="#">Edit Reg</a>		16 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$3,150.00</b> <a href="#">Edit Estimates</a>	<b>\$3,150.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Main Claimant:	<b>ONE2RENT CARS PTE LTD</b> , Co. Reg. No.: 201306179N								
Vehicle Reg. No.:	<b>SGF588G</b>	Date of Loss:	08/08/2019 14:00 - :59 [38 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MCT19080181</b>	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	<b>SHB4335C</b>	Policy No. (Claimant):	5108639457						
		Excess:							
Repairer:	<b>Teamwork Garage Pte Ltd (HQ)</b> 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Priya</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... [Final Rpt due 27/08/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>• III_SG (07/10/2019): Alert - Adj Mandate Approved (\$4106.95) - SGF588G - Claim Handler: Priya</li> <li>• III_SG (23/09/2019): Alert - Adj Mandate Approved (\$0.00) - SGF588G - Claim Handler: Priya</li> <li>• III_SG (28/08/2019): Alert - Adj Mandate Maintained - SGF588G - Claim Handler: Priya</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGF588G (MCT19080181)  
 [SHB4335C]  
 TP  
 ONE2RENT CARS PTE LTD  
 Aug 8 2019 2:00PM  
 [COMFORT TRANSPORTATION PTE LTD]  
 Teamwork Garage Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View
									View in Browser
<b>Video</b>									1 per page
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail	Print	<input checked="" type="checkbox"/>
1	28/08/19 11:15	Video - Accident					Load MP4		
<b>Photos/Images</b>									3 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	<input checked="" type="checkbox"/>
1	21/08/19 14:21	Chassis Number					Load JPG		<input checked="" type="checkbox"/>
2	21/08/19 14:21	Odometer Reading					Load JPG		<input checked="" type="checkbox"/>
3	21/08/19 14:23	General View					Load JPG		<input checked="" type="checkbox"/>
4	21/08/19 14:23	General View					Load JPG		<input checked="" type="checkbox"/>
5	21/08/19 14:23	General View					Load JPG		<input checked="" type="checkbox"/>
6	21/08/19 14:23	General View					Load JPG		<input checked="" type="checkbox"/>
7	21/08/19 14:23	General View					Load JPG		<input checked="" type="checkbox"/>
8	21/08/19 14:23	General View					Load JPG		<input checked="" type="checkbox"/>
9	21/08/19 14:23	General View					Load JPG		<input checked="" type="checkbox"/>
10	21/08/19 14:23	General View					Load JPG		<input checked="" type="checkbox"/>
11	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
12	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
13	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
14	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
15	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
16	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
17	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
18	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
19	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
20	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
21	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
22	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
23	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
24	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
25	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
26	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
27	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
28	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
29	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
30	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
31	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
32	21/08/19 14:24	General View					Load JPG		<input checked="" type="checkbox"/>
33	21/08/19 14:25	General View					Load JPG		<input checked="" type="checkbox"/>
34	21/08/19 14:25	General View					Load JPG		<input checked="" type="checkbox"/>
35	21/08/19 14:25	General View					Load JPG		<input checked="" type="checkbox"/>
36	21/08/19 14:25	General View					Load JPG		<input checked="" type="checkbox"/>
37	21/08/19 14:25	General View					Load JPG		<input checked="" type="checkbox"/>
38	21/08/19 14:25	General View					Load JPG		<input checked="" type="checkbox"/>
39	21/08/19 14:25	General View					Load JPG		<input checked="" type="checkbox"/>
40	21/08/19 14:25	General View					Load JPG		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
52	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
53	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
54	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
55	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
56	21/08/19 14:25	General View	 Load JPG	<input checked="" type="checkbox"/>
57	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
58	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
59	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
60	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
61	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
62	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
63	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
64	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
65	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
66	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
67	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
68	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
69	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
70	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
71	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
72	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
73	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
74	21/08/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
75	21/08/19 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
76	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	22/08/19 11:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	22/08/19 11:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	22/08/19 11:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	22/08/19 11:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	22/08/19 11:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	22/08/19 11:32	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
96	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
97	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
98	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
99	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
100	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
101	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
102	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
103	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
104	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
105	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
106	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
107	22/08/19 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
108	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
109	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
110	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
111	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
112	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
113	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
114	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
115	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
116	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
117	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
118	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
119	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
120	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
121	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
122	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
123	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
124	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
125	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
126	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
127	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
128	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
129	22/08/19 11:34	Reinspection Photo		<input checked="" type="checkbox"/>
130	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
131	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
132	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
133	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
134	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
135	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
136	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
137	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
138	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
139	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
140	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
141	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
142	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
143	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
144	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
145	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
146	04/09/19 13:18	After Repair Photo		<input checked="" type="checkbox"/>
147	10/09/19 19:02	After Repair Photo		<input checked="" type="checkbox"/>
148	10/09/19 19:02	After Repair Photo		<input checked="" type="checkbox"/>
149	10/09/19 19:02	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	16/08/19 18:59	EMAIL FROM III DD 16.8.19		Load PDF
2	16/08/19 18:59	TP GIA REPORT		Load PDF
3	22/08/19 08:58	TP ESTIMATE - MARKED		Load PDF
4	05/10/19 09:47	TP LOD		Load PDF
5	05/10/19 09:47	RENTAL RECEIPT & AGREEMENT		Load PDF
6	05/10/19 09:47	LTA SEARCH FEE		Load PDF
7	05/10/19 09:47	GIA RPT SEARCH FEE		Load PDF
8	04/11/19 10:17	WORKSHOP INVOICE		Load PDF
9	04/11/19 10:17	AUTHORISATION TO ACT FORM		Load PDF
10	04/11/19 10:17	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	20/08/19 10:37	Singapore Accident Statement IV SHB433SC		Load PDF

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19014331/HPA3Q2

Date: 04/11/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No : SGF588G Insured Vehicle No : SHB4335C  
 Date of Loss: 08/08/2019 Nature of Claim: TP Claim No: MCT19080181

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SGF588G**  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZR560814  
 Reg. Date: 02/06/2016 (Man. Year: 2016) Chassis No: MR053REH104548436  
 Colour: Pearl White Odometer: 265895 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Continental 4 mm Rear Left Side: Pirelli 4 mm  
 Front Right Side: Continental 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	9,423.90	2,444.65	6,979.25	74.06	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,350.00	1,490.00	860.00	36.60	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>11,773.90</b>	<b>3,934.65</b>	<b>7,839.25</b>	<b>66.58</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>3,150.00</b>			
	(S\$)	11,773.90	3,150.00	8,623.90	73.25
<b>+ GST 7.00/7.00% (S\$)</b>	824.17	220.50	603.67	73.25	
<b>Nett Amount (S\$)</b>	<b>12,598.07</b>	<b>3,370.50</b>	<b>9,227.57</b>	<b>73.25</b>	
<b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b>		600.00			
<b>+ Doc/Search Fee (S\$)</b>		36.45			
<b>Nett Liability (S\$)</b>		<b>4,006.95</b>			
<b>Global Sum Settlement (S\$)</b>		<b>4,000.00</b>			

## INSPECTION

Date of Assignment: 16/08/2019  
 Date Inspected: 20/08/2019 Inspected At: Teamwork Garage Pte Ltd (HQ)  
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park  
 Singapore 408934

Estimated Period of Repair: 5.0 days

---

**Adjuster:** LEE HOCK ANN

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference	
Part Source:	MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2019)
Parts:	143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGF588G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	582.00 FL	*458.00 FL
2	1		*FRONT BUMPER BRACKET	Serviceable	182.40 FL	*- FL
3	1		*FRONT BUMPER RETAINER	Dented	204.00 FL	*110.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	458.20 FL	*361.00 FL
5	1		*FRONT BUMPER LOWER GRILLE	Serviceable	186.00 FL	*- FL
6	1		*FRONT GRILLE ASSY	Cracked	678.00 FL	*372.80 FL
7	1		*FRONT FOG LAMP R/H	Cracked	390.00 FL	*244.70 FL
8	1		*FRONT FOG LAMP COVER R/H	Missing	114.00 FL	*114.00 FL
9	1		*FRONT GRILLE EMBLEM	Necessary	81.60 FL	*81.60 FL
10	1		*FRONT BRACE PANEL	Repair	186.00 FL	*- FL
11	1		*FRONT SUPPORT PANEL	Serviceable	1,186.80 FL	*- FL
12	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	78.00 FL	*- FL
13	1		*FRONT RH HEADLAMP	Cracked	2,795.00 FL	*750.00 FL
14	1		*FRONT RH FENDER	Serviceable	937.20 FL	*- FL
15	1		*FRONT RH FENDER EMBLEM	Necessary	89.10 FL	*89.10 FL
16	1		*FRONT FENDER INNER SHIELD	Cracked	240.00 FL	*96.00 FL
17	1		*BONNET	Serviceable	1,244.40 FL	*- FL
18	1		*BONNET INSULATOR	Serviceable	342.00 FL	*- FL
19	1		*BONNET HINGE	Serviceable	180.00 FL	*- FL
20	1		*FRONT RH SHOCK ABSORBER	Serviceable	559.10 FL	*- FL
21	1		*FRONT RH KNUCKLE ARM	Serviceable	501.30 FL	*- FL
22	1		*FRONT RH KNUCKLE ARM BEARING	Serviceable	211.50 FL	*- FL
23	1		*FRONT RH LOWER ARM	Bent	339.60 FL	*275.00 FL
24	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*20.00 FS
25	1		*SET SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	80.00 FS	*- FS
26	1		*SET FRONT GRILLE CLIP	Necessary	80.00 FS	*20.00 FS
27	1		*FRONT BUMPER SPONGE	Cracked	199.20 FL	*79.00 FL
28	1		*WIPER TANK	Dented	319.80 FL	*175.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>12,495.20</b>	<b>3,246.20</b>
- List Item Discount on L Items 25.00/25.00% (S\$)	3,071.30	801.55
<b>Total Parts (S\$)</b>	<b>9,423.90</b>	<b>2,444.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	50.00	20.00
2	CHECK FRONT WHEEL ALIGNMENT	New	200.00	50.00
3	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	600.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	800.00
5	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>2,350.00</b>	<b>1,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >