

ASS. REC. BY: Grant King REF: CS3/MSG19011558/Gyd3-1 Special Instructions: _____
 Surveyor: _____ ASSIGNMENT (Office) _____
 From (Person): _____ of MS14 Date/Time: 16/08/2019
 Estimated Cost: _____ Bill to: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: 4Y19577 Insured: SFC 8325R
 at Workshop n/s: A-TEC AUTOMOTIVE Tel: 6334 5206
 of: 8 KACI BUKIT AVE 4 #04-30
 Policy No: 2909690F Claim No: 592045
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A: 26/6/19
 (Client's Record)
 CA / REV / REP. / REV 24 HRS: 'PR5' H.O.D. Endorsement: _____
 Date/Time: _____ Person Contacted: Peggie Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SFC 8325R NAICT21018739/AN D P MICELAGI
	4Y19577 X
	Disassemble: 2/7/2019

Do Not Finalise

\$7000, 4 days.
 (Red \$5800-00, 89%)
 30/9/19 File to Typist

 21/9/2019

RECEIVED 30 SEP 2019

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Monday, 19 August 2019 1:59 PM
To: Admin-D (LKKAuto)
Cc: Accounts (LKKAuto)
Subject: RE: Report Send Back Alerts - GY1957T (TP)

Dear Nivitha,

FYNA Please...

Pending for Survey Report- CS3/MSG19011558/GCD3E2

18 16 Aug 2019 20:07	Ins Send Back Adj Rpt	Please do paper survey. Thanks.	[1] CRhia Nyuk Pul
19 16 Aug 2019 20:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/20	[1] Merimen Administrator
20 16 Aug 2019 20:07	Adj Mandate Set	Maintained.	[1] Merimen Administrator

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6841 1891 | email: account@lkkauto.com | fax: 6844-8805


Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 16 August 2019 8:20 PM
To: account@lkkauto.com
Subject: Report Send Back Alerts - GY1957T (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,
The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Sent: Monday, 19 August 2019 9:15 AM
To: assignments
Subject: AS.190894.aj. Our ref: 598045 (OIV: SKC8385R) DOA: 26.06.2019

Hi Morning

For your action.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chhia Nyuk Pui [mailto:NyukPui_Chhia@sg.msiga.com]
Sent: Friday, August 16, 2019 8:09 PM
To: SUR <sur@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FW: Your ref: AS.190894.aj. Our ref: 598045 (OIV: SKC8385R) DOA: 26.06.2019

Hi LKK Team

Please do paper survey for us.

TP documents granted in Merimen.

Thanks.

Chhia Nyuk Pui

Senior Executive, Claims Services

Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msiga.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msiga.com.sg | Follow us on  [@MSIG_SG](https://www.facebook.com/MSIG_SG)

A member of  INSURANCE GROUP

From: Chhia Nyuk Pui
Sent: Wednesday, 7 August, 2019 2:30 PM

To: info@chiaarul.com; Roy <roy@chiaarul.com>

Subject: Your ref: AS.190894.aj. Our ref: 598045 (OIV: SKC8385R) DOA: 26.06.2019

Dear Sir/Madam

Without Prejudice
Save as to Costs

We refer to your letter dated 05.08.2019

We are looking into the claim and shall come back to you soon.

Thank you.

Please note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data for the purpose of assessing your claim. This may include disclosing and sharing your personal data with our service providers and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore, for the proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws (collectively, "the Purpose"). We may also need to disclose or share your personal data with service providers who are sited outside Singapore for the Purpose.

Chhia Nyuk Pui
Senior Executive, Claims Services
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on  [@MSIG_SG](https://twitter.com/MSIG_SG)

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



SINCERE APPRAISAL SERVICES PTE LTD Co.Reg no: 201800639R
60 Paya Lebar Road #07-41 Paya Lebar Square Singapore 409051
Tel : 6636 4628 Fax : 6636 4638 E-mail : office@sincereappraisal.com.sg

INVOICE

Gis Healthcare Couriers Pte Ltd
C/O A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier
Singapore 415875

Invoice No: 110719-399
Our ref: 399/TP/2019
Date: 11/7/2019


Claim Type: Third Party	Date of Loss: 26/6/2019
Vehicle Reg No: GY1957T	Claimant: Gis Healthcare Couriers Pte Ltd
Vehicle Make/Model: Toyota Liteace 5 DR	

Description	Amount (SS)
1. Professional Fee (including Transport, 44 Photographs and Miscellaneous charges)	704
Total	704

Singapore Dollar: Seven hundred and four dollars only.

Cheques should be crossed A/C PAYEE and made payable to Sincere Appraisal Services Pte Ltd





SINCERE

APPRAISAL SERVICES PTE LTD

VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 399/TP/2019

Date: 11/7/2019

REFERENCE

Date of loss: 26/6/2019
 Claimant: Gis Healthcare Couriers Pte Ltd

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY1957T	Make &	Toyota
Reg date:	25/1/2005	Model	Liteace 5 DR
Colour:	Silver	Engine No:	3C4007306
Type:	Van	Chassis No:	CR425011110
Type of Claims:	Third Party	Odometer No:	759736km
		Engine Cap:	2184cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition: Good	Steering: Good	Engine Modification: Nil
Paint work: Good	Handbrake: Good	Pre-accident
	Footbrake: Good	Damage: Nil

CONDITION OF TYRES

Front Left Size: Sumitomo 165/R13 70%	Front Right Size: Sumitomo 165/R13 70%
Rear Left Size: Sumitomo 165/R13 70%	Rear Right Size: Sumitomo 165/R13 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS


	Repairer S\$	Adjuster S\$
Parts	S 5,467.50	S 5,467.50
Labour	S 3,210.00	S 2,650.00
Calculated Cost (S\$):	<u>S 8,677.50</u>	<u>S 8,117.50</u>

Recommended Lump Sum Repair Cost (S\$): S 6,500.00

Date of Assignment: 28/6/2019
 Date Inspected: 28/6/2019
 Est. repair Period: 10 days

Inspected At: A-Tec Automotive Pte Ltd
 8 Kaki Bukit Avenue 4
 #04-20 Premier
 Singapore 415875

POINT OF IMPACT



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle along CTE Expressway towards City before Braddell exit.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the rear portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$8,677.50. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$6,500.00.

We have not authorised the repair. Under normal circumstances, estimated **10** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Rear bumper assy	warped/grazed	\$ 660.00	\$ 660.00
2	2	Rear bumper bracket	bent/necessary	\$ 68.00	\$ X 68.00
3	2	Rear bumper reflector	bent/necessary	\$ 66.00	\$ X 66.00
4	1	Rear tailgate assy	dented/bent	\$ 1,283.00	\$ X 1,283.00
5	1	Rear tailgate inner trim board	necessary	\$ 175.00	\$ X 175.00
6	1	Rear tailgate lock mechanism	bent	\$ 117.00	\$ X 117.00
7	1	Rear tailgate lock catch	bent	\$ 47.00	\$ X 47.00
8	1	Rear tailgate weatherstrip	warped	\$ 152.00	\$ X 152.00
9	2	Rear tailgate no plate lamp	necessary	\$ 68.00	\$ X 68.00
10	1	Rear left taillamp	bent/cut	\$ 693.00	\$ X 693.00
11	1	Rear right taillamp	bent/cut	\$ 693.00	\$ X 693.00
12	1	Rear end lower panel	dented	\$ 782.00	\$ X 782.00
13	1	Rear exhaust muffler assy	bent	\$ 1,450.00	\$ X 1,450.00
14	2	Rear exhaust muffler rubber mounting	necessary	\$ 36.00	\$ X 36.00
				\$ 6,290.00	\$ 6,290.00
Less 25%				\$ 1,572.50	\$ 1,572.50
				\$ 4,717.50	\$ 4,717.50

Special Nett Items

1	10	Rear bumper clips	necessary	\$ 50.00	\$ / 50.00
2	10	Rear tailgate inner trim board clips	necessary	\$ 20.00	\$ X 20.00
3	1	Rear tailgate windscreen glass sealant	necessary	\$ 80.00	\$ X 80.00
4	1	Rear tailgate '70km/h' sticker	necessary	\$ 30.00	\$ X 30.00
5	1	Rear tailgate '6 pax' sticker	necessary	\$ 30.00	\$ X 30.00
6	1	Rear tailgate 'liteace' sticker	necessary	\$ 30.00	\$ X 30.00
7	1	Rear tailgate centre logo sticker	necessary	\$ 30.00	\$ X 30.00
8	1	Rear tailgate advertisement sticker	necessary	\$ 30.00	\$ X 30.00
9	2	Rear bumper reverse sensor	malfunction	\$ 250.00	\$ X 250.00
10	1	Rear end lower panel sealant	necessary	\$ 120.00	\$ X 120.00
11	1	Rear no plate	necessary	\$ 80.00	\$ X 80.00
				\$ 750.00	\$ 750.00

Total parts**\$ 5,467.50 \$ 5,467.50**

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,200.00	\$ 1,000.00	300
2	To putty and spray painting rear portion.	\$ 1,200.00	\$ 1,000.00	200
3	To check rear lighting and wiring.	\$ 50.00	\$ 30.00	/
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	\$ 60.00	X N
5	To remove and install rear inner trim to facilitate the repair.	\$ 140.00	\$ 120.00	60
6	To apply anti rust proofing to rear affected area.	\$ 120.00	\$ 100.00	X
7	To remove and install rear exhaust muffler assy.	\$ 100.00	\$ 80.00	X
8	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	\$ 120.00	X
9	To remove and install rear bumper reverse sensor.	\$ 80.00	\$ 60.00	40
10	Towing service.	\$ 100.00	\$ 80.00	X N
Total labour :		\$ 3,210.00	\$ 2,650.00	600

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 5,467.50	\$ 5,467.50
Total labour :	\$ 3,210.00	\$ 2,650.00
Total repair cost :	\$ 8,677.50	\$ 8,117.50

915
20% : 700

Adjusted Repair Cost (Lump Sum Repair)

\$ 6,500.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/06/2019 16:04
Date Of Accident	26/06/2019 12:10
Exact Location Of Accident	CTE TOWARDS CITY (BEFORE BRADDEL EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY1957T
Insured/Policyholder	
Name Of Registered Owner	GIS HEALTHCARE COURIERS PTE LTD
Co Reg No	200306279D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98424312

Vehicle Particulars

Manufacturer	TOYOTA
Model	LITEACE 5DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5106985107 TPFT
Cover Note Number	

Driver

Name of Driver	BALAN KUNJU RAMAN @BALAN S/O KUNJU RAMAN
NRIC No	S2672845B
Date Of Birth	05/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	25/07/1997
Driving Experience	21 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81616545
Fax Number	
Contact Number	

Address	BLK 730 CLEMENTI WEST STREET 2 #05-330
Postcode	120730
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKC8385R
Vehicle Make/Model/Colour	HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN JUN LIN KELVN
NRIC/Passport Number	
Contact Number	88164949
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for compliance with legal requirements under any regulations, laws or court orders.

GIS HEALTHCARE COURIER (PTE) LTD.
BLK 123 BUKIT MERAH JALAN
#03-70 SINGAPORE 150773
Email: courier@yehoo.com

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

LDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415033
Tel: 6741-697 Fax: 6740-305
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

27 JUN 2019

Sketch Plan #2 Pg. 1


SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26 Jun 2019, I was travelling along CTE towards city, before broadell exit. My vehicle was stationary when vehicle B hit the rear of my vehicle.

315 HEALTH CARE COURIERS PTE. LTD.
23 KAKI BUKIT (VAC)
23 KAKI BUKIT LANE 4
SINGAPORE 415933
Email: cover@hcc.com.sg


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

23 KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67415497 Fax: 67492305
Reporting Centre Personnel's Signature
Name: 
Email: 
NRIC/FIN No.:

27 JUN 2019

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/06/2019 10:06
Date Of Accident	26/06/2019 12:00
Exact Location Of Accident	CTE BEFORE BRADDELL EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC8385R
Insured/Policyholder	
Name Of Registered Owner	TAN JUN LUN KEVIN
NRIC No	S8420767E
Email Address	TJL_TAN@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-88164949
Alternative Phone No	Office-88164949

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELENTRA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29096907 QMX
Cover Note Number	

Driver

Name of Driver	TAN JUN LUN KEVIN
NRIC No	S8420767E
Date Of Birth	08/07/1984
Occupation	INDOOR
Date Of Driving Pass	14/02/2003

Driving Experience	16 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88164949
Fax Number	
Contact Number	OFFICE-88164949
EEmail Address	TJL_TAN@YAHOO.COM.SG
Address	338B ANCHORVALE CRESENT #13-59 542338
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY1957T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE

Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	NA NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 27/6/19
10:25am



Driver's Signature
(If driver is not the policyholder)
Date & Time: 27/6/19
10:25am



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068907
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. Z0-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1998 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form H.X.1
Individual Ownership

MOTOR MAX
Comprehensive

Certificate No. A 29096907 QMK

Excess : SGD500
Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SKCB385R

2. Name of Policyholder
Tan Jun Lun Kelvin

3. Effective Date of the Commencement of Insurance for the purposes of the Act
07/10/2018

4. Date of Expiry of Insurance
06/10/2019

5. Persons or Classes of Persons entitled to drive*

Tan Jun Lun Kelvin
Tan Chee Kok
Any other person provided he is driving on the Policyholder's order or with the
Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive
the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any
enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the
Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making
reliability trial speed-testing the carriage of goods other than
samples in connection with any trade or business or use for any
purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter
189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG
AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the
Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a
Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles
(Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles
(Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act
or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

for Chief Executive Officer

DL

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S9420767E**

TAN JUN LUN, KELVIN
(CHEN JUNLUN, KELVIN)

Birth Date: **08 Jul 1984**
Issue Date: **14 Feb 2000**

000001760



DL

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

Class 2 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2000 kilograms

PASS DATE
14 Feb 2002



NRIC



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jun 2019		01 Jul 2019 18:00 Edit Adj Rpt	S\$700.00 Edit Estimates	S\$700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TAN JUN LUN KEVIN, ID: S8420767E, Tel: +6588164949, Email: tj_l_tan@yahoo.com.sg								
Main Claimant:	GIS HEALTHCARE COURIERS PTE LTD, Co. Reg. No.: 200306279D								
Vehicle Reg. No.:	GY1957T	Date of Loss:	26/06/2019 12:00 - :59 [173 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 598045	Policy/Cover Note No.:	29096907 (Comprehensive) Coverage: 07/10/2018 - 06/10/2019						
Vehicle Reg. No. (Insured):	SKC8385R	Policy No. (Claimant):							
		Excess:							
Repairer:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pul - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/08/2019]								
Driver/Custodian (Insured):	TAN JUN LUN KEVIN (34 / Male) , NRIC: S8420767E, Tel: +6588164949 Email: tj_l_tan@yahoo.com.sg								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 28/06/19.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_5G (16/08/2019): Report Send Back Alerts - GY1957T (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GY1957T (598045)**
[SKC8385R]
TP
GIS HEALTHCARE COURIERS PTE LTD
Jun 26 2019 12:00PM
[TAN JUN LUN KEVIN]
A-Tec Automotive Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/07/19 17:02	Accident Statement From: SC - Reg. No: SKC8385R, Claimant: TAN JUN LUN KEVIN		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
2	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
3	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
4	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
5	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
6	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
7	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
8	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
9	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
10	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
11	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
12	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
13	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
14	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
15	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
16	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
17	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
18	08/07/19 14:49	General View		Load JPG <input checked="" type="checkbox"/>
19	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
20	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
21	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
22	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
23	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
24	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
25	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
26	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
27	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
28	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
29	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
30	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
31	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
32	08/07/19 14:49	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
33	08/07/19 14:50	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
34	08/07/19 14:50	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
35	08/07/19 14:50	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
36	08/07/19 14:50	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
37	08/07/19 14:50	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
38	08/07/19 14:50	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
39	08/07/19 14:50	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
40	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
44	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
48	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	08/07/19 14:50	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/07/19 17:03	Third Party Accident Report		
2	02/07/19 08:32	TP disagree on SJE		
3	15/08/19 15:55	TPD GY1957T - SURVEY REPORT & COLOUR PHOTO		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	01/07/19 17:57	Survey Request - Manual Assigned		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/19 09:52	PRS Invoice		
2	01/10/19 10:12	Colour Photo		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19011558/GYD3E2-1
Date: 01/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29096907
Claimant	Insured Vehicle No :	SKC8385R
Vehicle No : GY1957T	Nature of Claim:	TP
Date of Loss: 26/06/2019	Claim No:	598045

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY1957T	Engine No:	3C4007306
Make & Model:	TOYOTA LITEACE, 2.2 5 DR (A)	Chassis No:	CR425011110
Reg. Date:	25/01/2005 (Man. Year: 2004)	Odometer:	759737 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165 R13	Rear Tyre Size:	165 R13
Front Left Side:	Sumitomo 5 mm	Rear Left Side:	Sumitomo 5 mm
Front Right Side:	Sumitomo 5 mm	Rear Right Side:	Sumitomo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,467.50	315.00	5,152.50	94.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	630.00	2,580.00	80.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,677.50	945.00	7,732.50	89.11
Approved Total (Overridden) (S\$)		700.00		
	(S\$)	8,677.50	700.00	7,977.50
	+ GST 7.00/7.00% (S\$)	607.43	49.00	558.43
	Nett Amount (S\$)	9,284.93	749.00	8,535.93

INSPECTION

Date of Assignment:	01/07/2019	
Date Inspected:	01/07/2019 Inspected At:	8 Kaki Bukit Ave 4 #04-20 Repairer : A-Tec Automotive Pte Ltd (Kaki Bukit)
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Oct 2019)	
Parts:	N/A	TOYOTA LITEACE 2.2 5 DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY1957T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Warped / Grazed	660.00 FL	*380.00 FL
2	2		*REAR BUMPER BRACKET (BENT / NECESSARY)	Not Consistent With The Impact	68.00 FL	*- FL
3	2		*REAR BUMPER REFLECTOR (BENT / NECESSARY)	Not Consistent With The Impact	66.00 FL	*- FL
4	1		*REAR TAILGATE ASSY (DENTED / BENT)	Not Consistent With The Impact	1,283.00 FL	*- FL
5	1		*REAR TAILGATE INNER TRIM BOARD (NECESSARY)	Not Consistent With The Impact	175.00 FL	*- FL
6	1		*REAR TAILGATE LOCK MECHANISM (BENT)	Not Consistent With The Impact	117.00 FL	*- FL
7	1		*REAR TAILGATE LOCK CATCH (BENT)	Not Consistent With The Impact	47.00 FL	*- FL
8	1		*REAR TAILGATE WEATHERSTRIP (WARPED)	Not Consistent With The Impact	152.00 FL	*- FL
9	2		*REAR TAILGATE NO PLATE LAMP (NECESSARY)	Not Consistent With The Impact	68.00 FL	*- FL
10	1		*REAR LEFT TAILLAMP (BENT / CUT)	Not Consistent With The Impact	693.00 FL	*- FL
11	1		*REAR RIGHT TAILLAMP (BENT / CUT)	Not Consistent With The Impact	693.00 FL	*- FL
12	1		*REAR END LOWER PANEL (DENTED)	Not Consistent With The Impact	782.00 FL	*- FL
13	1		*REAR EXHAUST MUFFLER ASSY (BENT)	Not Consistent With The Impact	1,450.00 FL	*- FL
14	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING (NECESSARY)	Not Consistent With The Impact	36.00 FL	*- FL
15	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
16	10		*REAR TAILGATE INNER TRIM BOARD CLIPS (NECESSARY)	Not Consistent With The Impact	20.00 FS	*- FS
17	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT (NECESSARY)	Not Consistent With The Impact	80.00 FS	*- FS
18	1		*REAR TAILGATE 70KM/H STICKER (NECESSARY)	Not Consistent With The Impact	30.00 FS	*- FS
19	1		*REAR TAILGATE 6 PAX STICKER (NECESSARY)	Not Consistent With The Impact	30.00 FS	*- FS
20	1		*REAR TAILGATE LITEACE STICKER (NECESSARY)	Not Consistent With The Impact	30.00 FS	*- FS
21	1		*REAR TAILGATE CENTRE LOGO STICKER (NECESSARY)	Not Consistent With The Impact	30.00 FS	*- FS
22	1		*REAR TAILGATE ADVERTISEMENT STICKER (NECESSARY)	Not Consistent With The Impact	30.00 FS	*- FS
23	2		*REAR BUMPER REVERSE SENSOR (MALFUNCTION)	Not Consistent With The Impact	250.00 FS	*- FS
24	1		*REAR END LOWER PANEL SEALANT (NECESSARY)	Not Consistent With The Impact	120.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*REAR NO PLATE (NECESSARY)	Not Consistent With The Impact	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					7,040.00	410.00
- List Item Discount on L Items 25.00/25.00% (\$)					1,572.50	95.00
Total Parts (\$)					5,467.50	315.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,200.00	300.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,200.00	200.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	0.00
5	TO REMOVE AND INSTALL REAR INNER TRIM TO FACILITATE THE REPAIR	New	140.00	60.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	0.00
7	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	100.00	0.00
8	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	0.00
9	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	40.00
10	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (S\$)			3,210.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >