

**Esteem Performance Pte Ltd  
385 Sin Ming Drive, Vicom  
Vehicle Inspection Centre  
(575718)**

**Claim Reference:**  
**Assessment number: 013549**  
**Version: 1810**  
**Date calculated: 16/08/2019 7:28 PM**

**Full Report**  
**Registration: SLN155X**  
**Printed: 16/08/2019 7:29 PM**

---

**Summary Information**

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	AIG Asia Pacific Insurance Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:		Date of Incident:	08/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

<b>Vehicle</b>	
Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLN155X
VIN number:	
Odometer:	

**Esteem Performance Pte Ltd**  
**385 Sin Ming Drive, Vicom**  
**Vehicle Inspection Centre**  
**(575718)**

Claim Reference:  
 Assessment number: 013549  
 Version: 1810  
 Date calculated: 16/08/2019 7:28 PM

Full Report  
 Registration: SLN155X  
 Printed: 16/08/2019 7:29 PM


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
 Date of Inspection:

**Damage Areas**

All   
 Underbody



**Labour**

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R TAILGATE MOULDING		2.0	10.00
760101	R + R REAR SPOILER		5.0	25.00
750171	R + R MANUFACTURER BADGE		5.0	25.00
B420	RENEW REAR BUMPER		12.0	60.00
	INCLUDES: REAR BUMPER AND REQUIRED ATTACHED PARTS R + R			
B410)	R + R REAR BUMPER REINFORCEMENT		1.0	5.00
B407	R + R L/REAR LAMP CPL		4.0	20.00
B407	R + R R/REAR LAMP CPL		4.0	20.00
B450	R + R REAR SEAT CUSHION CPL		2.0	10.00
2711	REAR PANEL REPAIR		30.0*	150.00
2931	BOOTLID/TAILGATE REPAIR		30.0*	150.00

**Esteem Performance Pte Ltd**  
**385 Sin Ming Drive, Vicom**  
**Vehicle Inspection Centre**  
**(575718)**

Claim Reference:  
 Assessment number: 013549  
 Version: 1810  
 Date calculated: 16/08/2019 7:28 PM

Full Report  
 Registration: SLN155X  
 Printed: 16/08/2019 7:29 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	9.50	95.0	475.00
<b>Total of Labour</b>			<b>475.00</b>

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	REAR BUMPER NEW PART PAINT K1R	10.0
	REAR SPOILER NEW PART PAINT K1R	6.0
	REAR PANEL REPAIR PAINTING <50%	10.0
	BOOTLID/TAILGATE REPAIR PAINTING <50%	14.0
	L/R SIDE PANEL SURFACE PAINT	6.0
	R/R SIDE PANEL SURFACE PAINT	6.0

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	39.09
3045	REAR SPOILER NEW PART PAINT K1R	16.40
2711	REAR PANEL REPAIR PAINTING <50%	9.50
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	18.50
3481	L/R SIDE PANEL SURFACE PAINT	9.50
3482	R/R SIDE PANEL SURFACE PAINT	9.50

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	50.00 SGD/h		
Time Paint		52.0	
Preparation Main Work Metal	1.70	17.0	85.00
Preparation Comp. Work Plastic	0.30	3.0	15.00
<b>Total</b>	<b>10 WU/h</b>	<b>72.0</b>	<b>360.00</b>

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	55.49
Repair Painting	28.00
Surface-/Blend Paint	19.00
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	<b>129.59</b>

**Esteem Performance Pte Ltd**  
**385 Sin Ming Drive, Vicom**  
**Vehicle Inspection Centre**  
**(575718)**

Claim Reference:  
 Assessment number: 013549  
 Version: 1810  
 Date calculated: 16/08/2019 7:28 PM

Full Report  
 Registration: SLN155X  
 Printed: 16/08/2019 7:29 PM

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
2583	REAR BUMPER	52159 47913		497.50
2587	REAR COVER BUMPER	52453 47010		582.60
2589	REAR BUMPER COVER	52169 47020		27.50
2621	LEFT RETAINER	90467 09237		112.70
2622	RIGHT RETAINER	90467 09237		112.70
2635	L/R BUMPER CORNER	52566 47900		149.70
2636	R/R BUMPER CORNER	52565 47900		149.70
2640	REAR BUMPER REINF	52023 47030		398.90
2979	BOOT/T-GATE MOULDING	76801 47110A0		782.50
3013	REAR MANUFACT BADGE	75403 48010		61.70
3045	REAR SPOILER	76085 47914		1,567.83
1002	RR BUMPER CLIP	RR BUMPER CLIP		40.00
1003	LH REAR BUMPER	UNDER COVER		187.60
1004	RH REAR BUMPER	UNDER COVER		187.60
1005	RR BUMPER UNDER	COVER CLIP		14.00
1006	WORDING	"PRIUS"		51.90
1007	WORDING	"HYBRID"		55.47
f: OEM Parts	<b>Savings</b>			0.00
n: Non-OEM Parts	<b>Subtotal</b>			4,979.90
u: Used parts	<b>Subtotal Discount(+30.00%)</b>			-1,493.97
	<b>Total</b>			3,485.93

**Extras**

Code	Description	Price SGD
1001	REAR NO PLATE REAR NO PLATE	45.00*
1008	REVERSE SENSOR REVERSE SENSOR	200.00*
1009	R&R REVERSE SENSOR	120.00*
	<b>Total Extras</b>	365.00

**Esteem Performance Pte Ltd  
385 Sin Ming Drive, Vicom  
Vehicle Inspection Centre  
(575718)**

**Claim Reference:**  
**Assessment number: 013549**  
**Version: 1810**  
**Date calculated: 16/08/2019 7:28 PM**

**Full Report**  
**Registration: SLN155X**  
**Printed: 16/08/2019 7:29 PM**

**Final Calculation**

	SGD	SGD
<b>Parts</b>	4,979.90	
Total Discount(+30.00%)	-1,493.97	
<b>Total Parts</b>		<b>3,485.93</b>
<b>Labour Time Base 10 WU/h</b>		
Total 95.0 WU X 50.00 SGD/h	475.00	
<b>Total of Labour</b>		<b>475.00</b>
<b>Total Of Extras</b>		<b>365.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 72.0 WU X 50.00 SGD/h	360.00	
Material Cost	129.59	
<b>Total Paint Including Material</b>		<b>489.59</b>
<b>Repair Cost Excludes GST</b>		<b>4,815.52</b>
GST (+7.0%)		<b>337.09</b>
<b>Repair Cost Included GST</b>		<b>5,152.61</b>

**Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/08/2019 17:16
Date Of Accident	08/08/2019 19:20
Exact Location Of Accident	PIE TUAS AFTER STEVEN ROAD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN155X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN YONG HOO
NRIC No	S7303809Z
Date Of Birth	28/01/1973
Occupation	OUTDOOR
Date Of Driving Pass	06/02/1995
Driving Experience	24 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83222993
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address NA  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : P1  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I was driving on the expressway cautiously as the traffic was heavy. I was almost stopping when suddenly i felt an impact from my rear vehicle. I later realised that a van from my rear had hit the rear of my vehicle. I did not take much pictures a I was in the center of the expressway and it was dangerous, We exchange particulars. No injury involved.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBF5607L  
 Vehicle Make/Model/Colour NISSAN VAN  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver ABDUL GHANI BIN JOKI  
 NRIC/Passport Number  
 Contact Number 98362511  
 Address  
 Postcode  
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

ETCH PLAN

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any late reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 

I understand, acknowledge, agree and consent that:

  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms, which may be situated outside of Singapore, for one or more of the above Purposes.




9/9/19

VERIFIED BY AJAX MARS  
REPORTING OFFICER  
Mohammad Azaly Bin Abdullah

Policyholder's Signature / Date & Time      Driver's Signature (If driver is not the policyholder) / Date & Time      Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was driving on the expressway cautiously as the traffic was heavy. I was almost stopping when suddenly i felt an impact from my rear vehicle. I later realised that a van from my rear had hit the rear of my vehicle.

I did not take much pictures a I was in the center of the expressway and it was dangerous,

We exchange particulars.

No injury involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHAMMAD AZALY BIN ABDULLAH

MARS Officer:



Registered Owner or Driver's Signature

Job Complete Date/Time

9 August 2019 at 12:18 PM

Date/Time:

9 August 2019 at 12:18 PM