

ASS. REC. BY:

Surveyor: Steve

REF: CS/ASM19014443/Exd30

Special Instruction:

ASSIGNMENT (Office)

From (Person): Stacey Ng of ASM (AXA) Date/Time: 19/08/19

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 5218G Insured: _____

at Workshop m/s: National Automobile Tel: 9100 4340

of BLK 5033 Amk Ind. park '2 # 01-277

Policy No: _____ Claim No: SGMOIXEE

Sum Insured: _____ Amount: \$2250.00

Make of Veh: _____ D.O.A. 16/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 3:27pm 19/08/19 Person Contacted: Susan Vehicle: IN/OUT

Date/Time	Action/Instruction
	<u>SLK 5218G - X</u>
<u>20/8/19</u>	<u>Informed Stacey pending workshop est via SMART claim</u>
<u>21/8/19</u>	<u>Send preli revised via SMART claim</u>

ASS. REC. BY:

Steve

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$ 2250

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLX 5218 G

Yr Regn:

19/9/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota A1715

c.c

1598

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

39719

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR 053 REH 104561347

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 55R16

R:

21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

16/8/19

D.O.I.

19/8/19

Survey held at

Lawrence motor

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/8/19

Pending Workshop sent me estimate.

MV- 73K

17/9/19

Findings confirm \$3829.43, 6 days (Reel 2840-41, 432)

(Parts GST \$110.53)

RECEIVED 24 SEP 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 23/9- typist

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

200

Transportation:

S + RS: \$

Pinus

Others

TOTAL

200

Report Format:

SMART claim

Lump Sum / L&C:

P/P \$3829.43

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wash and

◀ Re:SLK 5218G-SUPPLEMENTARY - 9/19/19 Stacey

Type

🔗 Question

Message

sorry for delay in reply, please proceed

Reply

New Message

Type *

☒ Message

Subject *

Message *

Dear Stacey,

We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.

Kindly let us have your approval on the supplementary.

Best Regards, Veron Chen

New Message

Type *

☒ Message

Subject *

OD IA SUBMITTED FOR SLK 5218G

Message *

Dear Stacey,

Please be informed that IA submitted. Vehicle repair on part by part, we have Authorize repair..Thanks Veron Chen

Cancel

Send



Auto
Consultants
Pte Ltd

81, UBI AVE, L004-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408033 TEL : (067) 6286080 FAX : (067) 6286418

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/8/2019

Survey details

Date of loss	16/8/2019
Date of appointment	19/8/2019
Date of survey	19/8/2019
Location of survey	NATIONAL AUTOMOBILE SERVICE

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLK 5218G
Make and Model	TOYOTA ALTIS
Date of registration	19/1/2017
Excess	\$2,250
Market Value	\$73,000.00
Part Rebate	\$50,357.00
Nett Loss	\$22,643.00

Repair details

Initial Estimate	\$6,423.74
------------------	------------

Proposed/Revised repair cost:

Revised Estimate Amount	\$1,828.63
"Check items (Estimated)	\$829.25
Labour	\$1,850.00
Total Repair (Estimated)	\$4,507.88
Lump Sum (Estimated)	

Number of days of repair	6 DAYS
--------------------------	--------

Remarks:

The vehicle sustained damages at the front portion

Damages Consistent
Repair Cost Economical

We have authorise repair.



Service Request Details

Claim

S9M01XEE

Reference

None 

Loss Date

August 16, 2019

Report Date

Aug 19, 2019 1:10:00 PM

Request Date

August 19, 2019

Due Date

August 26, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLK5218G

Model
TOYXXX

Service Address

111

Primary Contact/Insured

NATIONAL AUTOMOBILE SERVICE

BLK 5033 ANG MO KIO IND PARK 2, #01-277, (OFF ANG MO KIO AVENUE 3), 569536, Singapore
64825577

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg
Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

Document Type

Document SubType

+ Upload Documents

Nivitha (LKK Auto)

From: Susan Fion <lawmotoramk@gmail.com>
Sent: Monday, 19 August 2019 12:18 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] Request For Surveyor
Attachments: scan0322.pdf

Categories: Raghav

Dear Officer,

Kindly arrange your surveyor to do an inspection for the following accident own damage claim :

Our Vehicle : SLK 5218 G (our insured)
Your Insured : SLK 5218 G (your insured)
Subject : Accident Involving SLK 5218 G & SJT 1180 H On 16.08.2019

Workshop : Lawrence Motor
Address : Blk 5033 Ang Mo Kio Industrial Park 2 #01-277 Singapore 569536

A copy of the GIA Report will be follow soon. We will provide the estimate upon the surveyor's arrival. Please confirm with us via email, fax (64841482) or phone. (90044565/91004390)

Thank you.

Regards,
Susan Lim (Hp 91004390)
National Automobile Services.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	900M
Vehicle Details	
Vehicle No.:	SLK5218G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	1ZRY343367
Chassis No.:	MR053REH104561347
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,982.00
Original Registration Date:	19 Jan 2017
First Registration Date:	19 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$17,982.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jan 2027
PARF Rebate Amount:	\$13,486.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$36,871.00
Total Rebate Amount:	\$50,357.00

The information contained herein is correct as at 20 Aug 2019

OK

MA1M19107860 / Ah Lim Motor Company - AMK
ENTRY DATE & TIME: 17/08/2019 13:38
SUBMITTED BY: Zia

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the QIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 17/08/2019 12:35
Date Of Accident 16/08/2019 17:35
Exact Location Of Accident EUNOS RD 8
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLK5218G
Insured/Policyholder
Name Of Registered Owner NATIONAL AUTOMOBILE SERVICE
Co Reg No 08238900M
Email Address CONTACTUS@BANHONGLEE.COM.SG
Mobile Phone No (LOCAL) +65-97890711
Alternative Phone No OFFICE-64825577
Vehicle Particulars
Manufacturer TOYOTA
Model COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? YES
If No, Please state action to be taken
Vehicle Category COMMERCIAL VEHICLE
Insurance Company
Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number P1921492
Cover Note Number 01/01/2019 - 31/12/2019
Driver
Name of Driver MOHD RAMLI B SAMSUDIN
NRIC No S0140300A
Date Of Birth 27/01/1947
Occupation INDOOR
Date Of Driving Pass 01/04/1991
Driving Experience 28 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97890711
Fax Number
Contact Number OFFICE-64825577
Email Address NOEMAIL

Address 528 BEDOK NORTH ST 3
#16-53D
Postcode 460528
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-

General information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number 5JT1180H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(if driver is not the policyholder)
Date & Time:




Reporting Officer/Insurer's Signature
Name:
NIC/FIN No.:

Sketch Plan Pg. 2

Resend 18-02-19 10:01 : Ah Lim Motor Company AMK RECEIVED 18/02/2019 10:28 # 2/ 2
+65 6483 6170

Date of accident: 16/8/19 Time: 5-33 PM Location: Eunos Rd B
My Vehicle A: SLK350 6 Vehicle B: S3T1180H Vehicle C:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Front vehicle stopped. I couldn't stop in time, hit the rear of front vehicle.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only


Remarks: Please forward a copy of my file accident report to:
My workshop: National Automobile Service
Email address: Conradus@banhony.com.sg
& myself
Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

(We declare the following particulars are true in every respect.)


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Person's Signature
Name:
NRIC/ID No.:

[Signature/Stamp]

National Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 #01-277-S569536

Hp 91004390 Tel 64846016 Fax 64841482

Email: lawmotoramk@gmail.com

M/s AXA Insurance Singapore Pte Ltd	DATE	19.08.2019
8 Shenton Way #27-01 AXA Tower	CAR NO	SLK 5218 G
Singapore 068811	MAKE	Toyota Altis

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLK 5218 G

Pc	Pcs	MR053REH104561347	UNIT PRICE	AMOUNT
1	pc	Front bumper / 00		\$181.90
2	pcs	Front bumper left & right hand side retainer / OR	\$27.82	\$55.64
2	pcs	Front bumper left & right hand side bracket X NN	\$58.85	\$117.70
1	pc	Front bumper reinforcement / 00		\$117.70
1	pc	Front bumper inner sponge ? / OR		\$48.15
1	pc	Front bumper lower grille / CUT		\$53.50
1	pc	Front bumper right side fog lamp ? X NN		\$96.30
1	pc	Front bumper right side fog lamp cover / CUT		\$53.50
1	pc	Front bonnet cover / 00		\$288.90
2	pcs	Front bonnet hinge / BT	\$32.10	\$64.20
1	pc	Front bonnet top lock X NN		\$69.55
1	pc	Front bonnet top lock cable X NN		\$29.96
1	pc	Front bonnet stand with clip / OR		\$18.19
1	pc	Front vertical panel X R		\$58.85
1	pc	Front support panel assy / 00		\$278.20
2	pcs	Front head lamp (left & right) (RH) - OR (LH) ? / CRA	\$224.70	\$449.40
1	pc	Front grille / OR		\$149.80
1	pc	Front grille top garnish ? X NN		\$32.10
1	pc	Radiator ? / BT		\$390.55
1	pc	Radiator top cowlng ? X NN		\$37.45
1	pc	Radiator fan motor X NN		\$149.80
1	pc	Air con condenser / 00		\$342.40
		To top up gas, labour for checking air con system, Dismantle & replace air con condenser.	120	\$220.00
		To dismantle and replace radiator.	50	\$130.00
		To top up radiator coolant.	20	\$30.00
			Total	

National Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 #01-277 S569536

Hp 91004390 Tel 64846016 Fax 64841482

Email: lawmotoramk@gmail.com

M/s AXA Insurance Singapore Pte Ltd	DATE	19.08.2019
8 Shenton Way #27-01 AXA Tower	CAR NO	SLK 5218 G
Singapore 068811	MAKE	Toyota Altis

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLK 5218 G

Pc	Pcs	MR053REH104561347	UNIT PRICE	AMOUNT
		Continue from page one.		\$3,463.74
		To provide labour, workmanship to re-align, straightening front left side fender, cutting front right side fender, top panel, dismantle & replace the above mentioned parts.	700	\$1,200.00
		Labour for respray front bumper, front top panel, front right/left side fender and front bonnet cover.	900	\$1,400.00
		Rust-proofing on the front accident affected	30	\$180.00
		To check front and rear electrical wiring system.	30	\$80.00
		Computer alignment.	X	\$100.00
		Steve (LKK) 8322 8813 OO - Authorise Excess - \$2250 20/8/19, 4.00pm P/P Resay before spray 6 days  2/8/19		1850
				6669.84
			Total	6,423.74

National Automobile Service

Page 2 of 2

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total

P - 1868.90

L - 1850

GST - 110.53

3829.43

National Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 #01-277 S569536

Hp 91004390 Tel 64846016 Fax 64841482

Email: lawmotoramk@gmail.com

M/s AXA Insurance Singapore Pte Ltd	DATE	22.08.2019
8 Shenton Way #27-01 AXA Tower	CAR NO	SLK 5218 G
Singapore 068811	MAKE	Toyota Altis

SUPPLEMENTARY CLAIMS FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLK 5218 G

Pc	Pcs	MR053REH104561347	UNIT PRICE	AMOUNT
1	pc	Front right side fender / 00		\$246.10 180 + 10% 198
Steve 22/8/19 LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				Total 246.10

National Automobile Service

1 Kaki Bukit Avenue 6, #01-104, Auto Bay @ Kaki Bukit, Singapore 417883
Tel: (65) 6747 4366 Fax: (65) 6747 7560
No. 1, Syed Alwi Road #01-03, Song Lin Building, Singapore 207828
Tel: (65) 6294 3696 Fax: (65) 6297 0448
Reg. No. 04049600X

No. 105750

Date 20.08.2019

M. National CASH SLK521A

Blk 5033, #01-279, AMK JNO MK 2

Specialize In All Types of Motor Vehicle's Radiator.

Sun Hong Lee

328

[illegible]

Checked by _____



豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)
No. 3 Kallang Way 2A Fong Tai Building Singapore 347493 Tel: 6749536/6749537 Fax: 6749536/6749537
28 Kallang Road 4, 401-22 Breeze @ 18 Singapore 417800 Tel: 8086 8569 / 0504 2235 Fax: 8086 2245
Bldg 655 801-024 Race Course Road Singapore 210605 Tel: 6255 4551 Fax: 6257 0774
Co. Reg. No.: 187602013M

GST Reg. No.: M2-00252314

INVOICE TO:
BAN HONG LEE MOTOR SERVICES
BLK 5033 ANK IND PK 2
#01-279 (OFF ANK AVE 3)
SINGAPORE 569536

Handwritten signature



TAX INVOICE NO.: 1L048225
INVOICE DATE : 22/08/2019
CREDIT TERMS : 60 DAYS
SALES ORDER NO.:
SALESMAN : KPC
PAGE(S) : 1

TAX INVOICE

PARTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)
COND0031	COND.IND 447750-1331		1	120.000	120.00
GST Excl Amount : 120.00					120.00
Special Discount : 8.40					8.40
GST @ 7 %					
TOTAL					128.40

FONG EE INDUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

PRINT BY :
KPC 22/08/2019 09:56:28

SIGNATURE


AUTHORISED SIGNATURE

Handwritten signature

豐達汽車私人有限公司
FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347403
 Tel: 67404988, 67479290 Fax: 67480980, 67477401 Website: www.fongtat.com
 Main Branch (Dover): 355-357 Selegie Road Singapore 259115 Tel: 62985333, 62984832
 Fax: 62982154, 62942354, 62950502
 Email: fongtat@fongtat.com.sg
 POC Reg No.: F18301435R

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL GENUINE PARTS
 TEL: 62464666 62464832 67479290
 67408878 62985333 67455824

MAZDA FORD HYUNDAI
 TEL: 62964666 62464832 67479290

INVOICE TO: BAN HONG LEE MOTOR SERVICES

BLK 5033-AWK IND PK 2

#01-279 (OFF AWK AVE 3)

SINGAPORE 569536

SKK578

TAX INVOICE

TAX INVOICE NO.: CL402998

INVOICE DATE: 21/08/2019

CREDIT TERMS: 60 Days

SALES ORDER NO.: C.J.W

SALES MAN: C.J.W

PAGE(S): 1

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)
F/RETAINER		1	25.00	25.00
FOG LAMP COVER RH		1 PCS	38.00	38.00
GST Excl Amount :				63.00
Special Discount :				4.41
GST @ 7 % :				

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

PRINT BY :

CJW 21/08/2019 15:54:03

GOODS RECEIVED

67.41

TOTAL

AUTHORISED SIGNATURE

SIGNATURE



豐達汽車私人有限公司
FONG TAT MOTOR CO. PTE. LTD.

Head Office No. 3 Kallang Way 3A, FONG TAT Building Singapore 347683
Tel: 01-4040384, 01-4747000 Fax: 01-4040381, 01-4747481 Website: www.fongtat.com
Main Branch (Coway) 305-307 Selegie Road Singapore 118115 Tel: 020823303, 020848552
Email: fongtat@fongtat.com.sg
FCB Reg No.: 198501405R

BAN HONG LEE MOTOR SERVICES

INVOICE TO: **BLK 5033 AMK IND PK 2**
#01-279 (OFF AMK AVE 3)
SINGAPORE 569536

SLK 5 248

GST Reg. No.: M2-0059747-8

AUTHORISED STOCKISTS:



GOODS SOLD ARE NOT RETURNABLE FOR CASH

PRINT BY :
CJM 21/08/2019 15:28:33

GOODS RECEIVED

TOTAL

1295.77

AUTHORISED SIGNATURE

SIGNATURE

TAX INVOICE
TAX INVOICE NO.: CL402994
INVOICE DATE : 21/08/2019
CREDIT TERMS : 60 Days
SALES ORDER NO.:
SALESMAN : CJM
PAGE(S) : 2


DESCRIPTION	LOC	QUANTITY	UNIT PRICE	(SIN)	(SIN)
GST Excl Amount :				1211.00	
Special Discount :				84.77	
GST @ 7 % :					



豐達汽車私人有限公司
FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG 347 Building Singapore 347469
 Tel: 67464988, 67476252 Fax: 67420850, 67477451 Website: www.fongtat.com
 Main Branch (Tampere): 355-367 Serangoon Road Singapore 210115 Tel: 62965333, 62943852
 Fax: 62962156, 62942554, 62920623
 Email: fongtat@fongtat.com.sg
 PCE Reg No.: 116801455R

AUTHORISED STOCKISTS:



NISSAN
 Genuine Parts
 TOYOTA OPEL
 GENUINE PARTS



MAZDA
 Genuine Parts
 TOYOTA OPEL
 GENUINE PARTS

NISSAN TOYOTA OPEL GENUINE PARTS
 TEL: 67420850 62942554 62920623
 67420850 62942554 62920623

MAZDA TOYOTA OPEL GENUINE PARTS
 TEL: 67420850 62942554 62920623

MAZDA TOYOTA OPEL GENUINE PARTS
 TEL: 67420850 62942554 62920623

INVOICE TO: **BAN HONG LEE MOTOR SERVICES**

BLK 5033 AMK IND PK 2

#01-279 (OFF AMK AVE 3)

SINGAPORE 569536

SK 5218

GST Reg. No.: M2-0059747-8

TAX INVOICE
 TAX INVOICE NO.: CL402994
 INVOICE DATE: 21/08/2013
 CREDIT TERMS: 60 Days
 SALES ORDER NO.:
 SALESMAN: CJM
 PAGE(S): 1



LOC.	QUANTITY	UNIT PRICE	(SIN)
	1	200.00	200.00
	1	200.00	200.00
	1	100.00	100.00
	1	160.00	160.00
	1	95.00	95.00
	1	42.00	42.00
	1	8.00	8.00
	1	23.00	23.00
	1	23.00	23.00
	1	180.00	180.00
	1	180.00	180.00

FONG TAT MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH
 GOODS RECEIVED
TOTAL

AUTHORISED SIGNATURE

14/140

SIGNATURE

Veron Chen (LKKAUTO)

From: Susan Fion <lawmotoramk@gmail.com>
Sent: Monday, 23 September 2019 3:48 PM
To: Veron Chen (LKKAUTO); Steve Chen (LKK Auto)
Subject: Final Invoice for SLK5218G (OD claims against AXA)
Attachments: SLK5218G (AXA) Final Invoice report.pdf

Dear Veron,

We refer to the above mentioned subject matter.

We enclosed herewith our Final Invoice with all other relevant documents for your kind perusal.

Kindly issue payment in favor of **National Automobile Service** upon receiving the needful.

Thank you & Best Regards
Susan Lim
91004390

National Automobile Service

National Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 AMK #01-277 (off AMK Ave 3)
Singapore 569536 HP 91004390/HP 91254449 Fax 64841482


Email : lawmotoramk@gmail.com

Invoice No : LM11098

M/s AXA Insurance Singapore Ltd Pte	DATE	17.09.2019
8 Shenton Way #27-01 AXA Tower	CAR NO	SLK 5218 G
Singapore 068811	MAKE	Toyota Altis

FINAL COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLK 5218 G (OD Claim)

Pc	Pcs	MR053REH104561347	UNIT PRICE	AMOUNT
		<u>Recommended Parts</u>		
1	pc	Front bumper		\$160.00
2	pcs	Front bumper LH & RH side reinforcement		\$25.00
1	pc	Front bumper reinforcement		\$95.00
1	pc	Front bumper inner sponge		\$45.00
1	pc	Front bumper lower grille		\$42.00
1	pc	Front bumper right side fog lamp cover		\$38.00
1	pc	Front bonnet cover		\$100.00
2	pcs	Front bonnet hinge	\$23.00	\$46.00
1	pc	Front bonnet stand with clip		\$8.00
1	pc	Front support panel assy		\$180.00
2	pcs	Front head lamp (left & right)	\$200.00	\$400.00
1	pc	Front grille		\$140.00
1	pc	Radiator		\$120.00
1	pc	Air-con condenser		\$120.00
1	pc	Front right side fender		\$180.00
				\$1,699.00
			Add 10%	\$169.90
			Parts Total	\$1,868.90
		<u>Recommended labour</u>		
		To top-up gas, labour for checking air-con system, dismantle and replace air-con condenser		\$120.00
		To dismantle and replace radiator		\$50.00
		To top-up radiator coolant		\$20.00
		continue on page 2		
			Page 1 of 2	Total


National Automobile Service

National Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 AMK #01-277 (off AMK Ave 3)
Singapore 569536 HP 91004390/HP 91254449 Fax 64841482


Email : lawmotoramk@gmail.com

Invoice No : LM11098

M/s	AXA Insurance Singapore Ltd Pte	DATE	17.09.2019
	8 Shenton Way #27-01 AXA Tower	CAR NO	SLK 5218 G
	Singapore 068811	MAKE	Toyota Altis

FINAL COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLK 5218 G (OD Claim)

Pc	Pcs	MR053REH104581347	UNIT PRICE	AMOUNT
		continue from page 1		\$2,058.90
		<u>Recommended Labour</u>		
		To provide labour, workmanship to re-align, straightening front left side fender, cutting front right side fender, top panel, dismantle & replace the above mentioned parts.		\$700.00
		Labour for respray front bumper, front top panel, front left & right side fender, front bonnet cover.		\$900.00
		Rust-proofing on the front accident affected area.		\$30.00
		To check front and rear electrical wiring system		\$30.00
		Sub Total		\$3,718.90
		Add 7% GST (\$1579)		\$110.53
		Less Excess		(\$2,250.00)
				\$1,579.43
Page 2 of 2				Total
				\$1,579.43


National Automobile Service

National Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 #01-277 (off AMK Ave 3)
Singapore 569536 HP 91004390/HP 91254449 Fax 64841482

Email : lawmotoramk@gmail.com

SATISFACTION & DISCHARGE VOUCHER

We, National Automobile Service, owner of vehicle number SLK 5218 G declare that our vehicle have been completed to our satisfaction and was discharged from National Automobile Service at Block 5033 Ang Mo Kio Industrial Park 2 #01-277 S569536 on the 27 day of August 2019.

Signature of Assured,

A circular stamp with the text "NATIONAL AUTOMOBILE SERVICE" around the perimeter and "SIGNED" in the center. Below the stamp is a handwritten signature in black ink.

National Automobile Service