

ASS. REC. BY:

REF: CS/AGI/9014452/Hvd3/02 Special Instruction:

Damage: Hbck Mr

ASSIGNMENT (Office)

From (Person): Ily Petilla of AGI Date/Time: 16/8/19 @ 4.23pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 1249S Insured: SAX 2329E

at Workshop m/s Teamwork Garage Tel: 68142475

of 53 Ubi Ave 1 # 01-24

Policy No: Claim No: C10003627/SM

Sum Insured: Excess:

Make of Veh: D.O.A. 30/07/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:13 am 19/8/19 Person Contacted: Damon Vehicle: IN/OUT

Date/Time	Action/Instruction	Signature
	SLP 1249S - NA/4P/19013389/24	
	SAX 2329E - NA/4P/19013389/24	

Surfplus H. ANN

REF: AGI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Team work

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 25 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

N/S	O/S

Veh No: SLP 12495 Yr Regn: 26/05/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: T. wish AT. C.C. 1798

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 239638km T/Radio: Insured / Std / NI / NA

Eng/No: _____

Ci/No: JTDGG20W30J006914

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65/R15
R: 195/65/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front 5 mm Briti comfort Rear 5 mm Briti comfort

L/Bal. 5 mm

D.O.A. 30/7/19 D.O.I. 15/10/19

Survey held at Team work

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* SLP 12495 Finalised 4/sum Ant COR = \$2150 DOR = 4 days (Reel 4884.25, 697) Agree by workshop ms Letitia (Team work)
	* SLP 12495 have Estimate case NON completed File NON know who handle
	MV - 78900 PV - 56355 NV - 22500
	RECEIVED 13 NOV 2019

Date/Time, File Pass to? : Proll. Report

1) : Final Report

Date/Time, File Return to? 2) 13/11 - typist

Report Format: TP

Lump Sum / I.B.I. (\$) 2150

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee: 290

Transportation: _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invs (\$)
 Weekend (\$)

Photos _____
Others _____

TOTAL 290

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Friday, 16 August 2019 4:23 PM
To: Darren; Admin-D (LKKAuto)
Cc: sur@lkkauto.com; Julie Mangubat
Subject: TPPD Survey: Claim ref:C10003627/JM || OI- SGX2329E (Brown) TP-SLP1249S || Est:0.00 || Teamwork Garage
Attachments: 2019_08_01_17_15_41.pdf

Hi Team,

We would like to arrange TP PRS for SLP1249S.

Please confirm.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may

be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Darren <claims@teamworkgarage.com>
Sent: Friday, 16 August 2019 4:04 PM
To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Cc: Julie Mangubat <julie.m@budgetdirect.com.sg>
Subject: RE: Our Ref: 1907-97 Your Ref: SGX2329E Accident between SLP1249S &SGX2329E at Peshurst Place Carpark on 30.07.2019 || C10003627

Hi Ivy,

Please LKK

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: [Ivy Ratilla](#)
Sent: Friday, 16 August 2019 2:32 PM
To: [Kenneth lian](#)
Cc: [Julie Mangubat](#)
Subject: RE: Our Ref: 1907-97 Your Ref: SGX2329E Accident between SLP1249S &SGX2329E at Peshurst Place Carpark on 30.07.2019 || C10003627

WITHOUT PREJUDICE

Hi Tricia,

We are still waiting for your response for our email (attached).

We will advise liability soon.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01

Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Kenneth lian <claims@teamworkgarage.com>
Sent: Friday, 16 August 2019 2:09 PM
To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Cc: Kenneth lian <claims@teamworkgarage.com>
Subject: Our Ref: 1907-97 Your Ref: SGX2329E Accident between SLP1249S & SGX2329E at Peshurst Place Carpark on 30.07.2019

Dear Sir/Madam,

Can I check the liability for this case?

Thank you ! 😊
Regards,

Tricia

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel : 68442475
Fax : 68442474

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	722Z
Vehicle Details	
Vehicle No.:	SLP1249S
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR1952800
Chassis No.:	JTDGG20W30J006914
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	26 May 2017
First Registration Date:	26 May 2017
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 May 2027
PARF Rebate Amount:	\$14,966.00
Intended COE Rebate Details	
COE Expiry Date:	25 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,406.00
COE Rebate Amount:	\$41,389.00
Total Rebate Amount:	\$56,355.00

The information contained herein is correct as at 16 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No. SLP1249S	
Make / Model TOYOTA / WISH 1.8 CVT	
Vehicle Type: Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover	Vehicle Attachment 1: No Attachment
Vehicle Scheme: Normal	Chassis No.: JTDGG20W30J006914
Propellant: Petrol	Engine No.: 2ZR1952800
Motor No.: -	Engine Capacity: 1798 cc
Power Rating: -	Maximum Power Output: 105.0 kW (140 bhp)
Maximum Laden Weight: 1935 kg	Unladen Weight: 1360 kg
Year Of Manufacture: 2017	Original Registration Date: 26 May 2017
Lifespan Expiry Date: -	COE Category: B - Car above 1600cc or 97kW (130bhp)
Quota Premium: \$54,406.00	COE Expiry Date: 25 May 2027
Road Tax Expiry Date: 25 Nov 2019	PARF Eligibility Expiry Date: 25 May 2027
Inspection Due Date: 25 May 2020	Intended Transfer Date: 16 Oct 2019
CO2 Emission: 159.00 (g/km)	CEV/VES Rebate Utilised Amount: -
CO Emission: -	HC Emission: -
NOx Emission: -	PM Emission: -

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (26 Nov 2019 to 25 May 2020)	\$488.00
Road Tax Renewal - 12 months (26 Nov 2019 to 25 Nov 2020)	\$976.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees. Any road tax that has been paid for the vehicle will be transferred to the next owner.

- Print
- Save as PDF
- Copy as Text

DON = 30/7/19
 MV - 78900
 PV - 56355
 IVU - 22500

Bahar → 7 yr bond
 Myle → 8800 yr
 $8800 \times 12 = 733 \text{ months}$
 $= 61600 + 7330 + 9977$
 $= 78907$

OK →

-
- New Cars
- Used Cars
- Sell My Car
- Directory
- Products
- Insurance
- Articles
- Forum
- Resources



TOYOTA WISH Price Range Depreciation 2017 Vehicle Type

Advanced Search

Home » Used Cars » Ka-Hup Vehicles Trading » Toyota Wish 1.8A

Toyota Wish 1.8A

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

PREMIUM AD



KA-HUP ESTABLISHED SINCE 1989



Price	\$82,800		
Depreciation ⓘ	\$9,440 /yr <small>View models with similar depre</small>	Reg Date	04-Jul-2017 <small>(7yrs 8mths 17days COE left)</small>
Mileage	57,000 km (24.9k /yr)	Manufactured ⓘ	2017
Road Tax ⓘ	\$976 /yr	Transmission	Auto
Dereg Value ⓘ	\$51,627 as of today (change)	OMV ⓘ	\$19,955
COE ⓘ	\$47,501	ARF ⓘ	\$19,955
Engine Cap	1,798 cc	Power	105.0 kW (140 bhp)
Curb Weight ⓘ	1,355 kg	No. of Owners ⓘ	1
Type of Vehicle	MPV		

Features

Powerful And Reliable 1.8L 16 Valves VVT-i DOHC Engine, Smooth 4 Speed Steptronic Gearbox, Airbags, ABS, Keyless Start/Stop Engine. View specs of the Toyota Wish (2009-2018)

Accessories

Sports Rims, Leather Upholstery, Knockdown Rear Seats, Solar Films, Armrest, Retractable Side Mirrors, Solar Film, Reverse Sensors.

Description

Low Mileage Done. Well Maintained & Excellent Unit By 1 Owner Only. Non PHV. Grab It Now Before It Is Obsolete. Fully Serviced By Borneo Motor Since Day 1. Warranty Still Valid By Agent. Transparent Dealing With No Hidden Cost. Bank Loan Package From 2.28% & In-House Full Loan Are Available. Contact Us For An Immediate Viewing Appointment. Thank You!

Compare



Click on the point to view the vehicle

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2019 18:24
Date Of Accident	30/07/2019 12:05
Exact Location Of Accident	FARLEIGH AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP1249S
Insured/Policyholder	
Name Of Registered Owner	ROSET LIMOUSINE SERVICES PTE LTD
Co Reg No	200406722Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V12322/VPZ/R00
Cover Note Number	

Driver

Name of Driver	RAZALY BIN AHMAD
NRIC No	S1764418A
Date Of Birth	27/07/1966
Occupation	OUTDOOR
Date Of Driving Pass	10/09/1986
Driving Experience	32 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88225324
Fax Number	
Contact Number	OFFICE-88225324
E-Mail Address	NOEMAIL

Address	BLK 30 TEBAN GARDENS ROAD #06-209
Postcode	600030
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGX2329E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1) Please report **correctly** on the details of the accident to speed up the claims process.
- 2) This form must be **completed by the policy holder and/or the authorised driver**.
- 3) Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) **Any false reporting may be referred to the police for investigation**.
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
 - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigations the accident and/or my claims;
 - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) For complying with requirements under my regulations, laws or court orders.




Policy holder's signature
Date / time:


Driver's signature
(if driver is not policy holder)
Date / time:


reporting centre personnel's Signature
Date / time:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight along Farleigh Ave. When i was approaching vehicle B which was trying to park into the parallel parking lot in the right , i waiting for him to park before moving off. When i saw that his vehicle was already half way in the lot and was stationary , i proceeded to go straight on the left and while i was travelling , vehicle B suddenly came out of the parking lot and collided onto the right portion of my vehicle.


DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policy holder's signature
Date & time:


Driver's signature
(if driver is not policy holder)
Date & time:


reporting centre personnel's Signature
Name:
NRIC/FIN No.:



Chassis Measurement Chart

Subsidiary/Branch-Company no. C&Y AUTO PTE LTD 53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK S'PORE 408934		Customer: TEAM WORK	
Reg. N.: SLP 1249 S		Mileage: Km/miles km	
First registration: TOYOTA WISH ANE10G 2WD 2003 - 2009 (32560)		Date: 15/10/2019	
Complaint or reason for measurement			
Tyres:make		Mileage:Km/miles	

Description		Mileage:Km/miles			
		front LH	front RH	rear LH	rear RH
Pressure measured (cold) bar/psi/kPa		2.2	2.2	2.2	2.2
Tread depth (mm)					
external					
centre					
internal					
		Before correction		After correction	
Vehicle level					
REAR AXLE	Camber +/- (°)	LH	-01.53°	-01.50°/ +00.75°-00.75°	-01.53°
		RH	-01.59°	-01.50°/ +00.75°-00.75°	-01.59°
		total	+00.43° *	+00.17°/ +00.22°-00.22°	+00.43° *
	Toe +/- (°)	LH	+00.30° *	+00.09°/ +00.11°-00.11°	+00.30° *
		RH	+00.13°	+00.09°/ +00.11°-00.11°	+00.13°
	Thrust angle		+00.08°	+00.00°/ +00.17°-00.17°	+00.08°
Camber +/- (°)	LH	-00.51°	-00.50°/ +00.75°-00.75°	-00.51°	
	RH	-01.96° *	-00.50°/ +00.75°-00.75°	-01.95° *	
Caster (°)	LH		+03.08°/ +00.75°-00.75°		
	RH		+03.08°/ +00.75°-00.75°		
FRONT AXLE	Lh steering lock lh wheel 20°				
	Rh steering lock rh wheel 20°				
Set Back		+00.10°		+00.10°	
Toe +/- (°)	total	-00.57° *	+00.00°/ +00.17°-00.17°	-00.57° *	
	LH	-00.36° *	+00.00°/ +00.09°-00.09°	-00.36° *	
	RH	-00.21° *	+00.00°/ +00.09°-00.09°	-00.21° *	
Maximum steering angle on wheel side on inside of bend (°)	LH				
	RH				



Chassis Measurement Chart

Subsidiary/Branch-Company no. C&Y AUTO PTE LTD 53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK S'PORE 408934		Customer: TEAM WORK	
Reg. N.: SLP 1249 S		Mileage: Km/miles km	
First registration: TOYOTA WISH ANE10G 2WD 2003 - 2009 (32560)		Date: 18/10/2019	
Complaint or reason for measurement		Vehicle ident. no. / Repair order no.	
Tyres: make		Mileage: Km/miles	

Description		Mileage: Km/miles			
		front LH	front RH	rear LH	rear RH
Pressure measured (cold) bar/psi/kPa		2.2	2.2	2.2	2.2
Tread depth (mm)					
external					
centre					
internal					
		Before correction		After correction	
Vehicle level					
REAR AXLE	Camber +/- (°)	LH	-01.60°	-01.50° / +00.75°-00.75°	-01.60°
		RH	-01.68°	-01.50° / +00.75°-00.75°	-01.68°
		total	+00.34°	+00.17° / +00.22°-00.22°	+00.34°
	Toe +/- (°)	LH	+00.25° *	+00.09° / +00.11°-00.11°	+00.25° *
		RH	+00.09°	+00.09° / +00.11°-00.11°	+00.09°
Thrust angle			+00.08°	+00.00° / +00.17°-00.17°	+00.08°
FRONT AXLE	Camber +/- (°)	LH	-00.68°	-00.50° / +00.75°-00.75°	-00.66°
		RH	-00.19°	-00.50° / +00.75°-00.75°	-00.24°
	Caster (°)	LH		+03.08° / +00.75°-00.75°	
		RH		+03.08° / +00.75°-00.75°	
Lh steering lock lh wheel 20°					
Rh steering lock rh wheel 20°					
Set Back			+00.01°		+00.05°
FRONT AXLE	total		-00.65° *	+00.00° / +00.17°-00.17°	+00.04°
	Toe +/- (°)	LH	+00.00°	+00.00° / +00.09°-00.09°	+00.05°
		RH	-00.65° *	+00.00° / +00.09°-00.09°	-00.01°
Maximum steering angle on wheel side on inside of bend(°)		LH			
		RH			

17/10/19
without previous
Hoek Am
25316883
15/10/19
4.55pm
Resurvey of the pain
Hoek Am @ 11/10/19
4 day

LKIA No. 03/19/19 hence notify the Insurer in the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
AUTO AND GENERAL INSURANCE
 • Third party survey is on a "Without Prejudice" basis
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
 is subject to final approval from Insurance Company
Singapore 239924

Vehicle number	SLP1249S
Make / Model	TOYOTA/WISH
Chassis number	JTDGG20W30J006914
Accident date	30 July 2019
Reference	1907-97

Acknowledged by Repairer
 Signature:
 Date:

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	FRONT RH FENDER ✓ BT	983.25 480 ✓
1	FRONT RH FENDER INNER SHIELD ✓ CRU	189.75 137.80 ✓
1	FRONT BUMPER ✓ CRU	669.25 395.50 ✓
1	FRONT BUMPER RETAINER R/H only ✓ see	138.00 49.50 ✓
1	FRONT RH HEADLAMP ✓ CRU	1092.50 650.180 ✓
1	FRONT WIPER WASHER TANK X SVC	103.65
1	FRONT WIPER WASHER TANK MOTOR X SVC	277.15
1	FRONT GRILLE ASSY X SVC	454.25
1	FRONT BUMPER SPONGE X SVC	130.00
1	FRONT BUMPER LOWER GRILLE RH <i>by Fas lug cover R/H ✓ see</i>	63.25 43.25 ✓
1	FROTN BUMPER LOWER GRILLE X <i>no use</i>	143.75
1	FRONT RH KNUCKLE ARM ✓ DM	552.00 280.80 ✓
1	FRONT RH KNUCKLE BEARING ✓ DM	155.25 98.70 ✓
1	FRONT RH LOWER ARM X SVC	565.80
1	FRONT RH SHOCK ABSORBER X SVC	461.15
		5979.00
	Less 25%	1494.75
	Subtotal	4484.25
	Balance C/F	4484.25
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
	Balance B/F	4484.25
1 SET	FRONT BUMPER CLIP ✓ see	40.00 20 ✓
1 SET	FRONT FENDER INNER TRIM CLIP ✓ see	30.00 15 ✓
1	RIM ✓ see → local Repair work \$ 80 ✓	600.00
1 BOT	BRAKE FUILD X SVC	50.00
	Subtotal	720.00
	Balance C/F	5204.25
S/No	LABOUR AND MISCELLANEOUS CHARGES	Balance B/F
		5204.25
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 20 ✓
2	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT → <i>align mt</i>	150.00 60 ✓
3	REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS - <i>photo</i>	200.00 80 ✓
4	PANEL BEATING ON AFFECTED AREAS <i>2dy</i>	600.00 400 ✓
5	SPRAY PAINTING ON AFFECTED AREAS <i>2ps</i>	700.00 400 ✓
6	APPLY ANTI RUST ON AFFECTED AREAS	120.00
	Subtotal	1830.00
	Grand total	7034.25

Resurvey H Am
16/10/19
11.45 Am
** need to Aligner*
report
** refer point need*
inform take
photo

Parts → 2136.35
less 25%
1602.26
net
item 115
labour 960
2677.26
1/5 less 20%
2141.80
Total
1/5 Amt → \$ 2150

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Wednesday, 13 November, 2019 9:11 AM
To: claims@teamworkgarage.com
Cc: Veron Chen (LKKAuto)
Subject: RE : SLP 1249S TOYOTA WISH FINALIZED CALCULATE

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear lititia ,

Good day, o.k will be process base on finalized total amount COR \$ 2150 lump sump repair and DOR 4 days close.

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims@teamworkgarage.com [mailto:claims@teamworkgarage.com]
Sent: Monday, 11 November, 2019 2:08 PM
To: Hock Ann (LKK Auto)
Cc: 'TEAMWORK GARAGE CLAIMS'
Subject: RE: SLP1249S TOYOTA WISH

Hi Hock Ann,

We confirm COR @ \$2150 and DOR @ 4 days

Thank you and have a nice day! 😊

Letitia
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1 #01-24 Paya Ubi Industrial Park
Singapore (408934)
Tel: 6844 2475 | Fax: 6844 2474

From: Darren [mailto:claims@teamworkgarage.com]
Sent: Wednesday, October 30, 2019 11:58 AM
To: HockAnn@lkkauto.com
Subject: RE: SLP1249S TOYOTA WISH

Hi,



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI19014452/Hvd3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 14-11-2019	
Code : AGI			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGX 2329E	Veh. Inspected	SLP 1249S
Policy No.		Coverage (\$)	0.00
Claim No.	C10003627/JM	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	16/08/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH 1.8 CVT	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDGG20W30J006914	Colour	SILVER
Odometer	239638	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GITI COMFORT	5 mm
L/H Front Tyre	195/65 R15	GITI COMFORT	5 mm
R/H Rear Tyre	195/65 R15	GITI COMFORT	5 mm
L/H Rear Tyre	195/65 R15	GITI COMFORT	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/07/2019	Inspection Date	15/10/2019
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 1249S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT RH FENDER	BENT	983.25	480.00
1	FRONT RH FENDER INNER SHIELD	CRUSHED	189.75	137.80
1	FRONT BUMPER	CRUSHED	669.25	395.50
2	FRONT BUMPER RETAINER	O/S NECESSARY	138.00	49.50
1	FRONT RH HEADLAMP	CRUSHED	1,092.50	650.80
1	FRONT WIPER WASHER TANK	SERVICEABLE	103.65	-
1	FRONT WIPER WASHER TANK MOTOR	SERVICEABLE	277.15	-
1	FRONT GRILLE ASSY	SERVICEABLE	454.25	-
1	FRONT BUMPER SPONGE	SERVICEABLE	130.00	-
1	FOG LAMP COVER R/H	CRUSHED	63.25	43.25
1	FRONT BUMPER LOWER GRILLE	NO USE	143.75	-
1	FRONT RH KNUCKLE ARM	DAMAGED	552.00	280.80
1	FRONT RH KNUCKLE BEARING	DAMAGED	155.25	98.70
1	FRONT RH LOWER ARM	SERVICEABLE	565.80	-
1	FRONT RH SHOCK ABSORBER	SERVICEABLE	461.15	-
	LESS 25% DISCOUNT		-1,494.75	-534.09
			4,484.25	1,602.26
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	40.00	20.00
1	SET FRONT FENDER INNER TRIM CLIP (SN)	NECESSARY	30.00	15.00
1	RIM (SN) (LOCAL REPAIR)	SCRATCHED	600.00	80.00
1	BOT BRAKE FLUID (SN)	SERVICEABLE	50.00	-
			720.00	115.00
<u>LABOUR</u>				
	CHECK FRONT WIRING AND LIGHTNING SYSTEM.		60.00	20.00
	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT.		150.00	60.00
	REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS.		200.00	80.00
	PANEL BEATING ON AFFECTED AREAS.		600.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		700.00	400.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	-
			1,830.00	960.00
GRAND TOTAL			7,034.25	2,677.26



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,150.00
---	--	--	----------

Report Ref No. CS/AGI19014452/Hvd3e2

LEE HOCK ANN
Asst. Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.