

AFS REC BY:

REF:

08/FWD 19014454/Kg d302

Special Instruction:

Assigner:

ASSIGNMENT (Office)

From (Person):

Venessa Chan

of

FWD

Date/Time:

19/8/19 @ 3:29pm

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKK 7762A

Insured:

SLE 9478C

at Workshop m/s

RC Auto

Tel:

9761 9383

of

160 Sin Ming Drive # 06-20

Policy No:

INPU2019-00013103

Claim No:

12019000 24362

Sum Insured:

Excess:

Make of Veh:

D.O.A

17/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:10pm @ 19/8/19

Person Contacted:

Mr. Tan

Vehicle IN/OUT

Date/Time

Action/Instruction

Initials ✓

SKK 7762A-X

SLE 9478C-X

19/8/19 @ 4:04pm Revised to Venessa Chan via Meimann.

23/8 615, 8350d Confirmed (Red & 9059.71, 77%)

ASS. REC. BY:

REF:

FWD

ASSIGNMENT

From:

Date:

20/8/19

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKK 7762A

at Workshop m/s

Re Auto

of 160 Bin Ming Drive #06-20

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

S 13,500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKK 7762A

Yr Regn:

01 / 10

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

NIS

Sylphy

C.C

14PR

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

25507P

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1BAA 61180 110605

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

17/8/19

D.O.I.

20/8/19

Survey held at

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 23 AUG 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 23/8 train

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

MER-TP

Lump Sum / L.P.:

3500

250

50

11

311

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Monday, 19 August 2019 3:29 PM
To: admin-d@lkkauto.com; admin-a@lkkauto.com
Cc: motorclaims.sg@fwd.com; lionel.tan@fwd.com
Subject: Notice to Conduct Pre-repair Survey - Your Ref: SLE 9478C - OurRef: SKK 7762A/RCA/jp/ps/ DOA: 17.08.2019
Attachments: 2nd PRS (accept) - FWD.pdf; PRI - KSCGP JURIS LLP.pdf

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen & our insured has yet to report.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: Monday, August 19, 2019 3:22 PM

To: Venessa Chan - SGUser

Cc: jiapei@kscgp.com

Subject: RE: Notice to Conduct Pre-repair Survey - Your Ref: SLE 9478C - OurRef: SKK 7762A/RCA/jp/ps

Dear Venessa,

We refer to the subject matter.

Please find enclosed 2nd Notice to Conduct Pre-repair Survey herewith.

Thank you.

Regards,

Sampu

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP
10 Hoë Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: venessa.chan@fwd.com [<mailto:venessa.chan@fwd.com>]
To: Accident@kscgp.com
Cc: jiapei@kscgp.com, motorclaims.sg@fwd.com, lionel.tan@fwd.com
Sent: Mon, 19 Aug 2019 06:57:30 +0000
Subject:

WITHOUT PREJUDICE

Dear Sampu,

We refer to your email dated on 19.08.2019 of the PRI Notice of your client's vehicle SKK7762A.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT Appraisal Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.

Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: Monday, August 19, 2019 2:52 PM

To: Motor Claims SG - SG Common

Cc: jiapei@kscgp.com

Subject: Notice to Conduct Pre-repair Survey - Your Ref: SLE 9478C - Our Ref: SKK 7762A/RCA/jp/ps

Dear Sirs,

We refer to the above matter.

Please find enclosed Notice to Conduct Pre-repair Survey herewith for your attention.

Thank you.

Regards,

Sampu

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT

been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Your Ref : SLE 9478C

Our Ref : **SKK 7762A/RCA/jp/ps**

Date : 19 August 2019

Fax : **6538 3708**

Tel : **3152 0984**

Email : **accident@kscgp.com**

FWD Singapore Pte Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 17 AUGUST 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that our client is agreeable to appointing LLK Auto Consultants Pte Ltd as a Single Joint Expert.

The said vehicle can be surveyed / inspected at:

Address : RC Auto
160 Sin Ming Drive
#06-20 Sin Ming Autocare
Singapore 575722

Contact Person/Tel : Mr Tan Chuan Kim / 9761 9383

Yours faithfully,

PS

Your Ref : SLE 9478C

Our Ref : SKK 7762A/RCA/jp/ps

Date : 19 August 2019

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 22 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLE9478C	Accident Date	: 17/08/2019
TP Vehicle No	: SKK7762A	Assignment Date	: 19/08/2019
Make	: NISSAN SYLPHY	Est. Duration of Repair	: 10.00
Date of Inspection	: 17/08/2019		
Inspection At	: RC AUTO-160 SIN MING (HQ) 160 SIN MING DRIVE, #06-20 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,559.71
Revised Amount	:S\$	7,307.27
Check Items (Estimated)	:S\$	1,928.34
Total	:S\$	9,235.61

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	434B
Vehicle Details	
Vehicle No.:	SKK7762A
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	HR15279709B
Chassis No.:	JN1BAAG11Z0110605
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,900.00
Original Registration Date:	20 Jan 2010
First Registration Date:	20 Jan 2010
Transfer Count:	3
Actual ARF Paid:	\$17,900.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jan 2020
PARF Rebate Amount:	\$8,950.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,502.00
COE Rebate Amount:	\$755.00
Total Rebate Amount:	\$9,705.00

The information contained herein is correct as at 22 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 10:59
Date Of Accident	17/08/2019 14:30
Exact Location Of Accident	YISHUN AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK7762A
Insured/Policyholder	
Name Of Registered Owner	MOHAMMAD RASHID BIN ISMAIL
NRIC No	S0081434B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85696159
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	NISSAN
Model	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00005624
Cover Note Number	21/03/2019 TO 20/03/2020
Driver	
Name of Driver	MOHAMMAD RASHID BIN ISMAIL
NRIC No	S0081434B
Date Of Birth	15/08/1953
Occupation	INDOOR
Date Of Driving Pass	12/09/1981
Driving Experience	37 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85696159
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	NOEMAIL

Address	APT BLK 19 SELETAR RD #01-42
Postcode	807020
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLE
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : FARIDAH RAFFIK
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE9478C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBJ1621A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SHD3307E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Paul 19/08/19

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

19/08/19

Reporting Centre/Personnel's Signature
Name:
NRIC/FIN No.: *19/08/19*

Sketch Plan Pg. 2

Date of accident: 17/08/19 Time: 1430 Location: Yishun Ave 2.
 My Vehicle: SHD 3307E Vehicle: SLE 9478C Vehicle C: GBJ 1621A
 SKETCH PLAN (D) (B) (A) SKK 7762A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The front vehicle slow down + reduce my speed to a stop and suddenly the rear car hit onto my rear.
 When I came down, I realised it's a 4-car collision.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: RC Auto
 Email address: 160, Sin Ming Autocity #06-20 sin ming
 & myself: Drive S575722
 Email address: Drive S575722

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle: SKK 7762A

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personal Signature
 Name:
 NRIC/FIN No.: 1910819

AH LIM MOTOR CO. (P) LTD.

ESTIMATE RC AUTO

Not with air
11 Sep @ 3500/- Max
Resurvey After Paint
10 days

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722
Tel : 97619383 Email: rcauto5555@gmail.com
Reg. No. 53199168K

SKK 7762 A

Date : 19/8/2019

Quantity	Description/Particular	Unit Price	Amount	
	REAR BOOTLID		\$ B ₁ 799.10	✓
2 PCS	REAR BOOTLID HINGES@70		\$ R 140.00	X
2 PCS	REAR BOOTLID REFLECTORS@78		\$ R ₂ 156.00	X
	REAR BOOTLID NUMBER PLATE CHROME		\$ W ₂ 340.70	✓
	REAR BOOTLID LOCK		\$ R ₂ 91.80	✓
	REAR BOOTLID RUBBER	37.10 SN	DIS/RS 74.20	502in
	REAR BOOTLID SYLPHY EMBLEM		\$ R ₂ 62.40	✓
	REAR BOOTLID NISSAN EMBLEM		\$ R ₂ 33.80	✓
	REAR BUMPER		\$ B ₁ 784.40	✓
	REAR BUMPER CHROME MOULDING		\$ CM 146.00	✓
1/2 PCS	REAR BUMPER BRACKETS@84.40	015 B ₁	\$ 168.80	4+
	REAR BUMPER INNER SPONGE		\$ R ₂ 32.80	X
2 PCS	REAR BUMPER SIDE RETAINER@64.40		\$ CM 128.80	✓
	REAR SPARE TYRE BOARD		\$ R ₂ 566.60	X
	REAR FLOORBOARD		\$ R ₂ 540.00	X
2 PCS	REAR TAILLAMP@345.40		\$ M ₂ CM 690.80	✓
	REAR END PANEL INNER GANISH		\$ CM 161.30	✓
2 PCS	REAR BOOTLID REFLECTORS@296.40		\$ R ₂ 592.80	X
1/2 PCS	REAR FENDERS@1787.80	215 R	015 B ₁ \$ 3,575.60	4+
	REAR FENDERS INNER GANISH@230		\$ R ₂ 460.00	X

Received the above goods in good order and condition

108

for RC AUTO

Received by

E.&O.E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price must be agreed
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised Signature

Acknowledged by Repairer

Signature:

Date:

INVOICE
RC AUTO

INVOICE NO:

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722
Tel : 97619383 Email: rcauto5555@gmail.com
Reg. No. 53199168K

Date : 19/8/2019

SKK 7762 A

Quantity	Description/Particular	Unit Price	Amount
	EXHAUST BOX		\$ 576.00
		TOTAL\$	\$ 10,121.90
		LESS-30% 10%	\$ 7,085.33
	TOWING FEES		\$ 70.00
	TO CHECK ALL WIRING		\$ 50.00
	TO REMOVE SEATS AND INNER GANISH TO FACILITATE REPAIR		\$ 120.00
1 SET	REAR BUMPER SENSORS		\$ <i>Nu</i> 280.00
	TO REMOVE AND REFIX REAR GLASS		\$ 150.00
	TO KNOCK AND RENEW ABOVE PARTS		\$ 1,500.00
	TO RESPRAY ALL AFFECTED PORTION		\$ 1,200.00
	TO RERFORM ANTI RUST		\$ 80.00
		TOTAL	\$ 10,535.33

Received the above goods in good order and condition

for **RC AUTO**

Received by

E.&O.E.

Authorised Signature
































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Aug 2019 Edit Reg		19 Aug 2019 00:00 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	GOH HWEE NGEE, ID: S8107712F								
Main Claimant:	MOHAMMAD RASHID BIN ISMAIL, ID: S0081434B								
Vehicle Reg. No.:	SKK7762A	Date of Loss:	17/08/2019 14:00 - :59 [114 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900024362	Policy/Cover Note No.:	PNPV2019-00013103 (Comprehensive) Coverage: 10/08/2019 - 09/08/2020						
Vehicle Reg. No. (Insured):	SLE9478C	Policy No. (Claimant):							
		Excess:							
Repairer:	Rc Auto-160 Sin Ming (HQ) 160 SIN MING DRIVE, #06-20 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKK7762A (1201900024362)**
[SLE9478C]
TP
MOHAMMAD RASHID BIN ISMAIL
Aug 17 2019 2:00PM
[GOH HWEE NGEE]
Rc Auto-160 Sin Ming

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	22/08/19 16:04	Adjuster Immediate Advice				 Load HTM			
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
2	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
3	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
4	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
5	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
6	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
7	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
8	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
9	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
10	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
11	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
12	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
13	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
14	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
15	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
16	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
17	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
18	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
19	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
20	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
21	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
22	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
23	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
24	23/08/19 12:01	Odometer Reading				 Load JPG		<input checked="" type="checkbox"/>	
25	23/08/19 12:01	Chassis Number				 Load JPG		<input checked="" type="checkbox"/>	
26	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
27	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
28	23/08/19 12:01	General View				 Load JPG		<input checked="" type="checkbox"/>	
Documentation						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)				Thumbnail		Print	
1	20/08/19 09:55	SLE9478C OI GIA				 Load PDF			
2	20/08/19 09:57	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK				 Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer	
<small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD19014454/KQD3E2

Date: 27/08/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00013103
Claimant Vehicle No : SKK7762A **Insured Vehicle No :** SLE9478C
 Date of Loss: 17/08/2019 Nature of Claim: TP Claim No: 1201900024362

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK7762A**
 Make & Model: NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A) Engine No: HR15279709B
 Reg. Date: 20/01/2010 (Man. Year: 2009) Chassis No: JN1BAAG11Z0110605
 Colour: Metallic Grey Odometer: 255079 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,389.71	4,837.27	4,552.44	48.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	2,470.00	700.00	22.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,559.71	7,307.27	5,252.44	41.82
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	12,559.71	3,500.00	9,059.71	72.13

INSPECTION

Date of Assignment: 19/08/2019
 Date Inspected: 20/08/2019 Inspected At: Rc Auto-160 Sin Ming (HQ)
 160 SIN MING DRIVE, #06-20 SIN MING
 AUTOCITY
 Singapore 575722

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2019)
Parts:	143	NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK7762A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	799.10 FL	*799.10 FL
2	2		*REAR BOOTLID HINGES	Repair	140.00 FL	*- FL
3	2		*REAR BOOTLID REFLECTORS	Serviceable	156.00 FL	*- FL
4	1		*REAR BOOTLID NUMBER PLATE CHROME	Warped	340.70 FL	*340.70 FL
5	1		*REAR BOOTLID LOCK	Dented	91.80 FL	*91.80 FL
6	1		*REAR BOOTLID RUBBER (\$74.20) (50%)	Distorted / Dented	66.78 FS	*37.10 FS
7	1		*REAR BOOTLID SYLPHY EMBLEM	Necessary	62.40 FL	*62.40 FL
8	1		*REAR BOOTLID NISSAN EMBLEM	Necessary	33.80 FL	*33.80 FL
9	1		*REAR BUMPER	Bent	784.40 FL	*784.40 FL
10	1		*REAR BUMPER CHROME MOULDING	Cracked	146.00 FL	*146.00 FL
11	1		*REAR BUMPER BRACKETS	O/S Bent	168.80 FL	*84.40 FL
12	1		*REAR BUMPER INNER SPONGE	Serviceable	32.80 FL	*- FL
13	2		*REAR BUMPER SIDE RETAINER	Cracked	128.80 FL	*128.80 FL
14	1		*REAR SPARE TYRE BOARD	Serviceable	566.60 FL	*- FL
15	1		*REAR FLOORBOARD	Serviceable	540.00 FL	*- FL
16	2		*REAR TAILLAMP	Mtg Cracked	690.80 FL	*690.80 FL
17	1		*REAR END PANEL INNER GARNISH	Cracked	161.30 FL	*161.30 FL
18	2		*REAR BOOTLID REFLECTORS	Serviceable	592.80 FL	*- FL
19	1		*REAR FENDERS	N/S Repair / O/S Buckled	3,575.60 FL	*1,787.80 FL
20	1		*REAR FENDERS INNER GARNISH	Serviceable	460.00 FL	*- FL
21	1		*EXHAUST BOX	Repair	576.00 FL	*- FL
22	1		*SET REAR BUMPER SENSORS	Dented	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **10,394.48** **5,348.40**
 - List Item Discount on L Items 10.00/10.00% (\$\$) 1,004.77 511.13

Total Parts (\$\$) **9,389.71** **4,837.27**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEES	New	70.00	50.00
2	TO CHECK ALL WIRING	New	50.00	20.00
3	TO REMOVE SEATS AND INNER GANISH TO FACILITATE REPAIR	New	120.00	100.00
4	TO REMOVE AND REFIX REAR GLASS	New	150.00	120.00
5	TO KNOCK AND RENEW ABOVE PARTS	New	1,500.00	1,100.00
6	TO RESPRAY ALL AFFECTED PORTION	New	1,200.00	1,000.00
7	TO RERFORM ANTI RUST	New	80.00	80.00
Gross Labour Cost (S\$)			3,170.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >