



Service Request Details

Claim	S9M01X83
Reference	None
Loss Date	8 August 2019
Report Date	16 Aug 2019 1:38:00 PM
Request Date	16 August 2019
Due Date	19 August 2020
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Fire

Actions

Next Step **Finish the work**

Complete Work

More ▾

Vehicle Information

Incident Vehicle YN5078Z
Registration #

Make MITSUBISHI

Model CANTER FEB21ER4SDEB

Service Address

,,,

Primary Contact/Insured

PN-I SERVICES PTE LTD
21 BUKIT BATOK CRESCENT, #24-73 WCEGA
TOWER, 658065, Singapore
65674755
HONGYEN.CHONG@ALLINK.COM.SG

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

FIRE - OD CLAIM

1

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement		Merimen	
 Fire Report - YN 5078Z.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	20 February 2020
 Investigation Report - YN 5078Z.pdf	Reports & Statement	Investigator / Adjustor Report	LKK AUTO CONSULTANTS PTE LTD (OD)	20 February 2020
 Discharge Voucher - YN 5078Z.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (OD)	20 February 2020
 Workshop Invoice - YN 5078Z.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (OD)	20 February 2020
 RESURVEY PHOTOS (2).pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	18 February 2020
 RESURVEY PHOTOS (1).pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	18 February 2020
 IA 23.9.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	23 September 2019
 MARK ESTIMATE.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	23 September 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 EMAIL TO VINS MOTOR- AWARD REPAIR TENDER- S9M01X83NPS - YN5078Z (FIRE CASE) - TENDER AWARD EMAIL(REPAIR).msg	Letters and Correspondence	Workshop	NG Stacey	11 September 2019
 EMAIL TO LKK- RE YN5078Z FIRE-OD CLAIM Ref S9M01X83.msg	Letters and Correspondence	Surveyor / Assessor	NG Stacey	11 September 2019
 SURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	20 August 2019
 P1920074_CI_00004_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	DHAKAL Raghav	16 August 2019
 P1920074_RN_00004_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	DHAKAL Raghav	16 August 2019
 YN5078Z insd gia report.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	16 August 2019
 OD PRI FROM WORKSHOP.pdf	Letters and Correspondence	Workshop	DHAKAL Raghav	16 August 2019
 Notice of acct YN5078Z.pdf	Other	Other	DHAKAL Raghav	16 August 2019