



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 16/08/2019

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB270Y
Case Reference Number	BUS/08/19/7015
Registration Date	22/5/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Qin Tao
Type of Accident	Head On
Accident Date and Time	15/8/2019 8:45 AM
Accident Reported Date and Time	15/8/2019 11:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB270Y - FRONT PORTION SLC2289M (TP) - INSURED WITH AIG. LEFT CENTRE PORTION
Prepared Date and Time	16/8/2019 7:47 AM
Chassis Number	WMAA22ZZ2C7001323
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$5,318.46	\$0.00
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$5,318.46	\$0.00
Lump Sum Total	\$5,300.00	\$0.00
Number of Repair Days	5.0	4
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	16/08/2019 8:00 AM	
Signature		
Remarks		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve
8322 8813
WHL MHL 16/8/19
4 day 2.00 pm
Ry AL sy

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 16/08/2019

User ID : GohKK2

Section D - Details of Repair Estimates										
Part 1 - Labour Works										
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,120.00				1590			
Total Labour			\$2,120.00							
Part 2 - Spray Painting & Panel Beating Related Works										
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00				528			
Total Spray Painting & Panel Beating			\$786.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense										
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable			
TOWING CHARGE			\$200.00				/ APC (11/11/19)			
Total Other Costs			\$200.00							
Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
6010151	Body	F01001-CE265	BUMPER, FRONT CENTR E, FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	✓ OR (GAP)	
6010154	Body	F01001-CW263	FLAP, FRONT, FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	✓ OR (GAP)	
6010304			FRONT HEADLAMP LH	1.00	\$1,603.60	10.00	\$1,443.24	Replace	✓ OR	
6010306	VE	81-25320-6111	FLASHER, AUX HEADLAMP, LH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	✓ OR	
6010153	Body	F01001-CW264	COVER, HEADLAMP, RT , LH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	✓ OR	
6009375	VM		RETAINER, MALE & FEMALE, REAR LID, MAN BUS	1.00	\$74.80	0.00	\$74.80	Replace	✓ BT	
			STICKER, SMRT	1.00	\$75.00	0.00	\$75.00	Replace	✓ APC	
6010073	Body	F01001-CW262	DOVE, FRONT, FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	✓ R	
Total					\$10,187.60		\$6,648.07			
Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Total										