

2007/2008

ASS. REC. BY:

REF: CS/FCI 1901 4485/Urd3n2

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

CWS

From (Person): Severe ton

of

Ref

Date/Time: 7:04pm @ 10/8/2019

Estimated Cost:

Bill to:

OD/PEP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 7418X

Insured:

SHD 3619E

at Workshop n/s

Ben Hooker

Tel:

62816520

of

No. 6 Defn Lane 4

Policy No:

Claim No:

D19005272MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8/8/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

9:30am @ 20/8/19

Person Contacted:

Raymond

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

FBL 7418X - X

SHD 3619E - NS/INC/0020760/Gr1

2019: 12/5/201

20/8/19

Email preli revised to FCI

(08/11/13) wef

ACS: REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Ni / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27A 4598

18/10/19 Confirmed Final by 948.20 with Raymond.
(Red 399.80, 3090)

RECEIVED 14 OCT 2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

14/10 - typist

Report Format:

Lump Sum / I.B.I: (\$ 948.20)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

100
50
50
55
255



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19005272MFSH

Our ref: CS/FCI19014485/Uvd3

DATE: 20/8/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO FBL 7418X


We thank for your instruction on 19/8/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 19/8/2019 at the premises of M/s BAN HOCK HIN CO PTE LTD

Workshop Estimate Amount	: S\$1,348.00
Revised Estimate Amount	: S\$941.20
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion and n/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	15-08-2019	Our Ref No. D19005272MFSH
Accident Date	08-08-2019	Claim Type. Third Party
Insured Vehicle	SHD3619E	Third Party Vehicle. FBL7418X
Survey Location	NO. 6 DEFU LANE 4	
Contact Person.	RAYMOND	
Contact No.	62816520/ 0	Fax No. 62842969
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. COR - \$1442.36)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BAN HOCK HIN CO. PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 20 August 2019 9:13 AM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005272MFSH/1-FBL 7418X
Attachments: FBL 7418X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle FBL 7418X
Date of survey: 19/8/2019
Number of days (estimated) : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 20 August 2019 8:02 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serener@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005272MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 19 August 2019 7:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Serener@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005272MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.

www.avg.com



(/listing/usedbike/sym-sym-maxsym-400i/11547/)

SGD\$10800

Reg : 16/03/2016

Type: Scooters

400cc

58000km

SYM Maxsym 400 abs for sale. Viewing at Soon Hin Motors Pte Ltd. Address: Yishun Industrial Park A Block 1018 S768760. Tel 67524893. We accept Trade in and many other brands new and used mode...

Posted on : 31/07/2019

★ PAID AD

★ DEALER AD

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/SYM-SYM-MAXSYM-400I/11547/)

SYM Maxsym 400i (/listing/usedbike/sym-sym-maxsym-400i/13697/)



(/listing/usedbike/sym-sym-maxsym-400i/13697/)

SGD\$5999

Reg : 19/08/2013

Type: Scooters

400cc

67000km

Well Maintain. Bike Used For Going To Work & Home. Replace With New: Cone Bearing, Wheel Bearing, Front N Rear Tyre, Rear Brake Disc, Seat Cover, Brake Pad, Roller N Belting.

Posted on : 05/08/2019

★ DIRECT SELLER

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/SYM-SYM-MAXSYM-400I/13697/)

SYM Maxsym 400i (/listing/usedbike/sym-sym-maxsym-400i/13647/)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Club/Association/Organisation
Owner ID:	162D
Vehicle Details	
Vehicle No.:	FBL7418X
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2019
Vehicle Make:	SYM
Vehicle Model:	MAXSYM 400I CVT
Primary Colour:	Orange
Manufacturing Year:	2016
Engine No.:	MU107442
Chassis No.:	RFGLXA902HS800089
Maximum Power Output:	-
Open Market Value:	\$5,631.00
Original Registration Date:	27 Feb 2017
First Registration Date:	27 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$845.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,113.00
COE Rebate Amount:	\$4,595.00
Total Rebate Amount:	\$4,595.00

The information contained herein is correct as at 20 Aug 2019

OK

Transfer Fee Enquiry

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	FBL7418X
Vehicle Type:	P01 - Passenger Scooter
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	SYM
Vehicle Model:	MAXSYM 400I CVT
Chassis No.:	RFGLXA902HS800089
Propellant:	Petrol
Engine No.:	MU107442
Engine Capacity:	400 cc
Maximum Power Output:	-
Maximum Laden Weight:	399 kg
Unladen Weight:	219 kg
Year Of Manufacture:	2016
Original Registration Date:	27 Feb 2017
Lifespan Expiry Date:	-
COE Category:	D - Motorcycle
Quota Premium:	\$6,113.00
COE Expiry Date:	26 Feb 2027
Road Tax Expiry Date:	26 Aug 2019
Inspection Due Date:	26 Feb 2020
Intended Transfer Date:	19 Aug 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 26 Aug 2019. You may renew the road tax from 27 May 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 26 Aug 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 27 Aug 2019 to 26 Feb 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	55.00	-	55.00
Total Amount Payable:			80.00

Amount Payable (From 27 Aug 2019 to 26 Aug 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	110.00	-	110.00
Total Amount Payable:			135.00

You may print this page for reference.

OK

Print



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

MOTOR CLAIMS DEPT

VEHICLE NO. : FBL7418X
MAKE/MODEL : SYM / MAXSYM 400I CVT

NO. : 34599

DATE : 16/08/2019
CLAIM NO. : 11410
POLICY NO. :

FROM : RAYMOND

Not Adult
Lian
The phb Attorney
3 day
19/8/19
P/P \$948.20

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 29008	REPLACE	1.00	\$38.00	scr 38.00
2	COVER LIGHT BOX V56N P/N: 63376	REPLACE	1.00	\$80.00	scr 80.00 X
3	COVER OUTER ASSY .BK-001U P/N: 55354	REPLACE	1.00	\$119.00	scr 119.00
4	LABOUR P/N: 06766	Supply/Install *	1.00	\$350.00	220 350.00
5	LEVER LH P/N: 55102	REPLACE	1.00	\$83.00	scr 83.00
6	L-FR COVER GARNISH BK P/N: 55050	REPLACE	1.00	\$18.00	cur 18.00
7	MIRROR LH P/N: 57022	REPLACE	1.00	\$140.00	cur 140.00
8	SPRAY PAINTING - LH HANDLE COVER, LH FRONT COWLING, LH LOWER COVER, LH SIDE COVER & REAR BOX	* REPLACE	1.00	\$450.00	300 450.00
9	STICKER (ORANGEFORCE) BOX REAR NEW P/N: 54254	* REPLACE	1.00	\$35.00	nm 35.00
10	STICKER (ORANGEFORCE) COVER SIDE NEW P/N: 54256	* REPLACE	1.00	\$35.00	nm 35.00

SUB TOTAL
GST @ 7 %

GRAND TOTAL

\$1,348.00
\$94.36

\$1,442.36

50% deposit required before ordering of parts.



P-398
102
358.20
948.20
bizSAFE3



Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001: 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
Validity: 30 days					

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To survey damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - This work survey is on a "Without Prejudice" basis
 - No modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000268K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34599

- Rev. 3

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

DATE : 16/08/2019
CLAIM NO. : 11410
POLICY NO. :

MOTOR CLAIMS DEPT

FROM : RAYMOND

VEHICLE NO. : FBL7418X
MAKE/MODEL : SYM / MAXSYM 400I CVT

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 29008	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
2	COVER OUTER ASSY .BK-001U P/N: 55354	REPLACE	1.00	\$119.00 Disc %: 10.00	107.10
3	LABOUR P/N: 06766	Supply/Install	1.00	\$220.00	220.00
4	LEVER LH P/N: 55102	REPLACE	1.00	\$83.00 Disc %: 10.00	74.70
5	L-FR COVER GARNISH BK P/N: 55050	REPLACE	1.00	\$18.00 Disc %: 10.00	16.20
6	MIRROR LH P/N: 57022	REPLACE	1.00	\$140.00 Disc %: 10.00	126.00
7	SPRAY PAINTING - LH HANDLE COVER, LH FRONT COWLING, LH LOWER COVER, LH SIDE COVER & REAR BOX	REPLACE	1.00	\$300.00	300.00
8	STICKER (ORANGEFORCE) BOX REAR NEW P/N: 54254	REPLACE	1.00	\$35.00	35.00
9	STICKER (ORANGEFORCE) COVER SIDE NEW P/N: 54256	REPLACE	1.00	\$35.00	35.00

SUB TOTAL

GST @ 7 %

GRAND TOTAL

\$948.20

\$66.37

\$1,014.57

50% deposit required before ordering of parts.

Validity: 30 days



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0103
ISO 1001: 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	For & on Behalf of				Acknowledge & Accepted By
	BAN HOCK HIN CO PTE LTD				



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

bizSAFE₃

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19014485/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3619E	Veh. Inspected	FBL 7418X
Policy No.		Coverage (\$)	0.00
Claim No.	D19005272MFSH	Excess (\$)	0.00
Assign From	SERENE TAN	Assign Date	19/08/2019
2. Vehicle Particulars & Condition			
Make & Model	SYM MAXSYM	c.c	400
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RFGLXA902HS800089	Colour	ORANGE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70 R15	METZELER	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	100/60 R14	METZELER	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/08/2019	Inspection Date	19/08/2019
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 7418X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BALANCER HANDLE	SCRATCHED	38.00	38.00
1	COVER LIGHT BOX V56N	SERVICEABLE	80.00	-
1	COVER OUTER ASSY BK-001U	SCRATCHED	119.00	119.00
1	LEVER LH	SCRATCHED	83.00	83.00
1	L-FR COVER GARNISH BK	CUT	18.00	18.00
1	MIRROR LH	CUT	140.00	140.00
	LESS 10% DISCOUNT		-	-39.80
			478.00	358.20
SPECIAL NETT ITEMS				
1	STICKER (ORANGEFORCE) BOX REAR NEW (SN)	NECESSARY	35.00	35.00
1	STICKER (ORANGEFORCE) COVER SIDE NEW (SN)	NECESSARY	35.00	35.00
			70.00	70.00
LABOUR				
	LABOUR.		350.00	220.00
	SPRAY PAINTING-LH HANDLE COVER,LH FRONT COWLING,LH LOWER COVER,LH SIDE COVER & REAR BOX.		450.00	300.00
			800.00	520.00
GRAND TOTAL			1,348.00	948.20
RECOMMENDED COST OF REPAIRS				948.20

Report Ref No. CS/FCI19014485/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.