

CC 4/III 1901 4527, K 903

LKE  
IDAC

Surveyor: Kenneth.

DOI: 10/8/19

Date / Time: 20/8/19

Registered in Meriten: 20/8/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 1001E

Name of Insured : LTM

Insured Tel No. : HP: 15/8/19

Excess Sec II :SS D.O.A: 15/8/19

Is driver the owner? ( YES / NO ) Nature of Accident :

If NO, Driver Name / Age : TAN LUYE SEH

Driver Tel No. : (V/L: YES / NO )

Claim No. :

Policy No. : MUOMABLT

Make / Model : Toyota

Place of Accident : BCP

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SKN 2849B

SHC 1001E

SMW 21919

SW 8998C



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS: wei  
WSP: lee  
Tel:  
Liability:  
RMKS: TP



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time	STAGE	DATE/ PIC
23/8/19	Non-Reporting ltr (1st):	
23/8/19	Non-Reporting ltr (2nd):	
23/8/19	Non-Reporting ltr (Final):	
23/8/19	Notification ltr (if non-pickup):	
23/8/19	Call GI:	
23/8/19	After call ltr to GI:	
23/8/19	Documentation Check List: Handler Typist	
23/8/19	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
23/8/19	After call ltr to GI:	<input checked="" type="checkbox"/>
23/8/19	Authorization To Act:	<input checked="" type="checkbox"/>
23/8/19	Release Voucher:	<input checked="" type="checkbox"/>
23/8/19	Final Repair Bill:	<input checked="" type="checkbox"/>
23/8/19	Car Rental Invoice:	<input checked="" type="checkbox"/>
23/8/19	Towing Invoice:	<input checked="" type="checkbox"/>
23/8/19	LTA / GIA :	<input checked="" type="checkbox"/>
23/8/19	Medical Bill:	<input checked="" type="checkbox"/>
23/8/19	PIR:	<input checked="" type="checkbox"/>
23/8/19	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
23/8/19	LOD:	<input checked="" type="checkbox"/>
23/8/19	Payment Breakdown Form:	<input checked="" type="checkbox"/>
23/8/19	Post-Repair Photos:	<input checked="" type="checkbox"/>
23/8/19	Others:	<input checked="" type="checkbox"/>

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	Confirm with:	Confirm by: Kenneth
<b>FINALIZATION</b>	Date/Time:	Repair Cost: 45	SS 1180.00 (16 days) Reduction: 5248.40 % 52	Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time:	Confirm with	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 286 (11)	If NO or B 28, Ass. Lia : 0%	
Repair Cost:	SS 5146.00		C-C (01 last 3)	
Loss of Rental (LOR):	SS 15.00 (15 days)			
Loss of Use (LOU):	SS 350.00 (15 days)			
Loss of Income (LOI):	SS 15.00 (15 days)			
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> [Tick only one]				
GIA/LTA Search	SS 7.45			
Medical:	SS -			
Disbursement:	SS -	(e.g. Tow/ Independent)		
Legal Cost	SS -			
Total:	SS 5503.45	Global Sum SS:		
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	SS 5503.45	Name 1: Wei Lee Motor Works		
Payee 2: (Strike if N.A.)	SS -	Name 2:		
Payee 3: (Strike if N.A.)	SS -	Name 3:		

ASS. REC. BY:

REF:

7/1

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: MCAR M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NII / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

Date/Time, File Return to?

2

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fuel

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	813C
Vehicle Details	
Vehicle No.:	SMN2151G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	Z6871484
Chassis No.:	JM6BL10Z1A0158708
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$20,274.00
Original Registration Date:	24 Nov 2010
First Registration Date:	24 Nov 2010
Transfer Count:	2
Actual ARF Paid:	\$20,274.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Nov 2020
PARF Rebate Amount:	\$11,150.00
Intended COE Rebate Details	
COE Expiry Date:	23 Nov 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$4,885.00
Total Rebate Amount:	\$16,035.00

The information contained herein is correct as at 22 Aug 2019

OK

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.  
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

19, aug 2019

India International Insurance pl  
64 Cecil street #04/#05/#06-02  
IOB Building S 049711

Attn: Motor claim dept-3<sup>rd</sup> party claim

Claiming against your insured vehicle no: SHC1001E

Accident involving vehicle no: SMN2151G/SHC1001E/SLN8998C/SKN2849B/JSS6906

DOA: 15/08/2019 AT SLE(after Thomson)twds BKE

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SMN2151G

To supply--

Description	Qty	Amount	
Lid	1	Rs 1220.00	✓
Lid lock	1	Rs 187.00	✓
Lid-Mazda logo	1	Rs 75.00	✓
Lid-Mazda emb;em	1	Rs 39.00	✓
Lid-3 emblem	1	Rs 26.00	✓
Lid reflector	1	Rs 338.00	x
Rear bumper	1	Rs 1,103.00	✓
Rear bumper reflector @63	2	Rs 126.00	✓
End panel	1	430.00	?
End panel top garnish	1	203.00	?
Boot weatherstrip	1	148.00	?
Rear bumper enforcement	1	557.00	?
Front bumper	1	Rs 1,078.00	✓
Front bumper enforcement	1	464.00	?
Front bumper sponge	1	102.00	?
Front support panel	1	515.00	?
Front grille, center	1	Rs 239.00	✓
Front bumper tow cover	1	Rs 29.00	✓
Front bumper foglamp cover @72	2	144.00	?
Headlamp @1175	2	Rs 2,350.00	✓
Parts		9,373.00	
Parts less less 20%		1,874.60	
		7,498.40	
foglamp cover, RH	1	76.00	?

*Not Withheld  
L1 Reg 87  
Passing After Pain*

**WEE Auto Consultants** hereby certify  
the Repairer of the Insured Vehicle

- To return vehicle to owner as soon as possible
- To display damaged parts for inspection
- Parts prices are subject to market rates
- Third party survey is on a "no time limit" basis
- No illegal modifications to be made

Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*6-8 days*

Vehicle No: SMN2151G

To remove damaged parts and attachments, front n rear

Cut n weld damaged panel

Straighten chassis where necessary

Repair/reshape damaged/dented areas

Rep;ace/align all parts into position

To spray paint-front n rear

\$ 1,300.00 ?

\$ 1,250.00 1000/

---

\$ 10,048.40

## Nivitha (LKK Auto)

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 20 August 2019 9:41 AM  
**To:** karen Seah; sur@lkkauto.com; Admin-D (LKKAuto)  
**Subject:** RE: TP survey for vehicle no: SMN2151G & SHC1001E(III) on 15/08/2019  
**Attachments:** doc03158020190819131453.pdf

11-01 am @ 2018/19  
karen  
vehicle in  
sup Kennedy

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SMN2151G and let us have your report urgently.

This claim will be handled by Aida.

\*Kindly upload this survey request email to merimen.

Thank You.

Daniel Pooi  
**Motor Claims Department**  
**India International Insurance Pte Ltd**  
64 Cecil Street #04-02 IOB Building  
Singapore 049711  
Tel: 6347 6100 Ext 202 Fax: 6224 4174  
**S&P 'A-' rated Company**



**From:** karen Seah [mailto:weileemotorworks@gmail.com]  
**Sent:** Monday, 19 August, 2019 2:34 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** Re: TP survey for vehicle no: SMN2151G & SHC1001E(III) on 15/08/2019

Vehicle No: SMN2151G

Dear officer incharge  
We would like to have LKK Auto Consultants to survey the vehicle.  
Thank you.

On Mon, Aug 19, 2019 at 2:17 PM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Daniel Pooi

**Motor Claims Department**

**India International Insurance Pte Ltd**

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 202 Fax: 6224 4174

*S&P 'A-' rated Company*



**From:** karen Seah [mailto:[weileemotorworks@gmail.com](mailto:weileemotorworks@gmail.com)]

**Sent:** Monday, 19 August, 2019 1:15 PM

**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

**Subject:** TP survey for vehicle no: SMN2151G

Your insured vehicle no: SHC1001E

Accident involving vehicle no: SMN2151G/SHC1001E/SLN8998C/SKN2849B/JSS6906

DOA: 15/08/2019 AT SLE(after Upp Thomson twds BKE)

Dear officer incharge

I refer to the above case, attached with the accident report/police report.

Kindly arrange to survey the vehicle. ASAP.

thank you.

--

Best Regards,

Karen Seah

---

Wei Lee Motor Works

Block 9 Sin Ming Industrial Estate

#01-32 Singapore 575644

Tel: 6456 9830

Fax: 6458 0128

Company registration: 269436/00J

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



Best Regards,

Karen Seah

---

Wei Lee Motor Works  
Block 9 Sin Ming Industrial Estate  
#01-32 Singapore 575644  
Tel: 6456 9830  
Fax: 6458 0128  
Company registration: 269436/00J

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

威利摩哆  
**WEI LEE MOTOR WORKS**

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

06,Sep 2019

India International Insurance PL

Attn: Motor claim dept-3<sup>rd</sup> party claim

Claiming against your insured vehicle no: SHC1001E

Accident involving vehicle no:SMN2151G/SHC1001E/SLN8998C/SKN2849B/JSS6906

ON 15/08/2019 AT SLE -after Thomson twds BKE

Dear officer incharge

We are the workshop for the owner of vehicle no: SMN2151G

Regarding the claim for the case above, this is a liability clear case considering that your client's vehicle collided into the rear portion of our client's vehicle,the impact caused my client's vehicle move forward and hit to the front vehicle.

The claim for vehicle No: SMN2151G as follow:-

Cost of repair to SMN2151G	\$ 4,800.00	finalised with your surveyor
GST 7%	\$ 336.00	
Loss of use	\$ 480.00	\$80x06d
LTA search fee	\$ 7.45	

-----  
\$ 5,623.45

Enclosed with all the necessary document for your reference.

Kindly let us have your reply soonest possible.

Thank you.



## AUTHORIZATION TO ACT

I, KH Leasing Pte Ltd ("the third party claimant")  
of 261 A Upp Thomson Road (address),  
owner of SMN 2151 G (vehicle no.) hereby authorize  
Wei Lee Motor Works  
("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SMN 2151 G that was  
damaged pursuant to the accident which occurred on 5/8/19 (date) along  
3LE - after Thomson Leds BKE (location)  
involving vehicle no/s 8AC 1001 E / SN 8998 C ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment further to settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 15 day of Aug (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER

#### III-Direct Settlement (PODS)

India Ref: MCT19080361  
Claimant Ref: SMN2151G

We/I, WEI LEE MOTOR WORKS ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 5,136.00 (repair cost), S\$ 360.00 (loss of use), S\$ 7.45 (search fee), vehicle no. SMN2151G that was damaged pursuant to the accident which occurred on 15/08/2019 (date) at SLE (AFTER UPPER THOMSON) TOWARDS BKE (location) involving vehicle no. SHC1001E (insured vehicle). This is pursuant to the inspection conducted on 20/08/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner KH LEASING PTE. LTD. ("the third party claimant") of vehicle no. SMN2151G to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SMN2151G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 5,503.45 to WEI LEE MOTOR WORKS

Dated this 30 day of oct 2019

#### CLAIMANT:

Signature:


Name:

NRIC:

Address:

Nationality:

Occupation:

  
Signed by "the workshop" (with chop)  
Wei Lee Motor  
269436100J  
BK9, Sunway Ind  
#01-32

#### WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



KSC

Signed by appointed Surveyor

LKK Auto Consultants Pte Ltd

199607198R

51 Ubi Avenue 1  
#01-25 Paya Ubi Ind. Park S(408933)

威利摩托  
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-28,  
SINGAPORE 575644.  
TEL: 6459 9830 FAX: 6458 0128  
Business Regn No: 269436/00J  
GST Regn No: 26-943600-J

TAX INVOICE

M/S : India International Insurance PL

NO : WL03827

Vehicle No : SMN2151G

Date : 06-SEP-2019

<u>Quantity</u>	<u>Particulars</u>	<u>Unit Price</u>	<u>Amount Incl. GST</u>
<b>SMN2151G</b>			
1.00	Your insured vehicle no: SHC1001E Accident involving vehicle no: SMN2151G/SHC1001E/SLN8998C/SKN2849B/JS S6906 DOA: 15/08/2019		
1.00	Cost of repair for vehicle no: SMN2151G Lump sum repaired as recommended by your appointed surveyor, LKK Auto Consultants	\$4,800.00	\$4,800.00
1.00	GST 7%	\$336.00	\$336.00
Total Amount Incl. GST			<b>\$5,136.00</b>
Standard Rate GST Amount (7.00%)		\$336.00	
Total Amount Before GST		\$4,800.00	



**Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-190819-001352**

1 message

LTA <LTA-VTL@lta.gov.sg>  
To: weileemotorworks@gmail.com

Mon, Aug 19, 2019 at 12:42 PM

**Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-190819-001352**

Dear Sir/Madam

We wish to inform you that your transaction on "Enquire Vehicle Insurance Particulars" performed on 19 Aug 2019 was successful and the Receipt No. is ITNET-00000-190819-001352.

2. The details of the search results are as follow:

Vehicle No.	Search Date	Search Time	Search Result
-------------	-------------	-------------	---------------

SHC1001E	15 Aug 2019	21:30:00	INDIA INT'L INS PTE LTD
----------	-------------	----------	-------------------------

3. Please contact our customer service officers at tel : 1800-CALL LTA (1800-2255 582) should you require further assistance.
4. Visit [www.onemotoring.com.sg](http://www.onemotoring.com.sg) for more information, or go to [www.lta.gov.sg/feedback](http://www.lta.gov.sg/feedback) if you have any feedback. This email is auto-generated, please do not reply to this email.
5. Thank you.

If you are not the intended recipient of this communication, please delete it.

As it may contain confidential or official information, do not retain it or disclose the contents to any person as it may be an offence under the Official Secrets Act.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2019 <a href="#">Edit Reg</a>		20 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	KH LEASING PTE LTD, Co. Reg. No.: 201611813C								
Vehicle Reg. No.:	SMN2151G	Date of Loss:	15/08/2019 21:00 - :59 [104 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19080361	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC1001E	Policy No. (Claimant):	5111595419						
		Excess:							
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/08/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (23/10/2019): Alert - Adj Mandate Approved (S\$5503.45) - SMN2151G - Claim Handler: Zuhaidah Bt...</li> <li>III_SG (23/08/2019): Alert - Adj Mandate Approved (S\$0.00) - SMN2151G - Claim Handler: Zuhaidah Bte S...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SMN2151G (MCT19080361)  
[SHC1001E]  
TP  
KH LEASING PTE LTD  
Aug 15 2019 9:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Wei Lee Motor Works

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
2	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
3	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
4	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
5	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
6	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
7	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
8	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
9	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
10	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
11	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
12	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
13	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
14	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
15	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
16	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
17	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
18	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
19	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
20	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
21	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
22	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
23	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
24	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
25	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
26	22/10/19 19:01	General View		Load JPG	<input checked="" type="checkbox"/>		
27	22/10/19 19:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
28	22/10/19 19:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
29	22/10/19 19:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
30	22/10/19 19:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
31	22/10/19 19:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
32	22/10/19 19:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
33	22/10/19 19:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
34	22/10/19 19:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
35	22/10/19 19:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
36	22/10/19 19:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	20/08/19 15:24	EMAIL FROM III DD 20082019		Load PDF			
2	20/08/19 15:24	TP GIA REPORT		Load PDF			
3	22/08/19 17:23	TP ESTIMATE- MARKED		Load PDF			
4	21/10/19 16:34	LTA SEARCH		Load PDF			
5	08/11/19 10:30	WORKSHOP INVOICE		Load PDF			



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
6	08/11/19 10:30	AUTHORISATION TO ACT FORM		Load PDF
7	08/11/19 10:30	DISCHARGE VOUCHER		Load PDF
8	08/11/19 10:30	LOD		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/08/19 10:44	Singapore Accident Statement IV SHC1001E		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> <div></div> <div></div> </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19014527/KGB3Q2

Date: 08/11/2019

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: SMN2151G Insured Vehicle No: SHC1001E  
 Date of Loss: 15/08/2019 Nature of Claim: TP Claim No: MCT19080361

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN2151G**  
 Make & Model: MAZDA 3, 1.6 (A) Engine No: Z6871484  
 Reg. Date: 24/11/2010 (Man. Year: 2010) Chassis No: JM6BL10Z1A0158708  
 Colour: Metallic Grey Odometer: 124285 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 5 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,559.20	5,196.80	2,362.40	31.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,800.00	750.00	29.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,109.20</b>	<b>6,996.80</b>	<b>3,112.40</b>	<b>30.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
(S\$)	10,109.20	4,800.00	5,309.20	52.52
<b>+ GST 7.00/7.00% (S\$)</b>	707.64	336.00	371.64	52.52
<b>Nett Amount (S\$)</b>	<b>10,816.84</b>	<b>5,136.00</b>	<b>5,680.84</b>	<b>52.52</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,503.45</b>		

### INSPECTION

Date of Assignment: 20/08/2019  
 Date Inspected: 20/08/2019 Inspected At: Wei Lee Motor Works (HQ)  
 BLOCK 9 SIN MING INDUSTRIAL  
 ESTATE #01-32  
 Singapore 575644

Estimated Period of Repair: 6.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Oct 2019)

Parts: 144 MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMN2151G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LID	Bent	1,220.00 FL	*1,220.00 FL
2	1		*LID LOCK	Dented	187.00 FL	*187.00 FL
3	1		*LID -MAZDA LOGO	Necessary	75.00 FL	*75.00 FL
4	1		*LID -MAZDA EMBLEM	Necessary	39.00 FL	*39.00 FL
5	1		*LID-3 EMBLEM	Necessary	26.00 FL	*26.00 FL
6	1		*LID REFLECTOR	Serviceable	338.00 FL	*- FL
7	1		*REAR BUMPER	Buckled	1,103.00 FL	*1,103.00 FL
8	2		*REAR BUMPER REFLECTOR	Cracked	126.00 FL	*126.00 FL
9	1		*END PANEL	Repair	430.00 FL	*- FL
10	1		*END PANEL TOP GARNISH	Serviceable	203.00 FL	*- FL
11	1		*BOOT WEATHERSTRIP	Serviceable	148.00 FL	*- FL
12	1		*REAR BUMPER ENFORCEMENT	Bent	557.00 FL	*557.00 FL
13	1		*FRONT BUMPER	Mtg Cracked	1,078.00 FL	*1,078.00 FL
14	1		*FRONT BUMPER ENFORCEMENT	Bent	464.00 FL	*464.00 FL
15	1		*FRONT BUMPER SPONGE	Cracked	102.00 FL	*102.00 FL
16	1		*FRONT SUPPORT PANEL	Serviceable	515.00 FL	*- FL
17	1		*FRONT GRILLE ,CENTER	Dented	239.00 FL	*239.00 FL
18	1		*FRONT BUMPER TOW COVER	Dented	29.00 FL	*29.00 FL
19	2		*FRONT BUMPER FOG LAMP COVER	Serviceable	144.00 FL	*- FL
20	1		*HEADLAMP	O/S Mtg Cracked	2,350.00 FL	*1,175.00 FL
21	1		*FOG LAMP COVER ,RH	Distorted	76.00 FL	*76.00 FL

F=Franchise part. L=List Item Disc.

Sub Total (\$\$)	9,449.00	6,496.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,889.80	1,299.20
Total Parts (\$\$)	7,559.20	5,196.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS ,FRONT REAR CUT N WELD DAMAGED PANEL STRAIGHTEN CHASSIS WHERE NECESSARY REPAIR /RESHAPE DAMAGED /DENTED AREAS REPLACE /ALIGN ALL PARTS INTO POSITION	New	1,300.00	800.00
2	TO SPRAY PAINT- FRONT N REAR	New	1,250.00	1,000.00
Gross Labour Cost (\$\$)			2,550.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >