

22/03/2019

ASS. REC. BY:

REF: CF/MSG 19014530/Cgd3

Special Instruction:

Surveyor: Simon

ASSIGNMENT (Office)

Mekmen

From (Person): pang xiu shi

of

MSG

Date/Time: 14/8/19 5:03pm

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 5517

Insured:

at Workshop m/s

Ryder Auto

Tel: 6741 8277

of

2 keki Bukit Ave 2 # 02-19

Policy No: A29077929 QMY

Claim No:

601237

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

(Client's Record)

D.O.A.

28/7/2019

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Orson

Vehicle ☒ IN / OUT

| Date/Time | Action/Instruction                                                                               |
|-----------|--------------------------------------------------------------------------------------------------|
|           | Estimate <input checked="" type="checkbox"/>                                                     |
|           | SLL 5517                                                                                         |
|           | Cancel 16 Ryder feedback that they already received payment from MSG. <del>Cancel</del> 24/9/19. |
|           |                                                                                                  |
|           |                                                                                                  |



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)  
4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6827 7800  
[www.msig.com.sg](http://www.msig.com.sg)

Executive  
Claims Services

## Inspection Report

### Type of Survey:

|                      |     |
|----------------------|-----|
| OD - Excess          | 500 |
| TP Without Prejudice |     |

### Vehicle Details:

Vehicle Reg No  
Make  
Model  
Passenger capacity  
Paint colour & code  
Paint type

|             |
|-------------|
| SLL 551T    |
| KIA         |
| Cerato 1.6A |
| 05          |
| Silver      |
|             |

### Vehicle Extras:

In-built camera  
Modification

Yes / No  
Yes / No

### Vehicle Data:

Odometer reading  
Engine No  
VIN No  
Engine capacity  
Engine modification

|          |
|----------|
| 52849 km |
|          |
|          |
|          |
|          |

### Vehicle Condition:

Seviceable Yes / No

Handbrake  
Footbrake  
Steering  
Body  
Paint

|  |
|--|
|  |
|  |
|  |
|  |
|  |

### Tyre Condition:

Front right  
Front left  
Rear left  
Rear right

| Tread mm | Size                   | Condition |
|----------|------------------------|-----------|
| 5        | Michelin 215 / 45 / 17 |           |
| 5        | "                      |           |
| 4        | "                      |           |
| 4        | "                      |           |

### General Data:

Date of accident  
Date of inspection  
Date of assignment  
Inspection location

|            |
|------------|
| 28-07-2019 |
| 30-07-2019 |
| 30-07-2019 |
| Ryder.     |

### Painting Process:

Prepare off vehicle  
Painting off vehicle  
Neither (default)

|  |
|--|
|  |
|  |
|  |

### Cost Details:

Parts  
Supplementary  
Miscellaneous  
Body Labour  
Paint labour  
Paint material  
TOTAL  
Towing  
Excess  
Total less excess  
Estimated days for repair

| Repairer | Adjuster |
|----------|----------|
|          |          |
|          |          |
|          |          |
|          |          |
|          |          |
|          |          |
|          |          |
|          |          |
|          |          |
|          |          |

### Body Panel Repair:

Panel repair calculator used  
Yes / No

|  |
|--|
|  |
|  |

### Remarks:

Lump / Global Sum

|  |
|--|
|  |
|--|

Reason(s)

Margin Repair / Fast-line

### Others:

|  |
|--|
|  |
|  |
|  |
|  |

Repair Authorised

Date:

|  |
|--|
|  |
|--|

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                                               |
|------|-------------|---------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 29 Jul 2019 |               | 14 Aug 2019<br>17:03<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                   |                                                                                                                                                                                                                     |                        |                                                                              |
|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|
| Insured:          | FONG CHON KIAT, ID: S8086599F, Tel: +6597316849, Email: NOEMAIL                                                                                                                                                     |                        |                                                                              |
| Vehicle Reg. No.: | SLC551T                                                                                                                                                                                                             | Date of Loss:          | 28/07/2019 15:00 - :59<br>[38 Months and 29 Days From LTA Reg Date (Man Yr)] |
| Claim Type:       | OD / 601237                                                                                                                                                                                                         | Policy/Cover Note No.: | A29077929QMY (Comprehensive)<br>Coverage: 29/04/2019 - 28/04/2020            |
|                   |                                                                                                                                                                                                                     | Excess:                | S\$500.00                                                                    |
| Repairer:         | Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, 417921 Kaki Bukit - Tel:                                                                                                                   |                        |                                                                              |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pang Xiu Shi - 6594 2586]                                                                                                            |                        |                                                                              |
| Adjuster:         | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]                                                                                                                                  |                        |                                                                              |
| Driver/Custodian: | FONG CHON KIAT (38 / Male) , NRIC: S8086599F, Tel: +6597316849 Email: NOEMAIL                                                                                                                                       |                        |                                                                              |
| Adj Asg. Remarks: | As per Jason instruction, re-assigned to LKK to follow-up this case. To revert. Case has been assigned to Victor (IHS). Survey has been arranged for today morning (30/7/2019). Estimate will be given to surveyor. |                        |                                                                              |

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

[www.msig.com.sg](http://www.msig.com.sg)**PRELIMINARY ADVICE**


OD Claim / TP Claim

Attn : \_\_\_\_\_  
Date : \_\_\_\_\_Policy No : \_\_\_\_\_  
Claim No : \_\_\_\_\_Insured Vehicle No : SL4551TDate of Accident : 28-07-19TP Vehicle No : -Place of Survey : Ryder AutoMake & Model : KIA Cerato 1.6ADate of Survey : 30-07-19

Point of Impact / Damages :

Front.

Recommended Reserve :

Repairer's Estimate : \$ 7050.28Interim Adjustment : \$ 3117.26Check Items : \$ -Proposed : Part by Part / Lump Sum Repair \$2500/- Excess : \$ 500Estimate Repair Period : 03 daysPre-accident Market Value (for total loss consideration) : \$ 62000.00COE / PARF to owner : \$ 44048.00Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☒ OD Claim  
Excess : \$ \_\_\_\_\_  
(Authorised / Revert)

☐ TP Claim  
(Without Prejudice)

Vehicle No. SUL 551T

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 03 days

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 30-07-19

Victor - Seng @ sg.msig-asia.com

## ESTIMATE OF REPAIR

SLL551T Pg 1/1

Veh # : SLL551T Model : KIA FORTE K3 1.6A (16/11/2015)  
 Date Of Accident : 28/7/2019 OD : MSIG *victor*  
 Location : BT BATOK RD NEAR ITE COLLEGE WEST

| S/Nos. | Qty    | Description                                         | Surveyor<br>Remarks | Surveyor<br>Adj | Amount<br>\$        |                |
|--------|--------|-----------------------------------------------------|---------------------|-----------------|---------------------|----------------|
|        |        | <u>List Items</u>                                   |                     |                 |                     |                |
| 1      | 1 pc   | Front bumper / <i>Deformed</i>                      |                     |                 | 967.20              |                |
| 2      | 1 pc   | Front bumper cover (Lower) <i>X</i>                 |                     |                 | 398.70              |                |
| 3      | 1 pc   | Front bumper enforcement <i>X</i>                   |                     |                 | 609.20              |                |
| 4      | 10 pcs | Front bumper clips /                                |                     |                 | <del>65.00</del>    | <i>30</i>      |
| 5      | 2 pcs  | Front bumper o/s & n/s retainer / <i>braces</i>     |                     |                 | <del>206.20</del>   | <i>150</i>     |
| 6      | 1 pc   | Front grille / <i>braces</i>                        |                     |                 | 596.20              |                |
| 7      | 4 pcs  | Front grille clips / <i>well</i>                    |                     |                 | 26.00               |                |
| 8      | 1 pc   | Front bumper emblem / <i>braces</i>                 |                     |                 | 62.00               |                |
| 9      | 1 pc   | Front support panel <i>X</i>                        |                     |                 | 896.70              |                |
| 10     | 1 pc   | Air condenser <i>X</i>                              |                     |                 | 798.00              |                |
| 11     | 1 pc   | Radiator <i>X</i>                                   |                     |                 | 654.00              |                |
| 12     | 1 pc   | Number Plate garnish / <i>Deformed \$150</i>        |                     |                 | 5,279.20            | <i>+ \$450</i> |
| 13     | 1 pc   | Sponge / <i>Cracked - \$400</i> After -10%          |                     |                 | 4,751.28            | <i>+ \$405</i> |
|        |        | <u>Nett Items</u>                                   |                     |                 |                     |                |
| 1      | 1 pc   | Front reg. no. plate / <i>Deformed</i>              |                     |                 | 45.00               |                |
| 2      | 1 pc   | Front reg. no. plate bracket / <i>Deformed</i>      |                     |                 | 29.00               |                |
|        |        | Sub-Total                                           |                     |                 | 74.00               |                |
|        |        | <u>Labour</u>                                       |                     |                 |                     |                |
| 1      |        | To dismantle damaged parts, straighten and welding. |                     |                 | <del>1,000.00</del> | <i>500</i>     |
| 2      |        | To spray painting.                                  |                     |                 | <del>600.00</del>   | <i>400</i>     |
| 3      |        | To remove and refit air-cond condenser. <i>X</i>    |                     |                 | 120.00              |                |
| 4      |        | To remove and refit radiator. <i>X</i>              |                     |                 | 100.00              |                |
|        |        | Sub-Total                                           |                     |                 | 1,820.00            |                |
|        |        | Total                                               |                     |                 | 6,645.28            | <i>+ \$405</i> |
|        |        | After -20%                                          |                     |                 | 5,316.22            |                |

*Chan*

Chan San Choon  
 Director  
 DipEng, AAE MIMI, MSAE(Aust)



Authorised Workshop  
 Authorised Reporting Centre

8778 1999  
 24 hr accident call

**Mobil 1**

*bizSAFE*