

ASS. REC. BY:

REF:

CS/A3G19014542/Gvf312

Special Instruction:

Surveyor

G6

ASSIGNMENT (Office)

From (Person):

Har Yinul

of

A1G

Date/Time:

20.8.19 1.47p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMG 509J

Insured:

SMC 7798R

at Workshop m/s

King's Auto Repair & Service Pte Ltd

Tel:

6457 8629

of

BLK 176 Sing Ming Drive H02-10

Policy No:

1800085947

Claim No:

5864536949SG

Sum Insured:

Excess:

Make of Veh:

D.O.A. 17/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time:

20.8.19 3.56p.m

Person Contacted:

Annie

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMC 7798R - X

SMG 509J - X

22/8/19

@423pm Annie said case pass to lawyer

ASSIGNMENT

From: _____ Date: 21.8.2019
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SMG 509J
 at Workshop m/s King's Auto Repair
 of Blk 176 Sin Ming Drive #02-10
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehl: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMG 509J Yr Regn: 27 Apr 2018
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 420i G.C. 1998

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 15656 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA4H32010 BH132.89

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R18
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 21-08-19

Survey held at W/S 11:30

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

21/8 Estimate Given later

25/2 Finalized & placed with Alex (LS) CRad 4075.96, 5090

RECEIVED 25 FEB 2020

25/2/2020

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) esp - typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Report Format:

Merimen

Lump Sum / I.B.I. (\$)

4000/-

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS

) Photos

) Others

TOTAL

250

11

261

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2019 Edit Reg		20 Aug 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	GOH LICK CHAI, ID: S13953883								
Main Claimant:	POH AH WEE, ID: S6932932B								
Vehicle Reg. No.:	SMG509J	Date of Loss:	17/08/2019 17:00 - :59						
Claim Type:	TP / 5869536949SG	Policy/Cover Note No.:	1800085947 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMC7798R	Policy No. (Claimant):							
		Excess:							
Repairer:	King's Auto Air-conditioning (HQ) Blk 176 Sin Ming Dr #02-10 Singapore 575721, 575721 Sin Ming - Tel: 64578629								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (21/08/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION REQUEST – SMG509J vs SMC7798R (OI) on D.O.A.: 17/08/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Marissa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divy
Sent: 8/20/2019 1:47:00 PM
Attachments:  [PRJ-SMG509J.pdf](#)  [PRJ-SMG509J.PDF](#)

Hi,

Please refer to the enclosed request from **JusEquity Law Corporation**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

P. An

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.as

From: Alfred Ng (mailto:alfred_ng@juseq.com.sg)
Sent: Tuesday, August 20, 2019 11:34 AM
To: Hor, Yinnul
Subject: [EXTERNAL] ACCIDENT INVOLVING SMG509J AND SMC7798R ON 17/8/19

This message is from an external sender; be cautious with links and attachments.

Your ref: SMC7798R
Our ref: JEQ/SMC7798R/KA

Dear Yinnul,

We refer to your email today.

Our client is agreeable to appoint the following surveyor as our single joint expert.

Mr. Kenneth Kong-LKK Auto Consultants Pte Ltd.

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

King's Auto Repair & Service Pte Ltd
Blk 176 Sing Ming Drive
#02-10.
Singapore 575721
Tel: 6457-8629
Fax: 6451-7651
Person in charge : Alex Quek.

With Regards

Alfred Ng
Executive
On behalf of Mr Michael Yap
M/s JusEquity Law Corporation
No. 171 Chin Swee Road
#02-01/02/06 Singapore 169877
Tel : 6536 9339
Fax: 6536 5388

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

— Original Message —

From: Hor.Yinnul
To: alfred_ng@juseq.com.sg
Cc: Fong, Andy-SY ; Chin, Lee-Ying ; Abu Kassim, Noor Marissa ; Azlan, Syazairdina ; Chan, Yoke Shi ; Lim, Sheng Yang ; Mithoosingh, Aashweenjeetkaur ; Parthiban, Theerthan ; Subramaniam, Divyashni ; Tong, Wahxin
Sent: Tuesday, August 20, 2019 9:18 AM
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMC7798R AND SMG509J ON 17/08/2019



From: Alfred Ng [mailto:alfred_ng@juseq.com.sg]
Sent: Monday, August 19, 2019 4:15 PM
To: Hor, Yinrul
Subject: [EXTERNAL] NOTICE OF ACCIDENT

This message is from an external sender; be cautious with links and attachments.

Your ref: SMC7798R
Our ref: JEQ/SMG509J/KA

Dear Yinrul,

Kindly refer to our attachment

With Regards

Alfred Ng
Executive
On behalf of Mr Michael Yap
M/s JusEquity Law Corporation
No. 171 Chin Swee Road
#02-01/02/06 Singapore 169877
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06 CES Centre Singapore 169877
Telephone (65) 6536 9339 Fax: (65) 6536 5368 (Litigation)
Email : claims@juseq.com.sg Website: www.juseq.com.sg

Our Ref: JEQ/SMG509J/KA
Your Ref: SMC7798R

19 August 2019

AIG ASIA PACIFIC INSURANCE PTE LTD
(Claims Department)
78 Shenton Way
#08-16, AIG Building
Singapore 079120

VIA FAX
(Fax No. 6835-7416)

Dear Sir


ACCIDENT INVOLVING SMG509J AND SMC7798R ON 17 AUGUST 2019

We act for the owner of vehicle no. SMG509J.

We hereby notify you of a road traffic accident on 17/08/2019 at about 1700 hours at Ang Mo Kio McDonald carpark involving our client's vehicle and vehicle registration no. SMC7798R driven by your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Cc 
GOH LICK CHAI
229 Bishan Street 23
#05-57
Singapore 570229
(Your Ref: SMC7798R)

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 14:20
Date Of Accident	17/08/2019 17:00
Exact Location Of Accident	ANG MO KIO MCDONALD CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG509J
Insured/Policyholder	
Name Of Registered Owner	POH AH WEE
NRIC No	S6932932B
Email Address	ESLYNN.ESPRO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91886696
Alternative Phone No	OFFICE-91886696

Vehicle Particulars

Manufacturer	BMW
Model	420I-2.0 GRAN COUPE (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE

Fleet Policy NO

Policy Number P2229862

Cover Note Number

Driver

Name of Driver	POH AH WEE
----------------	------------

NRIC No S6932932B

Date Of Birth 30/09/1969

Occupation INDOOR

Date Of Driving Pass 26/02/1993

Driving Experience 26 YEARS AND 5 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-91886696

Fax Number

Contact Number OFFICE-91886696

Email Address ESLYNN.ESPRO@GMAIL.COM

Address	31 TERRASSE LANE #03-60
Postcode	544779
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO REPORT


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC7798R
Vehicle Make/Model/Colour	MITSUBISHI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GOH LICK CHAI
NRIC/Passport Number	S1395388J
Contact Number	97431789
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



A : SMG 509 J

B : SMC 7798R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I park my car in one of the parking lots available @ Amk McDonald. I was waiting for my friend when Mr. Goh reverse his Mitsubishi and hit my car. I was standing beside my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

19/8/19

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

AXA INSURANCE PTE LTD

8 Shenton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Centre #01-21
 Tel: 1800 8804888
 Website: www.axa.com.sg
 GST Registration Number : 199903512M
 customer.care@axa.com.sg



Original

Agent Code: 13854

Policy No. (if any):

New Business

SmartDrive Quote Ref:

MOTOR COVER NOTE

No. CN029238

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) - Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements.

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby HELD COVERED under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	POH AH WEE
MAKE AND DESCRIPTION OF VEHICLE	BMW 420 I GRAN COUPE LED NAV
VEHICLE REGISTRATION NO.	SMG509J
YEAR OF MANUFACTURE	2018
ENGINE NO.	F2741975B48B20A
CHASSIS NO.	WBA4H32010BH13289
ENGINE CAPACITY/TONNAGE	1998
COVER TYPE	COMPREHENSIVE
HIRE PURCHASE	DBS BANK LTD
VALUE (\$)	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: 04/01/2019 TO: 03/01/2020
EXCESS (\$)	900
AXA PREMIUM WORKSHOP?	NO



(WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).



Issued by SD CONTEGO SERVICES on 04/01/2019 10:19 am

AXA INSURANCE PTE LTD

Authorised Signature

Note: This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

- Premium for time on risk will be charged subject to minimum of S\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.
- An administrative fee of S\$26.75 (inclusive of GST) will be charged :
 - Cover note issued and cancelled before inception.
 - Retaining the old registration number for a new vehicle insuring with AXA.

PREMIUM WARRANTY

For Individual Customers:

Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.

For Non-Individual Customers:

Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days on inception / renewal / endorsement. For all other cases, the premium in full should be paid before inception.

MTRC/NOTE/01/03

**POLICYHOLDER ACKNOWLEDGEMENT FORM**Date: 14/8/19To: Owner of Vehicle Number: SMG 509 JThe following has been advised to you via your workshop, _____ through their staff,

Please tick the applicable box if you had been advised on any of the following:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☐ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/ personnel that the vehicle may not be road worthy.
- ☐ For vehicles below three (3) years old or under warranty with a local distributor, your insurance company will use only original parts to repair your vehicle.
- For vehicles above three (3) years old and no longer under warranty with a local distributor, your insurance company will be carrying out repairs where any damaged part that can be repaired will be repaired and any part that needs to be replaced will be replaced using *any combination* of original parts and/or original equipment manufacturer (OEM) parts and/or second-hand parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☐ Others _____

Signed and acknowledged by:

Name and signature of policyholder/ authorized driver* and company stamp (where applicable)

*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.

Name and signature of workshop personnel including company stamp

KING'S AUTO REPAIR & SERVICE PTE LTD

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721

TEL: 6457-8829 FAX: 6451-7651

Reg No. 201923475D

Tax : 62564314

DATE 27th Sept 2019

OUR REF Poh Ah Wee

31 Terrasse Lane

TO #03-60

Singapore 544779

RE Quotation For BMW 420i Gran Coupe LED NAV -S MG509J

Vg. 18.8

LKK

02/10/2019

Quantity	Item	Unit Price (\$)	Amount (\$)
1	Front Bumper Assy / Re		1,155.00 982.75
1	Front Bumper Sponge / ORA		55.00 43.05
1	Front Bumper Lower Garnish / BR BR		55.00 40.1
2	Front Parking Sensors X IPC IPC / DM	32.00 /	264.00 0
1	Front LH Head Lamp / CCA		2,970.00 2647.5
1	Front LH Fog Lamp /		506.00 276.4
1	Front Fog Lamp Grille / Re		77.00 /
1	Front Fog Lamp Garnish X repair.		143.00 X
1	Front LH Fender Inner Shield X NN		264.00 X
1	Front LH Fender X repair.		792.00 X
			6,281.00 4066.8
		less 5%	315.04
		TOTAL	5,965.96 3863.46

4198.8
3988.86

FOR LABOUR CHARGES

Quantity	Item	Unit Price (\$)	Amount (\$)
	Panel Beating		800.00 400
	Spray Painting x 3 panels		1,100.00 600
	Wiring and checking of all lightings		90.00 30
	Tp re-program for headlamp		120.00 X
	TOTAL		2,110.00 1030

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GRAND TOTAL FOR THIS QUOTATION 8,075.96 8076.95

5018.86 4893.46

20% = 7900

4 Days.

PAGE 1

5018.86

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19014542/GVF3N2
Date: 26/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800085947
Claimant Vehicle No : SMG509J **Insured Vehicle No :** SMC7798R
 Date of Loss: 17/08/2019 Nature of Claim: TP Claim No: 5869536949SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG509J**
 Make & Model: BMW 420i, 2.0 Gran Coupe (A) Engine No: F2741975B48B20A
 Reg. Date: 27/04/2018 (Man. Year: 2018) Chassis No: WBA4H32010BH13289
 Colour: Black Odometer: 15656 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R18 Rear Tyre Size: 225/45R18
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,966.95	3,988.86	1,978.09	33.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	1,030.00	1,080.00	51.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,076.95	5,018.86	3,058.09	37.86
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	8,076.95	4,000.00	4,076.95	50.48

INSPECTION

Date of Assignment: 20/08/2019
 Date Inspected: 21/08/2019 Inspected At: King's Auto Air-conditioning (HQ)
 Singapore 575721
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Deformed	1,155.00 FL	*982.75 FL
2	1		*FRONT BUMPER SPONGE	Cracked	55.00 FL	*43.05 FL
3	1		*FRONT BUMPER LOWER GARNISH	Broken	55.00 FL	*40.10 FL
4	1		*FRONT PARKING SENSORS (2 Pcs)	Damaged (1 Pc only)	264.00 FL	*132.00 FL
5	1		*FRONT LH HEAD LAMP	Cracked	2,970.00 FL	*2,647.50 FL
6	1		*FRONT LH FOG LAMP	Cracked	506.00 FL	*276.40 FL
7	1		*FRONT FOG LAMP GRILLE	Deformed	77.00 FL	*77.00 FL
8	1		*FRONT FOG LAMP GARNISH	Repair	143.00 FL	*- FL
9	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	264.00 FL	*- FL
10	1		*FRONT LH FENDER	Repair	792.00 FL	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	6,281.00	4,198.80
- List Item Discount on L Items 5.00/5.00% (S\$)	314.05	209.94
Total Parts (S\$)	5,966.95	3,988.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING X3 PANELS	New	1,100.00	600.00
3	WIRING AND CHECKING OF ALL LIGHTINGS	New	90.00	30.00
4	TO RE-PROGRAM FOR HEADLAMP	New	120.00	0.00
Gross Labour Cost (S\$)			2,110.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >