

A. REC. BY:

REF:

CS/MSG19014559/815f352

Special Instruction:

Surveyor: Rusu

ASSIGNMENT (Office)

From (Person): Pang Xiu Shi

of

MS19Date/Time: 20.8.19 16:24 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 56852

Insured:

at Workshop m/s

Volkswagen

Tel:

63057293of 247 Alexandra RoadPolicy No: 29028868AVW

Claim No:

602974

Sum Insured:

Excess: \$500.00

Make of Veh:

D.O.A.

15.2.2019

(Client's Record)

CA REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

20.8.19 5:33 p.m

Person Contacted:

MingVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLS 56852 :x</u>

<u>21/08/19</u>	<u>@ 16:56 pm revised PA to Pang Xiu Shi via messenger</u>
-----------------	--

<u>21/08/19</u>	<u>@ 16:58 pm mandate requested and sent repair to Pang Xiu Shi via messenger</u>
-----------------	---

<u>23/08/19</u>	<u>@ 09:13 am mandate approved by Eng Hwee Ni. informed via messenger</u>
-----------------	--

<u>23/08/19</u>	<u>@ 13:52 pm informed CA to my (Casper) via email</u>
-----------------	--

Manning

7820

ASSIGNMENT

Yr Regn: 2017 / SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☐ Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Aug 2019		20 Aug 2019 16:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	HO KAR FATT , ID: S7472782D, Tel: +6594304913, Email: KFHO@FOAMTEC.COM.SG								
Vehicle Reg. No.:	SLS5685Z	Date of Loss:	15/08/2019 07:00 - :59 [31 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 602974	Policy/Cover Note No.:	29028868AVW (Comprehensive) Coverage: 28/09/2018 - 27/09/2019						
		Excess:	S\$500.00						
Repairer:	Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD, 159934 Alexandra - Tel: 63057293								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pang Xiu Shi - 6594 2586]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/08/2019]								
Driver/Custodian:	HO KAR FATT (45 / Male) , NRIC: S7472782D, Tel: +6594304913 Email: KFHO@FOAMTEC.COM.SG								
Adj Asg. Remarks:	Survey appt 21/08/19, 10am. Owner waiting at Alexandra w/shop. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert.								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
<div> </div>									
ALL ASSOCIATED TASKS									
<div> View All Search Tasks Create New Task Complete </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Re: [EXT] Re: SLS5685Z - FINALISE

Shirley Hiew (LKK Auto)

Wed 25/9/2019 1:26 PM

To: Cheong Pearlyn (VGS - SG/Singapore) <Pearlyn.cheong@vw.com.sg>

Cc: Kong Charmaine (VGS - SG/Singapore) <charmaine.kong@vw.com.sg>; Wong Meiy (VGS - SG/Singapore) <meiy.wong@vw.com.sg>; Foo John (VGS - SG/Singapore) <John.Foo@vw.com.sg>; SUR <sur@lkkauto.com>

Hi Pearlyn,

Supplementary approved by MSIG.

Finalize amount confirmed.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong Pearlyn (VGS - SG/Singapore) <Pearlyn.cheong@vw.com.sg>

Sent: Thursday, 19 September 2019 12:35 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Kong Charmaine (VGS - SG/Singapore) <charmaine.kong@vw.com.sg>; Wong Meiy (VGS - SG/Singapore) <meiy.wong@vw.com.sg>; Foo John (VGS - SG/Singapore) <John.Foo@vw.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: [EXT] Re: SLS5685Z - FINALISE

FYI

Pearlyn Cheong
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7288
Main Line: +65 6305 7299
Main Fax: +65 6474 364
pearlyn.cheong@vw.com.sg
<http://www.vw.com.sg>

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Cheong Pearlyn (VGS - SG/Singapore) [<mailto:Pearlyn.cheong@vw.com.sg>]

Sent: Monday, 16 September, 2019 5:45 PM

To: Rasul (LKKAuto); SUR; Admin A; Admin-D (LKKAuto)

Cc: Kong Charmaine (VGS - SG/Singapore); Wong Meiy (VGS - SG/Singapore); Foo John (VGS - SG/Singapore)

Subject: SLS5685Z - FINALISE

Dear Rasul,

Please confirmed

COR \$3515.22 after less excess before GST

Pearlyn Cheong
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7288
Main Line: +65 6305 7299
Main Fax: +65 6474 364
pearlyn.cheong@vw.com.sg
<http://www.vw.com.sg>



Internal

⏮ Reply all ⏭ Delete ⏴ Junk Block ...

RE: [EXT] SLS 5685Z OD (MSIG) DOA - 15/08/2019

WM

Wong MeiY (VGS - SG/Singapore) <meiy.wong@vw.com.sg>

👍 ↶ ↷ → ...

Fri 23/8/2019 1:54 PM

Shirley Hiew (LKK Auto); Ong Germaine (VGS - SG/Singapore) <Germaine.ong@vw.com.sg> +3 o

Thanks Shirley.

Thanks and Best Regards,

Meiy
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7216

Main Line: +65 6305 7299

Main Fax: +65 6474 3643

meiy.wong@vw.com.sg

<https://www.volkswagen.com.sg/>



It's not e-mail, if you print it. Think Blue.

Internal

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Friday, 23 August 2019 1:53 PM

To: Wong MeiY (VGS - SG/Singapore) <meiy.wong@vw.com.sg>; Ong Germaine (VGS - SG/Singapore) <Germaine.ong@vw.com.sg>; Tang Shu Shi (VGS - SG/Singapore) <shushi.tang@vw.com.sg>; Chee Steven (VGS - SG/Singapore) <steven.chee@vw.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: [EXT] SLS 5685Z OD (MSIG) DOA - 15/08/2019

⏪ Reply all ⌵ 🗑 Delete 🚫 Junk 🚫 Block ...

RE: [EXT] SLS 5685Z OD (MSIG) DOA - 15/08/2019

Internal

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 23 August 2019 1:53 PM
To: Wong MeiY (VGS - SG/Singapore) <meiy.wong@vw.com.sg>; Ong Germaine (VGS - SG/Singapore) <Germaine.ong@vw.com.sg>; Tang Shu Shi (VGS - SG/Singapore) <shushi.tang@vw.com.sg>; Chee Steven (VGS - SG/Singapore) <steven.chee@vw.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: [EXT] SLS 5685Z OD (MSIG) DOA - 15/08/2019

Dear MeiY,

As instructed by our client, please proceed to repair the insured vehicle **SLS 5685Z (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLS5685Z (602974)**

OD

Aug 15 2019 7:00AM

[HO KAR FATT]

Volkswagen Group Singapore Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 25/09/2019 09:39 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4015.22) - SLS5685Z - Claim Handler: Pang Xiu Shi

Approved:4015.22:In order not to delay repair, we have authorised the repair. But payment of the claim is subject to a copy of police report. Please request owner to file police report (hit & run accident)

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLS5685Z (602974)**

OD

Aug 15 2019 7:00AM

[HO KAR FATT]

Volkswagen Group Singapore Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 23/08/2019 09:13 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4649.21) - SLS5685Z - Claim Handler: Pang Xiu Shi

Approved:4649.21:check items of \$459.83 to be verified. In order not to delay repair, we have authorised the repair. But payment of the claim is subject to a copy of police report. Please request owner to file police report (hit & run accident)

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 20 Sep 2019

Preliminary Advice

Vehicle No	: SLS5685Z	Accident Date	: 15/08/2019
Make	: VOLKSWAGEN SPORTSVAN	Policy No.	: 29028868AVW
Assignment Date	: 20/08/2019	Excess	: S\$500.00
Date of Inspection	: 21/08/2019	Est. Duration of Repair	: 5 days
Inspection At	: Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD Singapore 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,255.02 (inclusive supp)
Revised Amount	:S\$	4,015.22 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,015.22
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	48,160.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,840.00

Remarks

- (X) The vehicle is economical for repair. We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 20.98.
- () The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 21 Aug 2019

Preliminary Advice

Vehicle No	: SLS5685Z	Accident Date	: 15/08/2019
Make	: VOLKSWAGEN SPORTSVAN	Policy No.	: 29028868AVW
Assignment Date	: 20/08/2019	Excess	: S\$500.00
Date of Inspection	: 21/08/2019	Est. Duration of Repair	: 5 days
Inspection At	: Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD Singapore 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,234.04
Revised Amount	:S\$	4,649.21
Check Items (Estimated)	:S\$	459.83
Total	:S\$	5,109.04
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	48,160.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,840.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

04f

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 15/08/2019 18:46
 Date Of Accident 15/08/2019 07:30
 Exact Location Of Accident MARSILING MARKET OPEN CARPARK LOT NO 62
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLS5685Z
Insured/Policyholder
 Name Of Registered Owner HO KAR FATT
 NRIC No S7472782D
 Email Address KFHO@FOAMTEC.COM.SG
 Mobile Phone No (LOCAL) +65-94304913
 Alternative Phone No OFFICE-94304913

Vehicle Particulars

Manufacturer VOLKSWAGEN
 Model SPORTSVAN 1.4CLBMT 92 TSI D7F
 Exact Purpose for which vehicle was being used at time of accident PRIVATE
 Are you claiming under your own insurance policy for repair to your vehicle? YES
 If No, Please state action to be taken
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number A 29028868 AVW
 Cover Note Number

Driver

Name of Driver HO KAR FATT
 NRIC No S7472782D
 Date Of Birth 05/08/1974
 Occupation INDOOR
 Date Of Driving Pass 14/01/1998
 Driving Experience 21 YEARS AND 7 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-94304913
 Fax Number
 Contact Number OFFICE-94304913
 Email Address KFHO@FOAMTEC.COM.SG

Address APT BLK 523 WOODLANDS DRIVE 14
#09-389
Postcode 730523
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name 10 UBI AVENUE 3
Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: SINGAPORE
Police Station Contact TEL NO. - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

MORE DETAILS PLEASE REFER TO POLICE REPORT

Attachment(s)


Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

2.30 am

My car parking on 8.00 am. at 15 Aug 2019.

Discover someone hit & under B-20 am at front right corner area.

Location = Maricling Market. Lot no = 8/2 62

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Provan

May

MSIG (Utime)
00
847

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/08/2019 18:46
Date Of Accident	15/08/2019 07:30
Exact Location Of Accident	MARSILING MARKET OPEN CARPARK LOT NO 62
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS5685Z
Insured/Policyholder	
Name Of Registered Owner	HO KAR FATT
NRIC No	S7472782D
Email Address	KFHO@FOAMTEC.COM.SG
Mobile Phone No	(LOCAL) +65-94304913
Alternative Phone No	OFFICE-94304913

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	SPORTSVAN 1.4CLBMT 92 TSI D7F
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29028868 AVW
Cover Note Number	

Driver


Name of Driver	HO KAR FATT
NRIC No	S7472782D
Date Of Birth	05/08/1974
Occupation	INDOOR
Date Of Driving Pass	14/01/1998
Driving Experience	21 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94304913
Fax Number	
Contact Number	OFFICE-94304913
Email Address	KFHO@FOAMTEC.COM.SG

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

2.30 am

My car parking on Brdam. at 15 Aug 2019.
Discover someone hit & run on B-20 am at front right corner area.

Location = Maraling Market. Lot no = 8/2 62

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

15/8/19 3.40pm.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	782D
Vehicle Details	
Vehicle No.:	SLS5685Z
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Aug 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SPORTSVAN 1.4 AT AM13HZ CL
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	CZC084170
Chassis No.:	WVWZZZAUZGW564040
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$22,057.00
Original Registration Date:	28 Sep 2017
First Registration Date:	28 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$17,880.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2027
PARF Rebate Amount:	\$13,410.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,902.00
COE Rebate Amount:	\$34,750.00
Total Rebate Amount:	\$48,160.00

The information contained herein is correct as at 21 Aug 2019

OK

Accident Photo



Accident Photo

