

22/03/2019

ASS. REC. BY:

REF: CS3/A1G19014575/Ucd301

Special Instruction:

Supervisor: MAFUS

ASSIGNMENT (Office)

From (Person): ^{Mejimen} Chin Lee Yiny

of

A1G

Date/Time:

20/8/19 @ 9:54am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 8330K

Insured:

SME 97754

at Workshop m/s

Bluwel Automotive

Tel:

6745 2088

of

1 Icaiki Bkt Ave 6 # 01-55

Policy No:

1800123881

Claim No:

316024255086

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:49pm @ 20/8/19

Person Contacted:

Jiang

Vehicle IN / OUT

Date/Time

Action/Instruction Ishmail (X)

SJV 8330K - X

SME 97754 - X

Disassemble: 20/8/2019

After repair: 22/8/2019.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SV 8330K
 at Workshop m/s but
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SV 8330K Yr Regn: 9h 10
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (A)
 Make: NISSAN SYLPHY OPC.c.c 1498
 Colour: Black AC: Insured / Std / NI / NA
 Sp. Reading: 79402 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN1BAAG11Z0110657
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 195/65 215
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or continental
 Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 11/8/18 D.O.I. 20/8/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 1200
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Date / Time Action / Instruction
08/11/18 Sole plus
No settlement. NRS 214 8994
next 3006

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____

Days Of Repair: 3
 Resurvey No. of Trip: 2 Survey Fee: 180
 Transportation: _____

Report Format : DAR
 Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)) S + RS, SI
 : Interview (\$ _____)) Photos
 : Tech. Invs (\$ _____)) Others
 : Weekend (\$ _____))

TOTAL 191

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Aug 2019 Edit Reg		20 Aug 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	JIANG BOHONG, ID: S8265616B		
Main Claimant:	LEONG MUN TUCK, ID: S2615037Z		
Vehicle Reg. No.:	SJV8330K	Date of Loss:	11/08/2019 10:00 - :59
Claim Type:	TP / 3160242550SG	Policy/Cover Note No.:	1800123881 (Comprehensive)
Vehicle Reg. No. (Insured):	SME9775H	Policy No. (Claimant):	
		Excess:	
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/08/2019]		
Claimant's Solicitor:	M NEDUMARAN & CO - Tel: 65098480		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (21/08/2019): Request To Upload TP GIA Report 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 8/20/2019 9:54:18 AM
Attachments:  15082019095207.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Please reply to our Branch Office for this matter

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

⇒ **Branch Office:** 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/B1/1913220/st
Your Reference : SME 9775H

Date : 15th August 2019

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claims Department

BY FAX & EMAIL 6835-7416

Dear Sirs,

1. **NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**
2. **ACCIDENT ON 11/8/2019 INVOLVING VEHICLE NOS. SJV 8330K & SME 9775H ALONG JOHOR CHECKPOINT.**

We are instructed by MR LEONG MUN TUCK (owner of motor vehicle no. SJV 8330K) and/or BLUWEL AUTOMOTIVE SERVICE PTE LTD (the motor workshop for SJV 8330K) to notify you of a road traffic accident on 11/8/2019 at about 1030 hours along JOHOR CHECKPOINT involving our client's vehicle registration number [SJV 8330K] and [SME 9775H] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know **within 2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

M NEDUMARAN & CO

Nedumaran Muthukrishnan - (Branch Office)

Encl

c.c. 1) JIANG BOHONG

(Vehicle : SME 9775H)

2) NAME OF WORKSHOP :

Bluwel Automotive Service Pte Ltd

No. 1 Kaki Bukit Avenue 6

#01-55, Blk C Autobay @ Kaki Bukit

Singapore 417883

(Vehicle : SJV 8330K)

Telephone : 6745-2088

Facsimile : 6841-2088

(Attention : Ms Sally)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	037Z
Vehicle Details	
Vehicle No.:	SJV8330K
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	HR15287006B
Chassis No.:	JN1BAAG11Z0110655
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,713.00
Original Registration Date:	09 Feb 2010
First Registration Date:	09 Feb 2010
Transfer Count:	0
Actual ARF Paid:	\$17,713.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Feb 2020
PARF Rebate Amount:	\$8,856.00
Intended COE Rebate Details	
COE Expiry Date:	08 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$2,989.00
COE Rebate Amount:	\$138.00
Total Rebate Amount:	\$8,994.00

The information contained herein is correct as at 22 Aug 2019

OK

UPLOAD A PHOTO
of your beloved car to Facebook
& tag @mobillubes #askforMobil

OR

FOLLOW US
on Lazada

Flash it at our booth to
redeem a token to play
F1 Red Bull Simulator!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

One Fussy Lady Owner. Depre About \$6600 Per Year.



Owner Upgrade To Cross Over.
Direct Owner StarAd



Browse by Category

6 vehicles

Nissan Sylphy

Sort by Date Posted

Advanced Search

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
	Nissan	Sylphy	Any	Any	2010	Any	Any
	Nissan	Sylphy 2.0A	\$22,000	\$8,790 /yr	03-Nov-2010	1,997 cc	103,000 km
1 And Only In The Market! 1 Owner Since Brand New! Don't Miss It!							
Posted: 20-Aug-2019 Tags: 2010 Nissan Sylphy, 2010 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan							
	Nissan	Sylphy 1.5A (New 5-yr COE)	\$28,800	\$5,750 /yr	22-Jan-2010	1,498 cc	123,150 km
1 Careful Owner! New Road Tax Till Jan 2020! Very Well Maintained, Accident Free! Flexible 100% Loan Scheme/High Trade In Available Optional For 10 Years COE! Price Negotiable, Don't Miss!							
Posted: 19-Aug-2019 Tags: 2010 Nissan Sylphy, 2010 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan							
	Nissan	Sylphy 1.5A (New 5-yr COE)	\$28,300	\$5,650 /yr	10-Feb-2010	1,498 cc	97,000 km
New Arrival! New Road Tax Just Paid. Flawless Shining Sports Rims With New Tyres. Alpine Mobile Media Station. Reverse Camera. Sola Film. Very Quite Engine. Spacious Boot Space. Non Smoker Car. Very Cold Aircon. Fuel Efficient Car. Healthy Engine And Healthy Gearbox							
Posted: 18-Aug-2019 Tags: 2010 Nissan Sylphy, 2010 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan							
	Nissan	Sylphy 1.5A	\$15,300	\$9,520 /yr	06-May-2010	1,498 cc	-
One Owner Only! Well Maintained Unit! Selling Due To Relocation. Spacious And Comfortable! Perfect For Daily Commuting. Problem-Fr Car! Spend \$850 Per Month Till Scrap Or Renew COE Of Your Choice! Great Choice For PHV Usage. Consignment Unit. COE Loan Can Be							
Prem Roy Motoring Posted: 13-Aug-2019 Tags: 2010 Nissan Sylphy, 2010 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan							

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town approval in 2 days without effort! Enquire today.

Nissan Sylphy 1.5A	\$16,500	\$9,610 /yr	18-Jun-2010	1,498 cc	-
3k And Above To Apply. Hurry Before It's Sold. Purchase From An Award Winning Dealership! Accident Free, Quality Pre-Owned Mileage Done For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing. View Today! Very Well Maintain					

Compare

MSME18105085 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 13/08/2019 12:07
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/08/2019 12:07
Date Of Accident	11/08/2019 10:30
Exact Location Of Accident	JOHOR CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV8330K
Insured/Policyholder	
Name Of Registered Owner	LEONG MUN TUCK
NRIC No	S2615037Z
Email Address	LEONGSOOKHUAN08@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97348693
Alternative Phone No	OFFICE-97348693
Vehicle Particulars	
Manufacturer	NISSAN
Model	SYLPHY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5048380422-08
Cover Note Number	
Driver	
Name of Driver	LEONG MUN TUCK
NRIC No	S2615037Z
Date Of Birth	29/07/1960
Occupation	INDOOR
Date Of Driving Pass	18/12/1981
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97348693
Fax Number	
Contact Number	OFFICE-97348693
EMail Address	LEONGSOOKHUAN08@HOTMAIL.COM

Address BLK 35 CIRCUIT ROAD #06-444
 Postcode 370035
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1
 NAME: : KIEW POH WAN
 GENDER: : FEMALE
 Passenger 2
 NAME: : LEONG SOOK HUAN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 11/08/2019 AT ABOUT 10.30AM, I WAS TRAVLLING ALONG JOHOR CHECKPOINT ON THE RIGHT LANE. TRAFFIC VOLUME WAS HEAVY. VEHICLES WERE MOVING SLOWLY. WHEN MY CAR A CAME TO A STOP, I FELT AN IMPACT AT THE REAR OF MY CAR A. I ALIGHTED FROM MY CAR A AND FOUND OUT CAR B HAS HIT THE REAR OF MY CAR. WE EXCHANGED DETAILS.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SME9775H
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver JIANG BOHONG
 NRIC/Passport Number S8265616B
 Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

梁文德

梁文德

Policyholder's Signature

Date & Time: 13/8/19, 1030 am

Driver's Signature

(if driver is not the policyholder)

Date & Time: 13/8/19, 1030 am

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

GIAHMC SketchPlanForm_v3

BLUWEL

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11/8/19 at about 1030am, I was travelling along Johor checkpoint on the right lane. Traffic volume was heavy. Vehicles were moving slowly. When my car (A) came to a stop I felt an impact at the rear of my car (A). I alighted from my car (A) and found out. Car B has hit the rear of my car. We exchanged details.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

[Signature]

Policyholder's Signature

Date & Time: 13/8/19, 1030am

Driver's Signature

(if driver is not the policyholder)

Date & Time: 13/8/19, 1030am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

5JV 83301c

	Rear bumper	cut/ae	—
	Rear bumper chrome molding	nr	—
	Rear bumper side retainers OLS	set	—
1 set	Rear bumper clips	nr	—
	Rear bumper reflector OLS	one	—
	Taillamp OLS	one	—
	Rear fender OLS	R	X

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Aug 2019 Edit Reg		20 Aug 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	JIANG BOHONG , ID: S8265616B								
Main Claimant:	LEONG MUN TUCK , ID: S2615037Z								
Vehicle Reg. No.:	SJV8330K	Date of Loss:	11/08/2019 10:00 - :59 [114 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3160242550SG	Policy/Cover Note No.:	1800123881 (Comprehensive)						
Vehicle Reg. No. (Insured):	SME9775H	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/08/2019]								
Claimant's Solicitor:	M NEDUMARAN & CO - Tel: 65098480								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (21/08/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJV8330K (3160242550SG)**
[SME9775H]
TP
LEONG MUN TUCK
Aug 11 2019 10:00AM
[JIANG BOHONG]
Bluwel Automotive Service Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
2	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
3	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
4	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
5	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
6	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
7	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
8	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
9	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
10	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
11	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
12	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
13	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
14	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
15	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
16	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
17	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
18	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
19	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
20	23/08/19 11:28	General View							Load JPG	<input checked="" type="checkbox"/>		
21	23/08/19 11:30	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
22	23/08/19 11:30	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
23	23/08/19 11:30	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
24	23/08/19 11:30	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
25	23/08/19 11:30	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
26	23/08/19 11:30	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
27	23/08/19 11:30	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
28	23/08/19 11:30	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
29	23/08/19 11:30	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
30	23/08/19 11:31	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		
31	23/08/19 11:31	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		
32	23/08/19 11:31	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		
33	23/08/19 11:31	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		
34	23/08/19 11:31	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		
35	23/08/19 11:31	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19014575/UCD3E2
Date: 02/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800123881
Claimant Vehicle No : SJV8330K	Insured Vehicle No :	SME9775H
Date of Loss: 11/08/2019	Nature of Claim:	TP Claim No: 3160242550SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV8330K	Engine No:	HR15287006B
Make & Model:	NISSAN SYLPHY, 2.0 (A)	Chassis No:	JN1BAAG11Z0110655
Reg. Date:	09/02/2010 (Man. Year: 2009)	Odometer:	79402 km
Colour:	Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	20/08/2019	
Date Inspected:	20/08/2019 Inspected At:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Cut / Deformed	0.00 F	*- F	
2	1		*REAR BUMPER CHROME MOULDING	Necessary	0.00 F	*- F	
3	1		*REAR BUMPER SIDE RETAINER O/S	Bent	0.00 F	*- F	
4	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
5	1		*REAR BUMPER REFLECTOR O/S	Cracked	0.00 F	*- F	
6	1		*TAILLAMP O/S	Cracked	0.00 F	*- F	
7	1		*REAR FENDER O/S	Repair	0.00 F	*- F	
					Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >