

INS. CASE OWNER:

CC4/LPC19014581/

Ada3n2

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

20/8/2019

Date / Time: 19/08/2019

Registered in Meritmen:

Pre-assign / CCU / FTE



Insured Vehicle No. : YN 7687C

Claim No. : 19/19/VC05/022220

Name of Insured : Bok Hung Transport Service

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II : \$5 D.O.A : 03/08/2019

Place of Accident :

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

GBE 4018Z

INSRS:
WSP: KAI MOTOR
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	GBE 4018Z - CC3/AIG18014336/H1pa3q2; DOA:29/7/16	Non-Reporting ltr (1st):	
	- CC3/AIG17005243/H1za3q2; DOA: 13/3/17	Non-Reporting ltr (2nd):	
	YN 7687C - CS/MSG18013632/Kvd3n2; DOA: 20/7/18	Non-Reporting ltr (Final):	
20/08/19	OINR	Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
21/10/19	HUG PASS TO CYB MANDATE	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice	<input type="checkbox"/>
		LTA / GIA :	<input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time: Sent By:			
FINALIZATION Date/Time: Confirm with: Confirm by:			
Repair Cost:	\$5 (days) Reduction: %	Email <input type="checkbox"/> Call <input type="checkbox"/>	
FINAL SETTLEMENT Date/Time: 13/1/2020 Confirm with: Ms Kym Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>			
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : NIL	If NO or B 28, Ass. Lia :	
Repair Cost: (w/hp)	\$5 3852.00	OLD REVERED HIT TP	
Loss of Rental (LOR):	\$5 560.00 (4 days) x \$140	COPY SENT 15/1/2020	
Loss of Use (LOU):	\$5 - (\$ x days)		
Loss of Income (LOI):	\$5 - (\$ x days)		
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]			
GIA/LTA Search:	\$5 245	1) Claim status: Normal/Reject/Private Settle	
Medical:	\$5 -	2) Report Format: TP	
Disbursement:	\$5 - (e.g. Tow/ Independent)	3) Survey fee: \$400	
Legal Cost	\$5 -		
Total:	\$5 4419.45 Global Sum \$5: 4400.00		
FINAL PAYMENT Date/Time: Confirm with: Email <input type="checkbox"/> Call <input type="checkbox"/>			
Payee 1:	\$5 4400.00 Name 1: Kai Motor Trading		
Payee 2: (Strike if N.A.)	\$5 Name 2:		
Payee 3: (Strike if N.A.)	\$5 Name 3:		

Acanan

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

4

days

Res: _____

Yes or No

Lum Sum: _____

20

%

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: G3E 4018Z Yr Regn: 2015 Nov

Type: M.Car / M.Cycle / Bus (Van) / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace cc 2982

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading 92070 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT 02PS 00182630

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 20/08/19

Survey held at Kai motor

Des. of Damages: (Frt) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Con Pac

\$3600 (Red \$2834.15 / 442)

MV :

PV :

Nett :

152W

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Addendum Sheet Pg. 1

GENERAL
INSURANCE
ASSOCIATION
RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 - 17:00
UEN: S6A5500105 / GST Reg. No.: M400037730

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MF A2M108175 Vehicle Registration No: YN 7687C
Name (as shown in NRIC) : Subbairah Balasubramanian NRIC/FIN/Passport No : G 26 364141
(* Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : 85458631
Email Address : _____
Date of Accident : 11/08/2014 Time of Accident : 20:30
Place of Accident : Veerasamy Rd Car Park
Insurance Company : Longac



(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To upload :

Police Report

Policyholder / Driver's Signature
Date:


Reporting Centre Person's Signature
Name:
NRIC/FIN No.:
Date:



Status of Driving Licence

Qualified Driving Licence

Qualified Driving Licence Number

G2636914U

Status of Qualified Driving Licence

Valid

Class(es) of Qualified Driving Licence

2B,3C,3

Expiry Date

05/10/2020

Provisional Driving Licence

Provisional Driving Licence Number

G2636914U

Status of Provisional Driving Licence

Valid

Class(es) of Provisional Driving Licence

3

Expiry Date

01/02/2020

HOME (<https://www.police.gov.sg/>)

ABOUT US (<https://www.police.gov.sg/about-us>)

SGSECURE (<https://www.police.gov.sg/sgsecure>)

I-WITNESS (<https://www.police.gov.sg/iwitness>)

COMMUNITY PROGRAMMES (<https://www.police.gov.sg/community-programme>)

RESOURCES (<https://www.police.gov.sg/resources>)

NEWS & PUBLICATIONS (<https://www.police.gov.sg/news-and-publications>)

JOIN US (<https://www.police.gov.sg/join-us>)

FAQS (<https://va.ecitizen.gov.sg/cfp/CustomerPages/SPF/explorefaq.aspx>)

CONTACT US (<https://www.police.gov.sg/content/contact-us>)



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting

Attn: The Motor Claims Department

Your Insured veh no : YN 7687 C

Lompac Insurance Bhd
300 Beach Road,
#17-04/07 The Concourse
Singapore 199555

Jia Le.

68411972 LKK Niv.

JTFHT02P520182150

Dear Sir / Madam

**Estimate Cost repair Bill To Toyota Hiace Van No GBE 4018 Z & YN 7687 C on 03/08/2019
@17:30:00**

To Supply:-

1pc	Front bonnet <i>Dented</i>		\$ 845.10 ✓
2pcs	Front bonnet hinge <i>AC 100</i>	65.1	\$ 130.20 ✓
1pc	Front support panel <i>Repair</i>		\$ 515.00 ✓
2pcs	Front head lamp <i>Cracked</i>	951.1	\$ 1,902.20 ✓ <i>1562.80</i>
1pc	Front grille <i>Cracked</i>		\$ 588.10 ✓
1pc	Front lower grille <i>Cracked</i>		\$ 498.10 ✓
1pc	Front bumper <i>Dented</i>		\$ 531.10 ✓
10pcs	Front bumper clips <i>m</i>		\$ 50.00 <i>30</i>
2pcs	Front bracket <i>200</i>	148.1	\$ 296.20 ✓
2pcs	Front bumper side bracket <i>200</i> <i>LH can be</i>	158.1	\$ 316.20 ✓ <i>158.10</i>
			\$5,672.20
<i>4762.10</i> less			25% \$1,418.05
<i>3571.57</i>			\$4,254.15

To dismantle & replace damage parts, panel beat where necessary.

To putty, apply primer & spray paint on the affected portion.

To check wiring functions.

To top up air con gas

LKK Auto Consultants hereby notify the Repairer of the following:
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• No illegal modification is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6828.42

\$ 950.00 *500*

\$1,000.00 *400*

\$ 80.00 *30*

\$ 150.00 ✓

\$6,434.15

total: 4505.7

1536K

1pc Bonnet Lock and Key 118 ✓

Bonnet Logo New 98.20 ✓

Front LH corner Panel. *Dented* 309.50 ✓

Adrian L

4/8 20%

0400

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 19 August 2019 8:44 AM
To: Kai Motor; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: ACCIDENT INVOLVING VEHICLE NO GBE 4018 Z & YN 7687 C on 03/08/2019 @ 17:30:00 Our Ref: 19/19/19/VC05/022220 [External General]
Attachments: SAS Toyota Hiace Van GBE 4018 Z & YN 7687 C on 03082019 @173000.pdf

Lonpac External - General

Dear Nivitha

Please arrange Adrian Ling to conduct TP survey.

Fyi, our Insured has not reported the accident yet.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Kai Motor [mailto:kaimotor@gmail.com]

Sent: Friday, 16 August, 2019 5:14 PM

To: ONG LI LI

Cc: MT_Claim_SG

Subject: Re: ACCIDENT INVOLVING VEHICLE NO GBE 4018 Z & YN 7687 C on 03/08/2019 @17:30:00 Our Ref: 19/19/19/VC05/022220 [External General]

Hi Sir,

LKK

5 | Adrian Ling

☺ Have a nice day w thanks.

Ms Kym

On Fri, 16 Aug 2019 at 16:29, ONG LI LI <llong@lonpac.com> wrote:

Lonpac External - General

Without Prejudice

Save as to Costs

Dear Sir/Mdm

Our Insured has not reported the accident yet.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

1	Kalvin Ang
2	Xing Guo Qiang
3	Mohamad Taufikh
4	Mohammed Rasul
5	Adrian Ling
6	Marcus Chua
7	Kenneth Kong
8	Bryan Ang
9	Choo Beng Hai
10	Nicholas Tey

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Kai Motor [mailto:kaimotor@gmail.com]
Sent: Friday, 16 August, 2019 3:30 PM
To: GERALD POH WEE BIN; ONG LI LI
Subject: ACCIDENT INVOLVING VEHICLE NO GBE 4018 Z & YN 7687 C on 03/08/2019 @17:30:00

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1
#01-440, SINGAPORE 408701
TEL: 67474006 FAX: 67437591
E-mail : kaimotor@gmail.com
REG NO: 44223100L

Date : 16/08/2019

Attn: The Motor Claims Department
Your Insured veh no : YN 7687 C
Lonpac Insurance Bhd
300 Beach Road,
#17-04/07 The Concourse
Singapore 199555

Dear Sir / Madam

ACCIDENT INVOLVING VEHICLE NO GBE 4018 Z & YN 7687 C on 03/08/2019 @17:30:00

We are writing on behalf of **Bismillah Biryani Restaurant** the registered owner of **GBE 4018 Z B** which was involved on the above mentioned accident between **YN 7687 C**.

Investigation reveals that the motor vehicle number **YN 7687 C** was insured with you at the material time of the said accident.

As a result of the accident was caused solely and completely by the negligence of your insured vehicle number **YN 7687 C** Therefore, our client is holding you liable for the repair costs and other consequential loss which was sustained by him/her/them.

Kindly arrange your representative to survey our client's vehicle at **KAI MOTOR TRADING** Blk 3007, Ubi Road 1, #01-440, Singapore 408701 within **MONDAY 19/08/2019** from the date

hereof as to avoid further losses incur.

We enclosed hereby the GIA report of **GBE 4018 Z** for your kind attention.

Failing which, our client have no alternative but to proceed with the necessary repairs and the bill will be forward to you for reimbursement.

Yours faithfully,

--

Have a nice day w thanks.

Ms Kym

Kai Motor Trading

Blk 3007 Ubi Rd 1 #01-440
Singapore 408701
Telephone: 6747 4006

--

Have a nice day w thanks.

Ms Kym

Kai Motor Trading

Blk 3007 Ubi Rd 1 #01-440
Singapore 408701
Telephone: 6747 4006

Mei Kwan (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 22 August, 2019 2:25 PM
To: Mei Kwan (LKKAUTO); Jia Le (LKK Auto)
Cc: MT_Claim_SG; Admin A
Subject: RE: ACCIDENT INVOLVING VEHICLE NO GBE 4018 Z & YN 7687 C on 03/08/2019 @ 17:30:00 Our Ref: 19/19/VC05/022220 [External General]
Attachments: YN7687C 110819 (2).PDF
Categories: HMK

Lonpac External - General

Dear Mei Kwan

Attached is for our Insured's GIA report with addendum to include the Police report.

Please confirm the date of accident with Insured/TP and reply to us.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ONG LI LI
Sent: Wednesday, 21 August, 2019 2:29 PM
To: 'Admin-D (LKKAUTO)'; assignments
Cc: MT_Claim_SG; Admin A
Subject: RE: ACCIDENT INVOLVING VEHICLE NO GBE 4018 Z & YN 7687 C on 03/08/2019 @17:30:00 Our Ref: 19/19/VC05/022220 [External General]

Lonpac External - General

Dear Nivitha

Attached is our Insured's GIA report.

Please inform the case handler to confirm the date of accident (different from TP).


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Kai Motor [mailto:kaimotor@gmail.com]

Sent: Friday, 16 August, 2019 5:14 PM

To: ONG LI LI

Cc: MT_Claim_SG

Subject: Re: ACCIDENT INVOLVING VEHICLE NO GBE 4018 Z & YN 7687 C on 03/08/2019 @17:30:00 Our Ref: 19/19/VC05/022220 [External General]

Hi Sir,

LKK

5	Adrian Ling
---	-------------

👉 Have a nice day w thanks.

Ms Kym

On Fri, 16 Aug 2019 at 16:29, ONG LI LI <llong@lonpac.com> wrote:

Lonpac External - General

Without Prejudice

Save as to Costs

Dear Sir/Mdm

Our Insured has not reported the accident yet.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

1	Kalvin Ang
---	------------

Date : 16/08/2019

Attn: The Motor Claims Department

Your Insured veh no : YN 7687 C

Lonpac Insurance Bhd

300 Beach Road,

#17-04/07 The Concourse

Singapore 199555

Dear Sir / Madam

ACCIDENT INVOLVING VEHICLE NO GBE 4018 Z & YN 7687 C on 03/08/2019 @17:30:00

We are writing on behalf of **Bismillah Biryani Restaurant** the registered owner of **GBE 4018 Z B** which was involved on the above mentioned accident between **YN 7687 C**.

Investigation reveals that the motor vehicle number **YN 7687 C** was insured with you at the material time of the said accident.

As a result of the accident was caused solely and completely by the negligence of your insured vehicle number **YN 7687 C** Therefore, our client is holding you liable for the repair costs and other consequential loss which was sustained by him/her/them.

Kindly arrange your representative to survey our client's vehicle at **KAI MOTOR TRADING** Blk 3007, Ubi Road 1, #01-440, Singapore 408701 within **MONDAY 19/08/2019** from the date hereof as to avoid further losses incur.

We enclosed hereby the GIA report of **GBE 4018 Z** for your kind attention.

Failing which, our client have no alternative but to proceed with the necessary repairs and the bill will be forward to you for reimbursement.

Yours faithfully,

--

Have a nice day w thanks.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19014581/Ada3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 16-01-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7687C	Veh. Inspected	GBE 4018Z	
Policy No.	Z/19VC05/002308-001	Coverage (\$)	0.00	
Claim No.	19/19/19/VC05/022220	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	19/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTFHT02P500182130	Colour	SILVER	
Odometer	92070	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/08/2019	Inspection Date	20/08/2019	
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4018Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	DENTED	845.10	845.10
2	FRONT BONNET HINGE @\$65.10	NOT NECESSARY	130.20	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	515.00	-
2	FRONT HEAD LAMP @\$951.10	CRACKED	1,902.20	1,562.80
1	FRONT GRILLE	CRACKED	588.10	588.10
1	FRONT LOWER GRILLE	CRACKED	498.10	498.10
1	FRONT BUMPER	DEFORMED	531.10	531.10
10	FRONT BUMPER CLIPS	NECESSARY	50.00	30.00
2	FRONT BRACKET @\$148.10	NOT NECESSARY	296.20	-
2	FRONT BUMPER SIDE BRACKET @\$158.10	N/S CRACKED	316.20	158.10
1	BONNET LOCK	DAMAGED	118.00	118.00
1	BONNET LOGO	NECESSARY	98.20	98.20
1	FRONT LH CORNER PANEL	DENTED	309.50	309.50
	LESS 25% DISCOUNT		-1,549.48	-1,184.75
			4,648.42	3,554.25
LABOUR				
	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		950.00	500.00
	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION.		1,000.00	400.00
	TO CHECK WIRING FUNCTIONS.		80.00	30.00
	TO TOP UP AIR CON GAS.	NOT NECESSARY	150.00	-
	-		-	-
	-		-	-
	-		-	-
			2,180.00	930.00
GRAND TOTAL			6,828.42	4,484.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00



Report Ref No. CC4/LPC19014581/Ada3n2

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.