

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

19/08/2019

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

TP AXA  
Vivian

Accident date: 18/08/2019

Estimated repair cost for vehicle no: SLH8394B HONDA CRV 2.4 A '16

CHASSIS: MRHRM3850HP000119

S/n	Qty	Items	U/price	Amount
1	1	Front Grille <i>Emul d</i>		\$131.90 ✓
2	8	Front Grille Clip <i>m</i>	\$6.50	\$52.00 ✓
3	1	Front Grille Emblem Logo <i>m</i>		\$24.70 ✓
4	1	Front Grille Chrome Top <i>ut</i>		\$106.60 ✓
5	1	Front Grille Chrome Lower <i>ut</i>		\$128.10 ✓
6	1	Front Bumper <i>De hand</i>		\$498.10 ✓
7	10	Front Bumper Clip <i>m</i>	\$6.50	<del>\$65.00</del> 30 ✓
8	1	Front Bumper Center (black) <i>ut</i>		\$482.00 ✓
9	1	Front Bumper Lower Lid (silver) <i>Byis</i>		\$258.20 ✓
X 10	1	Front Bumper Reinforcement <i>Beats NLM</i>		\$281.50 2 ✓
11	2	Front Bumper Side Retainer <i>Nu RH</i>	\$22.00	<del>\$44.00</del> 22 ✓
12	1	Front R/H Bumper Fog Lamp <i>Emul d</i>		\$264.50 ✓
13	1	Front R/H Bumper Fog Lamp Cover <i>Emul d</i>		\$168.10 ✓
14	1	Front R/H Head Lamp <i>ut</i>		\$1,491.30 ✓
15	1	Front R/H Head Lamp Lower Bracket <i>Emul d</i>		\$38.00 ✓
16	1	Front R/H Fender <i>Byis</i>		\$631.50 ✓
17	1	Front R/H Fender Arch Protector <i>De hand</i>		\$94.50 ✓

Subtotal :- \$4,760.00

3537.80

2825.44

Labour charges

To check wiring

~~\$100.00~~ 30

Towing fee

\$150.00 \*

Tuff kote

1130

~~\$100.00~~ 30

Panel beating

~~\$800.00~~ 500

Spray painting

~~\$800.00~~ 600

Subtotal :- \$1,950.00

Total:- \$6,710.00

Adrian L  
\* 4/5 P/P ??

04 Days

total: 3985.44

H/S: 3.2K

3.2K

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: