

ASS. REC. BY:

REF: CS/1M1 190145019/ KH/302

Special Instruction:

Surveyor: KalvinASSIGNMENT (Office)From (Person): Dillen Santulan so Selva TM1Date/Time: 20.8.19 18.18p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 1891CInsured: SPK 52Rat Workshop m/s CombaradeganTel: 62148300of 51 Iyans BrivePolicy No: MJ001819Claim No: M1906397

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh:  
(Client's Record)D.O.A. 20.8.19

CA / REV / REP. / REV 24 HRS

Date/Time: 21.8.19 9.02a.mPerson Contacted: Jumadi

H.O.D. Endorsement: \_\_\_\_\_

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 1891C - CC3/11 19002610/KIP93 DOA - 11/05/2019
	SPK 52R - MA/ LIP/3018219/d2 DOA - 01/10/2013

(08/11/13)

Surveyor: Kalvin

REF: \_\_\_\_\_

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC1891C Yr Regn: 20 Sep 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 255897 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTRKBJFU10356X236

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / DR Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Davanti

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 20/8/19 D.O.I. 20/8/19

Survey held at C/DHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8/5 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/8/19	Checked PIP \$2157.33 / 3 Pys. Ured: 745.99 : 25% to kio PIP
	RECEIVED 26 AUG 2019

Date/Time, File Pass to?  : Preli. Report

1) 26/8 Typist  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: 250

Transportation: \_\_\_\_\_

\_\_\_\_\_ S + RS, \_\_\_\_\_ SI

Photos \_\_\_\_\_

Others 11

\_\_\_\_\_

TOTAL 261

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format: TP

Lump Sum / (I.B.): (\$ 2157.33)

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2019 Sendback Est	20 Aug 2019 17:27 S\$2,903.32	20 Aug 2019 18:18 Assign				<b>New Assignment</b> Cancel Case

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS									
Insured:	PUNGGOL EAST CAR RENTAL, Co. Reg. No.: 53338281E								
Main Claimant:	CTPL								
Vehicle Reg. No.:	SHC1891C	Date of Loss:	20/08/2019 01:00 - :59 [23 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1906397	Policy/Cover Note No.:	MJ001819 (TP, Fire & Theft) Coverage: 13/12/2018 - 12/12/2019						
Vehicle Reg. No. (Insured):	SFK562R	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/08/2019]								
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT								
<b>ASSOCIATED MAIL RECEIVED</b>									
			<a href="#">View All</a> <a href="#">Compose Case Mail</a>						
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
			<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

TP

Need Taxi Replacement

M

**COMFORTDELGRO ENGINEERING**

**ComfortDelGro Engineering Pte Ltd**

205 Braddell Road Singapore 579701  
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

**Workshops**  
59 Loyang Drive Singapore 508969 24 Senoko Loop Singapore 758158  
383 Sin Ming Drive Singapore 575717 7 Sungai Kadut Way Singapore 728791  
45 Pandan Road Singapore 609286 501 Vishnu Industrial Park A Singapore 768732  
29 Ubi Road Singapore 408799

Date/Time: 20.08.2019 12:18 Page : 1

ARC Repair TP(CLS0)1

**JOB CARD**

Sales Order:

JC NO.: 305325962

COMFORT TRANSPORTATION PTE LTD  
7010045  
383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755 (O)

REGN NO:	SHC1891C	MILEAGE
MAKE:	TOYOTA	FUEL E.....1/2.....F
MODEL	PRIUS HYBRID(G4)	DATE/TIME IN 20.08.2019 10:10
YR OF MANU	20.09.2017	TARGET DATE
CHASSIS CODE	JTDKB3FU103564236	COMPLETION DATE/TIME:

RD NO.

dent Date: 20.08.2019  
RE: 3P 20.08.19

JOB DESCRIPTION

PP


LKK-Kalvin

Merimen

TOKIO Marine - SFK 562R

LABOR CODE

DESCRIPTION



ASSESSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Exit Slip

Exit Pass

SHC1891C

LIMITS

Vehicle No.: SHC1891C

Advisor

Signature/Date

Name of Service Advisor

Date

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/08/2019 11:31
Date Of Accident	20/08/2019 01:50
Exact Location Of Accident	GEYLANG RD TWDS LAVENDER ST
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1891C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	LAM KEE LEONG
NRIC No	S1589067C
Date Of Birth	29/09/1963
Occupation	OUTDOOR
Date Of Driving Pass	05/06/1981
Driving Experience	38 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81186868
Fax Number	
Contact Number	
E Mail Address	TONYLAM@BLUEWEB.COM.SG

Address	BLK 272C SENGKANG CENTRAL #02-341
Postcode	543272
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFK562R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH JUN HUI JOHNNY
NRIC/Passport Number	
Contact Number	87867567
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	LEFT FRT

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

2018/19  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIA/IMC Sketch Plan Form V3



Sketch Plan Pg. 2

SKETCH PLAN



A- SHC 1891C  
B- SFK 562R

Along Geylang Rd twds Lavender *st*

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20.08.2019 @ 0150hrs I was travelling along Geylang Rd twds Lavender <sup>st</sup> with one male passenger onboard.
As I was travelling straight suddenly veh(B) SFK 562R cut into my lane and hit onto my vehicle <del>front</del> <sup>front</sup> right portion.
As it took place too fast I could not take evasive action to prevent the accident.
I have company video and photos at scene to support my claims .
No injury in the accident.
Veh(B) SFK 562R MR Koh Jun Hui Johnny HP:8786 7567

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 20.08.2019@ 1100HRS

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

20/8/19  
Jackson  
*[Signature]*

TOKIO Marine CP/P  
Lkk-kalvin.

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305325962  
REGN NO : SHC1891C  
MILEAGE : 000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 20.09.2017  
DATE/TIME IN : 20.08.2019 10:10  
ACCIDENT DATE : 20.08.2019

Davanti  
195/65R15

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	03-01-0302-2020-G	REAR SPORT RIM RH	1	1,555.10	25.00	1,166.32	-	brand
0002	28-01-9999-2023-A	REAR DOOR APPS RH	1	80.00		80.00	-	new
0003	195/65R15 DX390	REAR DAVANTI TYRE RH	1	216.00		216.00	X	3pc
								SUB-TOTAL : 1,462.32

Per Bumper xray  
Per fender (RH) xray  
Per Door (RH) xray

JOB NATURE

0000	PB	PANEL BEATING				<del>560.00</del>	300	
0001	SP	SPRAYPAINT-Rear Bumper&Fender RH				<del>750.00</del>	600	
0002	L	WHEEL ALIGNMENT				<del>120.00</del>	X	27
0003	20-05	TP MERIMEN				11.00	-	
								SUB-TOTAL : 1,441.00

LIMFS

MVA NAME & SIGNATURE  
DATE :

SURVEYOR NAME & SIGNATURE  
DATE :

Kalvin 16/08  
20/8/19 1345hr.  
3 Days.  
81P  
After Repair photo

TOTAL : 2,903.32

AUTHORISED : YES / NO

notify

on a "job" basis

covered and

Insurance Company

• Thro

• No illegal

• Supplement

is subject

Acknowledged by

Signature:

Date:

Our Job Ref No : 305325962

Date : 23/08/19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHC1891C

Date of Accident : 20-Aug-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SFK 562R

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,246.32

(b) Labour Charges \$911.00

**Total for Part-By-Part Repair Cost** \$2,157.32

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%


**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature 

Name : LIM T S

Name KALVIN

Tel : 62148398

Date : 23/8/19

Fax : 65468156

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305325962  
 REGN NO : SHC1891C  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 20.09.2017  
 DATE/TIME IN : 20.08.2019 10:10  
 ACCIDENT DATE : 20.08.2019

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	03-01-0302-2020-G	REAR SPORT RIM RH	1	1,555.10	25.00	1,166.32
0002	28-01-9999-2023-A	REAR DOOR APPS RH	1	80.00		80.00

SUB-TOTAL : 1,246.32

## JOB NATURE

0000	PB	PANEL BEATING				300.00
0001	SP	SPRAYPAINT-Rear Bumper&Fender RH				600.00
0002	20-05	TP MERIMEN				11.00

SUB-TOTAL : 911.00

TOTAL : 2,157.32



\_\_\_\_\_  
 MVA NAME & SIGNATURE  
 DATE :

\_\_\_\_\_  
 AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE  
 DATE :

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2019 <a href="#">Sendback Est</a>	20 Aug 2019 17:27 <b>S\$2,903.32</b>	20 Aug 2019 18:18 <a href="#">Edit Adj Rpt</a>	<b>S\$2,157.32</b> <a href="#">Edit Estimates</a>	<b>S\$2,157.32</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>PUNGGOL EAST CAR RENTAL</b> , Co. Reg. No.: 53338281E								
Main Claimant:	<b>CTPL</b>								
Vehicle Reg. No.:	<b>SHC1891C</b>	Date of Loss:	20/08/2019 01:00 - :59 [ <b>23</b> Months From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / M1906397</b>	Policy/Cover Note No.:	MJ001819 (TP, Fire & Theft) Coverage: 13/12/2018 - 12/12/2019						
Vehicle Reg. No. (Insured):	<b>SFK562R</b>	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Dillen Senthilan so Selvarajoo</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [ <b>Final Rpt due 29/08/2019</b> ]								
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a>   <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**SHC1891C (M1906397)**  
**[SFK562R]**  
**TP**  
**CTPL**  
**Aug 20 2019 1:00AM**  
**[PUNGGOL EAST CAR RENTAL]**  
**ComfortDelGro Engineering Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	20/08/19 17:27	<b>Repairer Estimates</b>	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	21/08/19 09:34	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	23/08/19 09:29	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
27	23/08/19 09:29	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
28	23/08/19 09:29	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	27/08/19 14:42	<b>LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee</b>	Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	20/08/19 17:28	<b>E-filed GIA report</b>	Load PDF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI19014599/K1TF3E2

**Date:** 28/08/2019

#### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	MJ001819
<b>Claimant Vehicle No :</b> SHC1891C	<b>Insured Vehicle No :</b>	SFK562R
Date of Loss: 20/08/2019	Nature of Claim:	TP Claim No: M1906397

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SHC1891C</b>	Engine No: 2ZRS063941
Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No: JTDKB3FU103564236
Reg. Date: 20/09/2017 (Man. Year: 2017)	Odometer: 255897 km
Colour: Blue	
Engine Capacity: 1798 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): <b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

#### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Davanti 7 mm	Rear Left Side:	Davanti 7 mm
Front Right Side:	Davanti 7 mm	Rear Right Side:	Davanti 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,462.32	1,246.32	216.00	14.77
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,430.00	900.00	530.00	37.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,903.32</b>	<b>2,157.32</b>	<b>746.00</b>	<b>25.69</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>203.23</b>	<b>151.01</b>	<b>52.22</b>	<b>25.70</b>
<b>Nett Amount (S\$)</b>	<b>3,106.55</b>	<b>2,308.33</b>	<b>798.22</b>	<b>25.69</b>

#### INSPECTION

Date of Assignment:	20/08/2019 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	20/08/2019 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$2,157.33

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2019)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC1891C)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SPORT RIM RH	Grazed	1,555.10 FL	*1,555.10 FL
2	1		*REAR DOOR APPS RH	Necessary	80.00 F	*80.00 FS
3	1		*REAR DAVANTI TYRE RH	Serviceable	216.00 F	*- FS
4	1		*REAR BUMPER (NPA)	Repair	-	*- FS
5	1		*REAR FENDER (RH) (NPA)	Repair	-	*- FS
6	1		*REAR DOOR (RH) (NPA)	Repair	-	*- FS
<b>Sub Total (S\$)</b>					<b>1,851.10</b>	<b>1,635.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>					<b>388.78</b>	<b>388.78</b>
<b>Total Parts (S\$)</b>					<b>1,462.32</b>	<b>1,246.32</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	560.00	300.00
2	SPRAY PAINTING	New	750.00	600.00
3	WHEEL ALIGNMENT	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,430.00</b>	<b>900.00</b>

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >