

ASS. REC. BY:

REF: CS/CT219014642/GVf3n2 Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Jern Tan Hui Ping of CT2

Date/Time: 21.8.19 14.19 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLL 6718T

Insured: SLV 3105J

at Workshop m/s Body Fix

Tel: 62571289

of 10 Amk Industrial Park 2A #04-06

Policy No: DMPC SN 30242219077

Claim No: SNM19D203852C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 17.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21.8.2019 23p.m

Person Contacted:


Yu Zhen

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 6718T - NA / IN / 1900220/h4 DOA - 22/02/2019
	SLV 3105J - (C3) / CT219014358 / Kwa392 DOA - 02/02/2018

ASSIGNMENT

From: _____ Date: 22.8.2019
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SLL C718T
at Workshop m/s Body fix
of 10 Amx Industrial Part 2A # 04-06
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 8 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS rap'

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLL6718T Yr Regn: 06 Mar 2017
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota sienta 1.567 1496
Colour: Brown A/C: Insured / Std / NI / NA
Sp. Reading: 178386 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: NSP1707058893
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: M / S/Rim / STD A/Rim or
Tyre Size: F: 185/60 R15
R: 11
BS/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 22-08-19
Survey held at w/s 5130pm
Des. of Damages: Frt / Rear / O/S / M/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
08/10 Finalized \$5850 with Yuzhen (Red 13,418.05, 6990)

RECEIVED 00 OCT 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 8/10 - typist

Report Format : Merimen

Lump Sum / I.B.I. (\$) 5850

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2019		21 Aug 2019 14:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:		H&H CAR RENTAL & LEASING							
Vehicle Reg. No.:		SLL6718T	Date of Loss:	17/08/2019 16:00 - :59					
Claim Type:		TP / SNM19D203852C02	Policy/Cover Note No.:	DMPCSN30242219077					
Vehicle Reg. No. (Insured):		SLU31053	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer:		Bodyfix (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #04-06, ANG MO KIO AUTO POINT, 568047 Ang Mo Kio - Tel:							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/08/2019]							
Adj Asg. Remarks:		PLEASE SURVEY AND REVERT							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 21 August, 2019 2:13 PM
To: assignments; bodyfix@singnet.com.sg
Cc: assignments
Subject: OUR REF: SNM19D203852-SLU3105J-OCK - FW: surveyor request for SLL 6718 T
Attachments: SLL 6718T GIA & Police report.pdf

WITHOUT PREJUDICES

Dear Sir (LKK),

We refer to the above matter.

Please liaise with **BODYFIX** to conduct PRS.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Lim Shu Min
Sent: Wednesday, 21 August, 2019 2:05 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: FW: OUR REF: SNM19D203852-SLU3105J-OCK - FW: surveyor request for SLL 6718 T

Thank you

Lim Shu Min
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Tuesday, 20 August, 2019 11:07 AM
To: Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; bodyfix@singnet.com.sg
Subject: OUR REF: SNM19D203852-SLU3105J-OCK - FW: surveyor request for SLL 6718 T

Dear Chin Kiat,

Please conduct PRS – SLL6718T.

Note: office in charge – Chin Kiat 63896174.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: BodyFix [<mailto:bodyfix@singnet.com.sg>]
Sent: Monday, 19 August, 2019 5:59 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: surveyor request for SLL 6718 T

Dear Officer,

Our ref: SLL 6718 T

Your insured: SLU 3105 J

DOA: 17/8/2019

Kindly arrange your surveyor to inspect my client's car at:

Workshop: Bodyfix

Address: blk 10 Ang Mo Kio Industrial Park 2A #04-06 AMK Autopoint S(568047)

GIA & police report as attached, pls acknowledge us by email or call 62571289, thanks.

Best Regards,
Yuzhen

BODYFIX

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-06 AMK AUTOPOINT

SINGAPORE 568047

TEL: 6257 1289 / 6483 7430 FAX: 6483 7432

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	980C
Vehicle No.:	SLL6718T
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5G A
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	2NR8684354
Chassis No.:	NSP1707058893
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$22,160.00
Original Registration Date:	06 Mar 2017
First Registration Date:	06 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$13,024.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Mar 2027
PARF Rebate Amount:	\$9,768.00
COE Expiry Date:	05 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,430.00
COE Rebate Amount:	\$37,227.00
Total Rebate Amount:	\$46,995.00

The information contained herein is correct as at 22 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 15:32
Date Of Accident	17/08/2019 16:00
Exact Location Of Accident	FABER GARDEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL6718T
Insured/Policyholder	
Name Of Registered Owner	H & H CAR RENTAL & LEASING
Co Reg No	53331980C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67433291
Vehicle Particulars	
Manufacturer	TOYOTA
Model	SIENTA 1.5G A
Exact Purpose for which vehicle was being used at time of accident	DRIVING CUSTOMER BACK TO THEIR CONDO
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5108503970
Cover Note Number	

Driver

Name of Driver	DONALD LIM CHAI KEE
NRIC No	S1171050F
Date Of Birth	06/11/1956
Occupation	OUTDOOR
Date Of Driving Pass	26/12/1978
Driving Experience	40 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81574479
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 510A YISHUN STREET 51 #07-565
 Postcode 761510
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER & LEASEE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : PASSENGER
 GENDER: : MALE
 Passenger 2 NAME: : PASSENGER
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name MARINE PARADE NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4428999 - FAX NO: 62447678
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ACCIDENT STATEMENT AS ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLU3105J
 Vehicle Make/Model/Colour BMW 3 SERIES
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TAN CHONG HWEE

NRIC/Passport Number	S7540760B
Contact Number	92276746
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	DONALD LIM CHAI KEE
Approximate Age	62
Injuries Sustain	
Injured person in which vehicle?	SLU3105J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 510A YISHUN STREET 51 #07-565
Postcode	761510

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or Agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Tan

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Joelle Tan

Reporting Centre Personnel's Signature
Name: Joelle Tan

NRIC/FIN No.: AMK AUTOPoint PTE LTD
17.08.2019

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO POLICE REPORT T/2019 0187

T/2019 0818/2031 ATTACHED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name: JOELLE TAN
NRIC/FIN No: AMK AUTOPoint PTE LTD
19.08.2019



**SINGAPORE
POLICE FORCE**



T/20190818/2031

1 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/20190818/2031

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/08/2019 11:11	Vide Report No.:	Station Diary No.: 26
--	------------------	--------------------------

Informant's Particulars

Name of Informant: DONALD LIM CHAI KEE			Address: APT BLK 510A YISHUN STREET 51 #07-565 SINGAPORE 761510		
ID Type / ID No.: NRIC NO / S1171050F			Contact No.: Home/Office: Mobile: 81574479		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 62	Date of Birth: 06/11/1956	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GoJek Driver			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/08/2019 16:00	Type of Location: Car Park
Location: Along Road 1 ANGKLONG LANE Faber Garden				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 15 Km/h
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Rear to side door.				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLL6718T	Car				Seriously Damaged	2
SLU3105J	Car					0



SINGAPORE
POLICE FORCE



T/20190818/20

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/201906

CONTINUATION OF REPORT

Brief Details.

On 17/08/2019, at about 1600hrs, I was at Angklong Lane, Faber Gardern, alighting them at the said condo. When I was driving along the carpark at the said location, suddenly a black in colour BMW, SLU3105J, suddenly reversed out from a parking lot and knocked onto the front and the rear passenger side of my car door. I then stop my car and came out to check on the damages of my car. Both the front and the rear passenger side door of my car was seriously dented. We then exchange particulars and took photos of the accident before leaving the scene. Earlier today, when I woke up, I felt pain at the left shoulder, as I had knocked it during the accident. I then consulted the doctor and was given 5 days of medical leaves due to the injuries I sustained during the accident.

Particulars of the driver of SLU3105J:

Name: Tan Chong Hwee
NRIC: S7540760B
H/P: 92276746



T/20190818/2031

3 of 3

Report No. T/20190818/2031

Station Of Origin:
Marine Parade N.P.C
100 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Staff Sgt KWOK WEI JIE, DANIEL

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SI ANG YI TING, STEPHANIE
Contact No.: 65476414

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
18/08/2019 11:11

Classification Of Case:

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

CHINA TAIPING INSURANCE (SINPORE) PTE LTD
3 ANSON ROAD #16-00 SPRINGLEAF TOWER
S'079909

Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Estimate : ES190822

Date : 22/08/2019
Vehicle Num. : SLL 6718 T
Make/Model : TOYOTA SIENTA-2016
Chassis/Eng# : NSP1707058893
Accident Date : 17/08/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	REAR FENDER (LH) <i>TN</i>		1,057.00
2.	1 PC	REAR FENDER INNER SHIELD - LH <i>X NN</i>		88.00
3.	1 PC	REAR DOOR (LH) <i>Buc</i>		1,279.00
4.	1 PC	REAR DOOR OUTER HANDLE (LH) <i>X NN</i>		167.00
5.	LH	REAR DOOR BOARD <i>X NN</i>		957.00
6.	2 PCS	REAR DOOR HINGES <i>X NN</i>	187.00	374.00
7.	1 PC	POWER WINDOW MOTOR (REAR LH) <i>X NN</i>		677.00
8.	1 PC	POWER WINDOW REGULATOR REAR LH <i>X NN</i>		225.00
9.	1 PC	FRONT DOOR (LH) <i>Buc</i>	1233.9	1,412.00
10.	1 PC	FRONT DOOR OUTER HANDLE (LH) <i>X</i>		395.00
11.	1 PC	FRONT DOOR WEATHER STRIP <i>X</i>		230.00
12.	LH	FRONT DOOR BOARD <i>X NN</i>		1,053.00
13.	2 PCS	FRONT DOOR HINGES <i>X</i>	187.00	374.00
14.	1 PC	POWER WINDOW MOTOR (FRONT LH) <i>X</i>		765.00
15.	1 PC	POWER WINDOW REGULATOR FRONT LH <i>X</i>		287.00
16.	1 PC	FRONT FENDER (LH) <i>Buc</i>	11/10	851.00
17.	1 PC	HEAD LAMP (LH) <i>Cut</i>	1287.5	1,712.45
18.	1 PC	FRONT BUMPER <i>Cut</i>		581.90
19.	10 PCS	FRONT BUMPER CLIPS <i>itc</i>	20 (SIV)	129.00
20.	1 PC	FRONT BUMPER SIDE RETAINER - LH <i>re</i>	12.90	178.90
21.	1 PC	REAR BUMPER <i>Repair</i>	55	481.90
22.	1 PC	REAR BUMPER SIDE RETAINER (LH) <i>X NN</i>		178.90
23.	1 PC	LH REAR DOOR PROTECTOR <i>CAT</i>		245.00
24.	1 PC	LH REAR FENDER PROTECTOR <i>CAT</i>		189.00
List TotalS\$:				13,888.05
SPECIAL NETT ITEMS :				
1.	1 PC	LH FRONT TYRE RIM <i>cover / Cut</i>	55	500.00

CONTINUE / ...

~~REAR DOOR LH Protector / Cut~~
~~REAR FENDER LH Protector / Cut~~
6338.3
25% : 4753.73

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

CHINA TAIPING INSURANCE (SINPORE) PTE LTD
3 ANSON ROAD #16-00 SPRINGLEAF TOWER
S'079909Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Estimate : ES190822

Date : 22/08/2019
Vehicle Num. : SLL 6718 T
Make/Model : TOYOTA SIENTA-2016
Chassis/Eng# : NSP1707058893
Accident Date : 17/08/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1 PC	LH FRONT TYRE X NN		300.00 X
3.	1 PC	LH REAR TYRE RIM Cover - Cut		500.00 X
4.	1 PC	LH REAR TYRE X NN		300.00 X
Special Nett Total S\$:				1,600.00
LABOUR :				
RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS				✓ 60 80.00
LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR & RE-ALIGN DAMAGE PARTS				✓ 1200 1,900.00
PUTTY & SPRAY PAINT FRONT & REAR DOOR, FRONT & REAR FENDER, FRONT & REAR BUMPER & OTHER AFFECTED AREAS				✓ 1200 1,800.00
Labour Total S\$:				3,780.00

8 Days.

put by put.

before paint photos.

M. M. M.
23/8/19.

7343.73

20% 15850

SingDollars : Nineteen Thousand Two Hundred Sixty-Eight & Cents Five Only

E. & O.E.

Total S\$: 19,268.05


for BODYFIX

Gao Qiang - 82 880822.

Gao Qiang @ lkk auto. com

22/8/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19014642/GVF3N2

Date: 09/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30242219077
Claimant Vehicle No :	SLL6718T	Insured Vehicle No :	SLU3105J
Date of Loss:	17/08/2019	Nature of Claim:	TP
		Claim No:	SNM19D203852C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL6718T	Engine No:	2NR8684354
Make & Model:	TOYOTA SIENTA, 1.5 G (A)	Chassis No:	NSP1707058893
Reg. Date:	06/03/2017 (Man. Year: 2016)	Odometer:	178386 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,488.05	4,883.72	10,604.33	68.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	2,460.00	1,320.00	34.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,268.05	7,343.72	11,924.33	61.89
Approved Total (Overridden) (S\$)		5,850.00		
(S\$)	19,268.05	5,850.00	13,418.05	69.64
+ GST 7.00/7.00% (S\$)	1,348.76	409.50	939.26	69.64
Nett Amount (S\$)	20,616.81	6,259.50	14,357.31	69.64

INSPECTION

Date of Assignment: 21/08/2019

Date Inspected: 22/08/2019 Inspected At:

Bodyfix (HQ)

10 ANG MO KIO INDUSTRIAL PARK
2A, #04-06, ANG MO KIO AUTO POINT
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2019)
Parts: M1-MPV	TOYOTA SIENTA 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL6718T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER (LH)	Torn	1,057.00 F	*1,057.00 FL
2	1		*REAR FENDER INNER SHIELD-LH	Not Necessary	88.00 F	*- FL
3	1		*REAR DOOR (LH)	Buckled	1,279.00 F	*1,279.00 FL
4	1		*REAR DOOR OUTER HANDLE (LH)	Not Necessary	167.00 F	*- FL
5	1		*REAR DOOR BOARD LH	Not Necessary	957.00 F	*- FL
6	2		*REAR DOOR HINGES	Not Necessary	374.00 F	*- FL
7	1		*POWER WINDOW MOTOR (REAR LH)	Not Necessary	677.00 F	*- FL
8	1		*POWER WINDOW REGULATOR REAR LH	Not Necessary	225.00 F	*- FL
9	1		*FRONT DOOR LH	Buckled	1,412.00 F	*1,233.90 FL
10	1		*FRONT DOOR OUTER HANDLE (LH)	Not Necessary	395.00 F	*- FL
11	1		*FRONT DOOR WEATHER STRIP	Not Necessary	230.00 F	*- FL
12	1		*FRONT DOOR BOARD LH	Not Necessary	1,053.00 F	*- FL
13	2		*FRONT DOOR HINGES	Not Necessary	374.00 F	*- FL
14	1		*POWER WINDOW MOTOR (FRONT LH)	Not Necessary	765.00 F	*- FL
15	1		*POWER WINDOW REGULATOR FRONT LH	Not Necessary	287.00 F	*- FL
16	1		*FRONT FENDER (LH)	Buckled	851.00 F	*410.00 FL
17	1		*HEAD LAMP (LH)	Cut	1,712.45 F	*1,287.50 FL
18	1		*FRONT BUMPER	Cut	581.90 F	*581.90 FL
19	1		*FRONT BUMPER SIDE RETAINER-LH	Deformed	178.90 F	*55.00 FL
20	1		*REAR BUMPER	Repair	481.90 F	*- FL
21	1		*REAR BUMPER SIDE RETAINER (LH)	Not Necessary	178.90 F	*- FL
22	1		*LH REAR DOOR PROTECTOR	Cut	245.00 F	*245.00 FL
23	1		*LH REAR FENDER PROTECTOR	Cut	189.00 F	*189.00 FL
24	10		*FRONT BUMPER CLIPS	Necessary	129.00 FS	*20.00 FS
25	1		*LH FRONT TYRE RIM COVER	Cut	500.00 FS	*55.00 FS
26	1		*LH FRONT TYRE	Not Necessary	300.00 FS	*- FS
27	1		*LH REAR TYRE RIM COVER	Cut	500.00 FS	*55.00 FS
28	1		*LH REAR TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,488.05	6,468.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,584.58
Total Parts (\$\$)	15,488.05	4,883.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS	New	80.00	60.00
2	LABOUR TO REPLACE ABOVE PARTS,PANEL BEAT,REPAIR & RE-ALIGN DAMAGE PARTS	New	1,900.00	1,200.00
3	PUTTY & SPRAY PAINT FRONT & REAR DOOR,FRONT & REAR FENDER,FRONT & REAR BUMPER & OTHER AFFECTED AREAS	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			3,780.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >