

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Paulin Tham of MS19 Date/Time: 21.8.19 1006a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMJ 9629X Insured: SKP 1206C

at Workshop m/s Auto Bullox Tel: 97649299

of 5345 Ave 1 #01-19

Policy No: 80410160 Claim No: 603137

Sum Insured: Excess:

Make of Veh: D.O.A. 16.8.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21.8.19 2.33p.m. Person Contacted: Kaman Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SMJ 9629X - N/A / INC K10146191 F DOA - 14/03/2019
	SKP 1206C - N/A / INC 19014340/24 DOA - 16/03/2019
27/8/19	Sand preli revised via meriman

Surveyor

612

REF: ms19

ASSIGNMENT

From: Date: 26.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ 9629X

at Workshop m/s Alto Bullox

of 53 Ula Ave 1 #01-19

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: ASX 10.000.000

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMJ9629X

Yr Regn: 26 Mar 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Noah 1.8X 1797

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading:

36599

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZWR 800358973

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F: 195/65 R15
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6 mm

Rear

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

26-08-19

Survey held at

w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

4 pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/8 Finalized \$ 2900 with karman. (15) Red 3833.38, 5710

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 29/8 - typist

Report Format :

merimen

Lump Sum / I.B.I. (\$

2900/-

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

) Photos

) Others

TOTAL

150

11

161

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 27 Aug 2019

Preliminary Advice

Insured Vehicle No	: SKP1206C	Accident Date	: 16/08/2019
TP Vehicle No	: SMJ9629X	Assignment Date	: 21/08/2019
Make	: TOYOTA NOAH HYBRID	Est. Duration of Repair	: 4
Date of Inspection	: 26/8/2019		
Inspection At	: AUTO BULLOX PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,033.38
Revised Amount	:S\$	3,669.85
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,669.85

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Aug 2019 18:20		21 Aug 2019 10:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		JENNY HENG SOO KHENG, ID: S1174678J							
Main Claimant:		SUPER STAR LIMO & CAR RENTAL, Co. Reg. No.: 53359119L							
Vehicle Reg. No.:		SMJ9629X	Date of Loss:	16/08/2019 17:00 - :59 [4 Months and 21 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 603137	Policy/Cover Note No.:	80410160 (Comprehensive) Coverage: 15/08/2019 - 14/08/2020					
Vehicle Reg. No. (Insured):		SKP1206C	Policy No. (Claimant):						
		Excess:							
Repairer:		Auto Bullox Pte Ltd (HQ) 53 UBI AVE 1, #01-19 PAYA UBI INDUSTRIAL PARK, 408934 Ubi - Tel:							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/08/2019]							
Driver/Custodian (Insured):		NG GUOXIONG LOUIS (/ Male) , NRIC: S9005350G Email:							
Adj Asg. Remarks:		on WP. Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Mr Kaman @ 9769 9299.							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No: 5108614334

Date of Accident: 16/08/2019 18:10

Vehicle No.(For Motor): SMJ9629X

Certificate Number:

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5108614334	5108614334-000011	SUPER STAR LIMO & CAR RENTAL	53359119L	GPM	drive CLASSIC	SMJ9629X	SMJ9629X	12/04/2019	11/04/2020

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	119L
Vehicle No.:	SMJ9629X
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID 7-SEATER 1.8X CVT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	2ZR0C80369
Chassis No.:	ZWR800358973
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,314.00
Original Registration Date:	26 Mar 2019
First Registration Date:	26 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$28,640.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2029
PARF Rebate Amount:	\$21,480.00
COE Expiry Date:	25 Mar 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,401.00
COE Rebate Amount:	\$37,719.00
Total Rebate Amount:	\$59,199.00

The information contained herein is correct as at 26 Aug 2019

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7114082B**

Name **SHAWN NG YEW SENG**

Birth Date **25 Apr 1971**

Issue Date **03 Oct 2014**

For LKK/NAC Use Only

002351555H

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7114082B**



Name **SHAWN NG YEW SENG**

Race **CHINESE**

Date of birth **25-04-1971**

Country/Place of birth **SINGAPORE**

Sex **M**

SUPER STAR LIMO & CAR RENTAL
Reg. No.: 53359119L

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class	Effective Date
Class 2B	26 Jan 2016
Class 2A	09 Apr 2017
Class 3	07 Oct 2014

Motorcycles <= 200 CC
Motorcycles between 201 CC and 400 CC
Motor cars <= 3600 kg with <= 7 passengers, exclusive of the driver, and motor tractors/vehicles <= 2500 kg

S / No. 9000267548

Licence No. **S7114082B**

N7 428A

5341834



NRIC No. **S7114082B**



Date of issue **20-08-2014**

APT BLK 12 TELOK BLANGAH CRESCENT #04-109
SINGAPORE 090012

NRIC No: **S7114082B** Date: **17/03/2019**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/08/2019 14:39
Date Of Accident	16/08/2019 18:10
Exact Location Of Accident	SLIP RD CANTONMENT LINK TWDS CANTONMENT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ9629X
Insured/Policyholder	
Name Of Registered Owner	SUPER STAR LIMO & CAR RENTAL
Co Reg No	53359119L
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96233308
Alternative Phone No	OFFICE-96233308

Vehicle Particulars

Manufacturer	TOYOTA
Model	NOAH HYBRID 7-SEATER 1.8X CVT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5108614334
Cover Note Number	

Driver

Name of Driver	SHAWN NG YEW SENG
NRIC No	S7114082B
Date Of Birth	25/04/1971
Occupation	OUTDOOR
Date Of Driving Pass	03/10/2014
Driving Experience	4 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88144187
Fax Number	
Contact Number	OFFICE-88144187
Email Address	NOEMAIL

Address	BLK 12 TELOK BLANGAH CRESCENT #04-109
Postcode	090012
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED BEFORE THE STOPPING LINE OF CANTONMENT LINK TO CHECK ONCOMING VEHICLES ON MY LEFT SIDE. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO VEHICLE B REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP1206C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	81188725
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :

DETAILS OF INJURED PERSON 1

Name

SHAWN NG YEW SENG

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SMJ9629X

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders

SUPER STAR LIM & CAR RENTAL
Reg. No.: 53359119L


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:


Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement -



DECLARATION

I/We declare the foregoing particulars are true in every respect

SUPER STAR LIMO & CAR RENTAL
Reg. No. 53359118L

Policyholder's Signature
Date & Time

Driver's Signature _____
(if driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LKK Auto Consultants henceforth
the Repairer of the following:

- To resurvey before after spray painting
- To do a 53 Ubi Avenue 1#01-49 Bayside Industrial Park Singapore 408934
- Parts prices are subject to change
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

AUTO BULLOX PTE LTD

Estimate

Vehicle: SMJ9629X

Make & Model: TOYOTA NOAH HYBRID

4 Days.

lump sum repair.

After repair photos.

Due Date 26/8/19.

[Signature]
27/8/19

No	Particular	Qty	Amount
	List Price		
1	Rear boot lid / <i>Buc</i>	1pc	1,920.50
2	Rear boot logo (Hybrid Synergy Drive) / <i>nc</i>	1pc	68.50
3	Rear boot Chrome moulding X	1pc	158.48
4	Rear boot inner lock X	1pc	524.60
5	Rear boot weatherstrip X	1pc	323.60
6	Rear boot inner trim board X	1pc	421.90
7	Rear bumper / <i>nc</i>	1pc	1,230.80
8	Rear bumper side holder @\$48.60 X	2pcs	97.20
9	Rear bumper side retainer @\$64.43 X	2pcs	128.86
10	Rear end panel X	1pc	824.60
11	Rear end panel garnish X	1pc	178.80
			5,877.84
	Less 25%		(1,469.46)
	Sub-Total cost for parts		4,408.38
	Part Replacement - Special		
	Nett Item		
1	Rear reverse sensor X <i>NN</i>	1 set	280.00
2	Rear bumper clip / <i>nc</i>	1 set	50.00
3	Rear boot inner trim clip / <i>nc</i>	1 set	35.00
	<i>Rear windscreen gum \$60 / nc</i>		365.00
	Labour & MISC Charges		
1	To remove, refix reverse sensor		60.00
2	To remove, refix rear interior upholstery to assist repair		150.00
3	To respray painting & etc		800.00
4	Panel beating, remove & replacing above parts		800.00
5	To respray undercoating		150.00
	Sub-Total Labour	7033.38	1,960.00
	Grand Total		6,733.38

To remove, refix windscreen \$120 - 100
17 rear boot assy \$120 - 60

3669.85
20%: 2900

3219.8

2414.85

PPS

40

60

400

400

50

950

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014648/GVF3N2

Date: 19/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80410160
Claimant Vehicle No :	SMJ9629X	Insured Vehicle No :	SKP1206C
Date of Loss:	16/08/2019	Nature of Claim:	TP
		Claim No:	603137

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ9629X	Engine No:	2ZR0C80369
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800358973
Reg. Date:	26/03/2019 (Man. Year: 2018)	Odometer:	36599 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,833.38	2,559.85	2,273.53	47.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,110.00	1,090.00	49.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,033.38	3,669.85	3,363.53	47.82
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	7,033.38	2,900.00	4,133.38	58.77

INSPECTION

Date of Assignment:	21/08/2019	
Date Inspected:	26/08/2019	Inspected At:
		Auto Bullox Pte Ltd (HQ)
		53 UBI AVE 1, #01-19 PAYA UBI
		INDUSTRIAL PARK
		Singapore 408934

Estimated Period of Repair: 4.0 days**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2019)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ9629X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Buckled	1,920.50 FL	*1,920.50 FL
2	1	*REAR BOOT LOGO (HYBRID SYNERGY DRIVE)	Necessary	68.50 FL	*68.50 FL
3	1	*REAR BOOT CHROME MOULDING	Not Necessary	158.48 FL	*- FL
4	1	*REAR BOOT INNER LOCK	Not Necessary	524.60 FL	*- FL
5	1	*REAR BOOT WEATHERSTRIP	Not Necessary	323.60 FL	*- FL
6	1	*REAR BOOT INNER TRIM BOARD	Not Necessary	421.90 FL	*- FL
7	1	*REAR BUMPER	Deformed	1,230.80 FL	*1,230.80 FL
8	2	*REAR BUMPER SIDE HOLDER	Not Necessary	97.20 FL	*- FL
9	2	*REAR BUMPER SIDE RETAINER	Not Necessary	128.86 FL	*- FL
10	1	*REAR END PANEL	Not Necessary	824.60 FL	*- FL
11	1	*REAR END PANEL GARNISH	Not Necessary	178.80 FL	*- FL
12	1	*SET REAR REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
13	1	*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
14	1	*SET REAR BOOT INNER TRIM CLIP	Necessary	35.00 FS	*35.00 FS
15	1	*REAR WINDSCREEN GUM	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,302.84	3,364.80
- List Item Discount on L Items 25.00/25.00% (S\$)	1,469.46	804.95
Total Parts (S\$)	4,833.38	2,559.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIX REVERSE SENSOR	New	60.00	40.00
2	TO REMOVE,REFIX REAR INTERIOR UPHOLSTERY TO ASSIST REPAIR	New	150.00	60.00
3	TO RESPRAY PAINTING & ETC	New	800.00	400.00
4	PANEL BEATING ,REMOVE & REPLACING ABOVE PARTS	New	800.00	400.00
5	TO RESPRAY UNDERCOATING	New	150.00	50.00
6	TO REMOVE ,REFIX WINDSCREEN	New	120.00	100.00
7	TO REMOVE ,REFIX REAR BOOT ASSY	New	120.00	60.00
Gross Labour Cost (S\$)			2,200.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >