

<< Service Request Details

Claim	S9M01XS2
Reference	CC4/ASM19014652/Ega3q2 
Loss Date	13 August 2019
Report Date	21 Aug 2019 8:47:32 AM
Request Date	21 August 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle	GZ8820C
Registration #	
Make	TPVD NISSAN
Model	NV200

Service Address

...

Primary Contact/Insured

PARAMESWARAN PRASHOBAN
603 YISHUN STREET 61, #04-345, 760603,
Singapore

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

1

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice1 (2)-AC2007312.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	11 November 2020

NAME	TYPE / Claim	SUB-TYPE	AMOUNT	DATE
 LKKInspection (1).pdf	Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 November 2020
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 November 2020
 LKK PHOTO-2.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 November 2020
 10 DAYS NOTICE TO TP.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 October 2020
 TP - IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	2 September 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	2 September 2019
 LKK SURVEY PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 September 2019
 TP PRI EMAIL FROM WORKSHOP WIT TP GIA.msg	Letters and Correspondence	Workshop	DHIWAR Namrata	21 August 2019
 FBM5098T INS GIA.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	21 August 2019
 SLE3654A GIA REPORT.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	21 August 2019