



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19014652/Ega3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 02-11-2020



ATTN:STACEY NG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBM 5098T	Veh. Inspected	GZ 8820C
Policy No.	VMX/P2223974	Coverage (\$)	0.00
Claim No.	S9M01XS2	Excess (\$)	0.00
Assign From		Assign Date	21/08/2019

### 2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VSKYBAM20Z0093743	Colour	SILVER
Odometer	149617	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14C	GOODYEAR	5 mm
L/H Front Tyre	175/70 R14C	GOODYEAR	5 mm
R/H Rear Tyre	175/70 R14C	GOODYEAR	5 mm
L/H Rear Tyre	175/70 R14C	GOODYEAR	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	13/08/2019	Inspection Date	27/08/2019
Survey held at	WENG KEE MOTOR BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------