

INSURANCE

INS. CASE OWNER:

725

CC 4/AXA1901 4655, R100639

LKK:

IDAC:

Surveyor:

Rasul

DOI:

ASSIGNMENT

21/8/19

Date / Time:

21/8/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YK 65932

Name of Insured:

KIAN SENG YONG IMPORT & EXPORT

Claim No.:

S9M02XPM / 132440

Policy No.:

P196904

Insured Tel No.:

HP:

PIC

Make / Model:

HIND

Excess Sec II :SS

D.O.A.:

19/8/19

Place of Accident:

TAGURF LANE

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO. Driver Name / Age: WNRV Kni21100

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SLK 534



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Goldbell



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time		STAGE	DATE / PIC
		Non-Reporting hr (1st):	
		Non-Reporting hr (2nd):	
		Non-Reporting hr (Final):	
		Notification hr (if non-pickup):	
		Call Of:	27/8/19
		After call hr to Of:	21/8/19
		Documentation Check List:	Handler Typist
		Notification hr (if non-pickup)	<input checked="" type="checkbox"/>
		After call hr to Of:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice:	<input checked="" type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/>
		Medical Bill:	<input checked="" type="checkbox"/>
		PIR:	<input checked="" type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input checked="" type="checkbox"/>
		Post-Repair Photos:	<input checked="" type="checkbox"/>
		Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost:	US	SS 200.00	( 2 days) Reduction: 204 * 50	Email <input type="checkbox"/> Call <input type="checkbox"/>
--------------	----	-----------	-------------------------------	--

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
------------------	------------	---------------	--

Final Liability:	%	100	(Agreed / Assessed) BOLA S/N No.:	N/C
------------------	---	-----	-----------------------------------	-----

Repair Cost:	(W/657)	SS 244.00		
--------------	---------	-----------	--	--

Loss of Rental (LOR):	SS	200.00	( 2 days) * 4100	
-----------------------	----	--------	------------------	--

Loss of Use (LOU):	SS	-	(5 x days)	
--------------------	----	---	------------	--

Loss of Income (LOI):	SS	-	(5 x days)	
-----------------------	----	---	------------	--

LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	(Tick only one)		
--	--	-----------------	--	--

GIA/LTA Search	SS	2.00		
----------------	----	------	--	--

Medical:	SS	-		
----------	----	---	--	--

Disbursement:	SS	-	(e.g. Tow/ Independent)	
---------------	----	---	-------------------------	--

Legal Cost	SS	-		
------------	----	---	--	--

Total:	SS	951.00	Global Sum SS:	
--------	----	--------	----------------	--

FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
---------------	------------	---------------	--

Payee 1:	SS	951.00	Name 1:	Goldwell Engineering Pte Ltd
----------	----	--------	---------	------------------------------

Payee 2: (Strike if N.A.)	SS	-	Name 2:	
---------------------------	----	---	---------	--

Payee 3: (Strike if N.A.)	SS	-	Name 3:	
---------------------------	----	---	---------	--

✓ GIA

ASS. REQ. BY:

REF:

W

45Kc

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 534at Workshop m/s Pangan Lompof BLK KInsured: AXA

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 60K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLK 534 Yr Regn: 2016 / F6BType: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA VERZA / SXCVT c.c. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 092156 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU1106359Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/08/19D.O.I. 21/08/19Survey held at GOLOKEL PANGAN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>45 8700/- (Red - 5704 / 507-)</u>

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: \_\_\_\_\_

1) \_\_\_\_\_

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee: \_\_\_\_\_

2) \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

S + PS \$ \_\_\_\_\_

☐ : Interview (\$ \_\_\_\_\_)

Parking

☐ : Tech. invs (\$ \_\_\_\_\_)

Others: \_\_\_\_\_

☐ : Wash & dry (\$ \_\_\_\_\_)

TOTAL

Report Format: \_\_\_\_\_

Lump Sum A/E/B: \_\_\_\_\_

FOR SURVEYOR 21/08/2019

TP-AYA-LIS.

DATE : 21/8/2019  
TO : MSIG MOTOR CLAIMS DEPT  
ATTN :  
OFFICE / MOBILE :  
EMAIL ADDRESS :

VEHICLE NO. : SLK53Y  
MODEL NO. : HONDA VEZEL 1.5X CVT  
CHASSIS NO. : RU11106359  
ENGINE NO. : L15B4026365  
REG. DATE : 16/2/2016

FROM : GOLDBELL ENGINEERING PTE LTD  
ATTN : MOHAMAD OMAR  
OFFICE / MOBILE : 97396452  
FAX NO. :

REF. NO. :  
D.O.A. : 6/12/2019  
POLICY NO. : A 28876396 QMY  
CLAIM TYPE : 3rd Party Claim

WORKSHOP : Blk K, Pandan Loop Ind. Estate #01-12 Singapore 128219

S/N	PART NO.	DESCRIPTION	QUANTITY	LIST PRICE
1		RHS WING MIRROR ASSY-COMplete <i>cm</i>	1	\$ 794.00

SUB-TOTAL : \$ 794.00

PARTS TOTAL : \$ 794.00

**LABOUR CHARGES**

- 1 TO REMOVE AND RE-INSTALL RHS WING MIRROR,  
AND WIRING SYSTEM AND PROGRAMMING. \$ *100* ~~380.00~~
- 2 SPRAY PAINTING OF ACCIDENT SECTIONS \$ *100* ~~150.00~~
- 3 RE-WIRING \$ *40* ~~80.00~~

LABOUR TOTAL : \$ 610.00

TOTAL : \$ 1,404.00

7% GST \$ 98.28

GRAND TOTAL : \$ 1,502.28

PREPARED BY : MOHAMAD OMAR

DATE / TIME : *21/08/19 01410*

SURVEYOR : *Rasul*

MOBILE NO. : *90010068*

OFFICE FAX NO. :

EMAIL ADDRESS : *rasul@lkkauto.com*

LKK Auto Consultant, hence notify  
the Repairer of the following:

- To recovery before/after repair
- To display damaged parts during recovery
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be returned and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR : Rasul  
MOBILE NO. : 90010088  
OFFICE FAX NO. : \_\_\_\_\_  
EMAIL ADDRESS : rasul@1kkauto.com  
REPAIR TYPE : PART-BY-PART / LUMP SUM  
RE-SURVEY : BEFORE PAINT / AFTER PAINT  
NO. OF DAYS : 2 day  
REMARKS : \_\_\_\_\_

R

> Back to OneMotoring

## Enquiry PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 454C

### Vehicle Details

Vehicle No: SLK53Y  
Vehicle to be Exported: Yes  
Intend ed Deregistration Date: 20 Aug 2019  
Vehicle Make: HONDA  
Vehicle Model: VEZEL 1.5X CVT  
Primary Colour: Blue  
Manufacturing Year: 2015  
Engine No: L15B4026365  
Chassis No: RU11106359  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$18,997.00  
Original Registration Date: 16 Feb 2016  
First Registration Date: 16 Feb 2016  
Transfer Count: 0  
Actual PARF Paid: \$8,997.00

### Intend ed PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 15 Feb 2026  
PARF Rebate Amount: \$6,747.00

### Intend ed COE Rebate Details

COE Expiry Date: 15 Feb 2026  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$46,651.00  
COE Rebate Amount: \$30,280.00  
**Total Rebate Amount: \$37,027.00**

The information contained herein is correct as at 20 Aug 2019

OK

AXA → FAX! 68804838

MOTOR.SAVING @ AXA-COM.SG

## ◀ Service Request Details

**Claim**

S9M01XPU

**Reference**None **Loss Date**

August 19, 2019

**Report Date**

Aug 21, 2019 10:39:00 AM

**Request Date**

August 21, 2019

**Due Date**

August 28, 2019

**Vendor Name**

LKK AUTO CONSULTANTS PTE LTD (TP)

**Type of Loss**

Third Party Vehicle Damage

**Services**

Pending verification - Direct Settlement

P: Omar

T: 1.37p.m

V: 14

E: ✓

**Actions****Next Step**

Agree to perform service

**Vehicle Information****Incident Vehicle Registration #**

SLK53Y

Model

VEZEL 1.5 X CT

## Service Address

...

## Primary Contact/Insured

KIAN SENG YONG IMPORT &amp; EXPORT PTE LTD

BLK 23 PASIR PANJANG, #01-173 WHOLESALE CENTRE, 110023, Singapore

65674755

## Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

<sup>1</sup>  
Messages<sup>2</sup>  
Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

TYPE



SENT

8/21/19 11:25 AM

FROM

TAN Jas

SUBJECT

DL

BODY

please obtain DL and upload. thanks.



## Catherine Chong (LKK Auto)

---

**From:** Mohamad Bin Omar <MohamadOmar@goldbell.com.sg>  
**Sent:** Wednesday, 21 August, 2019 10:14 AM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Subject:** [EXTERNAL] SLK53Y>>>YP6593K ACC DATE: 19/08/2019  
**Attachments:** 010)SLK53Y.jpg; 001)SLK53Y.jpg; 002)SLK53Y.jpg; 003)SLK53Y.jpg; 004)SLK53Y.jpg; 005)SLK53Y.jpg; 006)SLK53Y.jpg; 007)SLK53Y.jpg; 008)SLK53Y.jpg; 009)SLK53Y.jpg

**Categories:** Shekhar

To Officer-Incharge

May I have arranged survey for the above vehicle no:SLK53Y ( ASAP )>at Pandan Loop Blk K.  
Thank You

REGARDS  
MOHAMAD OMAR  
CUSTOMER SERVICE ADVISOR-MOTOR CLAIMS  
PANDAN GOLDBELL ENGINEERING  
PH:97396452



Mohamad Bin Omar | Goldbell Engineering Pte Ltd  
Customer Service Advisor, Motor Claims

DID: | Tel: | Fax: |  
Mobile: |







Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/10/2019

### Survey Details:

Date of loss	19-Aug-19
Date of appointment	21-Aug-19
Date of survey	21-Aug-19
Location of survey	GOLDBELL ENGINEERING PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SLK 53Y
Make and Model	HONDA VEZEL 1.5X
Date of registration	16/2/2016
Excess	
Market Value	\$60,000
Parf Rebate	\$37,027
Nett Loss	\$22,973

### Repair details:

Initial Estimate	\$ 1,404.00
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 635.20
Check items (estimate)	\$ -
Labour	\$ 240.00
<b>Total</b>	<b>\$ 875.20</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 700.00</b>
Number of days for repair	2



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

--

**Mandate:**

Liability(TP)	100%	
Proposed repair cost	\$ 749.00	W/GST
Loss of use	\$ -	
Loss of rental	\$ 200.00	2days x \$100
Loss of income	\$ -	
LTA search fees	\$ 2.00	
Others	\$ -	
<b>Proposed Total</b>	<b>\$ 951.00</b>	



## <MANDATE IA> - S9M01XPU {ACCIDENT INVOLVING YK 6593K (OI) & SLK 53Y (TP) ON 19/08/2019}

Type

🔔 Question

Message

LIABILITY: 100%, OIV'S REAR DOOR HIT ONTO TPV. INFORMED OI ABOUT TP CLAIM AND NCD ISSUE.  
AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$951.00 (CLAIMING LOR). MANDATE IA  
HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION.  
THANKS - CCL

Reply



Re:<MANDATE IA> - S9M01XPU {ACCIDENT  
INVOLVING YK 6593K (OI) & SLK 53Y (TP) ON  
19/08/2019}

Type

🔗 Question

Message

please proceed.

Reply



# GOLDBELL ENGINEERING

Industrial Vehicles.  
20,000 Served. And Counting.

18<sup>th</sup> October 2019

Our Reference : SLK53Y  
Your Reference : YP6593K

Attn: Motor Claims Department

**AXA INSURANCE SINGAPORE PTE LTD**  
8 Shenton Way #27-01  
AXA Tower  
Singapore 068811

Dear Sir/Madam,

**Subject: Accident case between SLK53Y & YP6593K on 19/08/2019 at Along Road 1 Tagore Lane**

We refer to the above case.

We are instructed by our client to file claim for the damages against your insured.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of vehicle No. YP6593K

We quantify our client's claim as follows:

1. Cost of Repair (\$700 x 7% GST)	S\$	749.00
2. Loss of Rental (\$120 x 2 days)	S\$	240.00
3. Third Party Insurer Enquiry Fee	S\$	2.00
<b>Total</b>	<b>S\$</b>	<b>991.00</b>

We hereby append the following relevant documents for your perusal:

- I. Repair Bill Tax Invoice
- II. Third Party Insurer Enquiry Tax Invoice
- III. Letter of Authority
- IV. Car Rental Invoice

Please let us know within the next 14 days from the received of this letter, whether you are prepared to accept all the above amount.

Best regards,

CATHERINE CHONG  
Customer Service Advisor, Motor Claims  
Goldbell Engineering Pte Ltd (Kaki Bukit Branch)  
Mobile : 9736 1300  
Email : [CatherineChongKL@goldbell.com.sg](mailto:CatherineChongKL@goldbell.com.sg)

**GOLDBELL ENGINEERING PTE LTD**

Main Office: 8 Tuas Avenue 18 Singapore 638882 Tel: 6861 0007 Fax: 6861 3876

Finance: 8 Tuas Avenue 18 Singapore 638882 Tel: 6861 0007 Fax: 6862 3500

Website: [www.goldbell.com.sg](http://www.goldbell.com.sg)

Co. Reg. No.: 198003863Q





# GOLDBELL ENGINEERING

Industrial Vehicles.  
20,000 Served. And Counting.

## GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3878

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: [www.goldbell.com.sg](http://www.goldbell.com.sg)

Ce. Reg. No. 1880039932

Page 1 / 1

AXA INSURANCE SINGAPORE PTE LTD  
8 SHENTON WAY #27-01 AXA TOWER  
SINGAPORE 068811  
Attn: FINANCE DEPARTMENT

### TAX INVOICE

GST Reg No. : M9-0002514-E  
Invoice No. : EXI00194507  
Invoice Date. : 18-10-2019  
Account No. : C00000371  
Quotation No. : 95470  
Work Order No. : 874340  
Service Centre. : 8 TUAS AVE 18  
Agreement No. : GBE-43140

PARTICULARS		AMOUNT SGD			
Reg No	: SLK53Y				
Chassis No	: RU11106359				
Engine No	:				
Model No	: VEZEL				
Mileage	: 0				
SRR No	:				
GBE/SVC/SALES-PD/05-1309					
DATE OF ACCIDENT : 19/08/2019					
POLICY NUMBER : A28876396QMY					
TP CLAIM : AXA INSURANCE					
	<u>Description</u>	<u>QTY</u>	<u>Disc</u>	<u>Net Price</u>	<u>Ext Price</u>
	LUMP SUM REPAIR	1	N	700.00	700.00
				Parts Charges:	700.00
				Sub Total:	700.00
				GST @ 7.00 %	49.00
	E. & O. E				
				<b>TOTAL</b>	<b>749.00</b>

Please make all cheques payable to GOLDBELL ENGINEERING PTE LTD.

When making payment, please quote our invoice numbers.

No receipts will be issued for Cheque Payments.

#### Terms and conditions of sales

Interest at 1.5% per month will be charged on overdue account

This is a computer generated document. No signature is required.





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

30 AUGUST 2019

**KIAN SENG YONG IMPORT & EXPORT PTE LTD**  
23 WHOLESALE CENTRE  
#01-173  
SINGAPORE 110023

Dear Sir/ Mdm

OUR REF : CC4/ASM19014655/R1wb3 // S9M01XPU  
YOUR REF : YK 6593K  
ACCIDENT INVOLVING YK 6593K AND SLK 53Y ALONG/AT TAGORE LANE ON  
19/08/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third party claim(s) from GOLDBELL ENGINEERING PTE LTD acting on behalf of the owner of SLK 53Y against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com) within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to [cst@axa.com.sg](mailto:cst@axa.com.sg) or deliver it by hand to AXA Customer Care Centre.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact as at Ms. Vivian Lau (LKK Handler) 6841 8625 or [vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com). Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vivian Lau  
Case Handler  
DID: 6841 8625  
FAX: 6741 4108  
EMAIL: [vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)

cc AXA INSURANCE PTE LTD





**GOLDBELL**  
ENGINEERING

Industrial Vehicles.  
20,000 Served. And Counting.

**GOLDBELL ENGINEERING PTE LTD**

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Appendix A

LETTER OF AUTHORITY

I/We, Samantha Ong Chui Thing owner of 9LK53Y (Vehicle no.) hereby authorize GOLDBELL ENGINEERING PTE LTD to act on my/our behalf with respect to my/our claim for repair costs and/or rental and/or loss of use for my vehicle no. 9LK53Y that was damage pursuant to the accident which occurred on 19.03.2019 at/along Along Road / Tagore Lane involving vehicle no. YP 6593K.

I/We further authorize GOLDBELL ENGINEERING PTE LTD to have full discretion to settle my/our above mentioned claim in a manner that they deem fit and to sign any discharge voucher or receive any payment on my/our behalf further to the settlement of my/our claim with payment cheque/s being made in favor of GOLDBELL ENGINEERING PTE LTD.

I/We further acknowledge that any settlement that GOLDBELL ENGINEERING PTE LTD may reach on my/our behalf is in full and final settlement of my/our property damage claims against the owner/ driver/ motor insurer of the third party vehicle bearing registration number YP 6593K and is on a without prejudice / without admission of liability basis insofar as the driver/ owner/ motor insurer of vehicle concerned.

Date this 21 day of 03 (month) 2019 (year)

Signature of claimant

(With Company Stamp of applicable)

Name of claimant

Samantha Ong Chui Thing

Company reg. / NRIC no.

830-39454C



Certificate No: AJA(S)17/1243

Certificate No: AJA(S)17/1243



### AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	YK6593K	(Insd veh)	Model: HONDA VEZEL-1.8 1.8X CVT (A)
	SLK33Y	(TP veh)	
Date of Accident/ Time:	19/08/2019		

Repair Estimate	: \$	1,502.28	
Final Repair Cost (wGST)	: \$	749.00	
Loss of Use	: \$	-	days at \$ per day
Rental (if any)	: \$	200.00	2 days at \$ 100.00 per day
LTA / GIA Search Fee	: \$	2.00	
Others	: \$	-	
	: \$		
Final Settlement Sum	: \$	951.00	
Payee Name : GOLDBELL ENGINEERING PTE LTD			
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:		Agreed Liability _____ (%)
B)	For GIA Registered Workshop:		BOLA Applicable: Yes/ <input checked="" type="checkbox"/> No BOLA Scenario No: <u>NL</u>
	BOLA Liability: _____ (%)		Assessed Liability (*) : <u>100</u> (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			

#### NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/i confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

  Signature of workshop representative / Workshop stamp Name of Representative: <u>Chong Kai Ling</u> Date: <u>24 Oct 2019</u>	  Signature of Witness / Workshop stamp (if applicable) Name of Witness: <u>Kon Yin Siew</u> Date: <u>24.10.2019</u>
Signature of AXA's surveyor/representative: Name of AXA's surveyor /Representative: Date:	

**Without Prejudice  
any claim for  
personal injury**

# PC LEASING

BLK K, PANDAN LOOP INDUSTRIAL ESTATE #01-12 SINGAPORE 128219

TEL: 67730073 / FAX: 67730928

REG. NO: 52986061M

INVOICE NO: **PC/0229/15**

GOLDBELL ENGINEERING PTE LTD  
10, TUAS AVENUE 18  
SINGAPORE 638894

TERMS: 30 DAYS

DATE: 22.8.2019

ITEM	DESCRIPTION	AMOUNT
	Payment for 2 Days rental @ \$120 per day	\$ 240.00

Vehicle Number : SLG 1176 R

Rental Period : 20th August 2019 - 22nd August 2019



TOTAL AMOUNT: \$ 240.00

RECEIVED BY



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-19-135393

Date of Request: 21/08/2019

Your Ref No:

Online Purchase

Goldbell Engineering Pte Ltd  
29, Tanjong Panjuru  
Singapore 609026

Dear Sir/Madam,

Enquiry Date 21/08/2019  
Enquiry By Mohamad Bin Omar  
TP Vehicle No. YP6593K  
Accident Date 19/08/2019

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
YP6593K	AXA Insurance Pte Ltd	29/06/2019-28/06/2020	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-19-135393  
Date of Request: 21/08/2019

Your Ref No: Online Purchase

Goldbell Engineering Pte Ltd  
29, Tanjong Penjuru  
Singapore 609026

Dear Sir/Madam,

Enquiry Date 21/08/2019  
Enquiry By Mohamad Bin Omar  
TP Vehicle No. YP6593K  
Accident Date 19/08/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19014655/R1gb3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:JAS

Date : 30-10-2019



Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	YK 6593K	Veh. Inspected	SLK 53Y
Policy No.	P1969204	Coverage (\$)	0.00
Claim No.	S9M01XPU	Excess (\$)	0.00
Assign From		Assign Date	21/08/2019

**2. Vehicle Particulars & Condition**

Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11106359	Colour	BLUE
Odometer	92156	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	215/60 R16	TOYO	6 mm
L/H Front Tyre	215/60 R16	TOYO	6 mm
R/H Rear Tyre	215/60 R16	TOYO	6 mm
L/H Rear Tyre	215/60 R16	TOYO	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

Accident Date	19/08/2019	Inspection Date	21/08/2019
Survey held at	GOLDBELL ENGINEERING PTE LTD 10 TUAS AVE 18 SINGAPORE 638894		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No, 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 53Y**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<b>REPLACEMENT OF PARTS</b>	CRACKED		
	RHS WING MIRROR ASSY-COMPLETE (CONSISTENT)		794.00	794.00
	LESS 20% DISCOUNT		-	-158.80
			794.00	635.20
	<b>LABOUR</b>			
	TO REMOVE AND REINSTALL RHS WING MIRROR ,AND WIRING SYSTEM AND PROGRAMMING.		380.00	100.00
	SPRAY PAINTING OF ACCIDENT SECTIONS.		150.00	100.00
	RE-WIRING.		80.00	40.00
			610.00	240.00
<b>GRAND TOTAL</b>			<b>1,404.00</b>	<b>875.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>700.00</b>

Report Ref No: CC4/ASM19014655/R1gb3q2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

⏪ Service Request Details

Claim

SYN01XPU

Reference

CC4/ASM19014655/B1gb3o2 

Loss Date

19 August 2019

Report Date

21 Aug 2019 10:39:00 AM

Request Date

21 August 2019

Due Date

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TPP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SLK53Y

Make

BMW

Model

VEZEL 1.5 X CT

Service Address

...

Primary Contact/Insured

KIAN SENG YONG IMPORT & EXPORT PTE LTD  
BLK 23 PASIR PANJANG, #01-173 WHOLESALE CENTRE, 110023, Singapore  
65674755

Claim Handler

TAN Jai  
6568804844  
jai.tan@axa.com.sg

Actions

Next Step

Wait for: Approve Invoice

ADD Invoice

Additional Instructions

1

Messages

Invoices

History

Documents

Assessment


Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement		Mertimen	



NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (2).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
CIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
LETTER TO Olignt	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 October 2019
PAIR COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 October 2019
TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 October 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 October 2019
MANDATE IA DO 18102019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 October 2019
LOD AND OTHER DOCUMENTS	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 October 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP-IA 53.pdf	Reports & Statement	Others	L&K AUTO CONSULTANTS PTE LTD (TP)	22 August 2019
 TP GOLDBELL EMAIL TP RPL.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	21 August 2019