

VIVIAN

FOR SURVEYOR 21/08/2019

TP-AXA-LMS.

DATE : 21/8/2019  
TO : MSIG MOTOR CLAIMS DEPT  
ATTN :  
OFFICE / MOBILE :  
EMAIL ADDRESS :

VEHICLE NO. : SLK53Y  
MODEL NO. : HONDA VEZEL 1.5X CVT  
CHASSIS NO. : RU11106359  
ENGINE NO. : L15B4026365  
REG. DATE : 16/2/2016

FROM : GOLDBELL ENGINEERING PTE LTC  
ATTN : MOHAMAD OMAR  
OFFICE / MOBILE : 97396452  
FAX NO. :

REF. NO. :  
D.O.A. : 6/12/2019  
POLICY NO. : A 28876396 QMY  
CLAIM TYPE : 3rd Party Claim

WORKSHOP : Blk K, Pandan Loop Ind. Estate #01-12 Singapore 128219

| S/N | PART NO. | DESCRIPTION                              | QUANTITY       | LIST PRICE  |
|-----|----------|------------------------------------------|----------------|-------------|
| 1   |          | RHS WING MIRROR ASSY-COMPLETE <i>CRU</i> | 1              | \$ 794.00   |
|     |          |                                          | 794            |             |
|     |          |                                          | SUB-TOTAL :    | \$ 794.00   |
|     |          |                                          | 202            |             |
|     |          |                                          | PARTS TOTAL :  | \$ 794.00   |
|     |          |                                          | 635.20         |             |
|     |          |                                          | 240.00         |             |
|     |          |                                          | 875.20         |             |
|     |          |                                          | 202            |             |
|     |          |                                          | 700.16         |             |
|     |          |                                          | 43.700         |             |
|     |          |                                          | LABOUR TOTAL : | \$ 610.00   |
|     |          |                                          | TOTAL :        | \$ 1,404.00 |
|     |          |                                          | 7% GST         | \$ 98.28    |
|     |          |                                          | GRAND TOTAL :  | \$ 1,502.28 |

PREPARED BY : MOHAMAD OMAR  
DATE / TIME : 21/08/19 @ 1410  
SURVEYOR : *Rajini*  
MOBILE NO. : *9001068*  
OFFICE FAX NO. :  
EMAIL ADDRESS : *rasul@lkkauto.com*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR : Rasul  
MOBILE NO. : 90010068  
OFFICE FAX NO. : \_\_\_\_\_  
E MAIL ADDRESS : rasul@lkkauto.com

REPAIR TYPE : PART-BY-PART / LUMP SUM  
RE-SURVEY : BEFORE PAINT / AFTER PAINT  
NO. OF DAYS : 2 day  
REMARKS : \_\_\_\_\_

R

21/08/19 @ 1400