

FOR SURVEYOR 21/08/2019
\$7P-AXA-LMS.

DATE : 21/8/2019
TO : MSIG MOTOR CLAIMS DEPT
ATTN :
OFFICE / MOBILE :
EMAIL ADDRESS :

VEHICLE NO. : SLK53Y
MODEL NO. : HONDA VEZEL 1.5X CVT
CHASSIS NO. : RU11106359
ENGINE NO. : L15B4026365
REG. DATE : 16/2/2016

FROM : GOLDBELL ENGINEERING PTE LTD
ATTN : MOHAMAD OMAR
OFFICE / MOBILE : 97396452
FAX NO. :

REF. NO. :
D.O.A. : 6/12/2019
POLICY NO. : A 28876396 QMY
CLAIM TYPE : 3rd Party Claim

WORKSHOP : Blk K, Pandan Loop Ind. Estate #01-12 Singapore 128219

S/N	PART NO.	DESCRIPTION	QUANTITY	LIST PRICE
1		RHS WING MIRROR ASSY-COMPLETE <i>cr</i>	1	\$ 794.00

SUB-TOTAL : \$ 794.00

PARTS TOTAL : \$ 794.00

LABOUR CHARGES

1 TO REMOVE AND RE-INSTALL RHS WING MIRROR,
AND WIRING SYSTEM AND PROGRAMMING.

\$ ~~100~~ 380.00

2 SPRAY PAINTING OF ACCIDENT SECTIONS

\$ ~~100~~ 150.00

3 RE-WIRING

\$ ~~40~~ 80.00

LABOUR TOTAL : \$ 610.00

TOTAL : \$ 1,404.00

7% GST \$ 98.28

GRAND TOTAL : \$ 1,502.28

PREPARED BY : MOHAMAD OMAR

DATE / TIME : 21/08/19 @ 1410

SURVEYOR : *Rasul*

MOBILE NO. : 90010068

OFFICE FAX NO. :

EMAIL ADDRESS : *rasul@lkkauto.com*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR : Rasul
MOBILE NO. : 90010088
OFFICE FAX NO. : _____
E MAIL ADDRESS : rasul@lkkauto.com
REPAIR TYPE : PART-BY-PART / LUMP SUM
RE-SURVEY : BEFORE PAINT / AFTER PAINT
NO. OF DAYS : 2 day
REMARKS : _____

R