

22/03/2003

ASS. REC. BY

REF

CS³/SM019014674 R1c302

Special Instruction:

Surveyor: RUSAASSIGNMENT (Office)From (Person): Agnes Chan Shin Hui of SMDDate/Time: 21.2.19 8.49a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGJ 8021BInsured: SKT 9339Dat Workshop m/s Willy motorTel: 92767180of 27A Jurong Pk RoadPolicy No: D18M PV 01015284Claim No: CMTD 1903932

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 18.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 21.2.19 10.19a.mPerson Contacted: ms khooVehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SGJ 8021B - ✓

SKT 9339D - ✓

4/10 -

No estimate,

After repair: 28/8/2019

ASS. REC. BY:

REF:

158C

COB EXPIRY: 2026/Jun

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGJ 8021Bat Workshop m/s WILLY MOTORof 27A, Juncuba Port RDInsured: SMU

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 40K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGJ 8021B Yr Regn: 2006 / JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA ALTIS 1.6A c.c. 1598Colour: GRN A/C: Insured / Std / NI / NASp. Reading: 29 2279 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0532EC107127337Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRM / STD A/Rim orTyre Size: F: 185/70R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIP / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 18/08/19 D.O.I. 21/08/19Survey held at WILLY MOTORDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	repair limit 8k
	Route / days - (7k - 8k) / 10 days

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 10

1)

☐

Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week end (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others:

TOTAL

Report Format: PRE.

Lump Sum / LBJ: \$

100


60

11

171

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Aug 2019		21 Aug 2019 08:49 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS							[Created by insurer]		
Insured:		TAN WOON SZU, ID: S1624025G							
Main Claimant:		STEVEN TEO ENG HOCK, ID: S0087158C							
Vehicle Reg. No.:		SGJ8021B			Date of Loss:		18/08/2019 15:00 - :59		
Claim Type:		TP / CMTD1903932			Policy/Cover Note No.:		D18MTPV01015284 (Comprehensive)		
Vehicle Reg. No. (Insured):		SKT9339D			Policy No. (Claimant):				
					Excess:				
Repairer:		Willy Motor Company (HQ) 27A JURONG PORT ROAD, #01-32, 619101 Jurong Island - Tel:							
Handling Insurer:		Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/08/2019]							
Driver/Custodian (Insured):		ANG WOON CHOO (), NRIC: S1796044Z, Tel: +6586138249 Email:							
Adj Asg. Remarks:		WS: MS KHOO 92767180							
ASSOCIATED MAIL RECEIVED							View All		Compose Case Mail
There are no mail for this case.									
<div>  ALL ASSOCIATED TASKS </div> <div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> </div> <div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div>									
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	158C
Vehicle Details	
Vehicle No.:	SGJ8021B
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4590090
Chassis No.:	MR053ZEC107127337
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,950.00
Original Registration Date:	21 Jul 2006
First Registration Date:	21 Jul 2006
Transfer Count:	1
Actual ARF Paid:	\$17,545.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2026
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$46,454.00
COE Rebate Amount:	\$31,846.00
Total Rebate Amount:	\$31,846.00

The information contained herein is correct as at 22 Aug 2019

OK

40,000
31,846

8,154
(8k)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 14:49
Date Of Accident	18/08/2019 15:30
Exact Location Of Accident	PIE TO CHANGI AIRPORT BEFORE EXIT - 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGJ8021B
Insured/Policyholder	
Name Of Registered Owner	STEVEN TEO ENG HOCK
NRIC No	S0087158C
Email Address	SSTEO1234@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90220544
Alternative Phone No	OFFICE-90220544

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5080832270-03
Cover Note Number	

Driver

Name of Driver	STEVEN TEO ENG HOCK
NRIC No	S0087158C
Date Of Birth	09/11/1946
Occupation	INDOOR
Date Of Driving Pass	28/05/1971
Driving Experience	48 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90220544
Fax Number	
Contact Number	OFFICE-90220544

Address	BLK 10 LAKEPOINT DRIVE #08-56
Postcode	648927
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MIN WOO YUTT TEE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT9339D
Vehicle Make/Model/Colour	NA
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	MS ANG WOON CHOO
NRIC/Passport Number	
Contact Number	NA
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Travelling along PIE to Terminal 4 Airport
Suddenly was hit from behind
The lady driver apologises and
we exchange particulars.
2 vehicles & no one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

19/8/2019
Pudus

Sketch Plan #2


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If Driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Richard 19/8/2015

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Aug 2019		21 Aug 2019 08:49 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAN WOON SZU , ID: S1624025G									
Main Claimant: STEVEN TEO ENG HOCK , ID: S0087158C									
Vehicle Reg. No.: SGJ8021B		Date of Loss: 18/08/2019 15:00 - :59 [156 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / CMTD1903932		Policy/Cover Note No.: D18MTPV01015284 (Comprehensive)							
Vehicle Reg. No. (Insured): SKT9339D		Policy No. (Claimant):							
		Excess:							
Repairer: Willy Motor Company (HQ) 27A JURONG PORT ROAD, #01-32, 619101 Jurong Island - Tel:									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/08/2019]									
Driver/Custodian (Insured): ANG WOON CHOO () , NRIC: S1796044Z, Tel: +6586138249 Email:									
Adj Asg. Remarks: WS: MS KHOO 92767180									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGJ8021B (CMTD1903932)
[SKT9339D]

TP

STEVEN TEO ENG HOCK









































Aug 18 2019 3:00PM






























[TAN WOON SZU]

Willy Motor Company

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print	
1	21/08/19 08:49	Accident Statement From: SC - Reg. No: SKT9339D, Claimant: TAN WOON SZU	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
34	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
35	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
36	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
37	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
38	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	
39	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
40	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
54	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
55	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
56	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
57	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
58	04/10/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
59	04/10/19 17:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	04/10/19 17:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	04/10/19 17:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	04/10/19 17:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	04/10/19 17:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	04/10/19 17:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	04/10/19 17:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	04/10/19 17:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	20/08/19 16:26	Pre-Repair Survey +GIA	 Load PDF	
2	21/08/19 08:50	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19014672/R1CF3E2

Date: 07/10/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01015284
Claimant Vehicle No :	SGJ8021B	Insured Vehicle No :	SKT9339D
Date of Loss:	18/08/2019	Nature of Claim:	TP
		Claim No:	CMTD1903932

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGJ8021B	Engine No:	3ZZ4590090
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107127337
Reg. Date:	21/07/2006 (Man. Year: 2006)	Odometer:	292279 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/08/2019	
Date Inspected:	21/08/2019	Inspected At: Willy Motor Company (HQ) 27A JURONG PORT ROAD, #01-32 Singapore 619101
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 -\$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGJ8021B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >