

ASS. REC. BY:

REF:

CS/ASM19014677/At d362

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Chan Kian chuen

of ASM(AXA)

Date/Time: 20/8/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 2681L

Insured:

at Workshop in/s

CAS Garage

Tel:

97916119 @ 64842220

of

1 kaki Bukit Ave 6 # 02-22

Policy No:

Claim No:

S9M01UPF

Sum Insured:

Excess:

0.00

Make of Veh:

D.O.A.

19/07/2019

(Client's Record)

CA / AE / REP. / REV 24 HRS

22/8/19 @ Client Adrian Suny

H.O.D. Endorsement:

Date/Time:

10:25am @ 21/8/19

Person Contacted:

Nicole

Vehicle IN/OUT

Date/Time

Action/Instruction

Johny ✓

SLH 2681L

23/8-9:43am Revert via smart claim.

26/8-1:32pm- uploaded cost price & IA.

26/8-1:42pm- authorise repair by Kian Chan.

ASS. REC. BY: AdnanREF: ASN (AXA)

ASSIGNMENT

From:

Date:

22.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLH 2681Lat Workshop m/s CAS Garageof 1 Kaki Bukit Ave 6 # 02-22

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLH 2681L

Yr Regn:

2016, OctType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo S60

C.C

1969

Colour:

Red.

A/C:

Insured / Std / NI / NA

Sp. Reading

825/6

T/Radio:

Insured / Std / NI / NA

Eng/No:

YVIFSA8CDH 2426336.

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R16.

R:

215/55R16.BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

22/08/19.

Survey held at

CAS.Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AXAlump sum \$6000 (Red: 11356.48, 65%)MV: 80KPV: 54.2KNet: 25.8K.According to insurance received Dr k Final Bill.

Date/Time, File Pass to?



: Preli. Report

1) 9/9 typist

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

290290

Report Format:

OD

Lump Sum / L.B.F. (\$)

6000




Service Request Details

Claim

S9M01UPF

Reference

None 

Loss Date

July 19, 2019

Report Date

Jul 22, 2019 2:42:08 PM

Request Date

August 20, 2019

Due Date

August 27, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLH2681L

Model

S60 D4

Service Address

...

Primary Contact/Insured

CUPPACHOICE INTERNATIONAL PTE LTD

15 JALAN TEPONG, #05-03 JURONG FOOD HUB, 619336, Singapore

68972822

FECELIA@DAGLEN.COM/CS@DAGLEN.COM

Claim Handler

CHAN Kian Chuan

68805444

kianchuan.chan@axa.com.sg

Additional Instructions

XS \$0.00 WS: CAS GARAGE PTE LTD

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Re:RE: Re:AI uploaded SLH 2681H

Type

 Question

Message

PLS PROCEED TO AUTHORIZED REPAIRS

Reply

MODEL
S60 D4

Service Address

...

Primary Contact/Insured

CUPPACHOICE INTERNATIONAL PTE LTD
15 JALAN TEPONG, #05-03 JURONG FOOD HUB, 619336, Singapore
68972822
FECELIA@DAGLEN.COM/CS@DAGLEN.COM

Claim Handler

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg

Additional Instructions
XS \$0.00 WS: CAS GARAGE PTE LTD

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

New Message

TYPE	<div>?</div>
SENT	8/26/19 1:42 PM
FROM	CHAN Kian Chuan
SUBJECT	Re:RE: Re:AI uploaded SLH 2681H
BODY	PLS PROCEED TO AUTHORIZED REPAIRS
	<div>↩</div>

TYPE	<div>?</div>
SENT	8/26/19 1:32 PM

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 26 August 2019 5:02 PM
To: Allan Goh; SUR
Cc: Nicole Chong
Subject: RE: Scan Data from FX-C8F072

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLH 2681H (Excess \$0.00/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Allan Goh <allangoh.cas@gmail.com>
Sent: Thursday, 22 August 2019 6:19 PM
To: SUR <sur@lkkauto.com>
Cc: Nicole Chong <nicolechong.cas@gmail.com>
Subject: Fwd: Scan Data from FX-C8F072

Hi Sur,

Please refer to the cost price estimate for Volvo S60 SLH2681L .

We would like to request for lumpsum repair.

Thank you

Regards,
Allan Goh
CAS Garage Pte. Ltd.
No.1 Kaki Bukit Ave 6
#02-22
Singapore 417883
UEN: 201828067M
Tel: 6484 2220
Mobile: 8782 7171



Re:AI uploaded SLH 2681H

Type

🔗 Question

Message

PLS CLARIFY ON THE COR & SEEK MANDATE FOR AUTHORIZATION OD CLAIM UNABLE TO HOLD.

Reply



AI uploaded SLH 2681H

Type

🔗 Question

Message

Dear Kian Chun, Please be inform that the Damage Consistent, Repair cost economical, Pending cost price, Repairer is asking of lump sum, We did not authorize repair. Regards Denise

Reply

MODEL
S60 D4

Service Address

...

Primary Contact/Insured



CUPPACHOICE INTERNATIONAL PTE LTD
15 JALAN TEPONG, #05-03 JURONG FOOD HUB, 619336, Singapore
68972822
FECELIA@DAGLEN.COM/CS@DAGLEN.COM

Claim Handler

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg
Additional Instructions
XS \$0.00 WS: CAS GARAGE PTE LTD

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

New Message

TYPE	
SENT	8/23/19 9:48 AM
FROM	LKK AUTO CONSULTANTS PTE LTD (OD)
SUBJECT	AI uploaded SLH 2681H
BODY	Dear Kian Chun, Please be inform that the Damage C...
	

TYPE	?					
SENT	8/21/19 2:44 PM					

KADRI Mateen

From: Nicole Chong <nicolechong.cas@gmail.com>
Sent: Tuesday, August 20, 2019 10:29 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Allan Goh; Cher Yip
Subject: [EXTERNAL] PRI - SLH 2681L DOA 19.07.2019 (OWN DAMAGE CLAIM)
Attachments: 2681est.pdf

Categories: Mateen

Dear Sir /Madam,

Please find the attached estimate.

Kindly arrange survey our client's vehicle.

Do let us know when is the available date and time for inspection of the vehicle at:

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Once arranged, please contact Allan Goh at 8782 7171 during the inspection.

Thank you and have a nice day! Hope to hear from you soon

Regards,

Nicole Chong

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Hp: 9791 6119

Office: 6484 2220

UEN: 201828067M



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

Date: 23/8/2019

To : AXA Insurance Pte Ltd

Survey details

Date of loss	19-Jul-19
Date of appointment	22-Aug-19
Date of survey	22-Aug-19
Location of survey	CAS Garage

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLH 2681L
Make and Model	VOLVO S60 D4
Date of registration	27/10/2016
Excess	0.00
Market Value	\$80,000
Parf Rebate	\$54,187
Nett Loss	\$25,813

Repair details

Initial Estimate	\$23,185
------------------	----------

Proposed/Revised repair cost:

Parts	\$11,869
Check item	\$0
Labour	\$780
Total	\$12,649
Lump Sum(if applicable)	\$10,200

Number of days of repair	4
--------------------------	---

Remarks:

Damage Consistent
Repair cost economical
Pending cost price
Repairer is asking of lump sum

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 134Z

Vehicle Details

Vehicle No.: SLH2681L

Vehicle to be Exported: No

Intended Deregistration Date: 24 Jul 2019

Vehicle Make: VOLVO

Vehicle Model: S60 D4

Primary Colour: Red

Manufacturing Year: 2016

Engine No.: D4204T141759831

Chassis No.: YV1FSA8CDH2426336

Maximum Power Output: 140.0 kW (187 bhp)

Open Market Value: \$27,841.00

Original Registration Date: 27 Oct 2016

First Registration Date: 27 Oct 2016

Transfer Count: 0

Actual ARF Paid: \$20,978.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Oct 2026

PARF Rebate Amount: \$15,733.00

Intended COE Rebate Details

COE Expiry Date: 26 Oct 2026

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$54,200.00

COE Rebate Amount: \$38,454.00

Total Rebate Amount: \$54,187.00

The information contained herein is correct as at 23 Jul 2019

OK

Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.
Advertise it for sale at just \$58, list till sold.

Volvo S60 Price Range Depreciation 2016 Vehicle Type

Advanced Search

Home » Used Cars » Carsmart Pte Ltd » Volvo S60 Diesel D4

Volvo S60 Diesel D4

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$85,000	Fuel Type	Diesel (Euro 5 Engine and Above)
Depreciation	\$10,830 /yr View models with similar depre	Reg Date	21-Jun-2016 (6yrs 10mths 28days COE left)
Mileage	61,000 km (19.8k /yr)	Manufactured	2016
Road Tax	\$1,864 /yr	Transmission	Auto
Dereg Value	\$48,101 as of today (change)	OMV	\$27,316
COE	\$47,604	ARF	\$20,243
Engine Cap	1,969 cc	Power	140.0 kW (187 bhp)
Curb Weight	1,615 kg	No. of Owners	2
Type of Vehicle	Luxury Sedan		

Features

Powerful Yet Economical 2L Inline 4 Cylinders Twin Turbo 187 Bhp, 400NM Of Torque, 0 To 100 Km At 7.6 Secs, 8 Speed Automatic Transmission. View specs of the Volvo S60 Diesel (2013-2017)

Accessories

Digital Display, Multi-Function Steering, Cruise Control, Keyless Entry/Start, Rain Sensors, Bluetooth Connectivity, Power Memory Seats.

Description

Consignment Unit! 1 Owner Only! Agent Warranty With Fully Agent Serviced! 1 Remaining Servicing. Well Known For Its Stability And Safety! Original BBS Rim, New Battery & Tyres! Front/Back Camera! Owner Changing Car To 7 Seaters MPV Due To Family Expansion. Car Number Plate Will Be Retained By Existing Owner. STA/VICOM/AA Evaluation Friendly. Welcome Trade-in. Bank Loan And In House Loan Supported!

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company	Carsmart Pte Ltd » dealer's pricelist » 5 vehs sold 7 vehs available	
Address	21 Woodlands Close #05-15 Search cars nearby this location	
Location	Primz Bizhub	
Office No	62006351	
Contact Person(s)	Tony	88213020
	Vince	86878866

Posted on: 29-Jun-2019 | Last Updated on: 29-Jun-2019

Upfront Payment:

» more Financial info

Tr: - -
Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/07/2019 11:10
Date Of Accident	19/07/2019 15:15
Exact Location Of Accident	CROSS JUNCTION OF BOONLAY WAY CORPORATION ROAD.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH2681L
Insured/Policyholder	
Name Of Registered Owner	CUPPACHOICE INTERNATIONAL PTE LTD
Co Reg No	200105134Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-82289202

Vehicle Particulars

Manufacturer	VOLVO
Model	S60 D4

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA404190/1
Cover Note Number	

Driver

Name of Driver	CHONG SING RUI
NRIC No	S9607207D
Date Of Birth	07/02/1996
Occupation	INDOOR
Date Of Driving Pass	04/04/2017
Driving Experience	2 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83380086
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 666A JURONG WEST ST 65 #03-191
 Postcode 641666
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 19th JULY 2019 AT ABOUT 1515HRS AT THE CROSS JUNCTION OF BOON LAY WAY AND CORPORATION ROAD. I WAS TURNING RIGHT TOWARDS CORPORATION ROAD. AS I MOVED OFF, VEHICLE B SLX6723P SLOWED DOWN INFRONT OF ME. I DID NOT STOP MY VEHICLE IN TIME CAUSING MY VEHICLE A (SLH2681L) TO HIT THE REAR PORTION OF VEHICLE B. THERE WERE NO PASSENGER IN BOTH VEHICLES AS THE ACCIDENT HAPPENED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLX6723P
 Vehicle Make/Model/Colour
 Details Of Properties VEH B
 Vehicle Category PRIVATE CAR
 Name of Driver TIAR NAN CHEAN
 NRIC/Passport Number S7106150G
 Contact Number 82087171
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Cos Garage

Accident Sketch Plan Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14th July 2019 at about 1515 HRS at the cross-junction of Broomley Way and Corporation Road. I was turning right towards Corporation Road. As I moved off, vehicle (B), SIX6723P slowed down in front of me. I did not stop my vehicle in time causing my vehicle (A), SLH2681L to hit the rear portion of vehicle (B).

There were no passengers in both vehicles as the accident happened.



Reporting Centre Personnel's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LETTER OF UNDERTAKING

I/We, Chong Sing Rui, the owner of vehicle no. S4H 2681L

My/Our Insurance is under M/s AXA Insurance Pte Ltd, I/we shall decide whether claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, Cos Garage

Signed and Acknowledge by:

SSHHH500C

Nric no. & signature of policyholder



Company stamp

Date

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AXA INSURANCE

Address: NO 8, SHENTON WAY, #24-01
AXA TOWER, S(068811)

Telephone: 68804888 Fax: 68804740

Email: motor.survey@axa.com.sg

Make/ Model : VOLVO S60 D4

Date: 16.08.2019

Chassis No : YV1FSA8CDH2426336

Vehicle No: SLH2681L

Date/Time of Accide 19.07.2019/1515

Reg date : 27.10.2016

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	COST PRICE \$	COST PLUS	FINAL PRICE \$
1	FRONT BUMPER Def	1	\$ 1,856.00	10%	\$ 2,041.60
2	FRONT BUMPER RETAINERS met	2	\$ 130 65.00	10%	\$ 143.00
3	FRONT BUMPER LOWER BRACKETS RH dented	2	\$ 85.00	10%	\$ 187.00
4	FRONT BUMPER REINFORCEMENT COVER dented	1	\$ 285.00	10%	\$ 313.50
5	FRONT BUMPER REINFORCEMENT Bent	1	\$ 450.00	10%	\$ 495.00
6	FRONT BUMPER DAYLIGHT X nn	2	\$ 350.00	10%	\$ 770.00
7	FRONT BUMPER DAYLIGHT COVER X nn	2	\$ 105.00	10%	\$ 231.00
8	FRONT BUMPER DAYLIGHT COVER GARNISH X 2m	2	\$ 65.00	10%	\$ 143.00
9	FRONT BUMPER LOWER GRILLE nn X	1	\$ 90.00	10%	\$ 99.00
10	FRONT BUMPER LOWER COVER cra	1	\$ 350.00	10%	\$ 385.00
11	FRONT RADIATOR SUPPORT GUIDE cra	2	\$ 185.00	10%	\$ 407.00
12	FRONT SUPPORT PANEL + nn	1	\$ 750.00	10%	\$ 825.00
13	FRONT CONDENSER + nn	1	\$ 480.00	10%	\$ 528.00
14	FRONT INTERCOOLER dent	1	\$ 1,380.00	10%	\$ 1,518.00
15	FRONT RADIATOR GRILLE cracked	1	\$ 745.80	10%	\$ 820.38
16	FRONT RADIATOR GRILLE LOGO rec	1	\$ 55.00	10%	\$ 60.50
17	FRONT BONNET X nn	1	\$ 2,235.00	10%	\$ 2,458.50
18	FRONT FENDER INNER COWLING X nn	2	\$ 125.00	10%	\$ 275.00
19	FRONT HEADLAMP cracked	2	\$ 920.00	10%	\$ 2,024.00
20	FRONT HEADLAMP BRACKETS + nn	2	\$ 60.00	10%	\$ 132.00
Total List Price Cost					\$ 13,856.48

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	FRONT NUMBER PLATE WITH CASING <i>Bent</i>	1 SET	\$ 50.00	✓	\$ 50.00
2	FRONT BUMPER UNDER COVER CLIPS <i>Nec</i>	1 SET	\$ 30.00	✓	\$ 30.00
3	FRONT BUMPER CLIPS <i>Nec</i>	1 SET	\$ 30.00	✓	\$ 30.00
Total Special Nett Items					\$ 110.00

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN ,STRAIGHTENED MEMBER	\$ 1,600.00
	500
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,200.00
	250
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 150.00
TO REMOVE/ REFIT WIRING CHECKS FOR FRONT HEADLAMPS AND RESET	\$ 30 120.00
TO REMOVE/ REFIT FRONT CONDENSER AND TOP UP AIR CON GAS	\$ 7 120.00
TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	\$ 7 200.00
Total Others Cost	\$ 590.00
GRAND TOTAL	
	\$ 17,356.48

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax : 6509 9501
 TEL: 64842220

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AXA INSURANCE

Address: NO 8, SHENTON WAY, #24-01
AXA TOWER, S(068811)

Telephone: 68804888 Fax: 68804740

Email: motor.survey@axa.com.sg

Make/ Model : VOLVO S60 D4

Date: 16.08.2019

Chassis No : YV1FSA8CDH2426336

Vehicle No: SLH2681L

Date/Time of Accide: 19.07.2019/1515

Reg date : 27.10.2016

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BUMPER <i>Rebuilt</i>	1	\$ 2,956.30	✓	\$ 2,956.30
2	FRONT BUMPER RETAINERS <i>new</i>	2	\$ 121.50	✓	\$ 243.00
3	FRONT BUMPER LOWER BRACKETS <i>PA Weld</i>	2	\$ 135.60	135.60	\$ 271.20
4	FRONT REINFORCEMENT ABSORBER <i>Weld</i>	1	\$ 435.60	✓	\$ 435.60
5	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 580.90	✓	\$ 580.90
6	FRONT BUMPER DAYLIGHT <i>old new</i>	2	\$ 498.70	x	\$ 997.40
7	FRONT BUMPER DAYLIGHT COVER <i>new</i>	2	\$ 157.50	x	\$ 315.00
8	FRONT BUMPER DAYLIGHT COVER GARNISH <i>new</i>	2	\$ 97.80	x	\$ 195.60
9	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 145.80	x	\$ 145.80
10	FRONT BUMPER LOWER COVER <i>could</i>	1	\$ 367.50	✓	\$ 367.50
11	FRONT RADIATOR SUPPORT GUIDE <i>new part could</i>	2	\$ 284.20	284.20	\$ 568.40
12	FRONT RADIATOR GRILLE <i>could</i>	1	\$ 1,354.80	✓	\$ 1,354.80
13	FRONT RADIATOR GRILLE LOGO <i>new</i>	1	\$ 95.60	✓	\$ 95.60
14	FRONT SUPPORT PANEL <i>new</i>	1	\$ 1,012.80	x	\$ 1,012.80
15	FRONT CONDENSER <i>new</i>	1	\$ 650.30	x	\$ 650.30
16	FRONT INTERCOOLER <i>new dentured</i>	1	\$ 1,985.60	x	\$ 1,985.60
17	FRONT BONNET <i>new</i>	1	\$ 3,587.60	x	\$ 3,587.60
18	FRONT FENDER INNER COWLING <i>new</i>	2	\$ 198.60	x	\$ 397.20
19	FRONT HEADLAMP <i>could</i>	2	\$ 1,659.80	✓	\$ 3,319.60
20	FRONT HEADLAMP BRACKETS <i>new</i>	2	\$ 102.60	x	\$ 205.20
Total List Price Cost					\$ 19,685.40

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	FRONT NUMBER PLATE WITH CASING <i>Best</i>	1 SET	\$ 50.00		\$ ✓ 50.00
2	FRONT BUMPER UNDER COVER CLIPS <i>re</i>	1 SET	\$ 30.00		\$ ✓ 30.00
3	FRONT BUMPER CLIPS <i>Mer</i>	1 SET	\$ 30.00		\$ ✓ 30.00
Total Special Nett Items					\$ 110.00

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN ,STRAIGHTENED MEMBER	\$ 1,600.00 500
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,200.00 250
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ X 150.00
TO REMOVE/ REFIT WIRING CHECKS FOR FRONT HEADLAMPS AND RESET	\$ 30 120.00
TO REMOVE/ REFIT FRONT CONDENSER AND TOP UP AIR CON GAS	\$ X 120.00
TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	\$ X 200.00
Total Others Cost	\$ 590.00
GRAND TOTAL	\$ 23,185.40

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allangoh.cas@gmail.com
Fax : 6509 9501
TEL: 64842220

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
1/5 22/08/19.
04 Days.